

INS. CASE OWNER:

June

CC 3 / CT118003241

Kles38

LKK:

IDAC:

Surveyor:

KALVIN

DOI:

ASSIGNMENT

20/02/18

Date / Time:

20/02/18

Registered in Morion:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKF 7456K

Claim No.:

9NM18D0093602

Name of Insured:

YEO KIAN LEE

Policy No.:

DMPCSN 3049361701

Insured Tel No.:

HP: 9750 6872

Make / Model:

AUDI

Excess Sec II :SS

D.O.A.: 17/02/18

Place of Accident:

JUNCTION OF XILING AVE & UPP  
CHANGI RD EAST

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

% Final ? Yes / No

SHC 6915K



INSRS:

WSP: Premier Auto (Chang)

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SHC 6915K - CC3/DAI18003241/KLES D.O.A.: 14/02/18  
 - CS1/MG17022162/KLES D.O.A.: 16/1/17  
 - CS3/ITE11025535/KLES D.O.A.: 19/12/14  
 - NA/IVC09017834/PI D.O.A.: 02/04/09  
 - NA/IVC1401561/PI D.O.A.: 14/2/14  
 SKF 7456K - CC3/AEG15003265/AEG D.O.A.: 06/02/18  
 - CC4/AEG16015127/KWJ D.O.A.: 12/03/18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

EMAIL 27/2/18

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

☐☒☒☒☒☒☒☒☒☒☒☒☒☒☒

PRELIMINARY ADVICE

Date/Time: 21/02/18

Sent By:

Shirley H.iew

FINALIZATION

Date/Time: 26/2/18

Confirm with: GARY

Repair Cost:

SS 1150.00

( 2 days) Reduction:

63 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time: 22/3/18

Confirm with: GARY

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

27

Repair Cost:

SS 1,230.50

OI REPAIR ENDED TP

Loss of Rental (LOR):

SS 410.88

( 4 days) x 102.12

Loss of Use (LOU):

SS -

( 5 x days)

Loss of Income (LOI):

SS 160.00

( 5 40 x 4 days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LO ☒

[Tick only one]

GIA/LTA Search

SS 2.00

Medical:

SS -

Disbursement:

SS -

(e.g. Tow/ Independent)

Legal Cost

SS -

Total:

SS 1,803.38

Global Sum SS:

FINAL PAYMENT

Date/Time: 22/3/18

Confirm with: GARY

Payee 1:

SS 1,803.38

Name 1:

PREMIER AUTOMOTIVE SERVICES PTE LTD

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: P 400

COPY SENT  
27/03/18

Time: 10:15 Calvin

REF:

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimate Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp at Vehicle No: \_\_\_\_\_

at Work Stop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHC 6915K

Yr Regn: 904 21

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA optima

C.C. 168

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 249074

T/Radio: Ins 0 / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KNA 6A 414 MF 5 (2224)

Gen. Cond: Good / 0 / Poor / Burnt

Steering: In order / 0 / Jammed / Leaked / Burnt or

Brake: In order / 0 / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or.

Tyre Size: F: 205 / 65 R 16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Pirelli

Front

Rear

R/Bal. 7 mm

R/Bal. 7 mm

L/Bal. 7 mm

L/Bal. 7 mm

D.O.A. 17/2/18

D.O.I. 2/2/18

Survey held at Pirelli

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

CTI

45:41.150 (RBD: 42,414.30 60%)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_ \$ + RS \_\_\_\_\_ \$

Photos: \_\_\_\_\_

Other: \_\_\_\_\_



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                                                                         |                                                                                         |                 |                             |                                                                                     |
|-------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|-----------------|-----------------------------|-------------------------------------------------------------------------------------|
| CHINA TAIPING INSURANCE (S) PTE LTD                                                                                                       |                                                                                         |                 | Ref : CC3/CTI18003241/K1es3 |                                                                                     |
| 3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERS SINGAPORE 079909                                                                                 |                                                                                         |                 | Date : 20-02-2018           |  |
|                                                                                                                                           |                                                                                         |                 | Code : CTI                  |                                                                                     |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                                                                         |                                                                                         |                 |                             |                                                                                     |
| Insured Veh.                                                                                                                              | SKF 7456K                                                                               | Veh. Inspected  | SHC 6915K                   |                                                                                     |
| Policy No.                                                                                                                                | DMPCSN3049361701                                                                        | Coverage (\$)   | 0.00                        |                                                                                     |
| Claim No.                                                                                                                                 | SNM18D00936C02                                                                          | Excess (\$)     | 0.00                        |                                                                                     |
| Assign From                                                                                                                               |                                                                                         | Assign Date     | 20/02/2018                  |                                                                                     |
| <b>2. Vehicle Particulars &amp; Condition</b>                                                                                             |                                                                                         |                 |                             |                                                                                     |
| Make & Model                                                                                                                              |                                                                                         | c.c             | 0                           |                                                                                     |
| Engine No.                                                                                                                                | HIDDEN                                                                                  | Year of Reg.    |                             |                                                                                     |
| Chassis No.                                                                                                                               |                                                                                         | Colour          |                             |                                                                                     |
| Odometer                                                                                                                                  | -                                                                                       | Steering        |                             |                                                                                     |
| Brakes                                                                                                                                    |                                                                                         | Modification    |                             |                                                                                     |
| General                                                                                                                                   |                                                                                         |                 |                             |                                                                                     |
| <b>3. Conditions of Tyres</b>                                                                                                             |                                                                                         |                 |                             |                                                                                     |
|                                                                                                                                           | Size                                                                                    | Make            | Balance                     |                                                                                     |
| R/H Front Tyre                                                                                                                            |                                                                                         |                 | mm                          |                                                                                     |
| L/H Front Tyre                                                                                                                            |                                                                                         |                 | mm                          |                                                                                     |
| R/H Rear Tyre                                                                                                                             |                                                                                         |                 | mm                          |                                                                                     |
| L/H Rear Tyre                                                                                                                             |                                                                                         |                 | mm                          |                                                                                     |
| <b>4. Description of Damages</b>                                                                                                          |                                                                                         |                 |                             |                                                                                     |
|                                                                                                                                           |                                                                                         |                 |                             |                                                                                     |
| <b>5. General Information</b>                                                                                                             |                                                                                         |                 |                             |                                                                                     |
| Accident Date                                                                                                                             | 17/02/2018                                                                              | Inspection Date | 20/02/2018                  |                                                                                     |
| Survey held at                                                                                                                            | PREMIER AUTOMOTIVE SERVICES PTE LTD<br>23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443 |                 |                             |                                                                                     |
| <b>5a. Remarks</b>                                                                                                                        |                                                                                         |                 |                             |                                                                                     |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                                                                         |                 |                             |                                                                                     |

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG: 200707743D GST REG: 200707743D

China Teiping

19-Feb-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6915 K

|          |                                                   |      |             |
|----------|---------------------------------------------------|------|-------------|
| 1 pc     | Rear bumper                                       |      | \$ 696.00   |
| 1 pc     | Rear bumper lower cover                           |      | \$ 206.00   |
| 2 pcs    | Rear bumper side bracket o/s & n/s @ \$29.00      | X 50 | \$ 58.00    |
| 1 pc     | Rear bumper inner sponge                          | X 50 | \$ 114.00   |
| 1 pc     | Rear bumper reinforcement                         | X 50 | \$ 607.00   |
| 2 pcs    | Rear bumper stay o/s & n/s @ \$53.00              | X 50 | \$ 108.00   |
| 2 pcs    | Rear bumper reinforcement lower bracket @ \$18.00 | X 50 | \$ 36.00    |
| 2 pcs    | Rear bumper reinforcement upper bracket @ \$18.00 | X 50 | \$ 36.00    |
| 1 pc     | Rear bumper reflector n/s                         | X 50 | \$ 46.00    |
|          |                                                   |      | \$ 1,907.00 |
| Less 10% |                                                   |      | \$ 190.70   |
|          |                                                   |      | \$ 1,716.30 |

### S/NETT

|                                                                                                                                                       |                   |  |                |
|-------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------|--|----------------|
| 1 set                                                                                                                                                 | Rear bumper clips |  | \$ 48.00       |
| 1 set                                                                                                                                                 | Reverse sensor    |  | \$ 280.00      |
| Sundry                                                                                                                                                |                   |  | \$ 50.00 X 20  |
| To dismantle / replace reverse sensor to new bumper and reset to the same                                                                             |                   |  | \$ 120.00 20   |
| To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs                                 |                   |  | \$ 180.00 X 20 |
| To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc |                   |  | \$ 650.00 20   |
| To putty and spray painting on rear bumper, end panel                                                                                                 |                   |  | \$ 400.00 180  |
| To apply rustproofing on the repaired and replaced panels.                                                                                            |                   |  | \$ 120.00 X 20 |
|                                                                                                                                                       |                   |  | \$ 3,564.30    |

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

26/2/18  
total 46,115.00 / 2 Pys.

Kelin 1/1/18  
20/2/18 0920h  
2 Pys.  
Defect Part p Lh

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

*Chma Taiping*

19-Feb-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6915 K


|          |                                                   |             |
|----------|---------------------------------------------------|-------------|
| 1 pc     | Rear bumper                                       | \$ 696.00   |
| 1 pc     | Rear bumper lower cover                           | \$ 206.00   |
| 2 pcs    | Rear bumper side bracket o/s & n/s @ \$29.00      | \$ 58.00    |
| 1 pc     | Rear bumper inner sponge                          | \$ 114.00   |
| 1 pc     | Rear bumper reinforcement                         | \$ 607.00   |
| 2 pcs    | Rear bumper stay o/s & n/s @ \$53.00              | \$ 108.00   |
| 2 pcs    | Rear bumper reinforcement lower bracket @ \$18.00 | \$ 36.00    |
| 2 pcs    | Rear bumper reinforcement upper bracket @ \$18.00 | \$ 36.00    |
| 1 pc     | Rear bumper reflector n/s                         | \$ 46.00    |
|          |                                                   | \$ 1,907.00 |
| Less 10% |                                                   | \$ 190.70   |
|          |                                                   | \$ 1,716.30 |

### S/NETT

|       |                                                                                                                                                       |                         |
|-------|-------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------|
| 1 set | Rear bumper clips                                                                                                                                     | \$ 48.00                |
| 1 set | Reverse sensor                                                                                                                                        | \$ 280.00<br><i>200</i> |
|       | Sundry                                                                                                                                                | \$ 50.00                |
|       | To dismantle / replace reverse sensor to new bumper and reset to the same                                                                             | \$ 120.00<br><i>20</i>  |
|       | To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.                                | \$ 180.00               |
|       | To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc | \$ 650.00<br><i>200</i> |
|       | To putty and spray painting on rear bumper, end panel                                                                                                 | \$ 400.00<br><i>180</i> |
|       | To apply rustproofing on the repaired and replaced panels.                                                                                            | \$ 120.00<br><i>20</i>  |
|       |                                                                                                                                                       | \$ 3,564.30             |

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.



*Kalin 1/1/14*  
*20/2/18 0930h*  
*2 Day*  
*P.P.P*  
*Before Part p.H*



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA  
Our ref: CC3/CTI18003241/K1es3

Date: 20/02/2018

The Motor Claims Department  
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO.**

**SHC 6915K**


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20.02.2018 at the premises of M/s Premier Automotive Services Pte Ltd (Changi South) and have the following to report

|                          |       |          |
|--------------------------|-------|----------|
| Workshop Estimate Amount | : S\$ | 3,564.30 |
| Revised Estimate Amount  | : S\$ | 1,459.80 |
| "Check" Items Amount     | : S\$ | -        |
| Market Value             | : S\$ | -        |
| LTA Reimbursement Value  | : S\$ | -        |
| Nett Value               | : S\$ | -        |

**Description of Damage:**

The vehicle sustained damages at the  
Rear Portion



**Comments/Present Status:**

Damages Consistent

Estimated normal period for repairs: 2.0 days

Remarks :

Yours faithfully,

KALVIN ANG  
Licensed Appraiser

## Shirley Hiew (LKK Auto)

---

**From:** Lucas Lee <lucas.lee@sg.cntaiping.com>  
**Sent:** Wednesday, 21 February 2018 2:50 PM  
**To:** Shirley Hiew (LKK Auto)  
**Cc:** Irene Tay  
**Subject:** RE: Direct Settlement - Accident Involving SKF7456K (OI : CTI - SNM18D00936C02) AND SHC6915K (TP : LKK REF - CC3/CTI18003241/K1es3) on 17/02/2018  
**Attachments:** leesz\_SNM18D00936C02-SKF7456K-LKKDirectSettlementAccidentLtr\_CLCR95.691.pdf; MSNH18024653-SKF7456K.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Irene Tay

Regards,

Lucas Lee  
Claims Department (Motor)  
China Taiping Insurance (Singapore) Pte. Ltd.  
3, Anson Road, #16-00  
Springleaf Tower,  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6181  
Fax: 6224 7175  
Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)  
Email: [lucas.lee@sg.cntaiping.com](mailto:lucas.lee@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]  
**Sent:** Wednesday, 21 February, 2018 9:22 AM  
**To:** Claims Dept of CTI; Irene Tay; Asher Sng (LKKAuto)  
**Cc:** Vic (LKKAuto); Admin A  
**Subject:** Direct Settlement - Accident Involving SKF7456K (OI : CTI - TBA) AND SHC6915K (TP : LKK REF - CC3/CTI18003241/K1es3) on 17/02/2018

### WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

We have inspected TP vehicle SHC 6915K at M/s Premier Automotive Services Pte Ltd - Changi South.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Asher and he can be contacted at DID: 6841 6051.

*To check availability of the case handler , you may contact the undersigned.*

Thank you.

Best Regards,

Shirley Hiew | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## Shirley Hiew (LKK Auto)

---

**From:** Lucas Lee <lucas.lee@sg.cntaiping.com>  
**Sent:** Wednesday, 21 February 2018 2:50 PM  
**To:** Shirley Hiew (LKK Auto)  
**Cc:** Irene Tay  
**Subject:** RE: Direct Settlement - Accident Involving SKF7456K (OI : CTI - SNM18D00936C02) AND SHC6915K (TP : LKK REF - CC3/CTI18003241/K1es3) on 17/02/2018  
**Attachments:** leesz\_SNM18D00936C02-SKF7456K-  
LKKDirectSettlementAccidentLtr\_CLCR95.691.pdf; MSNH18024653-SKF7456K.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Irene Tay

Regards,

Lucas Lee  
Claims Department (Motor)  
China Taiping Insurance (Singapore) Pte. Ltd.  
3, Anson Road, #16-00  
Springleaf Tower,  
Singapore 079909  
Co. Reg. No. 200208384E  
DID: 6389 6181  
Fax: 6224 7175  
Email: [claimsdept@sg.cntaiping.com](mailto:claimsdept@sg.cntaiping.com)  
Email: [lucas.lee@sg.cntaiping.com](mailto:lucas.lee@sg.cntaiping.com)  
Website: [www.sg.cntaiping.com](http://www.sg.cntaiping.com)

**From:** Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]  
**Sent:** Wednesday, 21 February, 2018 9:22 AM  
**To:** Claims Dept of CTI; Irene Tay; Asher Sng (LKKAuto)  
**Cc:** Vic (LKKAuto); Admin A  
**Subject:** Direct Settlement - Accident Involving SKF7456K (OI : CTI - TBA) AND SHC6915K (TP : LKK REF - CC3/CTI18003241/K1es3) on 17/02/2018

### WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

We have inspected TP vehicle SHC 6915K at M/s Premier Automotive Services Pte Ltd - Changi South.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Asher and he can be contacted at DID: 6841 6051.

*To check availability of the case handler , you may contact the undersigned.*

Thank you.

Best Regards,

Shirley Hiew | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366-0055 | email: [ShirleyHiew@lkkauto.com](mailto:ShirleyHiew@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI18003241/K1es3s2

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 02-04-2018



Code : CTI

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |                  |                |            |
|--------------|------------------|----------------|------------|
| Insured Veh. | SKF 7456K        | Veh. Inspected | SHC 6915K  |
| Policy No.   | DMPCSN3049361701 | Coverage (\$)  | 0.00       |
| Claim No.    | SNM18D00936C02   | Excess (\$)    | 0.00       |
| Assign From  |                  | Assign Date    | 20/02/2018 |

### 2. Vehicle Particulars & Condition

|              |                   |              |                    |
|--------------|-------------------|--------------|--------------------|
| Make & Model | KIA OPTIMA        | c.c          | 1685               |
| Engine No.   | HIDDEN            | Year of Reg. | 2015               |
| Chassis No.  | KNAGM414MF5623411 | Colour       | SILVER             |
| Odometer     | 249074            | Steering     | IN ORDER           |
| Brakes       | IN ORDER          | Modification | STANDARD ALLOY RIM |
| General      | FAIR              |              |                    |

### 3. Conditions of Tyres

|                | Size      | Make     | Balance |
|----------------|-----------|----------|---------|
| R/H Front Tyre | 205/65R16 | ACHILLES | 7 mm    |
| L/H Front Tyre | 205/65R16 | ACHILLES | 7 mm    |
| R/H Rear Tyre  | 205/65R16 | ACHILLES | 7 mm    |
| L/H Rear Tyre  | 205/65R16 | ACHILLES | 7 mm    |

### 4. Description of Damages

|                                                                            |
|----------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS. |
|----------------------------------------------------------------------------|

### 5. General Information

|                |                                                                                         |                 |            |
|----------------|-----------------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 17/02/2018                                                                              | Inspection Date | 20/02/2018 |
| Survey held at | PREMIER AUTOMOTIVE SERVICES PTE LTD<br>23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443 |                 |            |

### 5a. Remarks

|                                                                                                                                           |
|-------------------------------------------------------------------------------------------------------------------------------------------|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|-------------------------------------------------------------------------------------------------------------------------------------------|

### 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 2 Working Days |
|-------------------------------------|----------------|



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6915K

| Qty                         | Description of Parts                                                                                                                                   | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                                                                                                                                        |               |                           |                   |
| 1                           | REAR BUMPER                                                                                                                                            | DEFORMED      | 696.00                    | 696.00            |
| 1                           | REAR BUMPER LOWER COVER                                                                                                                                | CRACKED       | 206.00                    | 206.00            |
| 2                           | REAR BUMPER SIDE BRACKET O/S & N/S @ \$29.00                                                                                                           | SERVICEABLE   | 58.00                     | -                 |
| 1                           | REAR BUMPER INNER SPONGE                                                                                                                               | SERVICEABLE   | 114.00                    | -                 |
| 1                           | REAR BUMPER REINFORCEMENT                                                                                                                              | SERVICEABLE   | 607.00                    | -                 |
| 2                           | REAR BUMPER STAY O/S & N/S @ \$53.00                                                                                                                   | SERVICEABLE   | 108.00                    | -                 |
| 2                           | REAR BUMPER REINFORCEMENT LOWER BRACKET @ \$18.00                                                                                                      | SERVICEABLE   | 36.00                     | -                 |
| 2                           | REAR BUMPER REINFORCEMENT UPPER BRACKET @ \$18.00                                                                                                      | SERVICEABLE   | 36.00                     | -                 |
| 1                           | REAR BUMPER REFLECTOR N/S                                                                                                                              | SERVICEABLE   | 46.00                     | -                 |
|                             | LESS 10% DISCOUNT                                                                                                                                      |               | -190.70                   | -90.20            |
|                             |                                                                                                                                                        |               | 1,716.30                  | 811.80            |
| <b>SPECIAL NETT ITEMS</b>   |                                                                                                                                                        |               |                           |                   |
| 1                           | SET REAR BUMPER CLIPS (SN)                                                                                                                             | NECESSARY     | 48.00                     | 48.00             |
| 1                           | SET REVERSE SENSOR (SN)                                                                                                                                | SHORTED       | 280.00                    | 200.00            |
| 1                           | SUNDRY (SN)                                                                                                                                            | NOT NECESSARY | 50.00                     | -                 |
|                             |                                                                                                                                                        |               | 378.00                    | 248.00            |
| <b>LABOUR</b>               |                                                                                                                                                        |               |                           |                   |
|                             | TO DISMANTLE / REPLACE REVERSE SENSOR TO NEW BUMPER AND RESET TO THE SAME.                                                                             |               | 120.00                    | 20.00             |
|                             | TO DISMANTLE / REFIT THE INNER GARNISHES, INNER LININGS, INNER TRIMS, CUSHION SEAT, CARPET, ETC TO FACILITATE REPAIRS.                                 | NOT NECESSARY | 180.00                    | -                 |
|                             | TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS. INCLUDING KNOCK-OUT, STRAIGHTEN, REPAIR, RESHAPE AND ADJUST OF THE END PANEL ETC. |               | 650.00                    | 200.00            |
|                             | TO PUTTY AND SPRAY PAINTING ON REAR BUMPER, END PANEL.                                                                                                 |               | 400.00                    | 180.00            |
|                             | TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.                                                                                             | NOT NECESSARY | 120.00                    | -                 |
|                             |                                                                                                                                                        |               | 1,470.00                  | 400.00            |

Report Ref No. CC3/CTI18003241/K1es3s2



|                                                                         |  |          |          |
|-------------------------------------------------------------------------|--|----------|----------|
| GRAND TOTAL                                                             |  | 3,564.30 | 1,459.80 |
| RECOMMENDED COST OF LUMP SUM REPAIRS<br>(TO ITS PRE-ACCIDENT CONDITION) |  |          | 1,150.00 |

Report Ref No. CC3/CTI18003241/K1es3s2

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.