

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

China Teiping

19-Feb-18

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6915 K

1 pc	Rear bumper	\$ 696.00
1 pc	Rear bumper lower cover	\$ 206.00
2 pcs	Rear bumper side bracket o/s & n/s @ \$29.00 X	\$ 58.00
1 pc	Rear bumper inner sponge X	\$ 114.00
1 pc	Rear bumper reinforcement X	\$ 607.00
2 pcs	Rear bumper stay o/s & n/s @ \$53.00 X	\$ 108.00
2 pcs	Rear bumper reinforcement lower bracket @ \$18.00 X	\$ 36.00
2 pcs	Rear bumper reinforcement upper bracket @ \$18.00 X	\$ 36.00
1 pc	Rear bumper reflector n/s X	\$ 46.00
		\$ 1,907.00
	Less 10%	\$ 190.70
		\$ 1,716.30

S/NETT

1 set	Rear bumper clips	\$ 48.00
1 set	Reverse sensor	\$ 280.00 20.
	Sundry	\$ 50.00 X
	To dismantle / replace reverse sensor to new bumper and reset to the same	\$ 120.00 20
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs	\$ 180.00 X
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel etc	\$ 650.00 200
	To putty and spray painting on rear bumper, end panel	\$ 400.00 180
	To apply rustproofing on the repaired and replaced panels.	\$ 120.00 X
		\$ 3,564.30

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.

Kalin 11/11/17
20/2/18 0930h
2 Pys
Before Part p Lh