

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05728

Vehicle Insured : SJN2095X

Accident Date : 11-Feb-2018

Date : 20-Feb-2018

Our Ref : 218033 (DIRECTASIA) / CHAN

PAGE : 1

NG SIU BEE
12 HOUGANG STREET 92
#07-07
Singapore 538688

Not Authorized
11 Feb 18
Manny After Repair

ESTIMATED COST OF REPAIR FOR MAZDA 3 EU1212D

=====

1 pc Rear bumper fascia		<i>RM</i> 717.90 ✓
1 pc Rear bumper reinforcement		<i>RM</i> 403.40 X
2 pcs Bumper reinforcement bracket	@ S\$ 60.50	<i>RM</i> 121.00 X
1 pc Rear license plate lamp		234.60 ✓
1 pc Rear end panel		<i>RM</i> 346.90 X
1 pc End panel top garnish		<i>RM</i> 179.80 X
4 pcs Rear bumper clip	@ S\$ 3.50	<i>RM</i> 14.00 ✓

2,017.60

Less 20% : 403.52

2 pcs Rear bumper side lower lip	@ S\$144.00	<i>RM</i> 1,614.08
1 pc Rear number plate		<i>RM</i> 288.00 sn X
1 pc Rear bumper reverse sensor(set		<i>RM</i> 35.00 sn ✓

300.00 sn ✓

To remove roof lining, front and rear seats, trim board and carpet

RM 80.00 X

To apply undersealing

RM 80.00 X

To putty and spray replaced parts

800.00 *369*

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

750.00 *309*

Total : S\$ 3,947.08

=====

Singapore Dollars Three Thousand Nine Hundred and Forty Seven and Cents Eight Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: