

15/5/2010

INS. CASE OWNER:

CC 6 / CTI1800 3267, U#6302

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE:



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II :\$

Is driver the owner?

If NO, Driver Name / Age:

Driver Tel No.:

HP:

D.O.A.:

Nature of Accident:

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time:

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE:

After call ltr to OE:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

SS

5,100

Loss of Rental (LOR):

SS

1,100

(

100

ays)

100

Loss of Use (LOU):

SS

X

(\$

x

days)

Loss of Income (LOI):

SS

X

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

7.45

Medical:

SS

736.45

Disbursement:

SS

29.XX

(e.g. Tow/ Independent)

Legal Cost

SS

6,236.45

Total:

SS

6,236.45

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

6,236.45

Name 1:

TK LEE AUTOMOTIVE PTE LTD

Payee 2: (Strike if N.A.)

SS

X

Name 2:

X

Payee 3: (Strike if N.A.)

SS

X

Name 3:

X

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC6/CTI18003267/Ukb3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 21-02-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 3270S		Veh. Inspected	SKG 6127L
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	21/02/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer			Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/02/2018		Inspection Date	20/02/2018
Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933. TEL.: (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC6/CTI18003267/Ukb3

Date: 21.02.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SKG6127L

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 20.02.2018 at the premises of M/s LEE BROTHERS AUTOMOTIVE PTE. LTD. and have the following to report:-

Workshop Estimate Amount	: S\$	10,362.96
Revised Estimate Amount	: S\$	6,548.02
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

MARCUS CHUA
Licensed Appraiser



CERTIFICATE OF INSURANCE

Please call +65-6322-2072 for FWD Emergency Assistance
if Your Car breaks down or is involved in an accident.

All accidents must be reported within 24 hours of the incident regardless of whether it will lead to a claim.

POLICY NUMBER: PNPV2017-00007319 (Comprehensive - Classic Plan)

Car plate number: SKG6127L

Your name (As the policyholder): Firman Bin Suri

Coverage start date: 22/09/2017

Coverage end date: 21/09/2018

Covered geographical area: Singapore, West Malaysia and Southern Thailand

Who is insured to drive:

(a) You; and

(b) Anyone with a valid driving license who You give permission to drive Your Car.

Important things to know:

Your Policy comprises this Certificate of Insurance, the Contract, the Car Insurance Summary and any Endorsements attached by Us. These documents should be read together as one. You must make sure that any person You give permission to drive Your Car understands Your duties under this Policy and complies with its conditions.

Your Policy is only valid if Your Car is being used for non-commercial activities in accordance with Your contract.

Finance company: Sing Investments & Finance Ltd

We confirm that this Policy complies with the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189).

Issued on: 17/09/2017

Abhishek Bhatia
Chief Executive Officer
FWD Singapore Pte Ltd

Please immediately inform us at +65-6820-8888
or email us at contact.sg@fwd.com if any details
in this Certificate of Insurance need to be changed.

Shu Pei (LKKAUTO)

From: Angie Foo <angie.foo@sg.cntaiping.com>
Sent: Friday, 23 February 2018 9:36 AM
To: Shu Pei (LKKAUTO)
Cc: Jowyn Tay; Hsiao Tong (LKKAUTO); Zaini (LKK Auto); Admin A
Subject: OUR REF: SNM18D00894C02/0/LKKDS & YR REF: SKG6127L (TP : LKK REF - CC6/CTI18003267/Ukb3) on 13.02.2018
Attachments: MSM118022525-GBE3270S.pdf; FooLW_SNM18D00894C02-GBE3270S-LKKDirectSettlementAccidentLtr_CLCR95.386.pdf

Dear Shu Pei,

We refer to your email of 22.2.2018

We attached a copy of Assignment letter and SAS Report for your necessary action.

Kindly take note, the claim handler is Jowyn Tay 6389 6174.

Thank you.

Regards,
Angie Foo
Executive
Motor Division
Claims Department
China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road #16-00
Springleaf Tower
Singapore 079909
Co.Reg.No.200208384E
DID: 6389 6186
Fax: 6224 7478 /6224 7175
Email: angie.foo@sg.cntaiping.com
Email: claimsdept@sg.cntaiping.com
Website: www.sg.cntaiping.com

Disclaimer

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Thursday, 22 February, 2018 9:50 AM
To: Claims Dept of CTI
Cc: Jowyn Tay; Hsiao Tong (LKKAUTO); Zaini (LKK Auto); Admin A
Subject: Direct Settlement - Accident Involving GBE3270S (OI : CTI - TBA) AND SKG6127L (TP : LKK REF - CC6/CTI18003267/Ukb3) on 13.02.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SKG 6127L at M/s LEE BROTHERS AUTOMOTIVE PTE. LTD.,

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Zaini and he can be contacted at DID: 6841-2132.

Thank you

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupej@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.singapore.taiping.com
Co. Reg. No. 200208384E

Cur Reference: **SNM18D00894/C02/0**

Date : **23 FEBRUARY 2018**

via Ordinary & Registered Mail

**HAW WAH TRADING CO PTE LTD
BLK 6 HOUGANG AVE 3
#01-76
SINGAPORE 530006**

Dear Sir / Madam

**ACCIDENT INVOLVING GBE3270S AND SKG6127L ON 13 FEBRUARY 2018
ALONG JURONG GATEWAY ROAD SLIP ROAD TO TOH GUAN ROAD**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SKG6127L**, is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : ZAINI
Ref : TP : LKK REF -CC6/CTI18003267/Ukb3
Contact No : 6841 2132
via Email : Zaini@lkkauto.com

CC : Agent - (AN0421A) - VITESSE SOLUTIONS

F01/LKKDS-2013

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 1457Z

Vehicle Details

Vehicle No.: SKG6127L
Vehicle to be Exported: Yes
Intended De-registration Date: 13 Feb 2018
Vehicle Make: VOLKSWAGEN
Vehicle Model: POLO 1.4 AT 6R13E7 FRTFOGLAMP
Primary Colour: White
Manufacturing Year: 2010
Engine No.: CGG313454
Chassis No.: WVVWZZZ6RZAU024810
Maximum Power Output: 63.0 kW (84 bhp)
Open Market Value: \$15,424.00
Original Registration Date: 23 Mar 2010
First Registration Date: 23 Mar 2010
Transfer Count: 3
Actual ARF Paid: \$15,424.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 22 Mar 2020
PARF Rebate Amount: \$9,254.00

Intended COE Rebate Details

COE Expiry Date: 22 Mar 2020
COE Category: A - Car (1600cc & below)
COE Period(Years): 10
QP Paid: \$18,150.00
COE Rebate Amount: \$3,825.00
Total Rebate Amount: \$13,079.00

The information contained herein is correct as at 13 Feb 2018

OK

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8731457Z

Name
FIRMAN BIN SURI

Picture
JAVANESE

Date of Birth
09-10-1987

Sex
M

Country of Birth
SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number S8731457Z

Name
FIRMAN BIN SURI

Birth Date 09 Oct 1987

Issue Date 17 Sep 2009

001785542C

A0238764

NRIC No. S8731457Z

APT BLK 338D ANCHORVALE CRESCENT #04-25
SINGAPORE 544338

NRIC No: S8731457Z

Date: 16/10/2017

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3: Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg 17 Sep 2009

NP 428A

Licence No: S8731457Z

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1457Z
Vehicle Details	
Vehicle No.:	SKG6127L
Vehicle to be Exported:	Yes
Intended De-registration Date:	13 Feb 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	POLO 1.4 AT 6R13E7 FRTFOGLAMP
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	CGG313454
Chassis No.:	WVWZZZ6RZAU024810
Maximum Power Output:	63.0 kW (84 bhp)
Open Market Value:	\$15,424.00
Original Registration Date:	23 Mar 2010
First Registration Date:	23 Mar 2010
Transfer Count:	3
Actual ARF Paid:	\$15,424.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Mar 2020
PARF Rebate Amount:	\$9,254.00
Intended COE Rebate Details	
COE Expiry Date:	22 Mar 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$18,150.00
COE Rebate Amount:	\$3,825.00
Total Rebate Amount:	\$13,079.00

The information contained herein is correct as at 13 Feb 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	1457Z
Vehicle Details	
Vehicle No.:	SKG6127L
Vehicle to be Exported:	No
Intended De-registration Date:	20 Feb 2018
Vehicle Make:	VOLKSWAGEN
Vehicle Model:	POLO 1.4 AT 6R13E7 FRTFOGLAMP
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	CGG313454
Chassis No.:	WVWZZZ6RZAU024810
Maximum Power Output:	63.0 kW (84 bhp)
Open Market Value:	\$15,424.00
Original Registration Date:	23 Mar 2010
First Registration Date:	23 Mar 2010
Transfer Count:	3
Actual ARF Paid:	\$15,424.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Mar 2020
PARF Rebate Amount:	\$9,254.00
Intended COE Rebate Details	
COE Expiry Date:	22 Mar 2020
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$18,150.00
COE Rebate Amount:	\$3,791.00
Total Rebate Amount:	\$13,045.00

The information contained herein is correct as at 20 Feb 2018

OK

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

GBE3270S

ESTIMATE

DATE : 20.02.2018
VEHICLE NO : SKG6127L
MAKE/MODEL : VOLKS POLO
ACC DATE : 13.02.2018

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
<u>LIST PRICE</u>			
1	1 REAR TAILGATE <i>DD/Real 1601.32</i>	1,737.25	1,737.25
2	1 REAR TAILGATE RUBBER <i>Real</i>	195.90	195.90
3	2 REAR TAILGATE DAMPER RH/LH <i>11</i>	143.05	286.10 X
4	1 REAR TAILGATE LOCK <i>7m1</i>	184.05	184.05
5	1 REAR TAILGATE LOCK CATCH <i>11</i>	98.45	98.45 X
6	1 REAR TAILGATE INNER TRIM <i>11</i>	289.30	289.30 X
7	1 REAR BUMPER <i>DD/2e</i>	933.45	933.45
8	2 REAR BUMPER SIDE RETAINER RH/LH <i>Real</i>	80.35	160.70
9	1 REAR BUMPER BRACKET <i>cre</i>	95.65	95.65
10	1 REAR END PANEL <i>DD</i>	764.40	764.40
11	1 REAR END PANEL GARNISH <i>12 7m1</i>	145.75	145.75 X
12	1 REAR REINFORCEMENT <i>Real 488.63</i>	500.15	500.15
13	1 REAR EXHAUST BOX <i>n</i>	581.15	581.15 X
14	2 REAR EXHAUST BOX MOUNTING <i>11</i>	63.35	126.70 X
15	2 REAR TAILLAMP RH/LH <i>W/S cre</i>	286.05	572.10 700
16	2 REAR FENDER INNER TRIM RH/LH <i>11</i>	296.65	593.30 X
			7,264.40
		LESS 10%	726.44
			6,537.96

SPECIAL NETTS ITEM

1	1 (SET) REAR NUMBER PLATE WITH CASING <i>Real</i>	50.00	50.00
2	1 (SET) REAR BUMPER CLIP <i>Real</i>	45.00	45.00
3	1 (SET) REAR WINDSCREEN SPONGE TAPE <i>Real</i>	80.00	80.00
4	1 (SET) REAR WINDSCREEN SEALANT <i>Real</i>	20.00	20.00
5	1 (SET) REAR REVERSE SENSOR <i>smk</i>	280.00	280.00
6	1 REAR EXHAUST CHROME <i>Real</i>	350.00	350.00
			825.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LEE BROTHERS AUTOMOTIVE PTE. LTD.

PARTICULAR	UNIT PRICE	AMOUNT
QTY	S\$	S\$

LABOUR CHARGES :

1		1,400.00	880
	TO KNOCK OUT DENT, CUT/WELD REAR END PANEL AND REPALCE ACCIDENT PARTS		
2	TO SPRAY PAINTING ON ACCIDENT PORTION	1,000.00	820
3	TO CHECK WIRING	30.00	20
4	TO REMOVE, REPLACE REAR EXHAUST BOX	180.00	60
5	TO REMOVE, REPLACE REAR REVERSE SENSOR	120.00	50
6	TO REMOVE, REFIX REAR CUSHION AND INNER TRIM	180.00	60
7	TO TUFF KOTE	90.00	30
	TOTAL:	3,000.00	6415.31

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 10,362.96



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CT118003267/Ujb3n2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 02-10-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBE 3270S	Veh. Inspected	SKG 6127L	
Policy No.	DMCVSN3085271701	Coverage (\$)	0.00	
Claim No.	SNM18D00894/C02/0	Excess (\$)	0.00	
Assign From		Assign Date	20/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	VOLKSWAGEN POLO (A)	c.c	1390	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WVWZZZ6RZAU024810	Colour	WHITE	
Odometer	142139	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	GOODYEAR	6 mm	
L/H Front Tyre	195/55 R15	GOODYEAR	6 mm	
R/H Rear Tyre	195/55 R15	GOODYEAR	6 mm	
L/H Rear Tyre	195/55 R15	GOODYEAR	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/02/2018	Inspection Date	20/02/2018	
Survey held at	T K LEE AUTOMOTIVE PTE LTD NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKG 6127L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR TAILGATE	DENTED / BENT	1,737.25	1,601.32
1	REAR TAILGATE RUBBER	NECESSARY	195.90	195.90
2	REAR TAILGATE DAMPER LH/RH @\$143.05	NOT NECESSARY	286.10	-
1	REAR TAILGATE LOCK	TWISTED	184.05	184.05
1	REAR TAILGATE LOCK CATCH	NOT NECESSARY	98.45	-
1	REAR TAILGATE INNER TRIM	NOT NECESSARY	289.30	-
1	REAR BUMPER	DENTED / DEFORMED	933.45	933.45
2	REAR BUMPER SIDE RETAINER RH/LH @\$80.35	BENT	160.70	160.70
1	REAR BUMPER BRACKET	CRACKED	95.65	95.65
1	REAR END PANEL	DENTED	764.40	764.40
1	REAR END PANEL GARNISH	TWISTED	145.75	145.75
1	REAR REINFORCEMENT	BENT	500.15	488.63
1	REAR EXHAUST BOX	TO REPAIR SEE LABOUR	581.15	-
2	REAR EXHAUST BOX MOUNTING @\$63.35	NOT NECESSARY	126.70	-
2	REAR TAILLAMP RH/LH @\$286.05	N/S CRACKED	572.10	286.05
2	REAR FENDER INNER TRIM RH/LH @\$296.65	NOT NECESSARY	593.30	-
	LESS 10% DISCOUNT		-726.44	-485.59
			6,537.96	4,370.31
<u>SPECIAL NETT ITEMS</u>				
1	SET REAR BUMPER PLATE WITH CASING (SN)	BENT	50.00	40.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	45.00
1	SET REAR WINDSCREEN SPONGE TAPE (SN)	NECESSARY	80.00	40.00
1	SET REAR WINDSCREEN SEALANT (SN)	NECESSARY	20.00	20.00
1	SET REAR REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR EXHAUST CHROME (SN)	SERVICEABLE	350.00	-
			825.00	345.00

Report Ref No. CC6/CTI18003267/Ujb3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO KNOCK OUT DENT ,CUT/WELD REAR END PANEL AND REPLACE ACCIDENT PARTS .INCLUSIVE OF THE REPAIR OF REAR EXHAUST BOX .		1,400.00	680.00
	TO SPRAY PAINTING ON ACCIDENT PORTION .		1,000.00	800.00
	TO CHECK WIRING .		30.00	20.00
	TO REMOVE,REPLACE REAR EXHAUST BOX.		180.00	60.00
	TO REMOVE,REPLACE REAR REVERSE SENSOR .		120.00	50.00
	TO REMOVE,REFIX REAR CUSHION AND INNER TRIM .		180.00	60.00
	TO TUFF KOTE.		90.00	30.00
			3,000.00	1,700.00
	GRAND TOTAL		10,362.96	6,415.31
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,100.00

Report Ref No. CC6/CTI18003267/Ujb3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.