22/03/2002 ASS, REC, BY:	REF: CS/MSG 18063271 KVbn2   Special Instruction:
Surveyor .	Kennth ASSIGNMENT (Office)
From (Person):	Elaine Ngh of Mely Date/Time: 20/2/2018
Estimated Cost	
OD /TP / WS	TP RES / OD RES / EVA / INV / MV / CS
	nicle No: SCK 5599M Insured: STU 1420K
at Workshop m	us Oheng thoe Motor Pte Ltd Tel: 67556142
of	I have a finish to the finish the second of
Policy No:	8 0350547 QMX Claim No: 550051
Sum Insured:_	Excess:
Make of Veh: (Client's Record)	D.O.A [9 02 18
CA / REV /	REP. / REV 24 HRS WO
Date/Time:	Person Contacted: Vehicle IN LOUT
Date/Time	Action/Instruction ( Estimate
	NA/INC 18003175/24 - SCK5599M. DOA: 19618 MANMEN.
23/2/18	Send preli revised by merimen

Survey Department Check List (Case Handler)

Reference No.: CS MSG 800 3371
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

**Typist** 

) Office	Assign Form	Y-Date	N-Date	Y-Date	N-Date
С	Reference No.	~			
С	Customer Code				
N	Assign From				
С	Assign Date	~			
С	Veh No (Inspected)	~			
С	Veh No (Insured)	~			
С	D.O.A	~			
С	Policy No	-			
С	Claim No	/			
c	Insurance Authorisation (CA /REV/REP)				
c	Report Type	~			
c	Weekend Charges				
N	Survey held at/Repairer	-			
C	Excess	-			
				-	
urvey	or ( ): Case handler to make sure	the surveryor c	ompleted a	ll required	informa
) Assig	nment Form				,
С	Vehicle No	~			
С	Regn Month/Year	~			
N	Vehicle Type	-			
N	Make & Model	~			
С	Engine Capacity. (C.C)	/			
N	Colour	~			
С	Odometer. (Sp.Reading)	_			
c	Chassis No	~			
N	General Condition	~			
N	Steering	~			
N	Brake	~			
N	Modification (Modi)				
C	Tyre Size	~		-	
N	Tyre Make	_			1
C	Tyre Balance				-
C	Date of Inspection				
					0-1-1
N	Survey held		+		
N	Des.of Damages				
-	em - (Views/Merimen)				_
С	Damaged Vehicle Photographs Uploaded				
	kshop Estimate/Assignment Form				
3) Wor	ALL Parts condition	/			
- 00					
N			1 1		_
N C	Market Value for OD cases				
N C C	Market Value for OD cases Estimate Repair Cost for PRI (RSI, TMI, MSIG)	~			
N C C	Market Value for OD cases Estimate Repair Cost for PRI (RSI, TMI, MSIG) Days of repair	V V			
N C C C	Market Value for OD cases Estimate Repair Cost for PRI (RSI, TMI, MSIG) Days of repair Finalised Amount	v v			
N C C C	Market Value for OD cases Estimate Repair Cost for PRI (RSI, TMI, MSIG) Days of repair				

\*C: Critical \*N: Non-Critical



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

1401	O INCLIDANCE (O	Affiliated to Federation Internation				
MSI	G INSURANCE (SI	NGAPORE) PTE LTD	Ref : CS/MSG18003	271/KVb		
	AFFLES QUAY 01 HONG LEONG	BLDG SINGAPORE 048581	Date: 21-02-2018 Code: MSG			
1.		Policy Particulars	:- THIRD PARTY CLA	IM		
	Insured Veh.	SJU 1402K	Veh. Inspected	SCK 5599M		
	Policy No.	80350547QMX	Coverage (\$)	0.00		
	Claim No.	550056	Excess (\$)	0.00		
	Assign From	MERIMEN (ELAINE NGU)	Assign Date	21/02/2018		
2.		Vehicle Parti	culars & Condition			
	Make & Model		c.c	0		
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	120	Steering			
	Brakes		Modification			
	General					
3.		Condit	ions of Tyres			
		Size	Make	Balance		
	R/H Front Tyre			mm		
	L/H Front Tyre			mm		
	R/H Rear Tyre			mm		
	L/H Rear Tyre			mm		
4.		Descripti	on of Damages			
5.	interculou No. 18-18	Genera	I Information			
	Accident Date	19/02/2018	Inspection Date	22/02/2018		
	Survey held at	CHENG HOE MOTOR PL				
	CONTROL MUNICIPALITY OF THE STATE OF THE STA	BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761	4			
5a.		R	emarks			
		ON WAS CONDUCTED ON A"WITCE TO YOUR INSTRUCTIONS, W				

# ...CLAIM SUBFOLDER...(New Assignment)

LATIN SU	BFOLDER TRAC	KING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status	
Main	19 Feb 2018		20 Feb 2018 16:37 Assign				New Assigni Cancel Case	
	Main	Re	ference	Clai	m Details	Docum	ents	Show All
CLAIM S	UBFOLDER DET	AILS				[Created t	y insurer]	
Insured:		CHRISHTOPH	ER CHALSON, II	: S8410540F				
Main Cla	imant:	TAN CHENG K	IAT, ID: S11347	774F				
Vehicle Reg. No.:		SCK5599M		Da	te of Loss:	19/02/2018	08:00 - :59	
Claim Ty	pe:	<b>TP</b> / 550056		Po	licy/Cover Note No.	: 80350547Q Coverage: 1	MX 19/05/2017 - 18	/05/2018
Vehicle Reg. No. (Insured):		SJU1420K		Po	Policy No. (Claimant):			
(N)	77.			Ex	cess:			
Repairer	:	Cheng Hoe Mo 6142	otor Pte Ltd (Yish	iun) Blk 1019	#01-374/382, Yishun	Industrial Park	A, 768761 Yishu	n - Tel: 6755
Handling	Insurer:	MSIG Insuran 2540]	ice (Singapore) F	te. Ltd. (HQ)	- Tel: +65 6827 788	8 [Handled by	Elaine Ngu Sia	nu Mei - 6594
Adjuster	:	LKK Auto Con	sultants Pte Ltd	(HQ) - Tel: 62	56-3561 [Imm.A	dvice due 21	/02/2018]	
Driver/C (Insured	ustodian ):	CHRISHTOPHE	R CHALSON (), N	RIC: S841054	OF			
Adi Aca	Remarks:	please assign N	fr Kenneth Kong as	the surveyor.	Thank You.			
auj asy.								
80 -50	ATED MAIL REC	EIVED				View	All   Compos	se Case Mail
ASSOCI	ATED MAIL REC	30000000				View	All Compo	se Case Mail
ASSOCIATION There are		ase.	secure beauties	V. 00115-750-710	View All Search		All Compose	se Case Mail  Complete

Kenneth

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

From: LKK Auto Consultants Pte Ltd MSIG Insurance (Singapore) Pte. Ltd. To: 51 Ubi Ave 1 #01-25 4 Shenton Way Paya Ubi Industrial Park #21-01 SGX Centre 2 Singapore 408933 Singapore 068807 Date: 23 Feb 2018 Elaine Ngu Siau Mei Attn:

## **Preliminary Advice**

Insured Vehicle No	: SJU1420K		
TP Vehicle No	: SCK5599M	Accident Date	: 19/02/2018
Make	: TOYOTA COROLLA AXIO	Assignment Date	: 20/02/2018
Date of Inspection	: 20/02/2018	Est. Duration of Repair	: 7.00
Inspection At	: CHENG HOE MOTOR PTE LTD (* BLK 1019 #01-374/382, YISHUN I SINGAPORE 768761	YISHUN) NDUSTRIAL PARK A	

# Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	7,236.81
Revised Amount	:S\$	6,171.46
Check Items (Estimated)	:S\$	733.05
Total	:S\$	6,904.51
Lump Sum Repair	:S\$	

### **Total Loss Consideration**

:S\$	
:S\$	
:S\$	
:S\$	
:S\$	
	:S\$ :S\$ :S\$

#### Remarks

The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

# Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID:	4774F	
Vehicle Details		
Vehicle No.:	SCK5599M	
Vehicle to be Exported:	Yes	
Intended De-registration Date:	20 Feb 2018	
Vehicle Make:	ТОУОТА	
Vehicle Model:	COROLLA AXIO 1.5G CVT ABS D/AIRBAG 2WD	
Primary Colour:	Gold	
Manufacturing Year:	2016	
Engine No.:	2NR8654616	
Chassis No.:	NRE1610020244	
Maximum Power Output:	80.0 kW (107 bhp)	
Open Market Value:	\$19,228.00	
Original Registration Date:	15 Sep 2016	
First Registration Date:	15 Sep 2016	
Transfer Count:	0	
Actual ARF Paid:	\$9,228.00	
Intended PARF Rebate De	etails	
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	14 Sep 2026	
PARF Rebate Amount:	\$6,921.00	
Intended COE Rebate De	tails	
COE Expiry Date:	14 Sep 2026	
COE Category:	A - Car up to 1600cc & 97kW (130bhp)	
COE Period(Years):	10	
QP Paid:	\$53,334.00	
COE Rebate Amount:	\$42,667.00	
Total Rebate Amount:	\$49,588.00	

The information contained herein is correct as at 20 Feb 2018

#### SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy ability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5 Any false reporting may be referred to the Police for investigation.
  6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available

				7	_		1
AC		120	100	ΑІ	1 <b>–</b> 100	120	
	UIL				-		

19/02/2018 14:05 Date Of Report 19/02/2018 08:40 Date Of Accident

JUNC UBI LINK & UBI AVE 4 Exact Location Of Accident

SINGAPORE Country/State of Loss

### DETAILS OF OWN VEHICLE

SCK5599M Vehicle Registration Number

Insured/Policyholder

TAN CHENG KIAT Name Of Registered Owner

S1134774F NRIC No NOEMAIL Email Address

Mobile Phone No (LOCAL) +65-96525555 OFFICE-96525555

Alternative Phone No Vehicle Particulars

TOYOTA Manufacturer

COROLLA AXIO 1.5G CVT ABS D/AIRBAG 2WD Model

Exact Purpose for which vehicle was being used at

time of accident

INSTRUCTION CAR

Are you claiming under your own insurance policy

for repair to your vehicle?

NO

If No, Please state action to be taken

THIRD PARTY PRIVATE CAR

Insurance Company

Vehicle Category

NTUC INCOME INSURANCE CO-OPERATIVE LTD Name of Insurance Company

COMPREHENSIVE Type Of Coverage

NO Fleet Policy

5083995229-01 Policy Number

Cover Note Number

Driver

STELLA SOON JIA YI Name of Driver

S9800173E NRIC No 02/01/1998 Date Of Birth INDOOR Occupation 07/12/2017 Date Of Driving Pass

0 YEAR AND 2 MONTH Driving Experience

FEMALE Gender

(LOCAL) +65-83125992 Mobile Number

Fax Number

OFFICE-83125992 Contact Number

NOFMAIL EMail Address

/.ddress

BLK 27 CHAI CHEE ROAD

#18-357

Postcode

460027

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OTHER - DRIVING INSTRUCTOR

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident

Was any body injured in the Accident?

NO

Was any injured conveyed to hospital by

ambulance?

YES

Was any other material or property damaged? I have been approached by unknown person(s)

soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME: : MALE GENDER:

**Details of Police Action** 

Was the accident reported to the police?

NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given?

NO

If Yes, against whom?

Circumstances of Accident

ON STATED DATE AND TIME, I WAS STATIONARY WAITING ALONG THE JUNCTION AS THE MAIN ROAD HAVE INCOMING VEHICLE PASSING BY. SUDDENLY VEHICLE B HIT ONTO MY VEHICLE REAR PORTION.

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

NO

Was there any audio recorded?

NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SJU1420K

Vehicle Make/Model/Colour

Details Of Properties

PRIVATE CAR

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

### Accident Sketch Plan

and the second s		
		A: JCK CLATA
		75- 43V 14 20K
1	7	
A A B		
E B		
5		
~		
SCRIBE CIRCUMSTANC		
seter to Mm	tement.	
DECLARATION		
We declare the foregoing	particulars are true in every respect.	1 Ma
We declare the foregoing	particulars are true in every respect.  All doron.	Jan
DECLARATION  TWO declare the foregoing  Tolicyholder's Signature		Reporting Centre Personnel's Signature

# Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singap 768761 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg GST:201001158E RCB NO:201001158E

MSIG INSURANCE (S) PTE LTD (SGX) M/S:

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

68277660 TEL:

ATTN: Motor Claim Department

WS Ref:

Claim Type:

Third Party 19/02/2018

Accident Date: TP Veh Reg No:

SJU1420K

TP/MSIG/YS

FAX: 62257402

Not Authorises Resures B4 pains

Chassis No: Engine No:

Reg. Date:

Date:

Estimate No:

Policy No:

Veh Reg No:

Make/Model:

2NR8654616

ES1890157/YISHUN

TOYOTA COROLLA

AXIO 1.5G CVT ABS D/AIRBAG 2WD NRE1610020244

20 Feb 2018

SCK5599M

5083995229-01

15/09/2016

Estimate Repair Cost to Vehicle No :SCK5599M

	Description	U	/Price	Quantity	Lis	t Price	Amount
	List Price				0.657	<u>S\$</u>	<u>S</u>
	REAR BUMPER		590.50	1 PC	Ry	590.50	_
1	REAR BUMPER CLIPS		3.89	6 PCS	M	23.34	
2	A CONTRACTOR OF THE CONTRACTOR		740.10	1 PC	R	740.10	
3	REAR BOOT		50.20	1 PC	na	50.20	
4	REAR BOOT LOGO		59.10	1 PC	na	59.10	_
5	REAR BOOT EMBLEM (COROLLA)				ne	45.20	_
6	REAR BOOT EMBLEM (G)		45.20	1 PC	ar		8
7	REAR BOOT INNER RUBBER		185.20	1 PC	nu	185.20	
8	REAR BOOT INNER LOCK		360.40	1 PC	men	300.40	_/
9	REAR BOOT OUTER MOULDING	m	292.10			292.10	-
10	TAILLAMPS	Mem		2 PCS		,048.20	_
11	TAILLAMP LOWER RETAINERS		75.20	2 PCS	Su	150.40	X
12	REAR PANEL		672.90	1 PC	Ry	672.90	
13	REAR PANEL INNER GARNISH	n	241.80	1 PC	Res	241.80	
14	REAR SPARE TYRE TOP BOARD	nulin	390.70	1 PC		390.70	2
15	REAR BOOT OPENNER SENSOR		144.20	1 PC	cns	144.20	2
16	REAR BOOT HINGES		88.20	2 PCS	n	176.40	X
17	REAR EXHAUST PIPE		925.00	1 PCS	Ry	925.00	_
					(	5,095.74	
				Less 25%		,523.94	4,571.8
	Special Net				01		
18	REVERSE SENSOR		200.00	1 PC	Sherr	200.00	
				44		200.00	200.0
19	REAR NUMBER PLATE		45.00	1 PC	Sin	45.00	
						45.00	45.0

# Cheng Hoe Motor Pte Ltd

M/S: MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY Estimate No: ES1890157/YISHUN

#24-01 HONG LEONG BUILDING Date: 20 Feb 2018

SINGAPORE 048581 Policy No: 5083995229-01

TEL: 68277660 FAX: 62257402 Veh Reg No: SCK5599M

ATTN: Motor Claim Department Make/Model: TOYOTA COROLLA

AXIO 1.5G CVT ABS

D/AIRBAG 2WD
S Ref: TP/MSIG/YS Chassis No: NRE1610020244

WS Ref: TP/MSIG/YS Chassis No: NRE1610020244

Claim Type: Third Party Engine No: 2NR8654616

Accident Date: 19/02/2018 Reg. Date: 15/09/2016

Accident Date: 19/02/2018 Reg. Date: TP Veh Reg No: SJU1420K

# Estimate Repair Cost to Vehicle No :SCK5599M

	Description	U/Price	Quantity	List Price	Amount
	Constitution of the second			<u>SS</u>	<u>SS</u>
	Labour				
20	REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, REAR BOOT & ATTACHMENT, CUT, WELD & RENEW REAR PANEL, KNOCK & REPAIR REAR BOTH TAILLAMP PANELS, REAR BOTH FENDERS, STRAIGHTEN REAR SPARE TYRE COMPARTMENT & REALIGN THE SAME	1,100.00	1 LA	1,100.00	1000
21	REMOVE & REFIX REVERSE CAMERA, RESET SYSTEM	60.00	1 PC	60.00	
22	PUTTY & RESPRAY ON REAR PANEL, REAR SPARE TYRE COMPARTMENT, REAR BOTH FENDERS, BOOT, HINGES, REAR	1,200.00	1 LA	1,200.00	11001
	PANEL,REAR BUMPER	60.00	T.T.A	60.00	/
23	RUSTPROOFING	60.00	1 LA		
				2,420.00	2,420.00
				Total	S\$ 7,236.81
			Add GS	Г@ 7%	506.58
			Total Amount	Payable	S\$ 7,743.39

### For Cheng Hoe Motor Pte Ltd

the Repair • To resum • To displa • Party — Control	Consultants hence notify authorises before after spray pointing.  AUTHORIS correspond pointing resurvey and authorises are all and a property and and approve appr	SED SIGNATURE
A	Sanan	

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Email: sur@lkkauto.com;assignments@lkkauto.com Tel: 6256-3561 Fax: 6844-8805

## VEHICLE DAMAGE INSPECTION REPORT

Our File No:

CS/MSG18003271/KVBN2

Date:

04/04/2018

REFERENCE

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

80350547QMX

Claimant

SCK5599M

Insured Vehicle No:

SJU1420K

Vehicle No: Date of Loss:

19/02/2018

Nature of Claim:

TP

Claim No: 550056

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No:

SCK5599M

Make & Model:

TOYOTA COROLLA AXIO, 1.5 (A) 15/09/2016 (Man. Year: 2016)

Engine No: Chassis No: 2NR8654616

Reg. Date: Colour:

Metallic Gold

1496 cc

Odometer:

NRE1610020244 51265 km

**Engine Capacity:** Market Value/New Car

Price:

N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

195/60R15

Rear Tyre Size:

195/60R15

Front Left Side:

Yokohama 8 mm Yokohama 8 mm Rear Left Side: Rear Right Side: Yokohama 8 mm Yokohama 8 mm

Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS Parts	Repairer's 4,816.80	Adjuster's 4,571.70	Difference 245.10	Diff % 5.09
Miscellaneous Items	0.00	0.00	0.00	
Labour Paintwork Labour	2,420.00 0.00	2,220.00 0.00	200.00 0.00	8.26
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,236.80	6,791.70	445.10	6.15
+ GST 7.00/7.00% (S\$)	506.58	475.42	31.16	6.15
Nett Amount (S\$)	7,743.38	7,267.12	476.26	6.15

INSPECTION

Date of Assignment:

20/02/2018

Date Inspected:

20/02/2018 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial

Park A

Singapore 768761

Estimated Period of Repair:

7.0 days

Adjuster: KENNETH KONG Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Different 1 cents -Finalise amount: \$6791.71

# REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 04 Apr 2018)

Parts:

143

TOYOTA COROLLA AXIO 1.5 (A) (Catalogue: Merimen Singapore 1.0)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SCK5599M)

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

Recommended	Parts
-------------	-------

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	590.50 FL	*590.50 FL
2	6		*REAR BUMPER CLIPS	Necessary	23.34 FL	*23.34 FL
3	1		*REAR BOOT	Bent	740.10 FL	*740.10 FL
4	1		*REAR BOOT LOGO	Necessary	50.20 FL	*50.20 FL
5	1		*REAR BOOT EMBLEM (COROLLA)	Necessary	59.10 FL	*59.10 FL
6	1		*REAR BOOT EMBLEM (G)	Necessary	45.20 FL	*45.20 FL
7	1		*REAR BOOT INNER RUBBER	Cut	185.20 FL	*185.20 FL
8	1		*REAR BOOT INNER LOCK	Dented	360.40 FL	*360.40 FL
9	1		*REAR BOOT OUTER MOULDING	Mtg Cracked	292.10 FL	*292.10 FL
10	2		*TAILLAMPS	Mtg Cracked/Cut	1,048.20 FL	*1,048.20 FL
11	2		*TAILLAMP LOWER RETAINERS	Serviceable	150.40 FL	*-FL
12	1		*REAR PANEL	Bent	672.90 FL	*672.90 FL
13	1		*REAR PANEL INNER GARNISH	Dented	241.80 FL	*241.80 FL
14	1		*REAR SPARE TYRE TOP BOARD	Dented/Cracked	390.70 FL	*390.70 FL
15	1		*REAR BOOT OPENNER SENSOR	Cracked	144.20 FL	*144.20 FL
16	2		*REAR BOOT HINGES	Repair	176.40 FL	*-FL
17	1		*REAR EXHAUST PIPE	Bent	925.00 FL	*925.00 FL
18	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
19	1		*REAR NUMBER PLATE	Dented/Scratched	45.00 FS	*45.00 FS
F=Fr	anchise	part. S=SpcN	lett L=ListItemDisc.		and the same of th	
				Sub Total (S\$)	6,340.74	6,013.94
			- List Item Discount on L	Items 25.00/25.00% (S\$)	1,523.94	1,442.24
				Total Parts (S\$)	4,816.80	4,571.70

Adjuster Report Page 4 of 4

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

# Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labo	our Items			
1	REMOVE & REFIX REAR BUMPER ASSY,TAILLAMPS,REAR BOOT & ATTACHMENT,CUT,WELD & RENEW REAR PANEL,KNOCK & REPAIR REAR BOTH TAILLAMP PANELS,REAR BOTH FENDERS,STRAIGHTEN REAR SPARE TYRE COMPARTMENT & REALIGN THE SAME	New	1,100.00	1,000.00
2	REMOVE & REFIX REVERSE CAMERA, RESET SYSTEM	New	60.00	60.00
3	PUTTY & RESPRAY ON REAR PANEL, REAR SPARE TYRE COMPARTMENT, REAR BOTH FENDERS, BOOT, HINGES, REAR PANEL, REAR BUMPER	New	1,200.00	1,100.00
4	RUSTPROOFING	New	60.00	60.00
	Gross Labou	r Cost (S\$)	2,420.00	2,220.00
	Report was unsubmitted during	ng this print-out.		

< END OF ESTIMATES >