

ASS. REC. BY:

REF:

291

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Vehl:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

07 days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

ABE 8014H

Yr Regn:

03, 16

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota

c.c.

2886

Colour:

Silver

A/C:

Insured / Std / NI / NA

Sp. Reading:

68246

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

K0231

8023005

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N/A / S/Rim / STD A/Rim or

Tyre Size:

F:

195R15X8

R:

155R12XR10

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal:

4

mm

R/Bal:

33

mm

L/Bal:

4

mm

L/Bal:

33

mm

D.O.A.

13/2/18

D.O.A.

14/2/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

1st N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

12 File part to

5/4 85453.20 Cabman

(Reel # 178.40 / 34)

7 + 3PH + 1 PRS = 11 days.

Data/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Data/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ - RS - \$1

Photo:

Others:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format:

Lump Sum / I.B.I. (\$

TOTAL



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

31 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: TBA
Our ref: CC6/EQ18003280/Kws3

Date: 21.02.2018

The Motor Claims Department
M/s EQ INSURANCE COMPANY LTD

PRELIMINARY ADVICE OF VEHICLE NO.

GBE 8014H

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 14.02.2018 at the premises of M/s Cheng Hoe Motor Pte Ltd (Yishun) and have the following to report:-

Workshop Estimate Amount	: S\$	4,971.60
Revised Estimate Amount	: S\$	3,716.40
"Check" Items Amount	: S\$	84.00
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:
The vehicle sustained damages at the
Front N/S Portion



Comments/Present Status:
Damages Consistent
Estimated normal period for repairs: 7.0 days
Remarks :

Yours faithfully,

KENNETH KONG
Licensed Appraiser

Kw

Attn: Kenneth

Cheng Hoe Motor Pte Ltd

Bldg 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST: 201001158E RCB NO: 201001158E

GBE 8014H

TP/EA

M/S: EQ INSURANCE CO LTD
 22 GEMMILL LANE
 SINGAPORE 069257

TEL: 62239433

FAX: 62243903

ATTN: Motor Claim Department

WS Ref: TP/EQ/YS

Claim Type: Third Party

Accident Date: 13/02/2018

TP Veh Reg No: SLF3948Y

Claim No: ES1890155

Estimate No: ES1890155/YISHUN

Date: 14 Feb 2018

Policy No: DMCVSN3021021700

Veh Reg No: GBE8014H

Make/Model: TOYOTA DYNA 3.0M

Chassis No: KDY2318023005

Engine No: 1KD2578947

Reg. Date: 28/03/2016

Estimate Repair Cost to Vehicle No: GBE8014H

Pages: 1/1

Description	U/Price	Quantity	Cost S\$	Amount S\$
Cost Plus				
1 FRONT BUMPER	240.00	1 PC	240.00	
2 FRONT BUMPER LH BRACKET	105.00	1 PC	105.00	
3 LH HEADLAMP	350.00	1 PC	350.00	
4 FRONT PANEL	390.00	1 PC	390.00	
5 FRONT GRILLE	210.00	1 PC	210.00	
6 FRONT GRILLE LOGO	38.00	1 PC	38.00	
7 FRONT GRILLE CLIPS	2.00	3 PCS	6.00	
8 FRONT PANEL STICKER (DYNA)	39.00	1 PC	39.00	
9 FRONT WINDSCREEN GLASS RUBBER	95.00	1 PC	95.00	
10 FRONT LH CORNAL PANEL	85.00	1 PC	85.00	
11 FRONT LH CORNAL GARNISH	50.00	1 PC	50.00	
12 FRONT LH STEP GARNISH	55.00	1 PC	55.00	
13 FRONT LH DOOR	600.00	1 PC	600.00	
14 FRONT LH DOOR LAMP	30.00	1 PC	30.00	
			2,293.00	
	Add 20%		458.60	2,751.60
Special Net				
15 FRONT LH DOOR COY STICKER	20.00	1 PC	20.00	20.00
Labour				
16 REMOVE AND REFIX FRONT WINDSCREEN GLASS	60.00	1 LA	60.00	
17 REMOVE & REFIX DASH BOARD, METER ASSY & CHECK WIRING	250.00	1 LA	250.00	
18 REMOVE AND REFIX AIRCON, CHECK, VACUUM & REFILL	100.00	1 LA	100.00	
19 PANEL BEATING	900.00	1 LA	900.00	750
20 PUTTY & RESPRAY ON AFFECTED AREAS	800.00	1 LA	800.00	720
21 REMOVE & REFIX FRT LH DOOR GLASS	60.00	1 LA	60.00	
22 RUSTPROOFING	30.00	1 LA	30.00	
				2,200.00

Parts \$2803.20
 Supp \$660.00
 SN \$20.00
 Labour \$1970.00
 \$5453.20 ✓ OK

Total S\$ 4,971.60
 Add GST @ 7% 348.01
 Total Amount payable S\$ 5,319.61

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

Suppl 1

GBE8014H

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department
WS Ref: TP/EQ/YS
Claim Type: Third Party
Accident Date: 13/02/2018
TP Veh Reg No: SLF3948Y

Claim No: ES1890155
Estimate No: ES1890155/YISHUN
Date: 22 Feb 2018
Policy No: DMCVSN3021021700
Veh Reg No: GBE8014H
Make/Model: TOYOTA DYNA 3.0M
Chassis No: KDY2318023005
Engine No: 1KD2578947
Reg. Date: 28/03/2016

Estimate Repair Cost to Vehicle No : GBE8014H

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
Cost Plus				
1 AIR-CON CONDENSER WITH FAN MOTOR ASSY	420.00	1 PC <i>CM/Pn</i>	420.00	<u>==</u>
2 AIR-CON CONDENSER LIQUID PIPE	130.00	1 PC <i>B</i>	130.00	
			550.00	
	Add 20%		110.00	660.00

Total S\$ 660.00
GST Amount S\$ 46.20

Total Amount payable S\$ 706.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

5631.60

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	7257X
Vehicle Details	
Vehicle No.:	GBE8014H
Vehicle to be Exported:	Yes
Intended De-registration Date:	20 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 3.0M
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	1KD2578947
Chassis No.:	KDY2318023005
Maximum Power Output:	-
Open Market Value:	\$30,358.00
Original Registration Date:	28 Mar 2016
First Registration Date:	28 Mar 2016
Transfer Count:	0
Actual ARF Paid:	\$1,518.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	27 Mar 2026
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$42,036.00
COE Rebate Amount:	\$33,628.00
Total Rebate Amount:	\$33,628.00

The information contained herein is correct as at 20 Feb 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST201001158E RCB NO:201001158E

GBE 8014H

TP/ER

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433
ATTN: Motor Claim Department
WS Ref: TP/EQ/YS
Claim Type: Third Party
Accident Date: 13/02/2018
TP Veh Reg No: SLF3948Y

FAX: 62243903

Claim No: ES1890155
Estimate No: ES1890155/YISHUN
Date: 14 Feb 2018
Policy No: DMCVSN3021021700
Veh Reg No: GBE8014H
Make/Model: TOYOTA DYNA 3.0M
Chassis No: KDY2318023005
Engine No: 1KD2578947
Reg. Date: 28/03/2016

Not Authorised
1-B1
Refusing B4 painting

Estimate Repair Cost to Vehicle No : GBE8014H

Pages: 1/1

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Cost Plus				
1 FRONT BUMPER	240.00	1 PC	240.00	✓
2 FRONT BUMPER LH BRACKET	105.00	1 PC	105.00	✓
3 LH HEADLAMP	350.00	1 PC	350.00	✓
4 FRONT PANEL	390.00	1 PC	390.00	✓
5 FRONT GRILLE	210.00	1 PC	210.00	✓
6 FRONT GRILLE LOGO	38.00	1 PC	38.00	✓
7 FRONT GRILLE CLIPS	2.00	3 PCS	6.00	✓
8 FRONT PANEL STICKER (DYNA)	39.00	1 PC	39.00	✓
9 FRONT WINDSCREEN GLASS RUBBER	95.00	1 PC	95.00	✓
10 FRONT LH CORNAL PANEL	85.00	1 PC	85.00	✓
11 FRONT LH CORNAL GARNISH	50.00	1 PC	50.00	7
12 FRONT LH STEP GARNISH	55.00	1 PC	55.00	7
13 FRONT LH DOOR	600.00	1 PC	600.00	✓
14 FRONT LH DOOR LAMP	30.00	1 PC	30.00	X
			2,293.00	
	Add 20%		458.60	2,751.60
Special Net				
15 FRONT LH DOOR COY STICKER	20.00	1 PC	20.00	✓
				20.00
Labour				
16 REMOVE AND REFIX FRONT WINDSCREEN GLASS	60.00	1 LA	60.00	✓
17 REMOVE & REFIX DASH BOARD,METER ASSY & CHECK WIRING	250.00	1 LA	250.00	✓
18 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL	100.00	1 LA	100.00	✓
19 PANEL BEATING	900.00	1 LA	900.00	750
20 PUTTY & RESPRAY ON AFFECTED AREAS	800.00	1 LA	800.00	720
21 REMOVE & REFIX FRT LH DOOR GLASS	60.00	1 LA	60.00	✓
22 RUSTPROOFING	30.00	1 LA	30.00	✓
				2,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To return vehicle to original condition
- To display damaged panel during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications are allowed
- Supplemental charges will be required and is subject to approval from insurance company

Total S\$ 4,971.60
Add GST @ 7% 348.01
Total Amount payable S\$ 5,319.61

For Cheng Hoe Motor Pte Ltd

Authorized Signature

Signature

Date

AUTHORISED SIGNATURE

Shirley Hiew (LKK Auto)

From: Joel Goh <joel.goh@eqinsurance.com.sg>
Sent: Monday, 26 March 2018 4:38 PM
To: Shirley Hiew (LKK Auto)
Cc: Admin A; Joy Irene (LKKAuto); Vivian Lau (LKKAuto)
Subject: RE: Direct Settlement - Accident Involving SLF3948Y (OI : EQI - DM18HO00474-JG) AND GBE8014H (TP : LKK REF - CC6/EQI18003280/Kws3) on 13/02/2018
Attachments: SLF3948Y.PDF

Dear Shirley

Attached our insured's accident report for your attention.

Best Regards,

Joel Goh
Executive | Claims



EQ Insurance Company Limited

5 Maxwell Road #17-00 Tower Block MND Complex Singapore 069110
did 65 6500 6772 | tel 65 6223 9433 ext 772 | fax 65 6223 4190
www.eqinsurance.com.sg

A Member of Citicor

Privileged/Confidential information may be contained in this message. If you are not the intended recipient, please notify the

From: Shirley Hiew (LKK Auto) [mailto:ShirleyHiew@lkkauto.com]
Sent: Wednesday, March 21, 2018 1:15 PM
To: Janet Tan; Vivian Lau (LKKAuto)
Cc: eqiprs@eqinsurance.com.sg.; Joel Goh; Admin A; Joy Irene (LKKAuto)
Subject: Direct Settlement - Accident Involving SLF3948Y (OI : EQI - TBA) AND GBE8014H (TP : LKK REF - CC6/EQI18003280/Kws3) on 13/02/2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

We have inspected TP vehicle GBE 8014H at M/s Cheng Hoe Motor Pte Ltd - Yishun.

Enclosed for your perusal is:

- TP GIA report
- TP estimated cost of repair
- Preliminary advice

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Vivian and she can be contacted at DID: 6841 8625.

To check availability of the case handler , you may contact the undersigned.

Thank you.

Best Regards,

Shirley Hiew | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: ShirleyHiew@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Hsiao Tong (LKKAuto)

From: Cheng Hoe Motor Pte Ltd (Yishun-June) <chmotor@singnet.com.sg>
Sent: Saturday, 23 November 2019 11:59 AM
To: Hsiao Tong (LKKAuto)
Subject: ACCEPTANCE -our Ref: GBE8014H *Our Ref: CC6/EQI18003280/Kpa3 [ACCIDENT INVOLVING SLF 3948Y(EQ) AND GBE 8014H ON 13/02/2018]

Hi Hsiao Tong,

Your offer of S\$6450.00 is accepted.

Thank you.

Rgds
June Phua
Cheng Hoe Motor Pte Ltd
Tel :67556142
Fax : 67557719

From: Hsiao Tong (LKKAuto)
Sent: Saturday, November 02, 2019 9:35 AM
To: <mailto:chmotor@singnet.com.sg>
Subject: RE: Your Ref: GBE8014H *Our Ref: CC6/EQI18003280/Kpa3 [ACCIDENT INVOLVING SLF 3948Y(EQ) AND GBE 8014H ON 13/02/2018]

Without Prejudice

Dear Sirs/Mdm,

We refer to our email dated 12/10/2019.

Please confirm.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,
Hsiao Tong, Chew (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Saturday, 12 October 2019 1:19 PM

To: Cheng Hoe Motor Pte Ltd (Yishun-June) (chmotor@singnet.com.sg) <chmotor@singnet.com.sg>

Subject: Your Ref: GBE8014H *Our Ref: CC6/EQI18003280/Kpa3 [ACCIDENT INVOLVING SLF 3948Y(EQ) AND GBE 8014H ON 13/02/2018]

Your Ref: **GBE8014H**

Without Prejudice

Our Ref: CC6/EQI18003280/Kpa3

Dear Sirs/Mdm,

ACCIDENT INVOLVING SLF 3948Y(EQ) AND GBE 8014H ON 13/02/2018

We refer to the above matter.

We propose settlement at a global sum of \$6,450.00 (all-in).

Please confirm acceptance.

"Please note that our above settlement is made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our insured/driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Settlement and payment are subject to production of original documents on demand at any time and execution of Discharge Voucher (for settlement sum above \$20,000/-) by the Plaintiff/Claimant. Further all original documents shall be retained by us after we have made payment on the settlement sum."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC6/EQ18003280/Kpa3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 11-12-2019



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLF 3948Y	Veh. Inspected	GBE 8014H
Policy No.	DMCFHQ17-000185	Coverage (\$)	0.00
Claim No.	DM18HO00474-JG	Excess (\$)	0.00
Assign From		Assign Date	14/02/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KDY2318023005	Colour	SILVER
Odometer	68246	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15X8	MICHELIN	4 mm
L/H Front Tyre	195 R15X8	MICHELIN	4 mm
R/H Rear Tyre	155 R12X8 (D)	MICHELIN	3/3 mm
L/H Rear Tyre	155 R12X8 (D)	MICHELIN	3/3 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	13/02/2018	Inspection Date	14/02/2018
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 8014H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER (WCP)	BENT	240.00	240.00
1	FRONT BUMPER LH BRACKET (WCP)	DISTORTED	105.00	105.00
1	LH HEADLAMP (WCP)	CRACKED	350.00	350.00
1	FRONT PANEL (WCP)	BENT	390.00	390.00
1	FRONT GRILLE (WCP)	CRACKED / DENTED	210.00	210.00
1	FRONT GRILLE LOGO (WCP)	NECESSARY	38.00	38.00
3	FRONT GRILLE CLIPS @\$2.00 (WCP)	NECESSARY	6.00	6.00
1	FRONT PANEL STICKER (DYNA) (WCP)	NECESSARY	39.00	39.00
1	FRONT WINDSCREEN GLASS RUBBER (WCP)	NECESSARY	95.00	95.00
1	FRONT LH CORNAL PANEL (WCP)	BENT	85.00	85.00
1	FRONT LH CORNAL GARNISH (WCP)	MTG CRACKED	50.00	50.00
1	FRONT LH STEP GARNISH (WCP)	DENTED / CUT	98.00	98.00
1	FRONT LH DOOR (WCP)	BUCKLED	600.00	600.00
1	FRONT LH DOOR LAMP (WCP)	SCRATCHED	30.00	30.00
1	AIR-CON CONDENSER WITH FAN MOTOR ASSY (WCP) (ADDITIONAL)	CRACKED / PUNCTURE	420.00	420.00
1	AIR-CON CONDENSER LIQUID PIPE (WCP) (ADDITIONAL)	BENT	130.00	130.00
	COST PLUS 20%		577.20	577.20
			3,463.20	3,463.20
SPECIAL NETT ITEMS				
1	FRONT LH DOOR COY STICKER (SN)	NECESSARY	20.00	20.00
			20.00	20.00
LABOUR				
	REMOVE AND REFIX FRONT WINDSCREEN GLASS .		60.00	60.00
	REMOVE & REFIX DASH BOARD ,METER ASSY & CHECK WIRING.		250.00	250.00
	REMOVE AND REFIX AIRCON ,CHECK ,VACUUM & REFILL .		100.00	100.00
	PANEL BEATING.		900.00	750.00
	PUTTY & RESPRAY ON AFFECTED AREAS.		800.00	720.00

Report Ref No. CC6/EQI18003280/Kpa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REMOVE & REFIX FRT LH DOOR GLASS . RUSTPROOFING.		60.00	60.00
			30.00	30.00
			2,200.00	1,970.00
GRAND TOTAL			5,683.20	5,453.20
RECOMMENDED COST OF REPAIRS				5,453.20

Report Ref No. CC6/EQ118003280/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.