

Kw

Arthur Kenneth

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

GBE 8014H

TP/EO

M/S: EQ INSURANCE CO LTD
 22 GEMMILL LANE
 SINGAPORE 069257

TEL: 62239433

FAX: 62243903

ATTN: Motor Claim Department

WS Ref: TP/EQ/YS

Claim Type: Third Party

Accident Date: 13/02/2018

TP Veh Reg No: SLF3948Y

Claim No: ES1890155

Estimate No: ES1890155/YISHUN

Date: 14 Feb 2018

Policy No: DMCVSN3021021700

Veh Reg No: GBE8014H

Make/Model: TOYOTA DYNA 3.0M

Chassis No: KDY2318023005

Engine No: 1KD2578947

Reg. Date: 28/03/2016

Estimate Repair Cost to Vehicle No: GBE8014H

Pages: 1/1

Description	U/Price	Quantity	Cost S\$	Amount S\$
Cost Plus				
1 FRONT BUMPER	240.00	1 PC	240.00	
2 FRONT BUMPER LH BRACKET	105.00	1 PC	105.00	
3 LH HEADLAMP	350.00	1 PC	350.00	
4 FRONT PANEL	390.00	1 PC	390.00	
5 FRONT GRILLE	210.00	1 PC	210.00	
6 FRONT GRILLE LOGO	38.00	1 PC	38.00	
7 FRONT GRILLE CLIPS	2.00	3 PCS	6.00	
8 FRONT PANEL STICKER (DYNA)	39.00	1 PC	39.00	
9 FRONT WINDSCREEN GLASS RUBBER	95.00	1 PC	95.00	
10 FRONT LH CORNAL PANEL	85.00	1 PC	85.00	
11 FRONT LH CORNAL GARNISH	50.00	1 PC	50.00	
12 FRONT LH STEP GARNISH	55.00	1 PC	55.00	
13 FRONT LH DOOR	600.00	1 PC	600.00	
14 FRONT LH DOOR LAMP	30.00	1 PC	30.00	
			2,293.00	
	Add 20%		458.60	2,751.60

Special Net				
15 FRONT LH DOOR COY STICKER	20.00	1 PC	20.00	20.00

Labour				
16 REMOVE AND REFIX FRONT WINDSCREEN GLASS	60.00	1 LA	60.00	
17 REMOVE & REFIX DASH BOARD, METER ASSY & CHECK WIRING	250.00	1 LA	250.00	
18 REMOVE AND REFIX AIRCON, CHECK, VACUUM & REFILL	100.00	1 LA	100.00	
19 PANEL BEATING	900.00	1 LA	900.00	750
20 PUTTY & RESPRAY ON AFFECTED AREAS	800.00	1 LA	800.00	720
21 REMOVE & REFIX FRT LH DOOR GLASS	60.00	1 LA	60.00	
22 RUSTPROOFING	30.00	1 LA	30.00	
				2,200.00

Parts \$2803.20

Supp \$660.00

SN \$20.00

Labour \$1970.00

\$5453.20 ✓ ok

Total S\$ 4,971.60

Add GST @ 7% 348.01

Total Amount payable S\$ 5,319.61

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

Suppl 1

GBE8014H

M/S : EQ INSURANCE CO LTD
22 GEMMILL LANE
SINGAPORE 069257

TEL: 62239433 FAX: 62243903
ATTN: Motor Claim Department
WS Ref: TP/EQ/YS
Claim Type: Third Party
Accident Date: 13/02/2018
TP Veh Reg No: SLF3948Y

Claim No: ES1890155
Estimate No: ES1890155/YISHUN
Date: 22 Feb 2018
Policy No: DMCVSN3021021700
Veh Reg No: GBE8014H
Make/Model: TOYOTA DYNA 3.0M
Chassis No: KDY2318023005
Engine No: 1KD2578947
Reg. Date: 28/03/2016

Estimate Repair Cost to Vehicle No : GBE8014H

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary 1				
Cost Plus				
1 AIR-CON CONDENSER WITH FAN MOTOR ASSY	420.00	1 PC <i>CM/Pu</i>	420.00	<i>=</i>
2 AIR-CON CONDENSER LIQUID PIPE	130.00	1 PC <i>Bz</i>	130.00	<i>=</i>
			550.00	
	Add 20%		110.00	660.00

Total	S\$ 660.00
GST Amount	S\$ 46.20
Total Amount payable	<u>S\$ 706.20</u>

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE