

Premium Carz

Co. Reg. No.: 201416720C
1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883
Tel : 6636 9100 Fax : 6636 9113

Date : 19/2/18

TO: China Taiping Insurance (Singapore) Pte Ltd
3 Anson Road
#16-00 Spingleaf Tower
Singapore 079909

Attn : Motor Claim Department
Fax : 6224 7478

Our Customer : Isoteam Access Pte Ltd
Vehicle No : YN9170M
Model : Hino XZU605R 10FT
Manufacture Year : 2015
Date of Accident : 12/02/2018
Total Estimate Repair Days : 20
Total Page : 3

JH1HACS3H60K002734

Re: Repair Estimate For Third Party Claim against SLQ466H

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front bumper <i>Distorted</i>	1	\$594.00	\$594.00	✓
2	Front bumper bracket RH <i>Here</i>	1	\$282.00	\$282.00	x
3	Front bumper bracket LH <i>Bent</i>	1	\$282.00	\$282.00	✓
4	Headlamp RH <i>LT</i>	1	\$1,256.00	\$1,256.00	685
5	Headlamp LH <i>Cracked</i>	1	\$1,256.00	\$1,256.00	685
6	Fog lamp RH <i>Here</i>	1	\$385.00	\$385.00	x
7	Fog lamp LH <i>Cracked</i>	1	\$385.00	\$385.00	✓
8	Front grille <i>Cracked</i>	1	\$753.00	\$753.00	✓
9	Front grille "HINO" logo <i>new</i>	1	\$93.00	\$93.00	✓
10	Front grille clip <i>new</i>	8	\$5.00	\$40.00	✓
11	Front corner panel RH <i>Here</i>	1	\$542.00	\$542.00	x
12	Front corner panel LH <i>Repair</i>	1	\$542.00	\$542.00	x
13	Front door RH <i>Distorted</i>	1	\$1,895.00	\$1,895.00	155
14	Front door LH <i>Distorted</i>	1	\$1,895.00	\$1,895.00	1780
15	Front door trimboard RH <i>Cracked</i>	1	\$718.00	\$718.00	445
16	Front door trimboard LH <i>Cracked</i>	1	\$718.00	\$718.00	445
17	Front door trimboard clip <i>new</i>	20	\$5.00	\$100.00	60
18	Front door lock RH <i>Cracked</i>	1	\$450.70	\$450.70	✓
19	Front door lock LH <i>Cracked</i>	1	\$450.70	\$450.70	✓
20	Front door power window motor RH <i>new</i>	1	\$569.30	\$569.30	x
21	Front door power window motor LH <i>new</i>	1	\$569.30	\$569.30	x
22	Front door power window regulator RH <i>new</i>	1	\$496.20	\$496.20	x
23	Front door power window regulator LH <i>new</i>	1	\$496.20	\$496.20	x
24	Front door signal lamp RH <i>new</i>	1	\$278.00	\$278.00	x
25	Front door signal lamp LH <i>new</i>	1	\$378.00	\$378.00	x
26	Front door outer moulding RH <i>new</i>	1	\$378.00	\$378.00	x
27	Front door outer moulding LH <i>new</i>	1	\$187.30	\$187.30	x
30	Front door weatherstrip RH <i>new</i>	1	\$275.60	\$275.60	✓
31	Front door weatherstrip LH <i>new</i>	1	\$275.60	\$275.60	✓
32	Front door hinges RH <i>Bent</i>	1	\$169.50	\$169.50	70
33	Front door hinges LH <i>Bent</i>	1	\$169.50	\$169.50	70
34	Front door check RH <i>new</i>	1	\$196.30	\$196.30	48
35	Front door check LH <i>new</i>	1	\$196.30	\$196.30	48
36	Front door "616" sticker RH <i>new</i>	1	\$98.00	\$98.00	✓



Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel : 6636 9100 Fax : 6636 9113

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
37	Front door "616" sticker LH <i>NEC</i>	1	\$98.00	\$98.00	✓
38	Front door chanel RH <i>?</i>	1	\$281.75	\$281.75	X
39	Front door chanel LH <i>?</i>	1	\$281.75	\$281.75	X
40	Front door lower rubber RH <i>?</i>	1	\$145.50	\$145.50	X
41	Front door lower rubber LH <i>?</i>	1	\$145.50	\$145.50	X
42	Front door pillar RH <i>Best</i>	1	\$970.80	\$970.80	✓
43	Front door pillar LH <i>Distorted</i>	1	\$970.80	\$970.80	✓
44	Front door frame RH <i>Repair</i>	1	repair	repair	X
45	Front door frame LH <i>Repair</i>	1	repair	repair	X
46	Side mirror RH assy <i>?</i>	1	\$1,027.60	\$1,027.60	X
47	Side mirror LH assy <i>?</i>	1	\$1,027.60	\$1,027.60	X
48	Front step panel RH <i>Distorted</i>	1	\$300.00	\$300.00	225
49	Front step panel LH <i>Distorted</i>	1	\$300.00	\$300.00	225
50	Front floor panel RH <i>Repair</i>	1	\$1,467.75	\$1,467.75	X
51	Front floor panel LH <i>Repair</i>	1	\$1,467.75	\$1,467.75	X
52	Air filter housing assy <i>NEC</i>	1		\$0.00	X
53	Air-con condenser <i>Distorted</i>	1	\$1,285.00	\$1,285.00	695
54	Air-con fan blade <i>?</i>	1	\$140.00	\$140.00	X
55	Air-con condenser fan motor <i>?</i>	1	\$493.00	\$493.00	X
56	Air-con cowling <i>could</i>	1	\$228.00	\$228.00	✓
57	Rear under run bumper <i>Repair</i>	1	\$1,700.00	\$1,700.00	X
58	Rear under run bumper bracket <i>Repair</i>	2	\$510.00	\$1,020.00	X
59	Tail lamp RH <i>cracked</i>	1	\$430.00	\$430.00	205
60	Tail lamp LH <i>cracked</i>	1	\$430.00	\$430.00	205
61	Tail lamp bracket RH <i>Best</i>	1	\$150.00	\$150.00	90
62	Tail lamp bracket LH <i>Distorted</i>	1	\$150.00	\$150.00	90
63	Rear number plate lamp <i>could</i>	1	\$90.00	\$90.00	✓
64	Rear number plate holder <i>Best</i>	1	\$97.50	\$97.50	✓
65	Rear fender LH <i>NEC</i>	1	\$225.00	\$225.00	X
			Sub Total	\$32,293.80	
			Less 10%	\$3,229.38	
			Sub-Total 1	\$29,064.42	
B. Spare Parts (S/Nett)					
1	Front number plate <i>Best</i>	1	\$35.00	\$35.00	✓
2	Air-con discharge pipe <i>?</i>	1	\$310.00	\$310.00	X
3	Air-con aluminium pipe <i>NEC</i>	1	\$280.00	\$280.00	X
4	Air-con liquid pipe <i>?</i>	1	\$270.00	\$270.00	X
5	Rear under run bumper sticker <i>NEC</i>	1	\$80.00	\$80.00	50
6	Tail facelift torsion reflector sticker <i>NEC</i>	1	\$80.00	\$80.00	50
7	Hydraulic pump - large LH <i>Best</i>	2	\$2,500.00	\$5,000.00	1800
8	Hydraulic pump - small <i>?</i>	2	\$1,800.00	\$3,600.00	X
9	Hydraulic pipe <i>?</i>	1	\$185.00	\$185.00	X
10	Rear number plate <i>Best</i>	1	\$35.00	\$35.00	✓
11	Stow arm RH <i>Repair</i>	1	\$168.00	\$168.00	X
12	Stow arm LH <i>Repair</i>	1	\$168.00	\$168.00	X
13	Control casing box complete <i>cracked</i>	1	\$575.00	\$575.00	✓
14	Control casing box bracket <i>NEC</i>	1	\$198.00	\$198.00	X
15	Power pack casing cover <i>cracked</i>	1	\$395.00	\$395.00	✓
16	Power pack cover clip <i>new</i>	1	\$45.00	\$45.00	20

Premium Carz

Services Pte Ltd

Co. Reg. No.: 201416720C

1 Kaki Bukit Ave 6 #01-90 Autobay@Kaki Bukit Singapore 417883

Tel : 6636 9100 Fax : 6636 9113

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
17	Side stopper LH (yellow colour) <i>Missing</i>	1	\$69.00	\$69.00	✓
18	Side stopper bracket assy LH <i>Not</i>	1	\$575.00	\$575.00	✗
19	Retraction cylinder RH <i>Not</i>	1	\$1,700.00	\$1,700.00	✗
20	Retraction cylinder bracket RH	1		\$0.00	✓
21	Retraction cylinder chain safety device	1		\$0.00	✓
22	Eye Retraction cylinder RH	1		\$0.00	✓
23	Torsion bar RH	1	repair	repair	✗
24	Rear End cap RH	1		\$0.00	✗
25	Rear End stopper RH	1		\$0.00	✗
26	Floor mat <i>3 ne</i>	1	\$70.00	\$70.00	✗
27	Floor carpet <i>3 ne</i>	1	\$110.00	\$110.00	✗
<i>3029</i> Sub-Total 2				\$13,948.00	
Total for Parts				\$43,012.42	
C.	Labour				
1	To check wiring.			\$150.00	60
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$2,400.00	1600
3	Spray painting all affected parts & areas.			\$2,200.00	1400
4	To spray anti-rust undercoat.			\$150.00	80
5	To remove and refit front door glass RH.			\$100.00	80
6	To remove and refit front door glass LH.			\$100.00	80
7	To remove and replace, to cut and weld tail lift damaged parts & areas (including hydraulic pump).			\$650.00	400
8	To remove and replace damaged air-con parts, and to vacuum air-con system and charge up air-con gas.			\$300.00	120
Total Labour				\$6,050.00	
Total Repair Cost				\$49,062.42	

3820.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Surveyor's Details

Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No

total 15,398.33
4/5: 155K
14Days.

155K