

TRANS-CAB AUTO SERVICES PTE LTD
 NO.2 ANG MO KIO ST63 SINGAPORE 569111
 TEL NO. 6287 6666 FAX NO. 6257 1330
 CO/GST REG NO. 201019626G
SHB9950T -

AAD1802-186

Not Authoised
11 May 8/900

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHB9950T - JASMINE
 VF1ABL15AUC273390
 RENAULT
 LATITUDE
 15.02.2018
AIG

PART			LIST	
1	1	BUMPER COVER FRT	\$	<i>Br</i> 1,259.42 ✓
2	1	BUMPER SPOILER FRT	\$	<i>Sm</i> 181.75 X
3	1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sm</i> 207.22 X
4	1	BUMPER RETAINER FRT RH	\$	<i>Dr</i> 151.41 ✓
5	1	BUMPER RETAINER FRT LH	\$	<i>Sm</i> 151.41 X
6	1	BUMPER SUPPORT FRT RH	\$	<i>Sm</i> 123.88 X
7	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08
8	1	RADAITOR GRILLE	\$	<i>Sm</i> 1,707.78
9	1	RADAITOR GRILLE BADGE 'RENAULT'	\$	<i>Sm</i> 225.36
10	1	RADAITOR GRILLE FRAME	\$	<i>Sm</i> 1,353.75
11	1	FRAME FULL SUPPORT PANEL	\$	<i>Sm</i> 615.90
12	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
13	1	BONNET	\$	<i>R</i> 1,941.63
14	1	HEADLALMP RH	\$	<i>Sm</i> 1,184.43
15	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15
16	1	FENDER PANEL FRT RH	\$	<i>R</i> 783.83
17	1	FENDER INSULATOR RH	\$	<i>Sm</i> 130.84
18	1	WHEEL HOUSING PANEL FRT RH	\$	<i>R</i> 4,682.09
19	1	WHEELARCH FRT RH	\$	<i>Sm</i> 278.84
20	1	LOWER ARM FRT RH	\$	<i>Sm</i> 685.76
21	1	KUNCKLE ARM FRT RH	\$	<i>Sm</i> 846.98
22	1	ABSORBER FRT RH	\$	<i>Sm</i> 360.54
23	1	DOOR MIRROR RH	\$	<i>Sm</i> 1,483.40
24	1	DOOR MIRROR GLASS RH	\$	<i>Sm</i> 148.20
25	1	DOOR MIRROR BACK COVER RH	\$	<i>Sm</i> 218.46
26	1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66
27	1	DOOR HINGE UPPER RH	\$	<i>R</i> 274.50
28	1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55

TOTAL	\$	23,298.61
10%	\$	2,329.86
	\$	20,968.75

Specical Nett

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-186

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9950T -

1	1SET	FRONT BUMPER CLIP	\$	<i>nn</i>	66.00	✓
2	1SET	WHEELARCH CLIP RH	\$	<i>nn</i>	66.00	} X
3	1	TOW COVER FRT	\$	<i>sn</i>	14.50	
4	1	CAP HUB RH FRT	\$	<i>sn</i>	35.00	
5	1	RIM RH FRT	\$	<i>sn</i>	385.00	
6	1	TYRE RH FRT	\$	<i>sn</i>	330.00	
7	1SET	BUMPER SUPPORT FRT CLIP RH	\$	<i>nn</i>	9.80	} X
8	1SET	BUMPR RETAINER FRT CLIP RH	\$	<i>nn</i>	12.50	
9	1	DOOR STICKER "Trans-cab"	\$	<i>nn</i>	80.00	<i>600</i>
10	1	DOOR STICKER "Classic"	\$	<i>nn</i>	30.00	<i>150</i>

TOTAL	\$	1,028.80
TOTAL PARTS	\$	21,997.55

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ *300*
2,800.00

To Check Electrical Lighting Concerned.

\$ 170.00 *150*

Putty and spray painting of the affected portion.

\$ 3,000.00 *600*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 X

Towing Fees

\$ *nn* 120.00 X

To transfer of tire, rim and on wheel balancing.

\$ *nn* 170.00 X

To rust-proofing of the affected areas.

\$ *nn* 170.00 X

To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.

\$ *nn* 170.00 X

To dismantle and refit front end suspension, undercarriage parts, final checking and testing.

\$ *nn* 380.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is not a valid defence
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to approval from Insurance Company

TOTAL \$ 7,200.00

Over All Total \$ 29,197.55

(PARTS BY PARTS) Repair Days

Acknowledged by Repairer
Signature:

10 Days

2 days