

Date : 20/2/2018

Vic

TO: India International Insurnace Pte Ltd
64 Cecil Street
#04/#05 IOB Building
Singapore 049711

Our Customer : Chui Seow Wing
Vehicle No : SGN3348X
Model : Toyota Altis
Manufacture Year : 2006 (COE:14/11/2026)
Date of Accident : 17/2/2018
Total Estimate Repair Days : 12
Total Pages : 2

Attn : Motor Claims Department
Fax : 6224 4174

Re: Repair Estimate For Third Party Claim against SH9065L

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
A.	Spare Parts				
1	Front fender RH <i>Repair</i>	1	<i>repair</i>	<i>repair</i>	X
2	Side mirror cover RH <i>Dented</i>	1	\$66.30	\$66.30	✓
3	Side mirror mechanism RH <i>new</i>	1	\$325.35	\$325.35	X
4	Front door RH <i>Dented</i>	1	\$1,243.00	(\$1,243.00)	1053
5	Front door trimboard RH <i>2 new</i>	1	\$455.41	\$455.41	X
6	Front door trimboard clip <i>2 new</i>	8	\$5.00	\$40.00	X
7	Front door outer handle RH <i>new</i>	1	\$63.14	\$63.14	X
8	Front door speaker RH <i>new</i>	1	\$228.70	\$228.70	X
9	Front door hinges <i>new</i>	2	\$85.00	\$170.00	X
10	Front door check RH <i>new</i>	1	\$74.20	\$74.20	X
11	Front door protector RH <i>2 Dislodge</i>	1	\$48.00	\$48.00	✓
12	Front door protector chrome RH <i>2 Dislodge</i>	1	\$27.00	\$27.00	✓
13	Front door lock RH <i>new</i>	1	\$250.48	\$250.48	X
14	Front door power window motor RH <i>2 new</i>	1	\$226.70	\$226.70	✓
15	Front door p/window regulator RH <i>2 new</i>	1	\$62.72	\$62.72	✓
16	Front door channel RH <i>new</i>	1	\$145.00	\$145.00	X
17	Front door weatherstrip RH <i>new</i>	1	\$85.00	\$85.00	✓
18	Front door outer moulding RH <i>new</i>	1	\$85.00	\$85.00	X
19	Front door sash pillar black sticker <i>new</i>	1	\$61.95	\$61.95	✓
20	Front door centre pillar RH <i>Repair</i>	1	<i>repair</i>	<i>repair</i>	X
21	Rear door RH <i>Dented</i>	1	\$1,243.00	(\$1,243.00)	1075
22	Rear door hinges RH <i>2 new</i>	2	\$85.00	\$170.00	X
23	Rear door check RH <i>2 new</i>	1	\$74.20	\$74.20	X
24	Rear door protector RH <i>2 Dislodge</i>	1	\$42.00	\$42.00	✓
25	Rear door protector chrome RH <i>2 Dislodge</i>	1	\$27.00	\$27.00	✓
26	Rear door lock RH <i>2 new</i>	1	\$250.48	\$250.48	X
27	Rear door power window motor RH <i>2 new</i>	1	\$226.70	\$226.70	X
28	Rear door p/window regulator RH <i>2 new</i>	1	\$62.72	\$62.72	X
29	Rear door channel RH <i>2 new</i>	1	\$145.00	\$145.00	X
30	Rear door outer moulding RH <i>2 new</i>	1	\$85.00	\$85.00	✓
31	Rear door sash pillar black sticker RH <i>new</i>	1	\$61.95	\$61.95	✓
32	Rear door quarter glass moulding <i>new</i>	1	\$42.77	\$42.77	X
33	Rear fender RH <i>Repair</i>	1	\$818.40	\$818.40	X
34	Rear fender lining clip <i>new</i>	8	\$5.00	\$40.00	X
35	Rocker panel <i>Dented</i>	1	\$254.89	\$254.89	✓
36	Rear windscreen moulding <i>new</i>	1	\$50.82	\$50.82	X
37	Rear shock absorber RH <i>new</i>	1	\$118.00	\$118.00	X
38	Rear wheel hub bearing LH <i>Dented</i>	1	\$637.41	(\$637.41)	348
39	Rear axle <i>2 new</i>	1	\$1,488.17	\$1,488.17	X

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
40	Rear bumper <i>Reps</i>	1	\$484.99	\$484.99	X
41	Rear bumper clip <i>3 per</i>	10	\$5.00	\$50.00	X
42	Rear bumper side retainer RH	1	\$19.74	\$19.74	X
	<i>3439.51</i> Total			\$10,051.19	
	Less 25%			\$2,512.80	
	<i>2579.63</i> Sub Total 1			\$7,538.39	
A.	Spare Parts (S/Nett)				
1	Rear tyre RH <i>new</i>	1	\$650.00	\$650.00	X
2	Rear rim RH <i>4x</i>	1	\$550.00	\$550.00	<i>400</i>
3	Rear windscreen sealant <i>Not New</i>	1	\$50.00	\$50.00	X
	<i>400</i> Sub Total 2			\$1,250.00	
	Total for Parts			\$8,788.39	
B.	Labour				
1	To check wiring.			\$120.00	<i>30</i>
2	Panel beating charges to remove and replace, to cut and weld, to knock and reshape damaged parts & areas.			\$1,200.00	<i>700</i>
3	Spray painting all affected parts & areas.			\$1,400.00	<i>1100</i>
4	To spray anti-rust undercoat.			\$120.00	<i>40</i>
5	To remove and replace rear undercarriage.			\$250.00	<i>80</i>
6	To check and align wheels with computerized wheel alignment.			\$120.00	<i>80</i>
7	To remove and refit front door glass RH.			\$100.00	<i>80</i>
8	To remove and refit rear door glass RH.			\$100.00	<i>80</i>
9	To remove and refit rear door quarter glass RH.			\$80.00	X
10	To remove and refit rear windscreen glass.			\$120.00	X
	Total Labour			\$3,610.00	
	Total Repair Cost			\$12,398.39	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Yours faithfully,

Aun Teng

f Premium Carz Services Pte Ltd

total: 5169.63

H/s: A.K ✓
06 Days

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No