

2/03/2002

ASS. REC. BY:

REF:

CG/MSG1800.3295/119602

Special Instruction:

Surveyor:

Taulia

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSG

Date/Time:

21/2/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SCZ 6623R

Insured:

G8B5842U

at Workshop m/s

Cycle & Carriage

Tel:

91817717 Eric Lee

of

188 Pandan Loop

Policy No:

28771079 MKC

Claim No:

550383

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

20/2/18

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

21/2/2018

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction

(✓) Estimate

SCZ 6623R - X

G8B5842U - CS3 / MSG 1800 2072 / Mid 3

D.O.A: 30/1/18

13/3/18@

114pm revised to Irene Tan via Messenger.

26/4/18@

1029am confirmed with Eric final fig \$3810.72, 3 days by email.


(Red \$1995.47, 34%)

26/4/18

Taufel

MSIC

Page _____ Date _____
Estimated Cost _____
OD TP / WS / TP RES / OD RES / EVA / INV / MV
To inspect vehicle No _____
at Workshop no _____
of _____
Insured _____
Policy No _____
Claims No _____
Sum Insured _____ Excess _____
Client's Record _____
Make of Veh _____



(Policy Condition)
Remarks: The veh had commenced its repair at the time of inspection.
Est. of Market Value _____
IDAC Accident Report: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs 3 days Res: Yes or No
Lump Sum _____ % 3 yrs: Yes or No
CA / REV / REP. / 24 HRS lwp
Date _____ Person Contacted enc

Ref No SC26623R Page 2/15 Aug
Type MD / M Cycle / Euc / Van / Lorry / Taxi / Prime Mover
Truck / Trailer
Make Mercedes benz CLA/80 cc 1595
Colour Grey
So Reading 53736 T-Paid Insured Stb N/A
Eng No _____
C/Nr WDD 1173422 N 25 31 70
Gen Cont Good / Fair / Poor / Burnt
Steering In order / Jammed / Leaked / Burnt
Brake In order / Jammed / Leaked / Burnt
Mod Nil / SR / STD / A/Rum /
Type Size 225/40x18
BS / DUN / EXNOVA / GY / FS / LIZA / MIO / OHTSU / PR / SLV
TOYO / YOKO or Continental
Front: 6 Rear: 6
R.Ba. 6 L.Ba. 6
D.O.A. 12/3/18 02pm
Survey report C&E Roadside lwp
Des of Damages Fr / Fr / OS / NS / UC / Rectified
The UIC / Chassis/frame Body Structure affected due to collision

RECEIVED 27 APR 2018

Date Time File Pass: 19/4 Taufel
Date Time File Return: _____
Preli. Report ☐
Final Report ☐
Add Fee: ☐ ☐ ☐ ☐
Report Form: MER-7P
Lump Sum: 380.22

Days Of Repair: 3
Resurvey No. of Trip _____
Add Fee: ☐ ☐ ☐ ☐
200
6
210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18003295/T1qb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 21-02-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBB 5842U	Veh. Inspected	SCZ 6623R
Policy No.	28771079MKC	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	IRENE TAN	Assign Date	21/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/02/2018	Inspection Date	12/03/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		

5a. Remarks

--

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tan Gek Ing

Date: 13 Mar 2018

Preliminary Advice

Insured Vehicle No	: GBB5842U	Accident Date	: 20/02/2018
TP Vehicle No	: SCZ6623R	Assignment Date	: 21/02/2018
Make	: MERCEDES-BENZ CLA180	Est. Duration of Repair	: 3.00
Date of Inspection	: 12/03/2018		
Inspection At	: CYCLE & CARRIAGE INDUSTRIES PTE LTD (PANDAN LOOP) 188 PANDAN LOOP SINGAPORE 128378		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,805.69
Revised Amount	:S\$	3,810.22
Check Items (Estimated)	:S\$	675.47
Total	:S\$	4,485.69

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	21 Feb 2018		21 Feb 2018 11:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	D'FINE CATERING SERVICES PTE LTD, Co. Reg. No.: 199306413R		
Main Claimant:	CHEONG CHENG HUA, ID: S1695015G		
Vehicle Reg. No.:	SCZ6623R	Date of Loss:	20/02/2018 14:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	28771079MKC (Comprehensive) Coverage: 29/07/2017 - 28/07/2018
Vehicle Reg. No. (Insured):	GBB5842U	Policy No. (Claimant):	
		Excess:	S\$750.00
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/02/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAUTO)

From: Eric Lee Ming Hui <eric.lee@cyclecarriage.com.sg>
Sent: Wednesday, 21 February 2018 3:02 PM
To: Admin-D (LKKAUTO)
Subject: RE: SCZ6623R

Dear Catherine,

Vehicle not in. Awaiting for liability status.

Thank you.

Your Sincerely,

Eric Lee Ming Hui
Service Advisor - Body Care & Repair
Mercedes-Benz Body Care & Repair Center
Cycle & Carriage Industries Pte Ltd
188 Pandan Loop Service Center
Mobile: 9181 7717 | DID: 6771 4336 | Fax: 6872 1272
Website: www.mercedes-benz.com.sg

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 21 February, 2018 2:56 PM
To: Eric Lee Ming Hui
Subject: SCZ6623R

Dear Eric,

Can check if vehicle in doa: 20/02/2018 MSIG

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 26 April 2018 10:28 AM
To: 'Eric Lee Ming Hui'; SUR
Cc: Taufikh (LKKAUTO)
Subject: RE: SCZ6623R Finalize

Dear Eric,

Confirm final fig \$3,810.22 before GST and 3 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1,
#02-25 | S(408933)

-----Original Message-----

From: Eric Lee Ming Hui [<mailto:eric.lee@cyclecarriage.com.sg>]

Sent: Monday, 23 April 2018 6:09 PM

To: SUR <sur@lkkauto.com>

Cc: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>

Subject: SCZ6623R Finalize

Dear Taufikh,

Please proceed to finalize.

Thank you.

Your Sincerely,

Eric Lee Ming Hui

Service Advisor - Body Care & Repair

Mercedes-Benz Body Care & Repair Center

Cycle & Carriage Industries Pte Ltd

188 Pandan Loop Service Center

Mobile: 9181 7717 | DID: 6771 4336 | Fax: 6872 1272

Website: www.mercedes-benz.com.sg

DISCLAIMER:- This email and any attachment to it is confidential and intended only for the use of the individual or entity named above and may contain information that is privileged. If you are not the intended recipient, you are notified that any dissemination, distribution or copying of this email or any attachment is strictly prohibited. If you have received this email in error, please notify us immediately by return email and destroy the original message. Any views expressed are those of the individual sender, and not necessarily the views of Cycle Carriage Industries Pte Ltd and/or any of its related corporations.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/02/2018 17:04
Date Of Accident	20/02/2018 14:45
Exact Location Of Accident	PIE FILTER LANE TO BUKIT BATOK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SCZ6623R
Insured/Policyholder	
Name Of Registered Owner	CHEONG CHENG HUA
NRIC No	S1695015G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91288267
Alternative Phone No	OFFICE-91288267

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	CLA180

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	2100426398-02000
Cover Note Number	

Driver

Name of Driver	CHEONG CHENG HUA
NRIC No	S1695015G
Date Of Birth	25/07/1965
Occupation	INDOOR
Date Of Driving Pass	08/08/1988
Driving Experience	29 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91288267
Fax Number	
Contact Number	OFFICE-91288267
Email Address	NOEMAIL

Address	11A JALAN SENYUM
Postcode	418194
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS STATIONARY AT THE TRAFFIC LIGHT JUNCTION. CAR B (GBB5842U) AT MY BACK SUDDENLY RELEASE HIS BRAKES AND REAR ENDED MY CAR.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB5842U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	


SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Eric Lee Ming Hui
DID : 6771 4336 HP : 9181 7717
Email : eric.lee@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Reporting Centre Personnel's
Name:
NRIC/FIN No.:

SKETCH PLAN



A = SCZ 6623R

B = GBB 5842U

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I WAS STATIONARY AT THE TRAFFIC LIGHT JUNCTION. VEH B(GBB5842U) AT MY BACK SUDDENLY RELEASE HIS BRAKES AND REAR ENDED MY VEHICLE.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Please note that you have 14 calendar days to revert and file the claim under your own policy. Failing to do so, your insurance company will not allow nor accept the claim.

(Please contact your insurance company for any further details)

Policyholder's Signature
Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Eric Lee Ming Hui
DID : 6771 4336 HP : 9181 7717
Email : eric.lee@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Reporting Centre Personnel's
Name:
NRIC/FIN No.:



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SCZ6623R

Mr Cheong Cheng Hua

11A Jalan Senyum
Singapore 418194

Vehicle & Document Information

WIP No 21445
Reg No/Reg Date SCZ6623R / 31/08/2015
Date In/Mileage / 0
Chassis No WDD1173422N253170
Engine No 27091030732336
Make/Model MB/CLA 180 (C117) "URBAN"
Colour/Trim 027 787 Mountain Gr/ 041 151-Leather Twi

Account No	Terms	Date/Time Printed	CSE	Operator
C5M00128	Cash	20/02/2018/ 17:18	EL	350 / Eric Lee Ming Hui

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : 2100426398 // 20-2-18 TP VEH NO : GBB5842U - MSIG DATE IN/DATE SURVEY: BY/AUTHORIZED ON :			0.10	✓ 380.00
A BPILAB USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT				600 960.00
A BPIRES RESpray REAR BUMPER.				960 1920.00
A BPILAB DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.				✓ 120.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT	1.00	1118.59	00.00	de 1118.59
M REAR BUMPER	1.00	115.84	00.00	? 115.84 xnn
M BASIC MOUNTING FOR BUMPER	1.00	211.58	00.00	de 211.58
M REAR BUMPER BOTTOM TRIM	1.00	420.05	00.00	cut 420.05
M REAR BUMPER LOWER CHROME TRIM	1.00	559.63	00.00	? 559.63 xnn
M REAR CROSS MEMBER				

Tanfer 97495149
wif
12/3/18 @ 2 pm
Removal before paint
3 days
surc lkhant.com

Eric Lee Ming Hui
DID : 6771 4336 HP : 9181 7717
Email : eric.lee@cyclecarriage.com.sg
Cycle & Carriage Industries Pte Ltd
Customer Service Centre - Pandan Loop

Confirmed & accepted by

Nett 5,805.69
7% GST on 5805.69 406.40
Total Payable 6,212.09

Authorized signatory and company stamp

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally work or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Acknowledged by Repairer

Signature:

Date:

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SCZ6623R

Mr Cheong Cheng Hua

11A Jalan Senyum
Singapore 418194

WIP No

21445

Reg No/Reg Date

SCZ6623R / 31/08/2015

Date In/Mileage

12/03/2018 / 53336

Chassis No

WDD1173422N253170

Engine No

27091030732336

Make/Model

MB/CLA 180 (C117) "URBAN"

Colour/Trim

027 787 Mountain Gr/ 041 151-Leather Twi

Vehicle & Document Information

SCZ6623R

27091030732336

MB/CLA 180 (C117) "URBAN"

027 787 Mountain Gr/ 041 151-Leather Twi

Account No	Terms	Date/Time Printed	CSE	Operator				
CSM00128	Cash	23/04/2018/ 18:03	EL	350 / Eric Lee Ming Hui				
Description of Goods / Services					Qty	Unit Price	Disc%	Amount

M. BPNSUN

POLICY NO/ACC DATE : 2100426398 / 20-2-18

TP VER NO : 68888420 - MSIG

DATE IN/DATE SURVEY: 12-3-18 // 1400 // TAUFIKH - LKK

DIRECT SETTLEMENT : IRENE TAN - MSIG // 1-MAR-18

A BPILAB

USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD. NETT

A BPIRES

RESPRAY REAR BUMPER.

A BPILAB

DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH.

A BPILAB

CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE. NETT

X REAR BUMPER

1.00 1118.59 00.00

1118.59

X REAR BUMPER BOTTOM TRIM

1.00 211.58 00.00

211.58

X REAR BUMPER LOWER CHROME TRIM

1.00 420.05 00.00

420.05

ESTIMATE

Finalization

Confirmed & accepted by

Nett 3,810.22
7% GST on 3810.22 266.72
Total Payable 4,076.94

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003317/R1QBN2

Date: 27/04/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	28771079MKC
Claimant Vehicle No :	SCZ6623R	Insured Vehicle No :	GBB5842U
Date of Loss:	20/02/2018	Nature of Claim:	TP
		Claim No:	550383

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SCZ6623R	Engine No:	27091030732336
Make & Model:	MERCEDES-BENZ CLA180, 1.6 (R18 BI) (A)	Chassis No:	WDD1173422N253170
Reg. Date:	31/08/2015 (Man. Year: 2015)	Odometer:	53336 km
Colour:	Grey		
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40 R18	Rear Tyre Size:	225/40 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,425.69	1,750.22	675.47	27.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,380.00	2,060.00	1,320.00	39.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,805.69	3,810.22	1,995.47	34.37
+ GST 7.00/7.00% (S\$)	406.40	266.72	139.68	34.37
Nett Amount (S\$)	6,212.09	4,076.94	2,135.15	34.37

INSPECTION

Date of Assignment: 21/02/2018

Date Inspected: 12/03/2018 Inspected At:

Cycle & Carriage Industries Pte Ltd
(Pandan Loop)
188 Pandan Loop
Singapore 128378

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Apr 2018)
Parts: 143	MERCEDES-BENZ CLA180 1.6 (R18 BI) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SCZ6623R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,118.59 FS	*1,118.59 FS
2	1		*BASIC MOUNTING FOR BUMPER	Not Necessary	115.84 FS	*- FS
3	1		*REAR BUMPER BOTTOM TRIM	Deformed	211.58 FS	*211.58 FS
4	1		*REAR BUMPER LOWER CHROME TRIM	Cut	420.05 FS	*420.05 FS
5	1		*REAR CROSS MEMBER	Not Necessary	559.63 FS	*- FS
				Total Parts (S\$)	2,425.69	1,750.22

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	USING STAR DIAGNOSTIC TO CHECK ON CONTROL UNIT RESET MEMORY TO IDENTIFICATION STANDARD	New	380.00	380.00
2	RESPRAY REAR BUMPER	New	960.00	600.00
3	DISASSEMBLE AND REPLACE ATTACHED DAMAGED PARTS & REFINISH	New	1,920.00	960.00
4	CHECK REAR LIGHTING SYSTEM AND WATER TEST FOR ANY LEAKAGE	New	120.00	120.00
Gross Labour Cost (\$\$)			3,380.00	2,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >