



ASS. REC. BY: Marcus

ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TR / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: S2M 803P

at Workshop m/s peposus

of \_\_\_\_\_

Insured: SKL 3437K

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Veh No: S2M 803P Yr Regn: 3117

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (17)

Make: Toyota VIOS c.c. 1496

Colour: silver A/C: Insured / Std / NI / NA

Sp. Reading: 63731 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: MHFB29F3302008388

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/60R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 14/2/18

D.O.I. 21/2/18

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear & Rf

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	4s: @ 4,900 (RED: @ 5,243.70 52%)

Date/Time, File Pass to?  : Preli. Report  : Final Report

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

2) \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_) )  
 : Interview (\$ \_\_\_\_\_) )  
 : Tech. Invs (\$ \_\_\_\_\_) )  
 : Weekend (\$ \_\_\_\_\_) )

Survey Fee:	
Transportation:	
_____ S + RS _____ \$	
Photos	
Others	
TOTAL	

Report Format : \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC4/LPC18003298/Uea3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 21-02-2018	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SKL 3437K	Veh. Inspected	SLM 803P
Policy No.	Z17VP05015600	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020405	Excess (\$)	0.00
Assign From		Assign Date	21/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	14/02/2018	Inspection Date	21/02/2018
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

**Nivitha (LKK Auto)**

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Wednesday, 21 February 2018 4:02 PM  
**To:** assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG  
**Subject:** FW: Third Party Survey - SLM803P Your Insured - SKL3437K DOA: 14.02.2018  
**Attachments:** 21022018123926.pdf; SLM803P 14.02.2018 ADD.pdf

Our Ref : 17/18/18/VP05/020405

9.25am @ 22/2/18  
vehicle in  
sur @ Marcus

Dear Catherine,

Kindly proceed to survey the vehicle and revert to them on direct settlement.

Best Regards  
Gerald Poh  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Pegasus Engineering [mailto:claims@pegasusengr.com.sg]  
**Sent:** Wednesday, 21 February, 2018 12:43 PM  
**To:** MT\_Claim\_SG  
**Subject:** Third Party Survey - SLM803P Your Insured - SKL3437K DOA: 14.02.2018

Your Ref: SKL3437K

Our Ref: SLM803P

DOA: 14.02.2018

Without Prejudice

Dear Sir/Madam,

We refer to the above matter.  
We enclose the following documents for your attention:-

- a. Copy of our client's SAS report and damaged photos;
- b. Copy of the estimated cost of repair.

Pursuant to paragraph 6.2 of Pre-Action Protocol for NIMA Cases, please let us know within 2 working days whether you would like to conduct a pre-repair survey of our client's vehicle. If we do not hear from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

Please arrange for survey as soon as possible as the vehicle is currently grounded in our premises.

Thanks & Regards,

Alvin Low  
-AF

Pegasus Engineering & Trading Pte Ltd  
51 Defu Lane 10  
Singapore 539216

Tel : 6858 1846  
Fax : 6487 6070  
Email : [claims@pegasusengrg.com.sg](mailto:claims@pegasusengrg.com.sg)

## Mei Kwan (LKKAuto)

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Thursday, 1 March, 2018 9:00 AM  
**To:** Mei Kwan (LKKAuto)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: Third Party Survey - SLM803P Your Insured - SKL3437K DOA: 14.02.2018  
**Attachments:** 01032018085812.pdf

**Follow Up Flag:** Follow up  
**Flag Status:** Completed

**Categories:** HMK

Hi Mei Kwan,

We attached a copy of insured's GIA report for your attention.

Best Regards  
Gerald Poh  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Mei Kwan (LKKAuto) [mailto:Meikwan@lkkauto.com]  
**Sent:** Thursday, 1 March, 2018 8:32 AM  
**To:** GERALD POH WEE BIN  
**Cc:** MT\_Claim\_SG; ERIC WOO JUN KIAT; Asher Sng (LKKAuto); Vic (LKKAuto); Admin A  
**Subject:** RE: Third Party Survey - SLM803P Your Insured - SKL3437K DOA: 14.02.2018

Your ref: 17/18/18/VP05/020405  
LKK ref : CC4/LPC18003298/Uea3

### WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Mei Kwan (LKKAuto)  
**Sent:** Monday, 26 February, 2018 11:16 AM  
**To:** 'GERALD POH WEE BIN' <geraldpoh@lonpac.com>

---

**From:** GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]  
**Sent:** Wednesday, 21 February 2018 4:02 PM  
**To:** assignments@lkkauto.com  
**Cc:** MT\_Claim\_SG <mt\_claim@lonpac.com>  
**Subject:** FW: Third Party Survey - SLM803P Your Insured - SKL3437K DOA: 14.02.2018

Our Ref : 17/18/18/VP05/020405

Dear Catherine,

Kindly proceed to survey the vehicle and revert to them on direct settlement.

Best Regards  
Gerald Poh  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road, #17-04/07 The Concourse, Singapore 199555  
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Pegasus Engineering [mailto:claims@pegasusengrg.com.sg]  
**Sent:** Wednesday, 21 February, 2018 12:43 PM  
**To:** MT\_Claim\_SG  
**Subject:** Third Party Survey - SLM803P Your Insured - SKL3437K DOA: 14.02.2018

Your Ref: SKL3437K

Our Ref: SLM803P

DOA: 14.02.2018

Without Prejudice

Dear Sir/Madam,

We refer to the above matter.  
We enclose the following documents for your attention:-

- a. Copy of our client's SAS report and damaged photos;
- b. Copy of the estimated cost of repair.

Pursuant to paragraph 6.2 of Pre-Action Protocol for NIMA Cases, please let us know within 2 working days whether you would like to conduct a pre-repair survey of our client's vehicle. If we do not hear from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

**Please arrange for survey as soon as possible as the vehicle is currently grounded in our premises.**

Thanks & Regards,

Alvin Low

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	7200G
Vehicle Details	
Vehicle No.:	SLM803P
Vehicle to be Exported:	Yes
Intended De-registration Date:	22 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	2NRX136226
Chassis No.:	MHFB29F3302008398
Maximum Power Output:	79.0 kW (105 bhp)
Open Market Value:	\$12,946.00
Original Registration Date:	21 Mar 2017
First Registration Date:	21 Mar 2017
Transfer Count:	0
Actual ARF Paid:	\$7,946.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Mar 2027
PARF Rebate Amount:	\$5,959.00
Intended COE Rebate Details	
COE Expiry Date:	20 Mar 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,101.00
COE Rebate Amount:	\$40,080.00
<b>Total Rebate Amount:</b>	<b>\$46,039.00</b>

The information contained herein is correct as at 22 Feb 2018

OK



MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807  
Tel +65 6827 7888, Fax +65 6827 7800  
Co. Reg. No. 200412212G GST Reg. No. 20-041221G

## Certificate of Insurance

ROAD TRANSPORT ACT 1987 (MALAYSIA)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (FEDERATION OF MALAYSIA)  
THE MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP. 189 OF THE REVISED EDITION)  
(REPUBLIC OF SINGAPORE)  
THE MOTOR VEHICLES (THIRD-PARTY RISK AND COMPENSATION) RULES, 1996 EDITION (REPUBLIC OF SINGAPORE)  
OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF.

Form M.Z.400  
Cars for Hire

**COMMERCIAL VEHICLE - FLEET**  
**Comprehensive**

**Certificate No.** A 29069766 MKF

**Excess :** SGD2,000

**1. Index Mark and Registration Number of Vehicle**

SLM803P

**2. Name of Policyholder**

Grab Rentals Pte. Ltd.

**3. Effective Date of the Commencement of Insurance for the purposes of the Act**

01/02/2018

**4. Date of Expiry of Insurance**

31/01/2019

**5. Persons or Classes of Persons entitled to drive\***

Any other person provided he is driving on the Policyholder's order or with the Policyholder's permission.

\* Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

**6. Limitations as to use\***

Use for the carriage of passengers or goods in connection with the Policyholder's business.

Use for social domestic and pleasure purposes.

The Policy does not cover

(1) Use for racing pace-making reliability trial or speed-testing.

(2) Use whilst drawing a trailer except the towing (other than for reward) of any one disabled mechanically propelled vehicle.

\* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

This Certificate is not transferable to a new owner of the vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to the Insurer within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

MSIG Insurance (Singapore) Pte. Ltd.

Approved Insurers

Chief Executive Officer

e

# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

<b>From :</b>
<b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b> C/O 51 DEFU LANE 10 539216  Officer in Charge : WEE TZE FAH Tel : Email :

<b>Customer :</b>
<b>GRAB RENTALS PTE LTD</b> 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960  Attn : Tel : Fax :

*Not Submit*  
*2 wk*  
*2/s \$ 4900*  
*5 days*  
*21/2/18*  
*John Philip Attarap*

Quotation No : QO18/02-1123	Quotation Date : 20/02/2018	Terms : 30 DAYS
Vehicle No : SLM803P	Chassis No : MHFB29F3302008398	Third Party Insurer :
Model : VIOS		Date of Accident :

Remarks : TP INSURER: LONPAC , INSURED'S VEH NO:SKL3437K , DATE OF ACCIDENT: 14.02.2018

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	BOOTLID <i>762.47</i>	1 <i>pp/bul</i>	<del>1,662.4000</del>	<del>1,662.40</del>
2	BOOTLID VIOS BADGE	1 <i>per</i>	44.1000	44.10
3	BOOTLID CENTRE EMBLEM BADGE	1 <i>per</i>	59.8000	59.80
4	BOOTLID E BADGE	1 <i>per</i>	34.4000	34.40
5	BOOTLID LOCK	1 <i>twi</i>	90.4000	90.40
6	BOOTLID LOCK STRIKER	1 <i>17</i>	18.5000	18.50
7	BOOTLID WEATHERSTRIP	1 <i>twi</i>	188.8000	188.80
8	BOOTLID LOCK CABLE CLIPS	3 <i>17</i>	4.3000	12.90
9	BOOTLID WIRE HARNESS CLIPS	3 <i>17</i>	4.3000	12.90
10	BOOTLID HINGE	2 <i>17</i>	57.8000	115.60
11	BOOTLID INNER TRIM COVER	1 <i>101</i>	234.3000	234.30
12	BOOTLID INNER TRIM COVER CLIPS	4 <i>17</i>	4.3000	17.20
13	REAR END PANEL	1 <i>1</i>	694.7000	694.70
14	REAR END PANEL INNER TRIM	1 <i>17</i>	234.3000	234.30
15	REAR BUMPER	1 <i>pp/ae</i>	504.9000	504.90
16	REAR BUMPER REINFORCEMENT	1 <i>17</i>	322.3000	322.30
17	REAR BUMPER SIDE RETAINER	2 <i>bul</i>	116.3000	232.60
18	REAR BUMPER SIDE HOLDER	2 <i>17</i>	22.3000	44.60
19	REAR BUMPER CLIPS	10 <i>17</i>	4.3000	43.00
20	REAR BUMPER REFLECTOR	2 <i>17</i>	130.5000	261.00
21	REAR LICENCE PLATE LAMP	2 <i>17</i>	64.1000	128.20
22	REAR LAMP	2 <i>17</i>	375.8000	751.60
23	REAR LAMP CLIP HOLDER	4 <i>17</i>	4.3000	17.20

C/F 0.00

# PEGASUS

## ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

### Quotation

<b>From :</b> <b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b> C/O 51 DEFU LANE 10 539216  Officer in Charge : WEE TZE FAH Tel : Email :	<b>Customer :</b> <b>GRAB RENTALS PTE LTD</b> 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960  Attn : Tel : Fax :
---	---

Quotation No : QO18/02-1123	Quotation Date : 20/02/2018	Terms : 30 DAYS
Vehicle No : SLM803P	Chassis No : MHFB29F3302008398	Third Party Insurer :
Model : VIOS		Date of Accident :
Remarks : TP INSURER: LONPAC , INSURED'S VEH NO:SKL3437K , DATE OF ACCIDENT: 14.02.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
24	FRONT BUMPER	1	427.0000	427.00
25	FRONT BUMPER REINFORCEMENT	1	379.2000	379.20
26	FRONT BUMPER SIDE RETAINER	2	65.7000	131.40
27	FRONT BUMPER CLIPS	10	4.3000	43.00
28	FRONT BUMPER LOWER SPLASHIELD COVER	1	209.1000	209.10
29	FRONT BUMPER LOWER SPLASHIELD COVER CLIPS	8	4.3000	34.40
30	FRONT BUMPER SPOT LAMP GARNISH	2	56.6000	113.20
31	FRONT BUMPER CENTRE GRILLE	1	197.6000	197.60
32	FRONT BUMPER CENTRE GRILLE TOW COVER	1	52.4000	52.40
33	FRONT BUMPER CHROME GARNISH	2	66.8000	133.60
34	FRONT BUMPER EMBLEM BADGE	1	97.4000	97.40
35	FRONT BUMPER OUTER GARNISH	1	87.8000	87.80
36	FRONT CENTRE BRACE PANEL	1	143.6000	143.60
37	HEAD LAMP	2	588.1000	1,176.20
38	LESS 25% (ITEM 1 - 37)	1	-2,237.9000	-2,237.90
39	REAR BUMPER PARKING SENSOR	1 set	500.0000	500.00
40	REAR LICENCE PLATE	1	35.0000	35.00
41	FRONT LICENCE PLATE	1	35.0000	35.00
42	TO RUST-PROOFING OF THE AFFECTED AREAS	1	180.0000	180.00
43	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	60.0000	60.00
44	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE	1	150.0000	150.00
45	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	120.00

C/F 0.00

Page 2 of 3

  
**PEGASUS**  
**ENGINEERING & TRADING PTE LTD**  
 GST / ROC COMPANY NO : 201101753C

**Quotation**

<b>From :</b> <b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b> C/O 51 DEFU LANE 10 539216  Officer in Charge : WEE TZE FAH Tel : Email :	<b>Customer :</b> <b>GRAB RENTALS PTE LTD</b> 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960  Attn : Tel : Fax :
---	---

<b>Quotation No :</b> QO18/02-1123	<b>Quotation Date :</b> 20/02/2018	<b>Terms :</b> 30 DAYS
<b>Vehicle No :</b> SLM803P	<b>Chassis No :</b> MHFB29F3302008398	<b>Third Party Insurer :</b>
<b>Model :</b> VIOS	<b>Date of Accident :</b>	
<b>Remarks :</b> TP INSURER: LONPAC , INSURED'S VEH NO:SKL3437K , DATE OF ACCIDENT: 14.02.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
46	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	150.0000	60 150.00
47	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	1,000.0000	800 1,000.00
48	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,200.0000	1100 1,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary terms must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

<b>Sub Total</b>	10,143.70
<b>GST(7.00%)</b>	710.06
<b>Total (SGD)</b>	10,853.76

Please conduct the survey at  
 Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216



# PEGASUS

## ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

### Quotation

<b>From :</b>
<b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b> C/O 51 DEFU LANE 10 539216
Officer in Charge : WEE TZE FAH
Tel :
Email :

<b>Customer :</b>	<i>Not Present</i>
<b>GRAB RENTALS PTE LTD</b> 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960	<i>2/5</i> <i>5 days</i> <i>21/2/18</i> <i>John Philip Attaran</i>
Attn :	
Tel :	
Fax :	

<b>Quotation No :</b> QO18/02-1123	<b>Quotation Date :</b> 20/02/2018	<b>Terms :</b> 30 DAYS
<b>Vehicle No :</b> SLM803P	<b>Chassis No :</b> MHFB29F3302008398	<b>Third Party Insurer :</b>
<b>Model :</b> VIOS	<b>Date of Accident :</b>	
<b>Remarks :</b> TP INSURER: LONPAC , INSURED'S VEH NO:SKL3437K , DATE OF ACCIDENT: 14.02.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	BOOTLID <i>762.47</i>	1 <i>pp/heel</i>	1,662.4000	1,662.40
2	BOOTLID VIOS BADGE	1 <i>rel</i>	44.1000	44.10
3	BOOTLID CENTRE EMBLEM BADGE	1 <i>rel</i>	59.8000	59.80
4	BOOTLID E BADGE	1 <i>rel</i>	34.4000	34.40
5	BOOTLID LOCK	1 <i>twl</i>	90.4000	90.40
6	BOOTLID LOCK STRIKER	1 <i>17</i>	18.5000	18.50
7	BOOTLID WEATHERSTRIP	1 <i>twl</i>	188.8000	188.80
8	BOOTLID LOCK CABLE CLIPS	3 <i>17</i>	4.3000	12.90
9	BOOTLID WIRE HARNESS CLIPS	3 <i>17</i>	4.3000	12.90
10	BOOTLID HINGE	2 <i>17</i>	57.8000	115.60
11	BOOTLID INNER TRIM COVER	1 <i>101</i>	234.3000	234.30
12	BOOTLID INNER TRIM COVER CLIPS	4 <i>17</i>	4.3000	17.20
13	REAR END PANEL	1	694.7000	694.70
14	REAR END PANEL INNER TRIM	1	234.3000	234.30
15	REAR BUMPER	1 <i>pp/ae</i>	504.9000	504.90
16	REAR BUMPER REINFORCEMENT	1	322.3000	322.30
17	REAR BUMPER SIDE RETAINER	2 <i>rel</i>	116.3000	232.60
18	REAR BUMPER SIDE HOLDER	2 <i>rel</i>	22.3000	44.60
19	REAR BUMPER CLIPS	10 <i>rel</i>	4.3000	43.00
20	REAR BUMPER REFLECTOR	2 <i>17</i>	130.5000	261.00
21	REAR LICENCE PLATE LAMP	2 <i>17</i>	64.1000	128.20
22	REAR LAMP	2	375.8000	751.60
23	REAR LAMP CLIP HOLDER	4 <i>17</i>	4.3000	17.20

C/F 0.00

Page 1 of 3



# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

<b>From :</b>	<b>Customer :</b>
PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 539216  Officer in Charge : WEE TZE FAH Tel : Email :	GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960  Attn : Tel : Fax :

Quotation No : QO18/02-1123	Quotation Date : 20/02/2018	Terms : 30 DAYS
Vehicle No : SLM803P	Chassis No : MHFB29F3302008398	Third Party Insurer :
Model : VIOS	Date of Accident :	
Remarks : TP INSURER: LONPAC , INSURED'S VEH NO:SKL3437K , DATE OF ACCIDENT: 14.02.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
24	FRONT BUMPER	1	427.0000	427.00
25	FRONT BUMPER REINFORCEMENT	1	379.2000	379.20
26	FRONT BUMPER SIDE RETAINER	2	65.7000	131.40
27	FRONT BUMPER CLIPS	10	4.3000	43.00
28	FRONT BUMPER LOWER SPLASHIELD COVER	1	209.1000	209.10
29	FRONT BUMPER LOWER SPLASHIELD COVER CLIPS	8	4.3000	34.40
30	FRONT BUMPER SPOT LAMP GARNISH	2	56.6000	113.20
31	FRONT BUMPER CENTRE GRILLE	1	197.6000	197.60
32	FRONT BUMPER CENTRE GRILLE TOW COVER	1	52.4000	52.40
33	FRONT BUMPER CHROME GARNISH	2	66.8000	133.60
34	FRONT BUMPER EMBLEM BADGE	1	97.4000	97.40
35	FRONT BUMPER OUTER GARNISH	1	87.8000	87.80
36	FRONT CENTRE BRACE PANEL	1	143.6000	143.60
37	HEAD LAMP	2	588.1000	1,176.20
38	LESS 25% (ITEM 1 - 37)	1	-2,237.9000	-2,237.90
39	REAR BUMPER PARKING SENSOR	1 set	500.0000	500.00
40	REAR LICENCE PLATE	1	35.0000	35.00
41	FRONT LICENCE PLATE	1	35.0000	35.00
42	TO RUST-PROOFING OF THE AFFECTED AREAS	1	180.0000	180.00
43	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	60.0000	60.00
44	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE	1	150.0000	150.00
45	TO REINSTALL OF REAR BUMPER PARKING SENSOR	1	120.0000	120.00
				C/F 0.00



# PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

## Quotation

<b>From :</b>
<b>PEGASUS ENGINEERING &amp; TRADING PTE LTD</b> C/O 51 DEFU LANE 10 539216
Officer in Charge : WEE TZE FAH Tel : Email :

<b>Customer :</b>
<b>GRAB RENTALS PTE LTD</b> 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960
Attn : Tel : Fax :

<b>Quotation No :</b> QO18/02-1123	<b>Quotation Date :</b> 20/02/2018	<b>Terms :</b> 30 DAYS
<b>Vehicle No :</b> SLM803P	<b>Chassis No :</b> MHFB29F3302008398	<b>Third Party Insurer :</b>
<b>del :</b> VIOS		<b>Date of Accident :</b>
<b>Remarks :</b> TP INSURER: LONPAC , INSURED'S VEH NO:SKL3437K , DATE OF ACCIDENT: 14.02.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
46	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	150.0000	60 150.00
47	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	1,000.0000	800 1,000.00
48	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,200.0000	1100 1,200.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

<b>Sub Total</b>	10,143.70
<b>GST(7.00%)</b>	710.06
<b>Total (SGD)</b>	10,853.76

Please conduct the survey at  
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

## Asher Sng (LKKAuto)

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Monday, 5 March 2018 12:50 PM  
**To:** 'Pegasus Engineering'  
**Cc:** Admin A; Vic (LKKAuto)  
**Subject:** RE: Check Liability - Pegasus Ref: SM210022018; Lonpac Ref: TBA; Accident involving SLM803P(Grab) & SKL3437K (Lonpac) on 14.02.2018

WITHOUT PREJUDICE

Hi Sir/Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will base on the number of days of repair as recommended by our surveyor.

Kindly take note that the case handler in-charge is Asher and she can be contacted at her DID 6841 6051

In order to expedite the claim process, please forward all relevant documents for us (**LKK**) to proceed on negotiate settlement.

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Asher Sng (LKKAuto)  
**Sent:** Tuesday, 27 February 2018 8:53 AM  
**To:** Pegasus Engineering <claims@pegasusengrg.com.sg>  
**Cc:** Zaini (LKK Auto) <Zaini@lkkauto.com>; Admin A <admin-a@lkkauto.com>; Vic (LKKAuto) <vicalpeh@lkkauto.com>  
**Subject:** RE: Check Liability - Pegasus Ref: SM210022018; Lonpac Ref: TBA; Accident involving SLM803P(Grab) & SKL3437K (Lonpac) on 14.02.2018

Without Prejudice

Hi Sir,

We refer to the email below.

Please kindly note that we are still pending for our insured report from our principal.

Shall revert to you upon receiving our insured report.

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Pegasus Engineering [<mailto:claims@pegasusengrg.com.sg>]

**Sent:** Monday, 26 February 2018 6:36 PM

**To:** Zaini (LKK Auto) <[Zaini@lkkauto.com](mailto:Zaini@lkkauto.com)>; Asher Sng (LKKAuto) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** Check Liability - Pegasus Ref: SM210022018; Lonpac Ref: TBA; Accident involving SLM803P(Grab) & SKL3437K (Lonpac) on 14.02.2018

Dear All,

We refer to the above matter.

Survey has been conducted.

Meanwhile, please reply within two (2) days whether you are agreeable to direct settle with us at 100% liability on this matter.

Thanks & Regards,

Alvin Low

-AF

Pegasus Engineering & Trading Pte Ltd

51 Defu Lane 10

Singapore 539216

Tel : 6858 1846

Fax : 6487 6070

Email : [claims@pegasusengrg.com.sg](mailto:claims@pegasusengrg.com.sg)

## Asher Sng (LKKAuto)

---

**From:** GERALD POH WEE BIN <geraldpoh@lonpac.com>  
**Sent:** Tuesday, 9 October 2018 10:35 AM  
**To:** Asher Sng (LKKAuto)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: [MANDATE REQUEST] RE: Third Party Survey - SLM803P Your Insured - SKL3437K  
DOA: 14.02.2018  
**Attachments:** 09102018103330.pdf

Dear Asher,

Attached DV for your retention.

Kindly close your file and forward your bill to us.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Asher Sng (LKKAuto) [mailto:AsherSng@lkkauto.com]  
**Sent:** Monday, 17 September, 2018 9:22 AM  
**To:** GERALD POH WEE BIN  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: [MANDATE REQUEST] RE: Third Party Survey - SLM803P Your Insured - SKL3437K DOA: 14.02.2018

Hi Gerald,

We refer to the email below.

Our surveyor recommended 6days, therefore we proposed to settle 9days as follow:

21/02/18 (WED) – INSPECTION DATE  
22/02/18 (THU) – REPAIR DAY 1  
23/02/18 (FRI) – REPAIR DAY 2  
24/02/18 (SAT) – NON WORKING DAY  
25/02/18 (SUN) – NON WORKING DAY  
26/02/18 (MON) – REPAIR DAY 3  
27/02/18 (TUE) – REPAIR DAY 4  
28/02/18 (WED) – REPAIR DAY 5  
01/03/18 (THU) – REPAIR DAY 6

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** GERALD POH WEE BIN <[geraldpoh@lonpac.com](mailto:geraldpoh@lonpac.com)>

**Sent:** Monday, 17 September 2018 9:05 AM

**To:** Asher Sng (LKKAuto) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>

**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>

**Subject:** RE: [MANDATE REQUEST] RE: Third Party Survey - SLM803P Your Insured - SKL3437K DOA: 14.02.2018

Dear Asher,

Your surveyor recommended 5 days for the estimated repair period but you have proposed 9 days.

Please enlighten us.

By the way, Eric Woo is no longer with us.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Asher Sng (LKKAuto) [<mailto:AsherSng@lkkauto.com>]

**Sent:** Saturday, 15 September, 2018 2:46 PM

**To:** Mei Kwan (LKKAuto); GERALD POH WEE BIN

**Cc:** MT\_Claim\_SG; ericwoo; Admin A

**Subject:** [MANDATE REQUEST] RE: Third Party Survey - SLM803P Your Insured - SKL3437K DOA: 14.02.2018

Dear Sirs,

We refer to the above matter.

We have highlighted to your good office on 26/02/2018 of Third-Party's request to do Direct Settlement with our Principal, Lonpac Insurance Bhd.

The said chain collision involved 3 vehicles whereby our insured was the last vehicle.

In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.

Basing on the reports of the circumstance of the accident, we propose to settle third-party claim at 100% liability.

Summary to offer to repairer **PEGASUS ENGINEERING & TRADING PTE LTD** is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 10,853.76	\$ 5,243.00
2. Loss of Rental (9days x \$66.95)	\$ 602.55	\$ 602.55 (9days x \$66.95)
3. Loss of Income (9days x \$80)	\$ 720.00	\$ 450.00 (9days x \$50)
4. LTA/GIA Search Fee	\$ 7.49	\$ 7.49
<b>Total</b>	<b>\$ 12,183.80</b>	<b>\$ 6,303.04</b>

\*\*6 days recommendation for repair.

Relevant supporting claim documents are attached herewith for your perusal and reference.

**The above is for your approval please.**

Thank You.

Best Regards,

**Asher Sng** | Case Handler

**LKK Auto Consultants Pte Ltd**

phone: 6841-6051 | email: [ashersng@lkkauto.com](mailto:ashersng@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Mei Kwan (LKKAuto)

**Sent:** Thursday, 1 March 2018 8:32 AM

**To:** 'GERALD POH WEE BIN' <[geraldpoh@lonpac.com](mailto:geraldpoh@lonpac.com)>

**Cc:** 'MT\_Claim\_SG' <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>; 'ERIC WOO JUN KIAT' <[ericwoo@lonpac.com](mailto:ericwoo@lonpac.com)>; Asher Sng (LKKAuto) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>; Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** RE: Third Party Survey - SLM803P Your Insured - SKL3437K DOA: 14.02.2018

**Your ref:** 17/18/18/VP05/020405

**LKK ref:** CC4/LPC18003298/Uea3

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

Kindly let us have a copy of insured's accident report for our necessary action.

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Mei Kwan (LKKAuto)

**Sent:** Monday, 26 February, 2018 11:16 AM

**To:** 'GERALD POH WEE BIN' <[geraldpoh@lonpac.com](mailto:geraldpoh@lonpac.com)>

**Cc:** 'MT\_Claim\_SG' <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>; 'ERIC WOO JUN KIAT' <[ericwoo@lonpac.com](mailto:ericwoo@lonpac.com)>; Asher Sng (LKKAuto) <[AsherSng@lkkauto.com](mailto:AsherSng@lkkauto.com)>; Vic (LKKAuto) <[vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** RE: Third Party Survey - SLM803P Your Insured - SKL3437K DOA: 14.02.2018

**Your ref:** 17/18/18/VP05/020405

**LKK ref:** CC4/LPC18003298/Uea3

**WITHOUT PREJUDICE**

Dear Sir / Madam,

We refer to the above matter.

This is a third party direct settlement case.

Enclosed revert of vehicle: SLM 803P

Date of survey: 21.02.2018

We have not authorized repairs.

Enclosed for your perusal is:

- TP estimate (marked)
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Meanwhile, kindly let us have a copy of insured's accident report for our necessary action.

Please take note that the case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

*To check availability of the case handler, you may contact the undersigned.*

Thank you.

Best Regards,

**Mei Kwan** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6366 0055 | email: [MeiKwan@lkkauto.com](mailto:MeiKwan@lkkauto.com) | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)

**Sent:** Thursday, 22 February, 2018 9:27 AM

**To:** 'GERALD POH WEE BIN' <[geraldpoh@lonpac.com](mailto:geraldpoh@lonpac.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Cc:** 'MT\_Claim\_SG' <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>; Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>

**Subject:** RE: Third Party Survey - SLM803P Your Insured - SKL3437K DOA: 14.02.2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]

**Sent:** Wednesday, 21 February 2018 4:02 PM

**To:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com)

**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>

**Subject:** FW: Third Party Survey - SLM803P Your Insured - SKL3437K DOA: 14.02.2018

Our Ref : 17/18/18/VP05/020405

Dear Catherine,

Kindly proceed to survey the vehicle and revert to them on direct settlement.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

---

**From:** Pegasus Engineering [<mailto:claims@pegasusengrg.com.sg>]

**Sent:** Wednesday, 21 February, 2018 12:43 PM

**To:** MT\_Claim\_SG

**Subject:** Third Party Survey - SLM803P Your Insured - SKL3437K DOA: 14.02.2018

Your Ref: SKL3437K

Our Ref: SLM803P

DOA: 14.02.2018

Without Prejudice

Dear Sir/Madam,

We refer to the above matter.

We enclose the following documents for your attention:-

- a. Copy of our client's SAS report and damaged photos;
- b. Copy of the estimated cost of repair.

Pursuant to paragraph 6.2 of Pre-Action Protocol for NIMA Cases, please let us know within 2 working days whether you would like to conduct a pre-repair survey of our client's vehicle. If we do not hear from you within the stipulated timeline, our client shall proceed to repair the vehicle without further reference to you.

**Please arrange for survey as soon as possible as the vehicle is currently grounded in our premises.**

Thanks & Regards,

Alvin Low

-AF

Pegasus Engineering & Trading Pte Ltd

51 Defu Lane 10  
Singapore 539216

Tel : 6858 1846  
Fax : 6487 6070  
Email : [claims@pegasusengrg.com.sg](mailto:claims@pegasusengrg.com.sg)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC4/LPC18003298/Uea3n2

300 BEACH ROAD  
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 15-10-2018



Code : LPC2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKL 3437K	Veh. Inspected	SLM 803P
Policy No.	Z17VP05015600	Coverage (\$)	0.00
Claim No.	17/18/18/VP05/020405	Excess (\$)	0.00
Assign From	GERALD	Assign Date	21/02/2018

## 2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MHFB29F3302008398	Colour	SILVER
Odometer	63731	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	GOODYEAR	6 mm
L/H Front Tyre	205/60 R16	GOODYEAR	6 mm
R/H Rear Tyre	205/60 R16	GOODYEAR	6 mm
L/H Rear Tyre	205/60 R16	GOODYEAR	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	14/02/2018	Inspection Date	21/02/2018
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 803P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	BOOTLID	DENTED / BUCKLED	1,662.40	762.47
1	BOOTLID VIOS EMBLEM	NECESSARY	44.10	44.10
1	BOOTLID CENTRE EMBLEM BADGE	NECESSARY	59.80	59.80
1	BOOTLID E BADGE	NECESSARY	34.40	34.40
1	BOOTLID LOCK	TWISTED	90.40	90.40
1	BOOTLID LOCK STRIKER	NOT NECESSARY	18.50	-
1	BOOTLID WEATHERSTRIP	TWISTED	188.80	188.80
3	BOOTLID LOCK CABLE CLIPS @\$4.30	NOT NECESSARY	12.90	-
3	BOOTLID WIRE HARNESS CLIPS @\$4.30	NOT NECESSARY	12.90	-
2	BOOTLID HINGE @\$57.80	NOT NECESSARY	115.60	-
1	BOOTLID INNER TRIM COVER	NOT NECESSARY	234.30	-
4	BOOTLID INNER TRIM COVER CLIPS @\$4.30	NOT NECESSARY	17.20	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	694.70	-
1	REAR END PANEL INNER TRIM	NOT NECESSARY	234.30	-
1	REAR BUMPER	DENTED / DEFORMED	504.90	504.90
1	REAR BUMPER REINFORCEMENT	DENTED	322.30	322.30
2	REAR BUMPER SIDE RETAINER @\$116.30	BENT	232.60	232.60
2	REAR BUMPER SIDE HOLDER @\$22.30	NECESSARY	44.60	44.60
10	REAR BUMPER CLIPS @\$4.30	NOT NECESSARY	43.00	-
2	REAR BUMPER REFLECTOR @\$130.50	NOT NECESSARY	261.00	-
2	REAR LICENCE PLATE LAMP @\$64.10	NOT NECESSARY	128.20	-
2	REAR LAMP @\$375.80	NOT NECESSARY	751.60	-
4	REAR LAMP CLIP HOLDER @\$4.30	NOT NECESSARY	17.20	-
1	FRONT BUMPER	DENTED / DEFORMED	427.00	427.00
1	FRONT BUMPER REINFORCEMENT	DENTED	379.20	379.20
2	FRONT BUMPER SIDE RETAINER @\$65.70	NECESSARY	131.40	131.40
10	FRONT BUMPER CLIPS @\$4.30	NECESSARY	43.00	43.00
1	FRONT BUMPER LOWER SPLASHIELD COVER	NOT NECESSARY	209.10	-

Report Ref No. CC4/LPC18003298/Uea3n2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
8	FRONT BUMPER LOWER SPLASHIELD COVER CLIPS @\$4.30	NOT NECESSARY	34.40	-
2	FRONT BUMPER SPOT LAMP GARNISH @\$56.60	NOT NECESSARY	113.20	-
1	FRONT BUMPER CENTRE GRILLE	CUT / TWISTED	197.60	197.60
1	FRONT BUMPER CENTRE GRILLE TOW COVER	CUT	52.40	52.40
2	FRONT BUMPER CHORME GARNISH @\$66.80	NECESSARY	133.60	133.60
1	FRONT BUMPER EMBLEM BADGE	MISSING	97.40	97.40
1	FRONT BUMPER OUTER GARNISH	CRACKED	87.80	87.80
1	FRONT CENTRE BRACE PANEL	NOT NECESSARY	143.60	-
2	HEAD LAMP @\$588.10	CRACKED	1,176.20	1,176.20
	LESS 25% DISCOUNT		-2,237.90	-1,252.49
			6,713.70	3,757.48
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET REAR BUMPER PARKING SENSOR (SN)	SHORTED	500.00	200.00
1	REAR LICENCE PLATE (SN)	BENT	35.00	35.00
1	FRONT LICENCE PLATE(SN)	BENT	35.00	35.00
			570.00	270.00
	<b><u>LABOUR</u></b>			
	TO RUST -PROOFING OF THE AFFECTED AREAS.		180.00	60.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		60.00	20.00
	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE.		150.00	60.00
	TO REINSTALL OF REAR BUMPER PARKING SENSOR .		120.00	50.00
	TO REMOVE AND REFIT INTERIOR FITTINGS ,TRIMMINGS ,GARNISH AND OTHER ,TO ENABLE REPAIR.		150.00	60.00
	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION ,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF REAR END PANEL .		1,000.00	800.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,200.00	1,100.00
			2,860.00	2,150.00
	<b>GRAND TOTAL</b>		<b>10,143.70</b>	<b>6,177.48</b>



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,900.00
---	--	--	----------

Report Ref No. CC4/LPC18003298/Uea3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.