



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

Ref : CC3/LPC18003310/hb3

300 BEACH ROAD
#17-04/07 THE CONCOURSESINGAPORE 199555

Date : 21-02-2018



Code : LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GQ 9910S	Veh. Inspected	SKA 8899K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	21/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	14/02/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/LPC18003310/T1hb3

Date: 28.02.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SKA8899K


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 27.02.2018 at the premises of M/s Performance Motors Limited and have the following to report:-

Workshop Estimate Amount	: S\$	7,838.55
Revised Estimate Amount	: S\$	3,943.40
"Check" Items Amount	: S\$	2,064.15
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 3 days

Yours faithfully,

MOHD. TAUFIKH
Licensed Appraiser

Vic (LKKAUTO)

From: PBSP <pml-pbsp@simedarby.com.sg>
Sent: Monday, 23 April, 2018 1:26 PM
To: Taufikh (LKKAUTO); Asher Sng (LKKAUTO); Vic (LKKAUTO)
Subject: FINAL REPORT / SKA8899K
Attachments: Final Report SKA8899K.pdf; Final Report SKA8899K_2.pdf

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 2,014.00
Total Parts : 1,837.45
Total Labour & Parts : 3,851.45

Repair days: 3

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

Shu Pei (LKKAuto)

From: Shu Pei (LKKAuto)
Sent: Wednesday, 21 February 2018 4:28 PM
To: 'GERALD POH WEE BIN'; 'ERIC WOO JUN KIAT'; 'ONG LI LI'
Cc: 'MT_Claim_SG'; Admin A; Asher Sng (LKKAuto); Vic (LKKAuto)
Subject: Direct Settlement - Accident Involving GQ9910S (OI : LPC - TBA) AND SKA8899K (TP : LKK REF -CC3/LPC18003310/hb3) on 14.02.2018
Attachments: TP GIA REPORT.PDF; TP ESTIMATE.PDF

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case from M/s Performance Motors Limited.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- Estimated cost of repair
- TP's GIA report

Please be informed that preliminary advice is not ready yet.

Our case handler in-charge is Vic and he can be contacted at DID: 6841 2096.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Shu Pei (LKKAuto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Wednesday, 21 February 2018 4:33 PM
To: Shu Pei (LKKAuto)
Cc: MT_Claim_SG
Subject: RE: Direct Settlement - Accident Involving GQ9910S (OI : LPC - TBA) AND SKA8899K (TP : LKK REF -CC3/LPC18003310/hb3) on 14.02.2018
Attachments: 21022018163124.pdf

Our Ref : 17/18/18/VC00/020407

Dear Shu Pei,

We attached insured's GIA report for your attention.

Best Regards
Gerald Poh
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road, #17-04/07 The Concourse, Singapore 199555
Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, 21 February, 2018 4:28 PM
To: GERALD POH WEE BIN; ERIC WOO JUN KIAT; ONG LI LI
Cc: MT_Claim_SG; Admin A; Asher Sng (LKKAuto); Vic (LKKAuto)
Subject: Direct Settlement - Accident Involving GQ9910S (OI : LPC - TBA) AND SKA8899K (TP : LKK REF - CC3/LPC18003310/hb3) on 14.02.2018

WITHOUT PREJUDICE

Dear Sir / Madam,

We refer to the above matter.

This is a TP direct settlement case from M/s Performance Motors Limited.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:
- Estimated cost of repair
- TP's GIA report

Please be informed that preliminary advice is not ready yet.

Our case handler in-charge is Vic and he can be contacted at DID: 6841 2096.


MSIG

MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way, # 21-01, SGX Centre 2, Singapore 060007
 Tel +65 6827 7888, Fax +65 6827 7800
 Co. Reg. No. 200412212G GST Reg. No. 20-0412212G

BROKER'S COPY

SIME MOTOR PRIVATE
RENEWAL CERTIFICATE

Policy Number		Period of Insurance		Place of Issue
B 80264765 SMP		22/10/2017 to 21/10/2018		SINGAPORE
Name and Address of Insured				Date of Issue
Koh Thiam Soo 35 Pioneer Road Singapore 628503				24/10/2017
				Account Number
				212165
Premium	GST		Total Due	
SGD1,596.31	SGD111.74		SGD1,708.05	

RISK NUMBER 2
SIME MOTOR PRIVATE
OCCUPATION

Director

FINANCIAL INTEREST

 BMW Financial Services Singapore Pte. Ltd.
 as Hire Purchase Owners

SCOPE OF COVER Comprehensive

INTEREST INSURED

REGISTRATION NO.	SKA8899K	SUM INSURED	MARKET VALUE
MAKE/MODEL	BMW 740 LI	INCL. COE/PARF	YES
ENGINE NUMBER	09227442N54B30A	OFF-PEAK CAR	NO
CHASSIS NUMBER	WBAKB42000CY83200	NO CLAIM DISCOUNT	50.00% (or F/D)
YEAR OF MFG	2010	GOOD DRIVER'S	
CAPACITY	2979 C.C.	DISCOUNT	SGD84.02
SEATING CAPACITY	5 (INCL. DRIVER)	NCD PROTECTOR	COVERED
WINDSCREEN	UNLIMITED	EXCESS	SGD1,000
		ANNUAL PREMIUM	SGD1,596.31

ACCESSORIES Aircon, radio/cassette/compact disc player, in-vehicle unit, rust-proofing and other accessories that are factory fitted.

AUTHORISED DRIVERS

Koh Thiam Soo

NOTICE OF REPORTING

This is to confirm that KOH THIAM SOO, C/N: 9638 5845, NRIC: S0061335E has reported to the Police a non-injury traffic accident which happened at

Filter Lane along Sim Way towards Geylang Road

On 14/02/2018 at 2125hrs involving the following vehicles:

- 1) SKA8899K (One White coloured BMW 740i)
- 2) GQ9910S (One silver coloured Nissan Pickup vehicle)

2 If this accident was reported to the Police within 24 hours of its occurrence, then he/she has complied with Sec 84(2) of the Road Traffic Act, Cap 276.

Rank/Name of Issuing Officer:  T150175
SGT(2) T150175 Muhd Ash Shahidi B.M.P

Date: 15/02/2018 Time: 2013hrs

S/D Ref: 21

Aljunied NPP
33k 13 Joo Seng Rd
#01-69 S(360013)

Police Post/Unit: Aljunied NPP/Tanglin Divison

Original - to be issued to informant
Duplicate - to be submitted to Traffic Police

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190828 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

21 FEB 2018

1247013

Estimate No. : b1 45983
Date Estimated : 21/02/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -Koh Thiam Soo
223 Macpherson Road

Singapore 348565

- ACCOUNT - 40000Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKA8899K	CY83200	22/10/2010	740LiA	0

DESCRIPTION

To replace on rear bumper & all attachments cause by accident

850 2,550.00

Painting on rear bumper assembly

934 1,038.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

Sundries.

✓ 80.00

Total Labour 1: **3,845.00**DESCRIPTION

SET MOUNTS PDC SENSOR REAR

QTY PRIC

VALUE

RR BUMPER CARRIER

1 62.95

re- 62.95

RR BUMPER LH MOUNT

1 800.80

? 800.80

RR BUMPER RH MOUNT

1 198.30

? 198.30

RR BUMPER LOWER TRIM (PRIMED)

1 198.30

? 198.30

RR BUMPER TOW HOOK COVER (PRIMED)

1 224.45

de- 224.45

RR BUMPER (PDC)

1 50.65

de- 50.65

RR BUMPER CTR GUIDE

1 1,571.15

de- 1,571.15

ADAPTER (M)

1 51.50

? 51.50

DECOUPLING RING PDC TORQUE CONVERTE

1 77.65

? 77.65

BUMPER PDC SENSOR (300 ALPINWEISS)

4 5.05

re- 20.20

2 368.80

? 737.60

Total Parts : **3,993.55**

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

260, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 45983
Date Estimated : 21/02/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKA8899K	CY83200	22/10/2010	740LiA	0

Online CD / S	
Regn No.	
Date of Work	21/2/18
Worked by	Tanjin
Cost	9740549
Notes	WP
Remarks	Tanjin @ Pakan.com
No. of days	2 days

Labour 1	:	3,845.00
Parts	:	3,993.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	548.70
Grand Total	:	8,387.25

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401555W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190508 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

21 FEB 2018

Estimate No. : b1 45983	Page No. : 1 of 2
Date Estimated : 21/02/2018	
Prepared By : Kevin Leong Wai Kit	

<p>- ESTIMATE REPAIR FOR - Koh Thiam Soo 223 Macpherson Road Singapore 348565</p>	<p>- ACCOUNT - 40000 Cash Sales - Service Singapore</p>
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKA8899K	CY83200	22/10/2010	740LiA	0

DESCRIPTION	VALUE
To replace on rear bumper & all attachments cause by accident	850 - 2,550.00
Painting on rear bumper assembly	934 - 1,038.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 - 177.00
Sundries. <i>ku</i>	✓ 80.00
Total Labour 1:	3,845.00

DESCRIPTION	QTY	PRIC	VALUE
SET MOUNTS PDC SENSOR REAR	1	62.95	<i>uu rei</i> 62.95 X
RR BUMPER CARRIER	1	800.80	<i>uu</i> ? 800.80 X
RR BUMPER LH MOUNT	1	198.30	<i>uu</i> ? 198.30 X
RR BUMPER RH MOUNT	1	198.30	<i>uu</i> ? 198.30 X
RR BUMPER LOWER TRIM (PRIMED)	1	224.45	<i>de</i> 224.45 X
RR BUMPER TOW HOOK COVER (PRIMED)	1	50.65	<i>on/hall</i> 50.65 X
RR BUMPER (PDC)	1	1,571.15	<i>de</i> 1,571.15 X
RR BUMPER CTR GUIDE	1	51.50	<i>uu</i> ? 51.50 X
ADAPTER (M)	1	77.65	<i>uu</i> ? 77.65 X
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	<i>uu</i> ? 20.20 X
BUMPER PDC SENSOR (300 ALPINWEISS)	2	368.80	<i>uu</i> ? 737.60 X
Total Parts :			3,993.55

1908P

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190328 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45983
Date Estimated : 21/02/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKA8899K	CY83200	22/10/2010	740LiA	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims CD / 8	0	Regn No	
Date & Time	21/2/18	Surveyor Name	Tanpin
Surveyor No	97405449	Additional	WP
REG No		Surveyor Co	Tanpin @ Pakant.com
No. of Working Days			3 days

Labour 1	:	3,845.00
Parts	:	3,993.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	548.70
		<u>7,380.60</u>
Grand Total	:	8,387.25

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45983
Date Estimated : 21/02/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Koh Thiam Soo
223 Macpherson Road

- ACCOUNT - 158
Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

Singapore 348565

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SKA8899K	CY83200	22/10/2010	740LiA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments include knocking out dents caused by the accident	850.00		850.00
To spray paint rear bumper	934.00		934.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00
Sundries.	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RR BUMPER ADAPTER *	41.85	1.00		41.85
RR BUMPER LOWER TRIM (PRIMED)	224.45	1.00		224.45
RR BUMPER (PDC)	1,571.15	1.00		1,571.15

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,837.45
Total Labour & Parts :	3,851.45
Deduction for Excess :	
Total Repair Costs less Excess:	3,851.45
GST @7%:	269.60
Grand Total :	4,121.05

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 45983
Date Estimated : 21/02/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Koh Thiam Soo
223 Macpherson Road

- ACCOUNT - 158
Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

Singapore 348565

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SKA8899K	CY83200	22/10/2010	740LiA	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RR BUMPER ADAPTER *	41.85	1.00	<i>nee</i>	41.85 ✓

Total Labour :	
Total Parts :	41.85
Total Labour & Parts :	41.85

Vic (LKKAuto)

From: Vic (LKKAuto)
Sent: Friday, 27 July, 2018 1:53 PM
To: PBSP
Cc: Admin A; Vic (LKKAuto)
Subject: RE: REQ FOR DIRECT SETTLEMENT - SKA8899K & GQ9910S (LONPAC) ON 14.02.2018 ***LKK REF:CC3/LPC18003310/hb3
Attachments: DV.pdf

Without Prejudice

Dear Caroline,

We refer further to our below email and we confirmed in receipt of the LOD.

Purely for an amicable settlement on a without prejudice basis and without admission of liability to our Insured's part. We have our principal's mandate and we confirmed acceptance of your offer of **\$4,423.05** (all in) to settle your client's claim.

Kindly let the owner sign the attached DV and forward back to us(LKK) the original signed DV for payment processing.

Thank you.

"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK
Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: Vic (LKKAuto)
Sent: Friday, 23 February, 2018 4:03 PM
To: PBSP
Cc: Admin A; Asher Sng (LKKAuto); Vic (LKKAuto); Shu Pei (LKKAuto)
Subject: RE: REQ FOR DIRECT SETTLEMENT - SKA8899K & GQ9910S (LONPAC) ON 14.02.2018 ***LKK REF:CC3/LPC18003310/hb3

Your Ref: SKA 8899K

"WITHOUT PREJUDICE"

Our Ref: CC3/LPC18003310/hb3

Dear Caroline,

ACCIDENT INVOLVING VEHICLES GQ 9910S AND SKA 8899K ON 14/02/2018

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is clear subject to the BOLA guideline settlement.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle and admission of any liability to our Insured's part. The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Kindly forward the LOD and all supporting documents to us if available to proceed with the settlement.

Thank you.

Best Regards,

Vic Alpeh | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2096 | email: vicalpeh@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]

Sent: Friday, 23 February, 2018 3:57 PM

To: Shu Pei (LKKAuto); Vic (LKKAuto); Asher Sng (LKKAuto)

Cc: Admin A; CS A Team

Subject: Re: REQ FOR DIRECT SETTLEMENT - SKA8899K & GQ9910S (LONPAC) ON 14.02.2018 ***LKK
REF:CC3/LPC18003310/hb3

Dear Vic and Asher

Please advise if your insured had reported the accident?

Kindly reply on liability.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Sent: Wednesday, 21 February 2018 4:29:00 PM
To: PBSP
Cc: 甯瑒 ©; CS A Team
Subject: RE: REQ FOR DIRECT SETTLEMENT - SKA8899K & GQ9910S (LONPAC) ON 14.02.2018 ***LKK
REF:CC3/LPC18003310/hb3

Dear Caroline,

We refer to the above matter.

Please be informed that we are currently **pending for our insured's GIA report.**

Kindly note that for liability, claim negotiation and settlement, please contact Vic at 6841 2096.

Our respective case handler will look into the matter and revert to you in due course.

Thank you

To check availability of the case handler , you may contact the undersigned.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [<mailto:pml-pbsp@simedarby.com.sg>]
Sent: Wednesday, 21 February 2018 3:59 PM
To: CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: REQ FOR DIRECT SETTLEMENT - SKA8899K & GQ9910S (LONPAC) ON 14.02.2018

Dear Sirs

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,
Caroline

C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or

proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."



Lonpac Insurance Bhd
300 Beach Road
#17- 04/07 The Concourse
Singapore 199555
Attention: Motor Claims

Your Ref:

Our Ref:

Date:

Subject:

13 November 2018

ACCIDENT INVOLVING SKA8899K AND GQ9910S ON 14.02.2018

Dear Sirs

We refer to the above matter.

We are pleased to enclose the Discharge Voucher duly executed by our client.

Please let us have your settlement cheque made in favour of "Performance Motors Limited" within the next 14 days.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@simedarby.com.sg.

Performance Motors
Limited
1800-Call-BMW
(1800-2255-269)

www.pml.com.sg

303 Alexandra Road
Sime Darby
Performance Centre
Singapore 159941
Tel Sales 6319 0100
Tel Aftersales:
6319 0111
Fax 6474 7770

315 Alexandra Road
#01-01
Sime Darby
Business Centre
Singapore 159944
Tel Sales 6319 0511
Tel Aftersales
6319 0527
Fax 6479 6624

280
Kampong Arang Rd
East Coast Centre
Singapore 438180
Tel Aftersales
6319 0888
Fax 6344 1332

Registered office
305 Alexandra Road
#02-01
Vantage
Automotive Centre
Singapore 159942

Co. Reg. No:
197401559W

Yours sincerely

Teng Wai Khan
Customer Service Manager, Body & Paint



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref : CC3/LPC18003310/T1hb3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 27-11-2018	
		Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GQ 9910S	Veh. Inspected	SKA 8899K
Policy No.	Z/17/VC00/100186	Coverage (\$)	0.00
Claim No.	17/18/18/VC00/020407	Excess (\$)	0.00
Assign From		Assign Date	27/02/2018
2. Vehicle Particulars & Condition			
Make & Model	BMW 740LI	c.c	2979
Engine No.	HIDDEN	Year of Reg.	2010
Chassis No.	WBAKB42000CY83200	Colour	WHITE
Odometer	152733	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	275/40 R19	GOODYEAR	6 mm
L/H Front Tyre	275/40 R19	GOODYEAR	6 mm
R/H Rear Tyre	275/40 R19	GOODYEAR	6 mm
L/H Rear Tyre	275/40 R19	GOODYEAR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/02/2018	Inspection Date	27/02/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 8899K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	80.00	80.00
1	SET MOUNTS PDC SENSOR REAR (SN)	NOT NECESSARY	62.95	-
1	RR BUMPER CARRIER (SN)	NOT NECESSARY	800.80	-
1	RR BUMPER LH MOUNT (SN)	NOT NECESSARY	198.30	-
1	RR BUMPER RH MOUNT (SN)	NOT NECESSARY	198.30	-
1	RR BUMPER LOWER TRIM (PRIMED) (SN)	DEFORMED	224.45	224.45
1	RR BUMPER TOW HOOK COVER (PRIMED) (SN)	NOT NECESSARY	50.65	-
1	RR BUMPER (PDC) (SN)	DEFORMED	1,571.15	1,571.15
1	RR BUMPER CTR GUIDE (SN)	NOT NECESSARY	51.50	-
1	ADAPTER (M) (SN)	NOT NECESSARY	77.65	-
4	DECOUPLING RING PDC TORQUE CONVERTE (SN)	NOT NECESSARY	20.20	-
2	BUMPER PDC SENSOR (300 ALPINWEISS) (SN)	NOT NECESSARY	737.60	-
1	RR BUMPER ADAPTER (SN) (ADDITIONAL)	NECESSARY	41.85	41.85
			4,115.40	1,917.45
LABOUR				
TO REPLACE ON REAR BUMPER & ALL ATTACHMENTS CAUSE BY ACCIDENT.			2,550.00	850.00
PAINTING ON REAR BUMPER ASSEMBLY .			1,038.00	934.00
TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION.			177.00	150.00
			3,765.00	1,934.00
GRAND TOTAL			7,880.40	3,851.45
RECOMMENDED COST OF REPAIRS				3,851.45

Report Ref No. CC3/LPC18003310/T1hb3n2

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

HO LEONG CHUAN
Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.