

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

21 FEB 2018

Estimate No. : b1 45983	Page No. : 1 of 2
Date Estimated : 21/02/2018	
Prepared By : Kevin Leong Wai Kit	

- ESTIMATE REPAIR FOR - Koh Thiam Soo 223 Macpherson Road Singapore 348565	- ACCOUNT - 40000 Cash Sales - Service Singapore
---	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKA8899K	CY83200	22/10/2010	740LiA	0

DESCRIPTION	VALUE
To replace on rear bumper & all attachments cause by accident	850 2,550.00
Painting on rear bumper assembly	934 1,038.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Sundries.	✓ 80.00
Total Labour 1:	3,845.00

DESCRIPTION	QTY	PRIC	VALUE
SET MOUNTS PDC SENSOR REAR	1	62.95	re ✓ 62.95
RR BUMPER CARRIER	1	800.80	? 800.80
RR BUMPER LH MOUNT	1	198.30	? 198.30
RR BUMPER RH MOUNT	1	198.30	? 198.30
RR BUMPER LOWER TRIM (PRIMED)	1	224.45	de ✓ 224.45
RR BUMPER TOW HOOK COVER (PRIMED)	1	50.65	dl ✓ 50.65
RR BUMPER (PDC)	1	1,571.15	de ✓ 1,571.15
RR BUMPER CTR GUIDE	1	51.50	? 51.50
ADAPTER (M)	1	77.65	? 77.65
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	re ✓ 20.20
BUMPER PDC SENSOR (300 ALPINWEISS)	2	368.80	? 737.60
Total Parts :			3,993.55

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No.	: b1 45983	Page No. :	2 of 2
Date Estimated	: 21/02/2018		
Prepared By	: Kevin Leong Wai Kit		

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKA8899K	CY83200	22/10/2010	740LiA	0

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____

Date & Time 21/2/18

Surveyor's Name Tanjin repair

Surveyor's Tel 97405449

Authorised Code WP

RESURVEY PART PAINT SPRAY REPAIR YES NO

Surveyor's E-mail tanjin@pkant.com

No. of Working Days Recommend 3 days

Labour 1	:	3,845.00
Parts	:	3,993.55
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	548.70
Grand Total	:	8,387.25

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**
** PRICE FOR PARTS ARE SUBJECT TO CHANGE WITHOUT PRIOR NOTICE **