

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 3971S

DATE 20/2/2018 22:43

Jumani

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet ✓			\$ 1,526.00
	Bonnet Hinge (LH/RH) ✓		\$ 91.30	\$ 182.60
	Bonnet Lock ✓			\$ 50.90
	Bonnet Absorber ?		\$ 73.90	\$ 147.80
	Bonnet Insulator ?			\$ 50.88
	Bonnet Insulator Clips ?			\$ 73.92
	Radiator Grille ?			\$ 294.35
	Radiator Grille H Emblem ?			\$ 113.65
	Front Bumper Cover ✓			\$ 562.30
	Front Bumper Sponge ?			\$ 142.20
	Front Bumper Reinforcement ?			\$ 526.10
	Front Bumper Bracket Top (LH/RH) ?		\$ 22.40	\$ 44.80
	Front Bumper Bracket (LH/RH) ?		\$ 24.60	\$ 49.20
	Headlamp Support Top Cover ?			\$ 398.00
	Headlamp Support Panel Assy ?			\$ 1,067.50
	Headlamp (LH/RH) RH - LH?		\$ 1,388.00	\$ 2,776.00
	Radiator ?			\$ 850.20
	Radiator Fan Blade, Cowling, Motor Assy?			\$ 792.95
	Radiator Bracket (RH/LH) ?		\$ 6.50	\$ 13.00
	Radiator Hose Upper ?			\$ 47.40
	Radiator Guard ?		\$ 35.00	\$ 70.00
	Horn Unit (LH/RH) ?		\$ 86.75	\$ 173.50
	Air Duct ?			\$ 206.05
	Aircon Condenser ?			\$ 1,137.35
	Inter Cooler ?			\$ 921.90
	Inter Cooler Mounting (2 PCS) ?			\$ 25.90
				\$ 12,244.45
				\$ 2,448.89
				\$ 9,795.56
	Front Fender Advertisement Logo (RH) ✓			\$ 100.00
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 600.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Aircon & Refill Gas			\$ 150.00
				\$ 1,850.00
	ESTIMATE TOTAL			\$ 11,745.56
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

LKK Auto Consultants hence notify

the Repairer of the following:

• To resurvey before/after spray painting

• To LESS 20% of parts during resurvey

• Parts prices are subject to confirmation

• Third party survey is on a "Without Prejudice" basis

• No illegal modification is allowed

• Supplementary items must be surveyed and is subject to final approval by the Insurance Company

Acknowledged by:

Signature:

Date:

20/2/18

20/2/18 12:05 PM

3 Reps.

45

Atta Repair

Nett

4.00

3.60

20

20

8.00