

REPAIR ESTIMATE*

VEHICLE NO : SHD 4573X

DATE 20/2/2018 3:48

Jumani

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>Rebrand</i>			\$ 538.80
	Front Bumper Bracket Top (RH) <i>X su</i>			\$ 22.40
	Front Bumper Protector (RH) <i>X kgu</i>			\$ 29.20
	Front Bumper Side Bracket <i>X su</i>			\$ 14.30
	Headlamp (RH) <i>Rebrand</i>			\$ 797.90
	Front Fender (RH) <i>Rebrand</i>			\$ 593.00
	Front Fender Shield (RH) <i>X su</i>			\$ 86.00
	Front Fender Retainer <i>X su</i>			\$ 9.20
	SUB TOTAL			\$ 2,090.80
	LESS 20%			\$ 418.16
	DISCOUNTED TOTAL			\$ 1,672.64
	Front Fender Advertisement Logo (RH) <i>Rebrand</i>			\$ 100.00
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 560.00 <i>300</i>
	Spray Painting Charge			\$ 400.00 <i>360</i>
	Wiring Charge			\$ 50.00 <i>20</i>
	Tuff Kote			\$ 50.00 <i>30</i>
	TOTAL LABOUR			\$ 1,060.00
	ESTIMATE TOTAL			\$ 2,832.64

*Ka Lw (1/1/14)**20/2/18 1055L**3 Rys**4s**After Repair photo*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.