

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 4573X

DATE 20/2/2018 3:48

MAKE :

MODEL : HYUNDAI SONATA

EQ-LPK

Jumani

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 538.80
	Front Bumper Bracket Top (RH) ?			\$ 22.40
	Front Bumper Protector (RH) X Repair			\$ 29.20
	Front Bumper Side Bracket ?			\$ 14.30
	Headlamp (RH) ✓			\$ 797.90
	Front Fender (RH) ✓			\$ 593.00
	Front Fender Shield (RH) X			\$ 86.00
	Front Fender Retainer X			\$ 9.20
	SUB TOTAL			\$ 2,090.80
	LESS 20%			\$ 418.16
	DISCOUNTED TOTAL			\$ 1,672.64
	Front Fender Advertisement Logo (RH) ✓			\$ 100.00 Nett
				\$ 100.00
	Labour Charge			
	Panel Beating			\$ 560.00 300
	Spray Painting Charge			\$ 400.00 360
	Wiring Charge			\$ 50.00 20
	Tuff Kote			\$ 50.00 20
	TOTAL LABOUR			\$ 1,060.00
	ESTIMATE TOTAL			\$ 2,832.64
1/Calvin (1/1/14) 20/2/18 1055h 3 Rg, 4/5 After Repair p Lho				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				