

**Indeco**

VEHICLES &amp; EQUIPMENT DIVISION

No. 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

**ACCIDENT REPAIR ESTIMATES**

Our Ref:

Type of Claim : TPVehicle No. : SFH 4081 BMake & Model : TOYOTA PICNICYear of Manufacture : 2004Chassis No. : JTEGH23B105019364

Engine No. : \_\_\_\_\_

Policy No. : \_\_\_\_\_

Time of Accident : \_\_\_\_\_

Ins Company : NTUC

Excess : \_\_\_\_\_

Date of Accident : 19/2/2018

Suggested Days of Repair : \_\_\_\_\_

**Repair Estimates**Parts (a) Cost / List Price Items \$ 633.00Plus/Less \$ -Total of Cost / List \$ 633.00(b) Nett Price Items \$ -Less \$ -Total of Nett Item \$ -(c) Special Nett Items \$ 250.00Total Parts Cost (Appendix A) \$ 883.00Labour (Appendix B) \$ 1,420.00Total Repair Cost \$ 2,303.00

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Leo Qiang - 82880282Company : UKKSurvey conducted on : 22/2/18 at \_\_\_\_\_**Remarks By Surveyor**

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 2 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ \_\_\_\_\_

(e) Signature of surveyor : \_\_\_\_\_ Date: \_\_\_\_\_

part by part.  
before paint photos.



VEHICLES & EQUIPMENT DIVISION

No . 39 DEFU LANE 12, SINGAPORE 539139

Tel: (65) 382 2736 FAX: (65) 6382 2817

ANSON FAX: 62860908

### ESTIMATED REPAIR COST DETAILS

Vehicle No : SFH 4081 B Case Owner : 0

Make & Model : TOYOTA PICNIC Year Manufacture : \_\_\_\_\_

Chassis No : JTEGH23B105019364 Engine No : 0

Date & Time : \_\_\_\_\_ Supplier : HE XING

Order By : \_\_\_\_\_ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N
1	REAR BUMPER / <i>TV</i>	1		\$ 520.00		
2	REAR BUMPER RETAINER RH / <i>MSL</i>	1		\$ 45.00		
3	REAR BUMPER CLIPS / <i>MSL</i>	10		\$ 40.00		
4	TOW COVER RH / <i>MSL</i>	1		\$ 28.00		
5	REVERSE SENSOR (3PC 1 SET) / <i>DM</i>	1				\$ 250.00
6	0	0				
7	0	0				
8	0	0				
9	0	0				
10	0	0				
11	0	0				
12	0	0				
13	0	0				
14	0	0				
15	0	0				
16	0	0				
17	0	0				
18	0	0				
19	0	0				
20	0	0				
21	0	0				
22	0	0				
23	0	0				
24	0	0				
25	0	0				
26	0	0				
27	0	0				
28	0	0				
29	0	0				
30	0	0				

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

**TOTAL**

\$ - \$ 633.00 \$ - \$ 250.00



Tel: (65) 382 2736 FAX: (65) 6382 2817

Vehicle No. : SFH 4081 B  
Make & Model : TOYOTA PICNIC

Case Owner	:	<u>0</u>
Year of Manufacture	:	2004

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

*Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.*