

ASS. REC. BY:

REF: CS/MSG1800332014/b4/1

Special Instruction:

SURVILOR

From Person:

Merrill

ASSIGNMENT (Office)

Catherine Thia

of

MSLG

Date/Time:

21/2/18

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLT8160X

Insured:

SLT2636E

at Workshop m/s

Torque 5 Pte Ltd

Tel:

64521457

of

8 kaki Bukit Ave 4 # 01-50

Policy No:

28958730 TMC

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

19/2/18

CA / REV / REP. / REV 24 HRS

w/ Survey 21/2

H.O.D. Endorsement:

Date/Time:

2:58pm @ 21/2/18

Person Contacted:

Stephanie

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SLT8160X - X
	SLT2636E - X

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Feb 2018		21 Feb 2018 14:45 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	JCM Rental Pte Ltd, Co. Reg. No.: 201711659M		
Main Claimant:	EZGO Leasing Pte Ltd, Co. Reg. No.: 201532859G		
Vehicle Reg. No.:	SLT8160X	Date of Loss:	19/02/2018 11:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	28958730TMC (Third Party Only) Coverage: 17/05/2017 - 16/05/2018
Vehicle Reg. No. (Insured):	SLT2636E	Policy No. (Claimant):	
		Excess:	
Repairer:	Torque 5 Pte Ltd (Kaki Bukit) No. 8 Kaki Bukit Ave 4,, #01-50, 415875 Kaki Bukit - Tel: 64524457		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 22/02/2018]		
Adj Asg. Remarks:	request Adrian Ling for survey		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Handwritten notes:

- wj uvi - 15

15/02/2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18003320/Utb

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 21-02-2018

Code : MSG



1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SLT 2636E	Veh. Inspected	SLT 8160X
Policy No.	28958730 TMC	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	21/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	19/02/2018	Inspection Date	21/02/2018
Survey held at	TORQUE 5 PTE LTD 8 KAKI BUKIT AVENUE 4 #01-50 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	2859G
Vehicle Details	
Vehicle No.:	SLT8160X
Vehicle to be Exported:	No
Intended De-registration Date:	23 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	C-HR HYBRID 1.8S CVT
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	2ZR8221779
Chassis No.:	ZYX102082974
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,615.00
Original Registration Date:	13 Nov 2017
First Registration Date:	13 Nov 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	12 Nov 2027
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	12 Nov 2027
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$50,000.00
COE Rebate Amount:	\$48,607.00
Total Rebate Amount:	\$52,357.00

The information contained herein is correct as at 23 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/02/2018 15:26
Date Of Accident	19/02/2018 11:15
Exact Location Of Accident	JUNCTION OF UPPER PAYA LEBAR ROAD & UBI AVE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT8160X
Insured/Policyholder	
Name Of Registered Owner	EZGO LEASING PTE LTD
Co Reg No	201532859G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-88888888
Vehicle Particulars	
Manufacturer	TOYOTA
Model	C-HR HYBRID-1.8 S CVT (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5082798075-01
Cover Note Number	

Driver

Name of Driver	LEE AH WONG
NRIC No	S0213447J
Date Of Birth	13/01/1949
Occupation	OUTDOOR
Date Of Driving Pass	01/06/1972
Driving Experience	45 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92304922
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 142 MARSILING ROAD #07-2092
Postcode	730142
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LIM WEN JIE GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO SOUTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 81 ANG MO KIO AVE 3 , POSTCODE: 569929 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4519999 - FAX NO: 65535679
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER POLICE REPORT T/20180219/2089

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	PLEASE GET FROM WORKSHOP
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT2636E
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LEE AH HONG
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLT8160X
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

DETAILS OF INJURED PERSON 2

Name LIM WEN JIE
Approximate Age
Injuries Sustain
Injured person in which vehicle? SLT8160X
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to reassess policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out end/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRK/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180219/2089

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
190009
Tel No: 1800-4519999

1 of 3

Report No. T/20180219/2089

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 19/02/2018 15:53		Vide Report No.:		Station Diary No.: 103
Name of Informant: LEE AH WONG		Address: APT BLK 142 MARSILING ROAD #07-2092 SINGAPORE 730142		
ID Type / ID No.: NRIC: J10 / S0213447J		Contact No.: Home/Office: Mobile: 92304922		
Nationality: SINGAPORE CITIZEN		Email:		
Sex: Male	Age: 69	Date of Birth: 13/01/1949	Type of Informant: Driver	
Race: Chinese		Language: English	Institution / School Name:	
Occupation: PRIVATE TAXI DRIVER		Driving Licence Information: Class: 2B,2A,2,3 Date of Expiry:		

Type of Accident: Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 19/02/2018 11:15	Type of Location: X-Junction
Location: Along Road 1 UPPER PAYA LEBAR ROAD			
Cross junction of Upper Paya Lebar Road and Ubi Avenue 3			
Weather: Clear	Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Dual Carriage Way	Traffic Control: Traffic Light - Working	Traffic Volume: Moderate	
Type of Collision: Between Moving Vehicles - Side Swipe - Opposite Direction			Anyone conveyed by ambulance: No

Vehicle No	Type	Make	Model	Color	Condition	No of Passenger
SLT2636E	Car					0
SLT8160X	Car					1

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180219/2085

2 of 3

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

Report No. T/20180219/2085

CONTINUATION OF REPORT

Name	LEE AH WONG		ID No.	S0213447J
Related Vehicle	SLT8160X (Car)		Contact No.	92304922
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date	Class: 2B, 2A, 2, 3 Date of Expiry: NIL
Date Treatment	NIL		Date Discharge	NIL
No. of Days granted Medical Leave	NIL		Degree of Injury	NIL

Brief Details.

On 19/2/18 at about 1115hrs I was driving my vehicle (SLT8160X) along Upper Paya Lebar Road with one passenger seated at the front passenger seat. I was travelling straight along Upper Paya Lebar Road. While I was at the cross junction of Upper Paya Lebar Road and Ubi Avenue 3, there was another vehicle (SLT2636E) about to turn right from Paya Lebar Road into Ubi Avenue 3. However the driver did not stop for the oncoming traffic, he inched out a lot and I swerved to my left. However the right side of my vehicle swiped against the front of the other vehicle.

I then stopped at the side of the road as I knew that the other driver would come by to exchange particulars however he just drove off.

The right side of my vehicle's body is heavily scratched and dented. Neither me nor my passenger was injured at scene however I have some body pain.



**SINGAPORE
POLICE FORCE**



T/20180219/2089

Police Station Of Origin:
Ang Mo Kio South N.P.C
81 Ang Mo Kio Avenue 3 SINGAPORE
569929
Tel No: 1800-4519999

3 of 3

Report No. T/20180219/2089

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F.I. Sgt 2 RAMESH S/O KOLILINGAM <i>[Signature]</i>	Signature Of Informant <i>[Signature]</i>
Signature Of Interpreter: Not applicable	Date/Time: 19/02/2018 15:53
Officer In Charge Of Case: TP / HRT / SI TAN LEE HWANG DAWN Contact No: 65476215	Classification Of Case:
Authentication Stamp NP168 <i>[Stamp]</i> <i>[Signature]</i>	



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT8160X
Make & Model : TOYOTA,C-HR HYBRID 1.8S CVT,ZYX102082974
Year of : 2017
Manufacture

Estimation No. : E18020036
DOA : 19/02/2018

No	Description	Qty	U/P	Amt
<u>Section: List Items</u>				
1	REAR BUMPER <i>1X</i>	1.00	0.00	0.00
2	REAR BUMPER CLIPS <i>see ✓</i>	10.00	0.00	0.00
3	REAR BUMPER RETAINER (R) <i>11X</i>	1.00	0.00	0.00
4	REAR BUMPER BRACKET (R) <i>11X</i>	1.00	0.00	0.00
5	REAR BUMPER LOWER <i>found ✓</i>	1.00	0.00	0.00
6	REAR FENDER (R) <i>1X</i>	1.00	0.00	0.00
7	REAR FENDER COWLING (R) <i>11X</i>	1.00	0.00	0.00
8	REAR FENDER COWLING CLIPS (R) <i>11X</i>	10.00	0.00	0.00
9	REAR FENDER INNER TRIM (R) <i>11X</i>	1.00	0.00	0.00
10	REAR FENDER INNER TRIM CLIPS (R) <i>11X</i>	10.00	0.00	0.00
11	REAR FENDER ARCH GARNISH (R) <i>found ✓</i>	1.00	0.00	0.00
12	REAR FENDER ARCH GARNISH CLIPS (R) <i>see ✓</i>	10.00	0.00	0.00
13	REAR DOOR (R) <i>no/see ✓</i>	1.00	0.00	0.00
14	REAR DOOR WEATHER STRIP (R) <i>see ✓</i>	1.00	0.00	0.00
15	REAR DOOR INNER WEATHER STRIP (R) <i>see ✓</i>	1.00	0.00	0.00
16	REAR DOOR GARNISH (R) <i>no.5 ✓</i>	1.00	0.00	0.00
17	REAR DOOR GARNISH CLIPS (R) <i>see ✓</i>	10.00	0.00	0.00
18	REAR DOOR WINDOW MOULDING (R) <i>11X</i>	1.00	0.00	0.00
19	REAR DOOR POWER WINDOW GEAR (R) <i>?</i>	1.00	0.00	0.00
20	REAR DOOR POWER WINDOW MOTOR (R) <i>?</i>	1.00	0.00	0.00
21	REAR RIM (R) <i>see ✓</i>	1.00	0.00	0.00
22	REAR TYRE (R) <i>see X</i>	1.00	0.00	0.00
23	REAR ABSORBER (R) <i>11X</i>	1.00	0.00	0.00
24	REAR BEARING (R) <i>no.?</i>	1.00	0.00	0.00
25	REAR KNUCKLE ((R) <i>11X</i>	1.00	0.00	0.00

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT8160X
Make & Model : TOYOTA,C-HR HYBRID 1.8S CVT,ZYX102082974
Year of : 2017
Manufacture

Estimation No. : E18020036
DOA : 19/02/2018

No	Description	Qty	U/P	Amt
26	REAR LOWER ARM (R) 11X	1.00	0.00	0.00
27	REAR UPPER ARM (R) 11X	1.00	0.00	0.00
28	REAR TRUST ARM (R) 11X	1.00	0.00	0.00
29	REAR CROSSMEMBER (R) 11X	1.00	0.00	0.00
30	FRONT DOOR (R) 10/12/17	1.00	0.00	0.00
31	FRONT DOOR HINGE-UP (R) 11X	1.00	0.00	0.00
32	FRONT DOOR HINGE-DOWN (R) 11X	1.00	0.00	0.00
33	FRONT DOOR CHECKER (R) 11X	1.00	0.00	0.00
34	FRONT DOOR WEATHER STRIP (R) 11X	1.00	0.00	0.00
35	FRONT DOOR INNER WEATHER STRIP (R) 11X	1.00	0.00	0.00
36	FRONT DOOR GARNISH (R) 11X	1.00	0.00	0.00
37	FRONT DOOR WINDOW MOULDING (R) 11X	1.00	0.00	0.00
38	FRONT DOOR POWER WINDOW GEAR (R) ?	1.00	0.00	0.00
39	FRONT DOOR POWER WINDOW MOTOR (R) ?	1.00	0.00	0.00
40	FRONT DOOR INNER TRIM BOARD (R) ?	1.00	0.00	0.00
41	FRONT DOOR INNER TRIM BOARD CLIPS (R) ?	10.00	0.00	0.00
42	FRONT DOOR QUARTER GLASS MOULDING (R) 11X	1.00	0.00	0.00
43	SIDE MIRROR ASSY (R) 11X	1.00	0.00	0.00
44	SIDE SKIRT/ROCKER PANEL (R) 11X	1.00	0.00	0.00
45	FRONT FENDER (R) 11X	1.00	0.00	0.00
46	FRONT FENDER COWLING (R) 11X	1.00	0.00	0.00
47	FRONT FENDER COWLING CLIPS (R) 11X	10.00	0.00	0.00
48	FRONT FENDER INNER PANEL (R) 11X	1.00	0.00	0.00
49	FRONT FENDER EMBLEM - HYBRID WITH LOGO (R) 11X	1.00	0.00	0.00
50	FRONT FENDER TRIANGULAR GARNISH (R) 11X	1.00	0.00	0.00
51	FRONT FENDER ARCH GARNISH (R) 11X	1.00	0.00	0.00

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT8160X
Make & Model : TOYOTA, C-HR HYBRID 1.8S CVT, ZYX102082974
Year of Manufacture : 2017

Estimation No. : E18020036
DOA : 19/02/2018

No	Description	Qty	U/P	Amt
52	FRONT FENDER ARCH GARNISH CLIPS (R) <i>me ✓</i>	10.00	0.00	0.00
53	FRONT BUMPER <i>cut ✓</i>	1.00	0.00	0.00
54	FRONT BUMPER CLIPS <i>me ✓</i>	10.00	0.00	0.00
55	FRONT BUMPER FOG LAMP GARNISH (R) <i>11X</i>	1.00	0.00	0.00
56	FRONT BUMPER LOWER <i>cut ✓</i>	1.00	0.00	0.00
57	HEAD LAMP (R) <i>?</i>	1.00	0.00	0.00
58	HEAD LAMP CLIPS (R) <i>11X</i>	2.00	0.00	0.00
59	FRONT RIM (R) <i>cut ✓</i>	1.00	0.00	0.00
60	FRONT TYRE (R) <i>cut ✓</i>	1.00	0.00	0.00
61	FRONT ABSORBER (R) <i>?</i>	1.00	0.00	0.00
62	FRONT BEARING (R) <i>?</i>	1.00	0.00	0.00
63	FRONT KNUCKLE (R) <i>?</i>	1.00	0.00	0.00
64	FRONT LOWER ARM (R) <i>?</i>	1.00	0.00	0.00
65	FRONT DRIVE SHAFT (R) <i>cut ✓</i>	1.00	0.00	0.00
66	FRONT LINKAGE (R) <i>?</i>	1.00	0.00	0.00
67	FRONT STEERING RACK (R) <i>?</i>	1.00	0.00	0.00

Amt S\$ 0.00
Discount (25.00%) S\$ 0.00
Subtotal S\$ 0.00

Section: Special Nett Items

68	REAR FENDER SEALANT <i>11X</i>	1.00	80.00	80.00
69	REAR DOOR TINTED FIRM <i>11X</i>	1.00	100.00	100.00

Amt S\$ 180.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 180.00

Section: Labour Items

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLT8160X
Make & Model : TOYOTA,C-HR HYBRID 1.8S CVT,ZYX102082974
Year of : 2017
Manufacture :

Estimation No. : E18020036
DOA : 19/02/2018

No	Description	Qty	U/P	Amt
70	TO R&R ACCIDENT AFFECTED AREAS 1000	1.00	1,800.00	1,800.00
71	TO PUTTY & RESPRAY ACCIDENT AFFECTED AREAS 1400	1.00	2,000.00	2,000.00
72	TO RUST PROOF ACCIDENT AFFECTED AREAS 100	1.00	90.00	90.00
73	TO R&R REAR DOOR MECHANISM } 60	1.00	100.00	100.00
74	TO R&R QUARTER GLASS ?	1.00	150.00	150.00
75	TO R&R REAR UNDERCARRIAGE ?	1.00	280.00	280.00
76	TO R&R FRONT DOOR MECHANISM 60	1.00	100.00	100.00
77	TO CHECK WIRING LAYOUT & HEAD LAMP FOCUS 30	1.00	100.00	100.00
78	TO R&R FRONT UNDERCARRIAGE ?	1.00	280.00	280.00
79	TO DO WHEEL ALIGNMENT 80 100	1.00	200.00	200.00
80	TO CHECK FOR WATER SEEPAGE 11X	1.00	100.00	100.00

Amt S\$ 5,200.00

Discount (0.00%) S\$ 0.00

Subtotal S\$ 5,200.00

Not Aknd
Lbk
P/P
the above before party.
22/2/18
Teng.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

List Items Subtotal S\$ 0.00

Special Nett Items Subtotal S\$ 180.00

Labour Items Subtotal S\$ 5,200.00

Total S\$ 5,380.00

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Feb 2018		21 Feb 2018 14:45 Edit Adj Rpt	S\$2,750.00 Edit Estimates	S\$2,750.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	JCM Rental Pte Ltd, Co. Reg. No.: 201711659M								
Main Claimant:	EZGO Leasing Pte Ltd, Co. Reg. No.: 201532859G								
Vehicle Reg. No.:	SLT8160X	Date of Loss:	19/02/2018 11:00 - :59 [3 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 550209	Policy/Cover Note No.:	28958730TMC (Third Party Only) Coverage: 17/05/2017 - 16/05/2018						
Vehicle Reg. No. (Insured):	SLT2636E	Policy No. (Claimant):							
		Excess:							
Repairer:	Torque 5 Pte Ltd (Kaki Bukit) No. 8 Kaki Bukit Ave 4,, #01-50, 415875 Kaki Bukit - Tel: 64524457								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 22/02/2018]								
Adj Asg. Remarks:	request Adrian Ling for survey								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLT8160X (550209)
[SLT2636E]
TP
EZGO Leasing Pte Ltd
Feb 19 2018 11:00AM
[JCM Rental Pte Ltd]
Torque 5 Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View View in Browser	
Photos/Images							3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	22/02/18 20:07	Odometer Reading		Load JPG	☒			
2	22/02/18 20:07	General View		Load JPG	☒			
3	22/02/18 20:07	Chassis Number		Load JPG	☒			
4	22/02/18 20:07	General View		Load JPG	☒			
5	22/02/18 20:07	General View		Load JPG	☒			
6	22/02/18 20:07	General View		Load JPG	☒			
7	22/02/18 20:07	General View		Load JPG	☒			
8	22/02/18 20:07	General View		Load JPG	☒			
9	22/02/18 20:07	General View		Load JPG	☒			
10	22/02/18 20:07	General View		Load JPG	☒			
11	22/02/18 20:07	General View		Load JPG	☒			
12	22/02/18 20:07	General View		Load JPG	☒			
13	22/02/18 20:07	General View		Load JPG	☒			
14	22/02/18 20:07	General View		Load JPG	☒			
15	22/02/18 20:07	General View		Load JPG	☒			
16	22/02/18 20:07	General View		Load JPG	☒			
17	22/02/18 20:07	General View		Load JPG	☒			
18	22/02/18 20:07	General View		Load JPG	☒			
19	22/02/18 20:07	General View		Load JPG	☒			
20	22/02/18 20:07	General View		Load JPG	☒			
21	22/02/18 20:07	General View		Load JPG	☒			
22	22/02/18 20:07	General View		Load JPG	☒			
23	22/02/18 20:07	General View		Load JPG	☒			
24	22/02/18 20:07	General View		Load JPG	☒			
25	22/02/18 20:07	General View		Load JPG	☒			
26	22/02/18 20:07	General View		Load JPG	☒			
27	22/02/18 20:07	General View		Load JPG	☒			
28	22/02/18 20:07	General View		Load JPG	☒			
29	22/02/18 20:07	General View		Load JPG	☒			
30	22/02/18 20:07	General View		Load JPG	☒			
31	22/02/18 20:08	General View		Load JPG	☒			
32	22/02/18 20:08	General View		Load JPG	☒			
33	22/02/18 20:08	General View		Load JPG	☒			
34	22/02/18 20:08	General View		Load JPG	☒			
35	22/02/18 20:08	General View		Load JPG	☒			
36	22/02/18 20:08	General View		Load JPG	☒			
37	22/02/18 20:08	General View		Load JPG	☒			

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	22/02/18 20:08	General View	 Load JPG	☒
39	22/02/18 20:08	General View	 Load JPG	☒
40	22/02/18 20:08	General View	 Load JPG	☒
41	22/02/18 20:08	General View	 Load JPG	☒
42	22/02/18 20:08	General View	 Load JPG	☒
43	22/02/18 20:08	General View	 Load JPG	☒
44	22/02/18 20:08	General View	 Load JPG	☒
45	22/02/18 20:08	General View	 Load JPG	☒
46	22/02/18 20:08	General View	 Load JPG	☒
47	22/02/18 20:08	General View	 Load JPG	☒
48	22/02/18 20:08	General View	 Load JPG	☒
49	22/02/18 20:08	General View	 Load JPG	☒
50	22/02/18 20:08	General View	 Load JPG	☒
51	22/02/18 20:08	General View	 Load JPG	☒
52	22/02/18 20:08	General View	 Load JPG	☒
53	22/02/18 20:08	General View	 Load JPG	☒
54	22/02/18 20:08	General View	 Load JPG	☒
55	22/02/18 20:08	General View	 Load JPG	☒
56	22/02/18 20:08	General View	 Load JPG	☒
57	22/02/18 20:08	General View	 Load JPG	☒
58	22/02/18 20:08	General View	 Load JPG	☒
59	22/02/18 20:08	General View	 Load JPG	☒
60	22/02/18 20:08	General View	 Load JPG	☒
61	22/02/18 20:08	General View	 Load JPG	☒
62	22/02/18 20:08	General View	 Load JPG	☒
63	22/02/18 20:08	General View	 Load JPG	☒
64	22/02/18 20:08	General View	 Load JPG	☒
65	22/02/18 20:08	General View	 Load JPG	☒
66	22/02/18 20:08	General View	 Load JPG	☒
67	22/02/18 20:08	General View	 Load JPG	☒
68	22/02/18 20:08	General View	 Load JPG	☒
69	22/02/18 20:08	General View	 Load JPG	☒
70	22/02/18 20:08	General View	 Load JPG	☒
71	22/02/18 20:08	General View	 Load JPG	☒
72	22/02/18 20:08	General View	 Load JPG	☒
73	22/02/18 20:08	General View	 Load JPG	☒
74	22/02/18 20:08	General View	 Load JPG	☒
75	22/02/18 20:08	General View	 Load JPG	☒
76	22/02/18 20:08	General View	 Load JPG	☒
77	22/02/18 20:08	General View	 Load JPG	☒
78	22/02/18 20:08	General View	 Load JPG	☒
79	22/02/18 20:08	General View	 Load JPG	☒
80	22/02/18 20:08	General View	 Load JPG	☒
81	22/02/18 20:08	General View	 Load JPG	☒
82	22/02/18 20:08	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/02/18 14:21	PRI from Torque 5	 Load PDF	
2	21/02/18 14:21	SLT8160X E-file & Police Report	 Load PDF	
3	21/02/18 14:45	Survey Agree on SJE - LKK	 Load PDF	

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
4	28/02/18 09:21	police report lodged by OI, OID disappeared	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003320/UTBQ2

Date: 07/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 28958730TMC

Claimant Vehicle No: SLT8160X

Insured Vehicle No: SLT2636E

Date of Loss: 19/02/2018

Nature of Claim: TP

Claim No: 550209

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLT8160X

Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A)

Engine No: 22R8221779

Reg. Date: 13/11/2017 (Man. Year: 2017)

Chassis No: ZYX102082974

Colour: Grey

Odometer: 15835 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17

Rear Tyre Size: 215/60 R17

Front Left Side: Bridgestone 8 mm

Rear Left Side: Bridgestone 8 mm

Front Right Side: Bridgestone 8 mm

Rear Right Side: Bridgestone 8 mm

The above values represent the remaining tyre treads depth.

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,210.00	2,750.00	2,460.00	47.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,210.00	2,750.00	2,460.00	47.22
+ GST 7.00/7.00% (S\$)	364.70	192.50	172.20	47.22
Nett Amount (S\$)	5,574.70	2,942.50	2,632.20	47.22

INSPECTION

Date of Assignment: 21/02/2018

Date Inspected: 22/02/2018 Inspected At:

Torque 5 Pte Ltd (Kaki Bukit)
No. 8 Kaki Bukit Ave 4, #01-50
Singapore 415875

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

(REPAIR COST NOT CONCLUDE)

(EXCLUDE CHECK ITEMS S\$560.00 NETT)

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 May 2018)
Parts:	M1-SUV	TOYOTA C-HR HYBRID 1.8 S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT8160X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR BUMPER (NPA)	Repair	0.00 F	*-F
2	10	*REAR BUMPER CLIPS (NPA)	Necessary	0.00 F	*-F
3	1	*REAR BUMPER RETAINER (R) (NPA)	Not Necessary	0.00 F	*-F
4	1	*REAR BUMPER BRACKET (R) (NPA)	Not Necessary	0.00 F	*-F
5	1	*REAR BUMPER LOWER (NPA)	Grazed	0.00 F	*-F
6	1	*REAR FENDER (R) (NPA)	Repair	0.00 F	*-F
7	1	*REAR FENDER COWLING (R) (NPA)	Not Necessary	0.00 F	*-F
8	10	*REAR FENDER COWLING CLIPS (R) (NPA)	Not Necessary	0.00 F	*-F
9	1	*REAR FENDER INNER TRIM (R) (NPA)	Not Necessary	0.00 F	*-F
10	10	*REAR FENDER INNER TRIM CLIPS (R) (NPA)	Not Necessary	0.00 F	*-F
11	1	*REAR FENDER ARCH GARNISH (R) (NPA)	Grazed	0.00 F	*-F
12	10	*REAR FENDER ARCH GARNISH CLIPS (R) (NPA)	Necessary	0.00 F	*-F
13	1	*REAR DOOR (R) (NPA)	Dented / Bent	0.00 F	*-F
14	1	*REAR DOOR WEATHER STRIP (R) (NPA)	Necessary	0.00 F	*-F
15	1	*REAR DOOR INNER WEATHER STRIP (R) (NPA)	Necessary	0.00 F	*-F
16	1	*REAR DOOR GARNISH (R) (NPA)	Missing	0.00 F	*-F
17	10	*REAR DOOR GARNISH CLIPS (R) (NPA)	Necessary	0.00 F	*-F
18	1	*REAR DOOR WINDOW MOULDING (R) (NPA)	Not Necessary	0.00 F	*-F
19	1	*REAR DOOR POWER WINDOW GEAR (R) (NPA)	*Check	0.00 F	*-F
20	1	*REAR DOOR POWER WINDOW MOTOR (R) (NPA)	*Check	0.00 F	*-F
21	1	*REAR RIM (R) (NPA)	Cut	0.00 F	*-F
22	1	*REAR TYRE (R) (NPA)	Serviceable	0.00 F	*-F
23	1	*REAR ABSORBER (R) (NPA)	Not Necessary	0.00 F	*-F
24	1	*REAR BEARING (R) (NPA)	*Check	0.00 F	*-F
25	1	*REAR KNUCKLE (R) (NPA)	Not Necessary	0.00 F	*-F
26	1	*REAR LOWER ARM (R) (NPA)	Not Necessary	0.00 F	*-F
27	1	*REAR UPPER ARM (R) (NPA)	Not Necessary	0.00 F	*-F
28	1	*REAR TRUST ARM (R) (NPA)	Not Necessary	0.00 F	*-F
29	1	*REAR CROSSMEMBER (R) (NPA)	Not Necessary	0.00 F	*-F
30	1	*FRONT DOOR (R) (NPA)	Dented / Bent	0.00 F	*-F
31	1	*FRONT DOOR HINGE-UP (R) (NPA)	Bent	0.00 F	*-F
32	1	*FRONT DOOR HINGE-DOWN (R) (NPA)	Bent	0.00 F	*-F
33	1	*FRONT DOOR CHECKER (R) (NPA)	Bent	0.00 F	*-F
34	1	*FRONT DOOR WEATHER STRIP (R) (NPA)	Necessary	0.00 F	*-F
35	1	*FRONT DOOR INNER WEATHER STRIP (R) (NPA)	Necessary	0.00 F	*-F
36	1	*FRONT DOOR GARNISH (R) (NPA)	Distorted	0.00 F	*-F
37	1	*FRONT DOOR WINDOW MOULDING (R) (NPA)	Not Necessary	0.00 F	*-F
38	1	*FRONT DOOR POWER WINDOW GEAR (R) (NPA)	*Check	0.00 F	*-F
39	1	*FRONT DOOR POWER WINDOW MOTOR (R) (NPA)	*Check	0.00 F	*-F

Report was unsubmitted during this print-out.

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
40	1	*FRONT DOOR INNER TRIM BOARD (R) (NPA)	*Check	0.00 F	*- F
41	10	*FRONT DOOR INNER TRIM BOARD CLIPS (R) (NPA)	*Check	0.00 F	*- F
42	1	*FRONT DOOR QUARTER GLASS MOULDING (R) (NPA)	Not Necessary	0.00 F	*- F
43	1	*SIDE MIRROR ASSY (R) (NPA)	Not Necessary	0.00 F	*- F
44	1	*SIDE SKIRT /ROCKER PANEL (R) (NPA)	Cut	0.00 F	*- F
45	1	*FRONT FENDER (R) (NPA)	Badly Dented	0.00 F	*- F
46	1	*FRONT FENDER COWLING (R) (NPA)	Torn	0.00 F	*- F
47	10	*FRONT FENDER COWLING CLIPS (R) (NPA)	Necessary	0.00 F	*- F
48	1	*FRONT FENDER INNER PANEL (R) (NPA)	Repair	0.00 F	*- F
49	1	*FRONT FENDER EMBLEM -HYBRID WITH LOGO (R) (NPA)	Necessary	0.00 F	*- F
50	1	*FRONT FENDER TRIANGULAR GARNISH (R) (NPA)	Not Necessary	0.00 F	*- F
51	1	*FRONT FENDER ARCH GARNISH (R) (NPA)	Distorted	0.00 F	*- F
52	10	*FRONT FENDER ARCH GARNISH CLIPS (R) (NPA)	Necessary	0.00 F	*- F
53	1	*FRONT BUMPER (NPA)	Cut	0.00 F	*- F
54	10	*FRONT BUMPER CLIPS (NPA)	Necessary	0.00 F	*- F
55	1	*FRONT BUMPER FOG LAMP GARNISH (R) (NPA)	Not Necessary	0.00 F	*- F
56	1	*FRONT BUMPER LOWER (NPA)	Cut	0.00 F	*- F
57	1	*HEAD LAMP (R) (NPA)	*Check	0.00 F	*- F
58	1	*HEAD LAMP CLIPS (R) (NPA)	Not Necessary	0.00 F	*- F
59	1	*FRONT RIM (R) (NPA)	Cut	0.00 F	*- F
60	1	*FRONT TYRE (R) (NPA)	Serviceable	0.00 F	*- F
61	1	*FRONT ABSORBER (R) (NPA)	*Check	0.00 F	*- F
62	1	*FRONT BEARING (R) (NPA)	*Check	0.00 F	*- F
63	1	*FRONT KNUCKLE (R) (NPA)	*Check	0.00 F	*- F
64	1	*FRONT LOWER ARM (R) (NPA)	*Check	0.00 F	*- F
65	1	*FRONT DRIVE SHAFT (R) (NPA)	Not Necessary	0.00 F	*- F
66	1	*FRONT LINKAGE (R) (NPA)	*Check	0.00 F	*- F
67	1	*FRONT STEERING RACK (R) (NPA)	*Check	0.00 F	*- F
68	1	*REAR FENDER SEALANT (NPA)	Not Necessary	0.00 FS	*- FS
69	1	*REAR DOOR TINTED FIRM (NPA)	Not Necessary	0.00 FS	*- FS
Total Parts (\$\$)				0.00	0.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO R&R ACCIDENT AFFECTED AREAS	New	1,800.00	1,000.00
2	TO PUTTY & RESPRAY ACCIDENT AFFECTED AREAS	New	2,000.00	1,400.00
3	TO RUST PROOF ACCIDENT AFFECTED AREAS	New	100.00	100.00
4	TO R&R REAR DOOR MECHANISM }	New	100.00	60.00
5	TO R&R QUARTER GLASS }	New	150.00	0.00
6	TO R&R REAR UNDERCARRIAGE (*CHECK)	New	280.00	0.00
7	TO R&R FRONT DOOR MECHANISM	New	100.00	60.00
8	TO CHECK WIRING LAYOUT & HEAD LAMP FOCUS	New	100.00	30.00
9	TO R&R FRONT UNDERCARRIAGE (*CHECK)	New	280.00	0.00
10	TO DO WHEEL ALIGNMENT	New	200.00	100.00
11	TO CHECK FOR WATER SEEPAGE	New	100.00	0.00
Gross Labour Cost (S\$)			5,210.00	2,750.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >