

22/03/2018

ASS. REC. BY:

REF: CS/MSG/18003326/R11b

Special Instructions:

ASSIGNMENT (Office)

From (Person): Margaret Loh of MSG Date/Time: 21/2/2018

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SKB 9800H Insured: SLU 3644U

at Workshop m/s: MONA Automotive Tel: 62723892

of: Blk 1008, Blk Mrh Lane 3 #01-04

Policy No: A29 071318 QMX Claim No: 550142

Sum Insured: Excess:

Make of Veh: D.O.A. 15/2/2018

(Client's Record) 28/2/18 @ After 9am

CA / REV / REP. / REV 24 HRS 'WP' H.O.D. Endorsement:

Date/Time: 21/2/18 Person Contacted: Susan Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
17/01/18	CCA/EQ/18001042/R1pb3 - SKB 9800H TP SFL 6080U DCA: 13/1/2018
	Part by Part \$4527.16 (Red: 1105-3545:20%)
17/7	Double check with Denise, different 14 in memory system. Just Submit.

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle IN/OUT

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. 15/02/18 D.O.I. 28/02/18

Survey held at: PERFORMANCE

Des. of Damages: Frt (Red) / O/S / N/S / U/C / Rooftop on:

The UIC / Chassis frame / Body Structure affected due to collision

Date/Time Action/ Instruction

parts price ok ✓/PL

16/7/2018

RECEIVED T-6 JUL 2018

Date/Time File Pass to:

☐ : Prel. Report

Days Of Repair: 5

No. Typist

☒ : Final Report

Resurvey No. of Trip: 1

Survey Fee

Date/Time File Return to:

Transporter

F:

Add Fee: ☐ Site Insp: \$

F: 1-21-15

Report Format: TP

☐ Interview: \$

Phone

Lump Sum / (B): \$ 4527.16

☐ Tech Info: \$

Fax

☐ Need and: \$

Notes

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18003326/R11b

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 21-02-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLU 3644U	Veh. Inspected	SKB 9800H
Policy No.	A29071318QMX	Coverage (\$)	0.00
Claim No.	550142	Excess (\$)	0.00
Assign From	MERIMEN (MARGARET LOH)	Assign Date	21/02/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	15/02/2018	Inspection Date	28/02/2018
Survey held at	MOVA AUTOMOTIVE PTE LTD BLK 1008 BUKIT MERAH LANE 3 #01-04/06/08 SINGAPORE 159722		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/02/2018 09:28
Date Of Accident	15/02/2018 08:45
Exact Location Of Accident	AYE TOWARDS CTE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKB9800H
Insured/Policyholder	
Name Of Registered Owner	ONG KONG WEE
NRIC No	S7711790C
Email Address	OKW77@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-98205940
Alternative Phone No	OFFICE-98205940

Vehicle Particulars

Manufacturer	BMW
Model	523I-2.5 (A)
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	REPORTING ONLY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AIG ASIA PACIFIC INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	1700056963
Cover Note Number	

Driver

Name of Driver	ONG KONG WEE
NRIC No	S7711790C
Date Of Birth	28/04/1977
Occupation	INDOOR
Date Of Driving Pass	15/11/1994
Driving Experience	23 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98205940
Fax Number	
Contact Number	OFFICE-98205940
Email Address	OKW77@HOTMAIL.COM

Address	BLK 3 PANDAN VALLEY #14-304
Postcode	597627
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : ANG SHA KIN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU3644U
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


 Policyholder's Signature
 Date & Time:

Driver's Signature
 (if driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


LICENSE PLATE: SKB 9800 H	ACCIDENT DATE & TIME: 15/2/18, 0845 hrs.
CONTACT NUMBER: 98205940	E-MAIL ADDRESS: okw77@hotmail.com
LOCATION: AYE approaching CTE	
<p>I was on the AYE approaching CTE on the right most lane. The cars in front of me came to a stop due to traffic and I came to a stop too. The car behind me couldn't brake in time and bumped into my car's behind.</p> <p>My wife, Ong Shei Kim, was in the passenger seat. The lady driver behind me was Lee Pei San (S9333795F). The car number is SLU3644U. Contact 97242225.</p>	
<p>NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIM UNDER YOUR OWN POLICY. PLEASE CHECK YOUR POLICY FOR MORE INFORMATION</p>	
Please state:	
<input type="checkbox"/> Claim Own Policy <input type="checkbox"/> Claim Third Party <input type="checkbox"/> Claim OD/TP at other workshop <input checked="" type="checkbox"/> Reporting Only	

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Main Office:

 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:

 Block 1008,
 Bukit Merah Lane 3,
 #01-04/05/08/94
 Singapore 159722

 Tel: (65) 6272 3892
 Fax: (65) 6270 8314

 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

20/02/2018

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)
16, RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581.

 Attention :- **XA013**

Page # :- 1

Veh # :- SKB9800H

Veh Model :- BMW 523i

Estimate# :- CK417078

Claim # :-

ACC. Date :- 15/02/18

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BOOT LOGO	1 PC	82.60 <i>all</i>	82.60
2.	REAR BOOT EMBLEM - 523i	1 PC	85.30 <i>all</i>	85.30
3.	REAR BOOT LOCK	1 PC	256.85 <i>X sue</i>	256.85
4.	REAR BUMPER	1 PC	1,598.20 <i>DE</i>	1,598.20
5.	REAR BUMPER SENSOR (CENTER)	2 PC	275.65 <i>2 nu</i>	551.30
6.	REAR BUMPER REFLECTOR LH	1 PC	65.20 <i>X sue</i>	65.20
7.	REAR BUMPER INNER GUIDE LH & RH	2 PC	178.55 <i>2 nu</i>	357.10
8.	REAR BUMPER UNDER COVER	1 PC	98.60 <i>all</i>	98.60
9.	REAR BUMPER UNDER COVER CLIPS	6 PC	5.50 <i>all</i>	33.00
10.	REAR BUMPER DAMPER	1 PC	85.20 <i>2 nu</i>	85.20
11.	REAR BUMPER REINFORCEMENT	1 PC	795.20 <i>2 nu</i>	795.20
12.	REAR BUMPER INSULATION LH	1 PC	68.10 <i>2 nu</i>	68.10
13.	REAR BUMPER INSULATION RH	1 PC	68.10 <i>2 nu</i>	68.10
14.	REAR END PANEL TOP GARNISH	1 PC	158.70 <i>X</i>	158.70
15.	REAR BOOT - REPAIR	1 PC		
16.	REAR END PANEL - REPAIR	1 PC		
17.	REAR BUMPER INNER GUIDE	1 PC	95.86 <i>2 nu</i>	95.86
LIST TOTAL S\$				4,399.31
5% DISCOUNT S\$				-219.97
				4,179.34

LABOUR :

 TO REPAIR REAR END PANEL & REAR BOOT. TO
 REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS &
 REALIGN ALL AFFECTED AREAS.

TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS.

 TO REMOVE & REFIX REAR BOOT COMPARTMENT
 TRIMS, COVERINGS & OTHER ATTACHMENT PARTS.

 TO REMOVE & REFIX REVERSE SENSOR & CHECK
 WIRING.

LABOUR TOTAL S\$

 450 ~~550.00~~

 600 ~~700.00~~

 60 ~~80.00~~

 60 ~~80.00~~
1,410.00

Estimate

20/02/2018

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)
16, RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581.

Attention :- XA013

Page # :- 1 130816
Veh # :- SKB9800H
Veh Model :- BMW 523I
Estimate# :- CK417078
Claim # :-
ACC. Date :- 15/02/18
Terms :- C.O.D Days
Remarks :-

Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: **(65) 6476 3333**
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: **(65) 6272 3892**
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 5,589.34

GST @ 7 % 391.25

AMOUNT DUE S\$ 5,980.59

Diary

Customer's Signature/Co. Stamp **MOVA AUTOMOTIVE PTE LTD**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Paul
Hp 90010068
4-5 days
P/P
28/02/18 @ 1440
Rezy b4 part
6/3/18

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/08/08/94
 Singapore 159722

Tel: (65) 6272 3892
 Fax: (65) 6270 8314

Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

20/02/2018

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)
16, RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581.

Page # :- 1

Veh # :- SKB9800H

Veh Model :- BMW 523i

Estimate# :- CK417078

Claim # :-

ACC. Date :- 15/02/18

Terms :- C.O.D Days

Remarks :-

CK130816

Attention :- XA013

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	REAR BOOT LOGO	1 PC	82.60 <i>NEC</i>	82.60
2.	REAR BOOT EMBLEM - 523i	1 PC	85.30 <i>NEC</i>	85.30
3.	REAR BOOT LOCK	1 PC	256.80 X	256.80
4.	REAR BUMPER	1 PC	1,598.20 <i>NEC</i>	1,598.20
5.	REAR BUMPER SENSOR (CENTER)	2 PC	275.65 <i>? NEC</i>	551.30
6.	REAR BUMPER REFLECTOR LH	1 PC	65.20 X	65.20
7.	REAR BUMPER INNER GUIDE LH & RH	2 PC	178.55 X	357.10
8.	REAR BUMPER UNDER COVER	1 PC	98.60 <i>CRA</i>	98.60
9.	REAR BUMPER UNDER COVER CLIPS	6 PC	5.50 <i>NEC</i>	33.00
10.	REAR BUMPER DAMPER	1 PC	85.20 <i>? NEC</i>	85.20
11.	REAR BUMPER REINFORCEMENT	1 PC	795.20 <i>? NEC</i>	795.20
12.	REAR BUMPER INSULATION LH	1 PC	68.10 X	68.10
13.	REAR BUMPER INSULATION RH	1 PC	68.10 X	68.10
14.	REAR END PANEL TOP GARNISH	1 PC	158.70 X	158.70
15.	REAR BOOT - REPAIR	1 PC		
16.	REAR END PANEL - REPAIR	1 PC		
17.	REAR BUMPER INNER GUIDE	1 PC	95.96 <i>? CRA</i>	95.86
LIST TOTAL S\$				4,399.31
5% DISCOUNT S\$				-219.97
<i>* Supplementary</i>				
<i>1. Rear Bumper under cover RH (CR) / 108.60</i>				108.60
				4,179.34
LABOUR :				
TO REPAIR REAR END PANEL & REAR BOOT. TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS & REALIGN ALL AFFECTED AREAS.				
TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS.				
TO REMOVE & REFIX REAR BOOT COMPARTMENT TRIMS, COVERINGS & OTHER ATTACHMENT PARTS.				
TO REMOVE & REFIX REVERSE SENSOR & CHECK WIRING.				
LABOUR TOTAL S\$				1,410.00

PARTS (LIST): \$3533.86 - 5%
= \$3357.16

LABOUR: \$1170.00

Total: \$4527.16

5 days.

450 558.00

600 798.00

60 88.00

60 88.00

Main Office:
Mova Building
No. 22, Jalan Klang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1006,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 8892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

20/02/2018

MSIG INSURANCE (S) PTE LTD (SGX CENTRE)
16, RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581.

Page # :- 1 130816

Veh # :- SKB9800H

Veh Model :- BMW 523i

Estimate# :- CK417078

Claim # :-

ACC. Date :- 15/02/18

Terms :- C.O.D Days

Remarks :-

Attention :- XA013

No.	Description	Qty	U.Price	Amounts S\$
-----	-------------	-----	---------	-------------

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 5,589.34

GST @ 7 % 391.25

AMOUNT DUE S\$ 5,980.59

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary Item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Handwritten:
Rafael
Hp 90010068
4-5 days
P/P
28/02/18 @ 1440
Razzy by paint

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Feb 2018		21 Feb 2018 15:03 Edit Adj Rpt	S\$4,527.17 Edit Estimates	S\$4,527.17 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	CHUA GEK KEOW , ID: S6923532H								
Main Claimant:	ONG KONG WEE , ID: S7711790C								
Vehicle Reg. No.:	SKB9800H	Date of Loss:	15/02/2018 08:00 - :59 [80 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 550142	Policy/Cover Note No.:	A29071318QMX (Comprehensive) Coverage: 03/02/2018 - 17/03/2019						
Vehicle Reg. No. (Insured):	SLU3644U	Policy No. (Claimant):							
		Excess:							
Repairer:	Mova Automotive Pte Ltd (HQ) No. 22 Jalan Kilang, #07-01, Mova Building, 159419 Bukit Merah - Tel:								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Jasmine Lok Kheng Kwei - 6594 2550]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Imm.Advice due 22/02/2018]								
Driver/Custodian (Insured):	LEE PEI SAN (), NRIC: S9333795F, Tel: +6597242225								
Adj Asg. Remarks:	ON WP								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKB9800H (550142)**

[SLU3644U]

TP

ONG KONG WEE

Feb 15 2018 8:00AM

[CHUA GEK KEOW]

Mova Automotive Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Assessment Reports			1 per page <input type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/02/18 14:53	Accident Statement <small>From: SC - Reg. No: SLU3644U, Claimant: CHUA GEK KEOW</small>	Load HTM	<input type="checkbox"/>
Photos/Images			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
2	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
3	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
4	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
5	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
6	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
7	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
8	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
9	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
10	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
11	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
12	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
13	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
14	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
15	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
16	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
17	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
18	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
19	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
20	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
21	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
22	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
23	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
24	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
25	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
26	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
27	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
28	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
29	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
30	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
31	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
32	13/07/18 11:50	General View	Load JPG	<input checked="" type="checkbox"/>
33	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
34	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
35	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
62	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
63	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
64	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
65	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
66	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
67	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
68	13/07/18 11:51	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/02/18 14:53	E-FILE REPORT (SKB9800H) From: SC - Reg. No: SLU3644U, Claimant: CHUA GEN KEOW	Load PDF	
2	21/02/18 14:55	TP EST BILL & ACCDT REPORT	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/07/18 11:38	SUPPLEMENTARY PART	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No. 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003326/R1TBQ2

Date: 17/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: A29071318QMX

Claimant Vehicle No: SKB9800H

Insured Vehicle No: SLU3644U

Date of Loss: 15/02/2018

Nature of Claim: TP

Claim No: 550142

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKB9800H

Make & Model: BMW 523i, 2.5 (A)

Reg. Date: 16/05/2011 (Man. Year: 2011)

Colour: Grey

Engine Capacity: 2497 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

Engine No: 02867684N52B25AF

Chassis No: WBAFP320X0C864098

Odometer: 101213 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size: 225/55 R17

Front Left Side: Bridgestone 6 mm

Rear Left Side: Bridgestone 6 mm

Front Right Side: Bridgestone 6 mm

Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,282.51	3,357.17	925.34	21.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,410.00	1,170.00	240.00	17.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,692.51	4,527.17	1,165.34	20.47
+ GST 7.00/7.00% (S\$)	398.48	316.90	81.58	20.47
Nett Amount (S\$)	6,090.99	4,844.07	1,246.92	20.47

INSPECTION

Date of Assignment: 21/02/2018

Date Inspected: 28/02/2018 Inspected At:

Repairer :Mova Automotive Pte Ltd (HQ)
BLK 1008 BUKIT MERAH LANE 3 #01-
04/06/08
SINGAPORE 159722

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jul 2018)
Parts:	143	BMW 523i 2.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB9800H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LOGO	Necessary	82.60 FL	*82.60 FL
2	1		*REAR BOOT EMBLEM -523i	Necessary	85.30 FL	*85.30 FL
3	1		*REAR BOOT LOCK	Serviceable	256.85 FL	*- FL
4	1		*REAR BUMPER	Deformed	1,598.20 FL	*1,598.20 FL
5	2		*REAR BUMPER SENSOR (CENTER)	Not Working	551.30 FL	*551.30 FL
6	1		*REAR BUMPER REFLECTOR LH	Serviceable	65.20 FL	*- FL
7	2		*REAR BUMPER INNER GUIDE LH & RH	Serviceable	357.10 FL	*- FL
8	1		*REAR BUMPER UNDER COVER	Cracked	98.60 FL	*98.60 FL
9	6		*REAR BUMPER UNDER COVER CLIPS	Necessary	33.00 FL	*33.00 FL
10	1		*REAR BUMPER DAMPER	Bent	85.20 FL	*85.20 FL
11	1		*REAR BUMPER REINFORCEMENT	Bent	795.20 FL	*795.20 FL
12	1		*REAR BUMPER INSULATION LH	Serviceable	68.10 FL	*- FL
13	1		*REAR BUMPER INSULATION RH	Serviceable	68.10 FL	*- FL
14	1		*REAR END PANEL TOP GARNISH	Serviceable	158.70 FL	*- FL
15	1		*REAR BOOT (NPA)	Repair	0.00 FL	*- FL
16	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL
17	1		*REAR BUMPER INNER GUIDE	Cracked	95.86 FL	*95.86 FL
18	1		*REAR BUMPER UNDERCOVER RH	Cracked	108.60 FL	*108.60 FL

F=Franchise part, L=ListItemDisc.

Sub Total (\$\$)	4,507.91	3,533.86
- List Item Discount on L Items 5.00/5.00% (\$\$)	225.40	176.69
Total Parts (\$\$)	4,282.51	3,357.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR REAR END PANEL & REAR BOOT .TO REMOVE & REPLACE ALL ACCIDENT DAMAGED PARTS & REALIGN ALL AFFECTED AREAS	New	550.00	450.00
2	TO SPRAY PAINT ON ACCIDENT AFFECTED AREAS	New	700.00	600.00
3	TO REMOVE & REFIX REAR BOOT COMPARTMENT TRIMS ,COVERINGS & OTHER ATTACHMENT PARTS	New	80.00	60.00
4	TO REMOVE & REFIX REVERSE SENSOR & CHECK WIRING	New	80.00	60.00
Gross Labour Cost (S\$)			1,410.00	1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >