COMFORT DELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHB 4037M

MAKE

DATE 21/2/2018 12:58

ARM

DEL	: HYUNDAI SONATA		mang		PP
Qty	Parts Description/ Labour	Type	Unit Price		nount
	Rear Bumper X Agray			\$	578.40
	Rear Bumper Clip 🗶			\$	22.00
	SUB TOTAL			\$	600.40
	LESS 20%			\$	120.08
	DISCOUNTED TOTAL			\$	480.32
	DISCOUNTED TOTAL			1.0	400.32
	Rear Bumper Rubber Mat 😾			\$	50.00
				\$	50.00
	Labour Charge				100
	Panel Beating			\$	350.00
	Spray Painting Charge			\$	200.00
	Wiring Charge			\$	50.00
	Remove/Refix Reverse Sensor			\$	120.00
	TOTAL LABOUR			\$	720.00
	ESTIMATE TOTAL			\$ 1	,250.32
	, , ,				
	Ke Garllay				
	No. 1				
	2 ly.				
	1/1 2 2/2/-3 / 033 -				
	2 kg1.				
	00	LK	K Auto Consultante la		
	11		K Auto Consultants hence Repairer of the following	en a	
	111 Near 10 Ct	- 10	1 Courvey Defore/affor cores, a	-1-41	
	2 Ry. Prp Ather Ryer p U. (UH Rm)	7.10	uispidy damaged part/el dust-		
		• Th	rd party survey is on a "Withou	mation	
	(/H Rw)				
	(0)	* Su	Diementary cam/c must		ind
			A STATE OF THE STATE OF THE PARTY OF THE PAR	strance Co	mpany
			owledged by Repairer		
	This is an initial estimate based on a visual inspection of the	Signa			-

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.