

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05730

Vehicle Insured : SGY69M  
Accident Date : 14-Feb-2018

Date : 21-Feb-2018

Our Ref : 218036 (AXA) / CHAN

PAGE : 1

MS HO FUI FAH  
BLK 353 ANG MO KIO STREET 32  
#26-141  
Singapore 560353

*Not Authorised*  
*1-B1*  
*Resurvey Blk painting*

*3 days*

## ESTIMATED COST OF REPAIR FOR HONDA JAZZ 1.5A SLA708U

1 pc Rear bumper fascia  
1 pc Rear o/s bumper side retainer  
1 pc Rear o/s fender  
1 pc Rear o/s sport rim

*Painted* 492.60 ✓  
*na* 11.50 ✓  
*R* 610.90 X  
*Ref/Rep* 819.60 ✓

1,934.60

Less 20% : 386.92

1 pc Rear o/s tyre

1,547.68  
*See* 280.00 *sn X*

To check and adjust wheel alignment

65.00 *60*

To putty and spray replaced parts

800.00 *420*

To remove, cut-out damaged parts,  
panel beating, welding, align,  
refix and to renew above parts

900.00 *300*

To renew tyre & rim

80.00 *20*

Total : S\$ 3,672.68

Singapore Dollars Three Thousand Six Hundred  
and Seventy Two and Cents Sixty Eight Only

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: