

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Self Utk for Insurance

Customer : LONPAC INSURANCE BHD
 100 BEACH ROAD
 #19-00 SHAW TOWERS
 SINGAPORE 189702

Registration No : SLV7805R
 Chassis No : MRHFC5650HT000778
 Model : CMIC 1.6 VTI YM2017
 Owner's Name : BERNARD ONG TSAO WEY
 Ins Policy No. :
 Date of Accident : 18/2/2018

Document No. : SQT18000732 *Settlement* Page 1
 Date : 20. Feb 2018
 Customer No. : WZL009
 Svc Advisor : LIEW THYE WEI
 Engine No : R16B22001203
 Date | Time : 20. Feb 2018 8:44:06 AM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: BERNARD ONG TSAO WEY OWNER INSURER: TOKIO MARINE ACC DATE: 18/02/18 SURVEYED BY: DATE: REF NO: TP INSURER: LONPAC INSURANCE BHD TP VEH: GZ8573R						
71500-TEC-Q00ZZ	FACE ASSYRR.BUMPER <i>- RL</i>	1	617.20	25	462.90	32.40	495.30
71502-TEX-Y00	GARNISHRR.BUMPER LOWER <i>?</i>	1	35.30	25	26.47	1.85	28.32
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER <i>?</i>	1	160.00	25	120.00	8.40	128.40
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE <i>=</i>	1	2.20	25	1.65	0.12	1.77
71555-TBA-A00	BRACKETL.RR.BUMPER SIDE <i>=</i>	1	2.20	25	1.65	0.12	1.77
71593-TEA-T01	SPACERR.RR.BUMPER SIDE <i>=</i>	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE <i>=</i>	1	11.50	25	8.62	0.60	9.22
71508-TEA-T00	GARNISHL.RR.BUMPER SIDE <i>- SCR</i>	1	7.60	25	5.70	0.40	6.10
33555-TEA-T01	REFLECTOR ASSYL.RR. <i>X NA</i>	1	7.00	25	5.25	0.37	5.62
91505-TM8-003	CLIPBUMPER <i>- MCL</i>	7	2.00	25	10.50	0.74	11.24
75722-TBA-A00	EMBLEM SETRR. <i>- MCL</i>	1	11.50	25	8.62	0.60	9.22
75725-TEA-T01	EMBLEMRR. <i>- MCL</i>	1	10.60	25	7.95	0.56	8.51
33550-TEA-T01	TAILLIGHT ASSYL. <i>?</i>	1	273.10	25	204.82	14.34	219.16
39680-TEX-Y41ZT	SENSOR ASSYPARKING <i>- DM</i>	1	79.80	25	59.85	4.19	64.04
32131-TEA-R00	SUB CORDRR.BUMPER CORNER SENS <i>- MCL</i>	1	27.20	25	20.40	1.43	21.83
Sum Item					953.00	66.72	1,019.72
BOSUN	SUNDRIES <i>- MCL</i>	1	30.00		30.00	2.10	32.10
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00		80.00	5.60	85.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	120.00		120.00	8.40	128.40



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : LONPAC INSURANCE BHD
 100 BEACH ROAD
 #19-00 SHAW TOWERS
 SINGAPORE 189702

Registration No : SLV7805R
 Chassis No : MRHFC5650HT000778
 Model : CIVIC 1.6 VTI YM2017
 Owner's Name : BERNARD ONG TSAO WEY
 Ins Policy No. :
 Date of Accident : 18/2/2018

Document No. : SQT18000732 Page 2
 Date : 20. Feb 2018
 Customer No. : WZL009
 Svc Advisor : LIEW THYE WEI
 Engine No : R16B22001203
 Date | Time : 20. Feb 2018 8:44:06 AM
 Surveyor Name :
 Survey Date :
 Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	250.00	/	250.00	17.50	267.50
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS. (560)	1	1300.00	1120	1300.00	91.00	1391.00
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P) (450)	1	1500.00	1000	1500.00	105.00	1605.00
Sum Labor					3280.00	229.60	3,509.60

Survey By

Emo Qian - 8288 0282

Date & Time

22/2/18

Excess

Status

Signature

4 Days.

Total Amount 4,233.00 296.32 4,529.32

Total (Inclusive of GST) 4,529.32

before paint photos.

- All Consultants hence notify
 • Repaired in the following:
- To be surveyed before/after spray painting
 - To display damaged part(s) during resurvey
 - Final prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 20/2/2018 9:28:29 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)