

ASS. REC. BY:

ASS. REC. BY:

REF:

CS/MSG/18003342/Upd

Special Instruction:

Surveyor: Marcin

ASSIGNMENT (Office)

From (Person): Pearllyn Kory of MSG

Date/Time: 20/2/18

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SH 57C

Insured: _____

at Workshop m/s KIM Chua

Tel: _____

67465405/67417244

of Kahri Brucit

Policy No: 28809291 QMY

Claim No: _____

550037

Sum Insured: _____

Excess: _____

500

Make of Veh: _____

(Client's Record)

D.O.A. _____

13/2/18

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement: _____

Date/Time: _____

Person Contacted: _____

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	<u>SH 57C</u> x <u>To change to cost price.</u>
<u>20/02/18</u>	<u>Sent preli thru merimen</u>
	<u>Mandate approve & inform repairer authorize repair & excess</u>

REF:

M916

ASSIGNMENT

Form:

Date:

Estimated Cost:

☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No

SLH57C

at Workshop no

Kim Chwee Auto Pte Ltd

of

Insured:

Policy No

Claims No

Sum Insured

Excess:

500

(Client's Record)

To change to cost

Make of Ven:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

☒	☐
N/S	O/S
☐	☐

Bal. or Market Value:

706.

IDAC Accident Report

Consistent? Yes or No

OK / PR Seen:

Consistent? Yes or No

Est. Repairs

5

days

Res:

Yes or No

Lump Sum:

131

%

3 Val:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No: SLH57C Yr Regn: 1 12

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CAI

Make

Mer Benz C180 cc 1597

Colour

Black

A/C

Insured / Std / NI / NA

Sp Reading

71844

T/Radio

Insured / Std / NI / NA

Eng No

Chassis

WDD2040452A639974

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Burn / STD A/Rim or

Tyre Size

F:

225/40ZR18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal

mm

R/Bal

mm

L/Bal

mm

L/Bal

mm

D.O.A.

13/2/18

D.O.I.

21/2/18

Survey held at:

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision

24/4/18 Confirmed f.no/ fty 10400.90 with Alen.

Ref: 84908.36, 321

RECEIVED 26 APR 2018

Date/Time File Pass to?

☐

Prel. Report

By typist

☒

Final Report

Date/Time File Return to?

By

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee

Transporter

Add Fee:

☐

Site Insp

\$

☐

Interview

\$

☐

Technical

\$

☐

Workshop

\$

Report Format:

OD

Lump Sum / I.B.I. / S

10400.90

Photo

Notes

TOTAL

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Feb 2018		20 Feb 2018 16:27 Edit Adj Rpt				Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	SARANPAL SINGH, ID: S8438086E, Tel: +6591811470, Email: NOEMAIL		
Vehicle Reg. No.:	SLH57C	Date of Loss:	13/02/2018 18:00 - :59
Claim Type:	OD / 550037	Policy/Cover Note No.:	28809291QMY (Comprehensive) Coverage: 05/01/2018 - 04/01/2019
		Excess:	S\$500.00
Repairer:	Kim Chwee Auto Pte Ltd (HQ) 1 Kaki Bukit Avenue 6 #01-48, AutoBay@Kaki Bukit, 417883 Eunos - Tel: 67465405/67417244		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pearllyn Kang Yen Lin - 6594 2588]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Imm.Advice due 21/02/2018]		
Driver/Custodian:	SARANPAL SINGH (33 / Male), NRIC: S8438086E, Tel: +6591811470		
Adj Asg. Remarks:	Please survey and revert. To change to cost price. Thank you.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- MSIG_PKYL (20/02/2018): Survey arrangement



ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pearlyn Kang Yen Lin

Date: 22 Feb 2018

Preliminary Advice

Vehicle No	: SLH57C	Accident Date	: 13/02/2018
Make	: MERCEDES-BENZ C180	Policy No.	: 28809291QMY
Assignment Date	: 20/02/2018	Excess	: S\$500.00
Date of Inspection	: 21/02/2018	Est. Duration of Repair	: 5.00
Inspection At	: KIM CHWEE AUTO PTE LTD (HQ) 1 KAKI BUKIT AVENUE 6 #01-48, AUTOBAY@KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,309.26
Revised Amount	:S\$	8,537.90
Check Items (Estimated)	:S\$	2,947.00
Total	:S\$	11,484.90

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	70,000.00
COE / PARF Rebate	:S\$	41,875.00
Salvage Value	:S\$	
Margin for Repair	:S\$	28,125.00

Remarks

- (X) The vehicle is economical for repair.
- () The above survey was conducted on a 'without prejudice' basis.

Print Received Message

This mail is associated with :

***SLH57C (550037)**

OD

Feb 13 2018 6:00PM

[SARANPAL SINGH]

Kim Chwee Auto Pte Ltd

From MSIG Insurance (Singapore) Pte. Ltd. (MSIG_SG), sent on 22/02/2018 14:31 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$8537.90) - SLH57C - Claim Handler: Pearllyn Kang Yen Lin

Approved:8537.90:CHECK ITEMS TO BE VERIFIED AND CONFIRMED.

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Thursday, February 22, 2018 3:26 PM
To: 'Nancy Lam'
Cc: SUR
Subject: SLH 57C MSIG OD DOA: 12.02.2018

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLH 57C (excess \$500/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/02/2018 14:33
Date Of Accident	13/02/2018 18:30
Exact Location Of Accident	ECP >CHANGI AFTER TANJONG KATONG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLH57C
Insured/Policyholder	
Name Of Registered Owner	SARANPAL SINGH
NRIC No	S8438086E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91811470
Alternative Phone No	OTHERS-91811470

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	C 180 KOMPRESSOR
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A28809291 QMY
Cover Note Number	

Driver

Name of Driver	SARANPAL SINGH
NRIC No	S8438086E
Date Of Birth	20/11/1984
Occupation	INDOOR
Date Of Driving Pass	20/07/2006
Driving Experience	11 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91811470
Fax Number	
Contact Number	OTHERS-91811470
Email Address	NOEMAIL

Address	BLK 618D PUNGGOL DRIVE #02-733
Postcode	824618
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : - GENDER: : MALE
Passenger 2	NAME: : - GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO BELOW STATEMENT/SKETCH PLAN:

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLP853D
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SJR144E

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address


Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 13/02/2012 at about 17:30pm. I was
 travelling along ECF Towards Changi After.
 Tanjong Katong. I hit the front vehicle.
 I was involved in a three vehicles crash.
 Collision.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:

IDAC KAKI BURIT (VAC)
 23 KAKI BURIT AVE 4
 Singapore 415933
 Reporting Centre Personnel's Signature
 Name: Fax: 67492305
 MRIC/FIN No: Email: vic@idacsingnet.com.sg

15 FEB 2010

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	8086E
Vehicle Details	
Vehicle No.:	SLH57C
Vehicle to be Exported:	No
Intended De-registration Date:	21 Feb 2018
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	C 180 KOMPRESSOR
Primary Colour:	Black
Manufacturing Year:	2011
Engine No.:	27191031350255
Chassis No.:	WDD2040452A639974
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$31,076.00
Original Registration Date:	05 Jan 2012
First Registration Date:	05 Jan 2012
Transfer Count:	1
Actual ARF Paid:	\$31,076.00 15338
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	04 Jan 2022
PARF Rebate Amount:	\$20,199.00
Intended COE Rebate Details	
COE Expiry Date:	04 Jan 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$55,997.00
COE Rebate Amount:	\$21,676.00
Total Rebate Amount:	\$41,875.00

The information contained herein is correct as at 21 Feb 2018

OK

SGCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

GAME-CHANGER
TOMORROW



Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

Post an Ad

Advertiser Login

Ways of Selling

Mazda RX8 1.3A, Reg Date Of 24 Feb 2009, OMV Of \$30,27



Beautiful RX8 For Sale! Pristine Condition And Well Maintained By Monster Garage Direct Owner - StatAd



click here to view
our **PRISTINE USED CARS**
at **GREAT PRICES**

Browse by Category

Mercedes-Benz c180

Back (1 2 3) Next »

Sort by Date Posted

20 results/page

54 vehicles

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Mercedes-Benz c180		Any	Any	2012	Any	Any	Any	Available
	Mercedes-Benz C-Class C180K		\$74,800	\$14,820 /yr	02-Mar-2012	1,597 cc	80,000 km	Luxury	Available
C&C Unit. Showroom Condition. Low Maintenance And Powerful And Fuel Efficient. Reverse Camera. Flexible Loan Available. Small Yet Equipped With A Boot Enough To Stow Again One Large Golf Bag And Still...									
Posted: 21-Feb-2018 Tags: 2012 Mercedes-Benz C180K, Mercedes-Benz C180K, Mercedes-Benz, C180K, Used Mercedes-Benz									
	Mercedes-Benz C-Class C180K Avantgarde		\$73,800	\$14,370 /yr	22-Mar-2012	1,597 cc	70,000 km	Luxury	Available
C&C Unit. Full Servicing By Agent. Road Tax Till Sep/18. Comes With GPS. Powerful Yet Fuel Efficient. Well Maintained. Immaculate Interior Condition. Call Us For More Information Now.									
Auto Zoom Enterprise Pte Ltd									
Posted: 21-Feb-2018 Tags: 2012 Mercedes-Benz C180K, Mercedes-Benz C180K, Mercedes-Benz, C180K, Used Mercedes-Benz									
	Mercedes-Benz C-Class C180 CGI Avantgarde		\$75,800	\$14,430 /yr	17-Jan-2012	1,796 cc	-	Luxury	Available
CNY PROMO! 2.28% Interest! Free STA Evaluation! Free 1 Year Warranty! Limited Time Only! Rare! One Of The Very Few 1.8L C180 Facelifted Model! 7G-Tronic CGI Avantgarde Model! Come View Before It's Gon...									
ST Carz Pte Ltd									
Posted: 21-Feb-2018 Tags: 2012 Mercedes-Benz C180, Mercedes-Benz C180, Mercedes-Benz, C180, Used Mercedes-Benz									
	Mercedes-Benz C-Class C180K Avantgarde		\$78,500	\$14,970 /yr	16-May-2012	1,597 cc	91,200 km	Luxury	Available
1 Careful Owner. Excellent Condition In Town! Guaranteed Accident Free. Cycle And Carriage Unit. 100% Quality Buy! Vehicle In Showroom Condition By Professional Groomer. Elegant Silver With Black Leat...									
Posted: 21-Feb-2018 Tags: 2012 Mercedes-Benz C180K, Mercedes-Benz C180K, Mercedes-Benz, C180K, Used Mercedes-Benz									
Car Buying Car Selling Car Aftermarket Car Ownership On The Move Lifestyle Buy Tyres Online! Latest Special Offers from Tyropac!									
	Mercedes-Benz C-Class C180K		\$79,800	\$15,280 /yr	16-May-2012	1,597 cc	119,000 km	Luxury	Available
Sure Win CNY Ang Bao Draw! Full Serviced By C&C. Well Maintained And Serviced Done Regularly. Lowest Depreciation In Market. 1 Owner Only, Accident Free. Comes With Exclusive Polishing And Cleaning Pa...									
Euro Performance Asia Pte Ltd									
Posted: 25-Feb-2018 Tags: 2012 Mercedes-Benz C180K, Mercedes-Benz C180K, Mercedes-Benz, C180K, Used Mercedes-Benz									
	Mercedes-Benz C-Class C180K Avantgarde		\$74,800	\$14,040 /yr	10-May-2012	1,597 cc	91,000 km	Luxury	Available
Supercharged Kompressor Engine That Gave You Enormous Power, More Quiet Smooth And Help Fuel Efficiency, Meticulously Taken Care By Owner. Car In Tip Top Condition. STA And Vicom Evaluation Welcome, E...									
Shuang Hup Credit									
Posted: 20-Feb-2018 Tags: 2012 Mercedes-Benz C180K, Mercedes-Benz C180K, Mercedes-Benz, C180K, Used Mercedes-Benz									
Compare									

http://www.sgcarmart.com/used_cars/listing.php?MOD=Mercedes-Benz+c180&PRC=0&DEP=0&RGD... 21-Feb-18

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262-D

PAGE 1 OF 3

Estimate : 20149

Date : 20.02.2018

Vehicle Num : SLH 57C

Make/Model : MERCEDES C180

Chassis/Engine no :

Accident Date : 13.02.2018

Claim No : 0218-20149

Reference :

Policy No :

p/p #10400.90

not refund
nku

Tel: 62563561

Express 8500

th-phs. kshu poly

5 days.
21/2/18

Qty	Particular	Amount S\$
<u>List Item :</u>		
1 pc	Front bonnet 1020	✓ \$ Suc 1,044.70 1020
2 pc	Front bonnet hinges @ 53.00	- \$ bel 106.00
2 pc	Front bonnet absorber holder @ 63.00	\$ 11 126.00 X
1 pc	Front bonnet insulator 120	- \$ 22 123.90 120
1 pc	Front bonnet seal	- \$ 22 14.00
2 pc	Front bonnet stopper @ 13.00	\$ 11 26.00 X
2 pc	Front bonnet top lock @ 19.00	- \$ 741 38.00
1 pc	Front bonnet lock centre catch opener	- \$ 741 37.00
1 pc	Front grille with logo	- \$ 12 325.00
1 pc	Front bonnet logo	- \$ 12 42.00
2 pc	Front bonnet logo clip @ 4.00	\$ 22 8.00
1 pc	Front top panel	- \$ bel. 68.00
1 pc	Front brace panel	- \$ bel 39.00
2 pc	Front bonnet bottom lock @ 34.00	- \$ 741 68.00
1 pc	Front bonnet lock cable	\$ 11 35.00 X
2 pc	Front headlamp @ 540.00	n/c tra. o/s 2000 1,080.00 ✓
2 pc	Front headlamp panel @ 128.00	- \$ Suc 256.00
2 pc	Front headlamp side fender bracket @ 18.00	\$ 11 36.00 X
2 pc	Front fender @ 450.00	\$ 22 900.00 X
2 pc	Front fender under shield @ 60.00	\$ 11 120.00 X
2 pc	Front fender chrome moulding @ 22.00	- \$ 22 44.00
2 pc	Front fender blue efficiency emblem @ 38.00	- \$ 22 76.00
1 pc	Front number plate base	- \$ 70.1 85.00
1 pc	Front bumper	- \$ 715 690.00
1 pc	Front bumper top cover	- \$ 70.1 28.00
2 pc	Front bumper chrome moulding @ 48.00	- \$ 22 96.00
2 pc	Front bumper side retainer @ 15.00	15 - \$ o/s cm 30.00 120
2 pc	Front bumper corner inner parts @ 45.00	x \$ 25 90.00 X
		\$ 5,631.60

4255

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

PAGE 2 OF 3

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262-D

Estimate : 20149

Date : 20.02.2018

Vehicle Num : SLH 57C

Make/Model : MERCEDES C180

Chassis/Engine no :

Accident Date : 13.02.2018

Claim No : 0218-20149

Reference :

Policy No :

Qty	Particular	Amount S\$
<u>List Item :</u>		
2 pc	Front bumper centre retainer @ 20.00	1 \$ one 40.00 ✓
2 pc	Fog lamp (LED) @ 280.00	2 \$ 280.00 ✓
2 pc	Fog lamp outer corner @ 49.00 chrome	49 - \$ 49.00 98.00 2 pc ✓
1 pc	Front bumper sponge	1 \$ 55.00 ✓
1 pc	Front bumper air grille	1 \$ 72.00 ✓
1 pc	Front bumper reinforment	1 \$ 185.00 ✓
2 pc	Front bumper reinforment bracket @ 140.00	2 \$ 280.00 ✓
1 pc	Aircon condenser	1 \$ 680.00 ✓
2 pc	Aircon condenser cowling @ 32.00	2 \$ 64.00 1 pc ✓
1 pc	Power steering cooling pipe	1 \$ 185.00 ✓
1 pc	Inter cooler	1 \$ 650.00 ✓
1 pc	Inter cooler cowling	1 \$ 90.00 ✓
1 pc	Radiator assy	1 \$ 455.00 ✓
1 pc	Radiator fan assy	1 \$ 640.00 ✓
1 pc	Front top panel centre platis bracket	1 \$ 15.00 ✓
1 pc	Front top panel cover	1 \$ 68.00 ✓
1 pc	air duct	1 \$ 48.00 ✓
2 pc	Front windscreen glass side moulding @ 180.00	2 \$ 360.00 ✓
List Item Total :		\$ 10,176.60
Discount 10 % :		\$ 1,017.66
Mark up		\$ 1,194.26

P- 7519
plus 102
827090
S.N - 40
labor - 2090
TOTAL 810400.90

KIM CHWEE AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

PAGE 3 OF 3

Singapore 417883

Tel No: 67452063 / 67467158 Fax No: 67458520

Tax Reg No: 200006262-D

Estimate : 20149

Date : 20.02.2018

Vehicle Num : SLH 57C

Make/Model : MERCEDES C180

Chassis/Engine no :

Accident Date : 13.02.2018

Claim No : 0218-20149

Reference :

Policy No :

Qty	Particular	Amount S\$
-----	------------	------------

Special Nett Item :

1 set Front bonnet insulator clip
2 set Front fender inner shield clip @ 100.00
1 pc Front number plate
Special Nett Total

\$	11	50.00	✓
\$	17	200.00	✓
\$	cm	45.00	40
\$		295.00	40

Labour Charge :

To check wiring
Towing charge
Remove, refix & renew aircon condensor & refill aircon gas
Remove and renew radiator
Labour charge knock dents on front damage portion cut welding & renew parts
To spray painting and etc
Labour Charge Total :

\$		80.00	20
\$		120.00	✓
\$		200.00	100
\$	17	120.00	✓
\$		1,500.00	850
\$		1,800.00	1000
\$		3,820.00	

2090

E & O . E

Total Amount : \$ 15309.26

KIM CHWEE AUTO PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

亞平拖車服務
PENG TOWING SERVICES
BUSINESS REG. NO.: 53266267M
HP: 9187 9890



Messrs

Cash

CASH SALE No. 9888

Date:

13/2/18

車牌 Vehicle No. SLH 57C

車型 Model

C180

地點 Destination

ECR - Accident King Dolly

時間 Time

19.40 h

銀額 Amount \$

120/2

經手人 Signature



明義汽車私人有限公司

MIN GHEE AUTO PTE. LTD.

Head Office : 8, Jalan Lambah Kallang, #01-01 Min Ghee Building

Singapore 339564.

Tel: 6298 3888 Fax: 6297 0853 (Accounts)

E-mail : info@minghee.com

Website : http://www.minghee.com

PRO-FORMA INVOICE

INV NO :

DATE

07/04/2018

PAGE 1

TERM

30 Days Net

SALESMAN

Jing Hai

CUSTOMER REF.

SLH57C

OUR REF.

55449

CO REG NO. 198905613E

GST REG NO. M2-P080482-5 CO REG. NO.: 198905613E

ACCOUNT NUMBER FASTECH TIME:11:11

FASTECH AUTO PTE LTD

BLK 1, KAKI BUKIT AVE 6, #01-48

AUTOBAY @KAKI BUKIT

SINGAPORE 417883

417883

Telephone No : 67465405

ROUTE

DELIVER TO:
FASTECH AUTO PTE LTD
BLK 1, KAKI BUKIT AVE 6, #01-48
AUTOBAY @KAKI BUKIT
SINGAPORE 417883



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1 MBA204 880 10 57 64	HOOD	0B-7A	1 PC	17020.00	17020.00
2 MBA204 880 07 28	W204 ENGINE HOOD HINGE LH	1A-07B	1 PC	53.00	53.00
3 MBA204 880 08 28	W204 ENGINE HOOD HINGE RH	1A-07B	1 PC	53.00	53.00
4 MBA204 682 06 26	W204 ENGINE HOOD INSULATO	4G-1AA	1 PC	120.00	120.00
5 MBA204 880 02 97	ENGINE HOOD SEAL	1B-02G	1 PC	14.00	14.00
6 MBA212 880 00 60	ENGINE HOOD CATCH	1B-04G	2 PCS	19.00	38.00
7 MBA204 880 00 64	W204 ENGINE HOOD LOCK	1B-03F	1 PC	37.00	37.00
8 MBA204 880 00 23	W204 RADIATOR GRILLE AVAN	6A-7B	1 PC	325.00	325.00
9 MBA204 817 06 16	ENGINE HOOD LOGO	1B-06H	1 PC	42.00	42.00
10 MBA201 997 22 81	GROMMET	1E-12C	2 PCS	4.00	8.00
11 MBA204 620 02 72	STIFFENING	3B-01B	1 PC	39.00	39.00
12 MBA204 880 01 64	RETAINING HOOK	1B-04G	1 PC	34.00	34.00
13 MBA204 880 02 60	LOCK	1E-7C	2 PCS	540.00	1080.00
14 MBA204 820 97 59	HEADLAMP UNIT LH	6BB-2C	1 PC	540.00	540.00
15 MBA204 820 98 59	HEADLIGHT RH	6BB-3C	1 PC	128.00	128.00
16 MBA204 620 11 91	FRAME FOR LIGHT	3B-3B	1 PC	128.00	128.00
17 MBA204 620 12 91	FRAME FOR LIGHT	3B-3B	1 PC	128.00	128.00

3221

GOODS RECEIVED IN GOOD ORDER AND CONDITION

*GOODS SOLD ARE NOT RETURNABLE

*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT LATEST PREVAILING LENDING RATE

*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE

Exclusive Distributor

HDK

100% JAPAN MADE IN JAPAN

Stockists

SIGN & COMPANY'S STAMP

TOTAL

ADD GST

AMOUNT DUE



DATE

ALL CHECKQUES MUST BE MADE PAYABLE TO MIN GHEE AUTO PTE. LTD.

For MIN GHEE AUTO PTE.



明義汽車私人有限公司
MIN GHEE AUTO PTE. LTD.

Head Office : 8, Jalan Lembah Kallang, #01-01 Min Ghee Building
Singapore 339564.

Tel: 6298 3888 Fax: 6297 0603 (Accounts)

E-mail : info@minghee.com
Website : http://www.minghee.com

PRO-FORMA INVOICE

INV NO :

DATE	07/04/2018	PAGE	2
TERM	30 Days Net	SALESMAN	Eng Hai Cho
CUSTOMER REF.	5145 / C	OUR REF.	04449

REG NO. 198905613E

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E

ACCOUNT NUMBER: FASTECH TIME 11:11

FASTECH AUTO PTE LTD

BLK 1, KAKI BUKIT AVE 6, #01-48

AUTOBAY 8KAKI BUKIT

SINGAPORE 417883

417883

Telephone No : 67465405

DELIVER TO:
FASTECH AUTO PTE LTD
BLK 1, KAKI BUKIT AVE 6, #01-48
AUTOBAY 8KAKI BUKIT
SINGAPORE 417883



PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
18 MBZ204 690 39 30	WHEEL HUB	3A-2C	1 PC	60.00	60.00
19 MBZ204 690 31 62	FRT FENDER PROTECTOR LH	1D-01K	1 PC	22.00	22.00
20 MBZ204 690 32 62	FRT FENDER PROTECTOR RH	1D-01K	1 PC	22.00	22.00
21 MBZ204 811 72 20	LOGO	1B-06H	2 PCS	38.00	76.00
22 MBZ204 811 21 78	LICENSE PLATE GRANISH	1B-06J	1 PC	85.00	85.00
23 MBZ204 880 61 47 64 9	MBA204 880 61 47 9999/TR1	4B-1AA	1 PC	690.00	690.00
24 MBZ204 885 04 26 9999	CAP	1E-4C	1 PC	28.00	28.00
25 MBZ204 885 31 21 88a	MOULDING	1E-3K	1 PC	48.00	48.00
26 MBZ204 885 38 21	FRT BUMPER MOULDING LH	1E-3K	1 PC	48.00	48.00
27 MBZ204 881 08 06	MOUNTING RAIL	1E-7C	1 PC	15.00	15.00
28 MBZ204 885 40 65	FRT BUMPER FRAME CTR	1AA-VI	1 PC	44.00	44.00
29 MBZ204 520 07 23	ANTI-NOISE CAPSULE	1D-4II	1 PC	95.00	95.00

GOODS RECEIVED IN GOOD ORDER AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.
*OVERDUE ACCOUNTS SHALL BEAR INTEREST AT UOB'S PREVALING LENDING RATE

*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE

SIGN & COMPANY'S STAMP

Exclusive Distributor

HDK

C.V. JOINT
MADE IN JAPAN

Stockists



TOTAL

SIN

4,454.00

ADD GST

/8

311.78

AMOUNT DUE

SIN

4,765.78

DATE

ALL CHEQUES MUST BE MADE PAYABLE TO MIN GHEE AUTO PTE LTD.

For MIN GHEE AUTO PTE. LTD.



MIN GHEE AUTO PTE. LTD. PRO-FORMA INVOICE

Head Office : 8, Jalan Lembah Kallang, #01-01 Min Ghee Building

Singapore 339564.

Tel: 6298 3888 Fax: 6297 0863 (Accounts)

E-mail : info@minghee.com

Website : http://www.minghee.com

GST REG. NO.: M2-0090482-6 CO REG. NO.: 198905613E CO REG NO. 198905613E

ACCOUNT NUMBER: FASTECH TIME: 14:27

FASTTECH AUTO PTE LTD
BLK 1, KAKI BUKIT AVB 6, #01-48
AUTOBAY @KAKI BUKIT
SINGAPORE 417883

417883

Telephone No : 67465405

DELIVER TO:

FASTTECH AUTO PTE LTD
BLK 1, KAKI BUKIT AVB 6, #01-48
AUTOBAY @KAKI BUKIT
SINGAPORE 417883



INV NO :

DATE	18/04/2018	PAGE	1
TERM	30 Days Net	SALESMAN	Eng Hai Choon
CUSTOMER REF.	SLH5/C	OUR REF.	33687

PART NO.	PARTICULARS	LOC	QUANTITY	UNIT PRICE	AMOUNT
1	MBA204 885 00 65	1AA-7I	1 PC	40.00	40.00
2	MBA204 885 08 21	1E-3K	1 PC	49.00	49.00
3	MBA204 885 00 37	6I-00	1 PC	72.00	72.00
4	MBA204 885 21 23	1AA-1I	1 PC	55.00	55.00
5	MBA207 620 16 00	3B-02D	1 PC	185.00	185.00
6	MBA204 500 06 54	6B-1C	1 PC	680.00	680.00
7	MBA204 505 05 30	1D-4I	1 PC	32.00	32.00
8	MBA204 460 26 24	1C-081	1 PC	185.00	185.00
9	MBA204 500 00 00	6A-5C	1 PC	650.00	650.00
10	MBA204 500 01 55	1D-04K	1 PC	68.00	68.00
11	MBA204 500 43 03	6B-2C	1 PC	455.00	455.00
12	MBA204 906 68 02	6B-2C	1 PC	640.00	640.00
13	MBA204 505 34 30	1A-081	1 PC	90.00	90.00
14	MBA271 090 05 82	1D-07A	1 PC	48.00	48.00
15	MBA204 869 00 14	1B-1H	1 PC	15.00	15.00

GOODS RECEIVED IN GOOD ORDER AND CONDITION.

*GOODS SOLD ARE NOT RETURNABLE.

*LOWER ACCOUNTS SHALL BEAR INTEREST AT UOB'S PREVALING LENDING RATE

*CASH INVOICE MUST BE PAID WITHIN 7 DAYS FROM DATE OF INVOICE

SIGN & COMPANY'S STAMP

Exclusive Distributor

HDK

LOCAL AGENT
MADE IN JAPAN

Stockists



727519

DATE

ALL CHEQUES MUST BE MADE PAYABLE TO MIN GHEE AUTO PTE. LTD.

FOR MIN GHEE AUTO PTE. LTD.

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Feb 2018		20 Feb 2018 16:27 Edit Adj Rpt	\$510,400.90 Edit Estimates	\$510,400.90 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	SARANPAL SINGH, ID: S8438086E, Tel: +6591811470, Email: NOEMAIL								
Vehicle Reg. No.:	SLH57C	Date of Loss:	13/02/2018 18:00 - :59 [73 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 550037	Policy/Cover Note No.:	28809291QMY (Comprehensive) Coverage: 05/01/2018 - 04/01/2019						
		Excess:	\$500.00						
Repairer:	Kim Chwee Auto Pte Ltd (HQ) 1 Kaki Bukit Avenue 6 #01-48, AutoBay@Kaki Bukit, 417883 Eunos - Tel: 67465405/67417244								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Pearllyn Kang Yen Lin - 6594 2588]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 22/03/2018]								
Driver/Custodian:	SARANPAL SINGH (33 / Male), NRIC: S8438086E, Tel: +6591811470								
Adj Asg. Remarks:	Please survey and revert. To change to cost price. Thank you.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- MSIG_SG (25/04/2018): Alert - Adj Mandate Approved (\$510400.90) - SLH57C - Claim Handler: Pearllyn Kan... - MSIG_SG (22/02/2018): Alert - Adj Mandate Approved (\$8537.90) - SLH57C - Claim Handler: Pearllyn Kang... - MSIG_PKYL (20/02/2018): Survey arrangement									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLH57C (550037)

OD

Feb 13 2018 6:00PM

[SARANPAL SINGH]

Kim Chwee Auto Pte Ltd

Upload Documents

Upload Photos

Compose New Letter

View

View in Browser

Assessment Reports

1 per page

No	Finalized On	VAC (Kaki Bukit)		Thumbnail	Print
1	15/02/18 14:43	Accident Statement		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/02/18 11:18	Adjuster Immediate Advice		Load HTM	
2	25/04/18 14:12	Adjuster Immediate Advice		Load HTM	

Photos/Images

3 per page

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	22/02/18 11:23	General View		Load JPG	
2	22/02/18 11:23	General View		Load JPG	
3	22/02/18 11:23	General View		Load JPG	
4	22/02/18 11:23	General View		Load JPG	
5	22/02/18 11:23	General View		Load JPG	
6	22/02/18 11:23	General View		Load JPG	
7	22/02/18 11:23	General View		Load JPG	
8	22/02/18 11:23	General View		Load JPG	
9	22/02/18 11:23	General View		Load JPG	
10	22/02/18 11:23	General View		Load JPG	
11	22/02/18 11:23	General View		Load JPG	
12	22/02/18 11:23	General View		Load JPG	
13	22/02/18 11:23	General View		Load JPG	
14	22/02/18 11:23	General View		Load JPG	
15	22/02/18 11:23	General View		Load JPG	
16	22/02/18 11:23	General View		Load JPG	
17	22/02/18 11:23	General View		Load JPG	
18	22/02/18 11:23	General View		Load JPG	
19	22/02/18 11:23	General View		Load JPG	
20	22/02/18 11:23	General View		Load JPG	
21	22/02/18 11:23	General View		Load JPG	
22	22/02/18 11:23	General View		Load JPG	
23	22/02/18 11:23	General View		Load JPG	
24	22/02/18 11:23	General View		Load JPG	
25	22/02/18 11:23	General View		Load JPG	
26	22/02/18 11:23	General View		Load JPG	
27	22/02/18 11:23	General View		Load JPG	
28	22/02/18 11:23	General View		Load JPG	
29	22/02/18 11:23	General View		Load JPG	
30	22/02/18 11:23	General View		Load JPG	
31	22/02/18 11:23	General View		Load JPG	
32	22/02/18 11:23	General View		Load JPG	
33	22/02/18 11:23	General View		Load JPG	

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
				☒
34	22/02/18 11:23	General View	 Load JPG	☒
35	22/02/18 11:23	General View	 Load JPG	☒
36	22/02/18 11:23	General View	 Load JPG	☒
37	22/02/18 11:23	General View	 Load JPG	☒
38	22/02/18 11:23	General View	 Load JPG	☒
39	22/02/18 11:23	General View	 Load JPG	☒
40	22/02/18 11:23	General View	 Load JPG	☒
41	22/02/18 11:24	General View	 Load JPG	☒
42	22/02/18 11:24	General View	 Load JPG	☒
43	22/02/18 11:24	General View	 Load JPG	☒
44	22/02/18 11:24	General View	 Load JPG	☒
45	22/02/18 11:24	General View	 Load JPG	☒
46	22/02/18 11:24	General View	 Load JPG	☒
47	22/02/18 11:24	General View	 Load JPG	☒
48	22/02/18 11:24	General View	 Load JPG	☒
49	22/02/18 11:24	General View	 Load JPG	☒
50	22/02/18 11:24	General View	 Load JPG	☒
51	22/02/18 11:24	General View	 Load JPG	☒
52	22/02/18 11:24	General View	 Load JPG	☒
53	22/02/18 11:24	General View	 Load JPG	☒
54	22/02/18 11:24	General View	 Load JPG	☒
55	22/02/18 11:24	General View	 Load JPG	☒
56	22/02/18 11:24	General View	 Load JPG	☒
57	22/02/18 11:24	General View	 Load JPG	☒
58	22/02/18 11:24	General View	 Load JPG	☒
59	22/02/18 11:24	General View	 Load JPG	☒
60	22/02/18 11:24	General View	 Load JPG	☒
61	22/02/18 11:24	General View	 Load JPG	☒
62	22/02/18 11:24	General View	 Load JPG	☒
63	22/02/18 11:24	General View	 Load JPG	☒
64	22/02/18 11:24	General View	 Load JPG	☒
65	22/02/18 11:24	General View	 Load JPG	☒
66	22/02/18 11:24	General View	 Load JPG	☒
67	22/02/18 11:24	General View	 Load JPG	☒
68	22/02/18 11:24	General View	 Load JPG	☒
69	22/02/18 11:24	General View	 Load JPG	☒
70	22/02/18 11:24	General View	 Load JPG	☒
71	22/02/18 11:24	General View	 Load JPG	☒
72	22/02/18 11:24	General View	 Load JPG	☒
73	22/02/18 11:24	General View	 Load JPG	☒
74	22/02/18 11:24	General View	 Load JPG	☒
75	22/02/18 11:24	General View	 Load JPG	☒
76	22/02/18 11:24	General View	 Load JPG	☒
77	22/02/18 11:24	General View	 Load JPG	☒
78	22/02/18 11:24	General View	 Load JPG	☒
79	22/02/18 11:24	General View	 Load JPG	☒
80	22/02/18 11:24	General View	 Load JPG	☒
81	22/02/18 11:24	General View	 Load JPG	☒
82	22/02/18 11:24	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
83	22/02/18 11:24	General View	 Load JPG	☒
84	22/02/18 11:24	General View	 Load JPG	☒
85	22/02/18 11:24	General View	 Load JPG	☒
86	22/02/18 11:24	General View	 Load JPG	☒
87	22/02/18 11:24	General View	 Load JPG	☒
88	22/02/18 11:24	General View	 Load JPG	☒
89	22/02/18 11:24	General View	 Load JPG	☒
90	22/02/18 11:24	General View	 Load JPG	☒
91	22/02/18 11:24	General View	 Load JPG	☒
92	22/02/18 11:24	General View	 Load JPG	☒
93	22/02/18 11:24	General View	 Load JPG	☒
94	22/02/18 11:24	General View	 Load JPG	☒
95	22/02/18 11:24	General View	 Load JPG	☒
96	22/02/18 11:24	General View	 Load JPG	☒
97	22/02/18 11:24	General View	 Load JPG	☒
98	22/02/18 11:24	General View	 Load JPG	☒
99	22/02/18 11:24	General View	 Load JPG	☒
100	22/02/18 11:24	General View	 Load JPG	☒
101	22/02/18 11:24	General View	 Load JPG	☒
102	22/02/18 11:24	General View	 Load JPG	☒
103	22/02/18 11:24	General View	 Load JPG	☒
104	22/02/18 11:24	General View	 Load JPG	☒
105	22/02/18 11:24	General View	 Load JPG	☒
106	22/02/18 11:24	General View	 Load JPG	☒
107	22/02/18 11:24	General View	 Load JPG	☒
108	22/02/18 11:24	General View	 Load JPG	☒
109	22/02/18 11:24	General View	 Load JPG	☒
110	22/02/18 11:24	General View	 Load JPG	☒
111	22/02/18 11:24	General View	 Load JPG	☒
112	22/02/18 11:24	General View	 Load JPG	☒
113	22/02/18 11:24	General View	 Load JPG	☒
114	22/02/18 11:24	General View	 Load JPG	☒
115	22/02/18 11:24	General View	 Load JPG	☒
116	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
117	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
118	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
119	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
120	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
121	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
122	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
123	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
124	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
125	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
126	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
127	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
128	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
129	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
130	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
131	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
132	22/02/18 20:37	Reinspection Photo	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
133	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
134	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
135	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
136	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
137	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
138	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
139	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
140	22/02/18 20:37	Reinspection Photo	 Load JPG	☒
141	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
142	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
143	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
144	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
145	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
146	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
147	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
148	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
149	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
150	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
151	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
152	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
153	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
154	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
155	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
156	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
157	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
158	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
159	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
160	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
161	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
162	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
163	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
164	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
165	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
166	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
167	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
168	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
169	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
170	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
171	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
172	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
173	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
174	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
175	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
176	22/02/18 20:38	Reinspection Photo	 Load JPG	☒
177	26/02/18 20:38	Reinspection Photo	 Load JPG	☒
178	26/02/18 20:38	Reinspection Photo	 Load JPG	☒
179	26/02/18 20:38	Reinspection Photo	Load JPG	☒
180	26/02/18 20:38	Reinspection Photo	Load JPG	☒
181	26/02/18 20:38	Reinspection Photo	Load JPG	☒
182	26/02/18 20:38	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
183	26/02/18 20:38	Reinspection Photo	Load JPG	☒
184	26/02/18 20:38	Reinspection Photo	Load JPG	☒
185	26/02/18 20:38	Reinspection Photo	Load JPG	☒
186	26/02/18 20:38	Reinspection Photo	Load JPG	☒
187	26/02/18 20:38	Reinspection Photo	Load JPG	☒
188	26/02/18 20:38	Reinspection Photo	Load JPG	☒
189	26/02/18 20:38	Reinspection Photo	Load JPG	☒
190	26/02/18 20:38	Reinspection Photo	Load JPG	☒
191	26/02/18 20:38	Reinspection Photo	Load JPG	☒
192	26/02/18 20:38	Reinspection Photo	Load JPG	☒
193	26/02/18 20:38	Reinspection Photo	Load JPG	☒
194	26/02/18 20:38	Reinspection Photo	Load JPG	☒
195	26/02/18 20:38	Reinspection Photo	Load JPG	☒
196	26/02/18 20:38	Reinspection Photo	Load JPG	☒
197	26/02/18 20:38	Reinspection Photo	Load JPG	☒
198	26/02/18 20:39	Reinspection Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	20/02/18 15:09	Email from Kim Chwee Auto to arrange survey - Nancy Lam	Load PDF	
2	20/02/18 15:09	Kim Chwee Auto Estimate	Load PDF	
3	20/02/18 15:09	TP SLP853D (1/3) GIA Report	Load PDF	
4	20/02/18 15:09	TP SJR144E (2/3) GIA Report	Load PDF	
5	20/02/18 15:09	Enquire Transfer Fee	Load PDF	
6	20/02/18 15:09	Enquire Rebate	Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	22/02/18 11:22	SLH 57C ESTIMATE	Load PDF	
2	25/04/18 14:44	SLH 57C FINALISE ESTIMATE	Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	15/02/18 14:43	Accident Statement	Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	15/02/18 14:39	Accident Photo	Load JPG	☒
2	15/02/18 14:39	Accident Photo	Load JPG	☒
3	15/02/18 14:39	Accident Photo	Load JPG	☒
4	15/02/18 14:39	Accident Photo	Load JPG	☒
5	15/02/18 14:39	Accident Photo	Load JPG	☒
6	15/02/18 14:39	Accident Photo	Load JPG	☒
7	15/02/18 14:39	Accident Photo	Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	VAC (Kaki Bukit)	Thumbnail	Print
1	15/02/18 14:42	Sketch Plan	Load TIF	
2	15/02/18 14:42	Sketch Plan #2	Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18003342/URD3Q2

Date: 26/04/2018

REFERENCE

Insured/Claimant:	SARANPAL SINGH	Policy No:	28809291QMY	
Date of Loss:	13/02/2018	Nature of Claim:	OD	Claim No: 550037

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH57C		
Make & Model:	MERCEDES-BENZ C180, 1.6 Kompressor (A)	Engine No:	27191031350255
Reg. Date:	05/01/2012 (Man. Year: 2011)	Chassis No:	WDD2040452A639974
Colour:	Black	Odometer:	71844 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	S\$70,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/40Z R18	Rear Tyre Size:	225/40Z R18
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,489.26	8,310.90	3,178.36	27.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,820.00	2,090.00	1,730.00	45.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,309.26	10,400.90	4,908.36	32.06
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	14,809.26	9,900.90	4,908.36	33.14
+ GST 7.00/7.00% (S\$)	1,036.65	693.06	343.59	33.14
Nett Amount (S\$)	15,845.91	10,593.96	5,251.95	33.14

INSPECTION

Date of Assignment: 20/02/2018
Date Inspected: 21/02/2018 Inspected At:

Kim Chwee Auto Pte Ltd (HQ)
1 Kaki Bukit Avenue 6 #01-48,
AutoBay@Kaki Bukit
Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Apr 2018)
Parts:	143	MERCEDES-BENZ C180 1.6 Kompressor (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLH57C)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET (WCP)	Buckled	1,044.70 F	*1,020.00 F
2	2		*FRONT BONNET HINGES (WCP)	Bent	106.00 F	*106.00 F
3	2		*FRONT BONNET ABSORBER HOLDER (WCP)	Not Necessary	126.00 F	*- F
4	1		*FRONT BONNET INSULATOR (WCP)	Deformed	123.90 F	*120.00 F
5	1		*FRONT BONNET SEAL (WCP)	Necessary	14.00 F	*14.00 F
6	2		*FRONT BONNET STOPPER (WCP)	Not Necessary	26.00 F	*- F
7	2		*FRONT BONNET TOP LOCK CATCH (WCP)	Twisted	38.00 F	*38.00 F
8	1		*FRONT BONNET LOCK CENTRE CATCH OPENER (WCP)	Twisted	37.00 F	*37.00 F
9	1		*FRONT GRILLE WITH LOGO (WCP)	Cracked	325.00 F	*325.00 F
10	1		*FRONT BONNET LOGO (WCP)	Necessary	42.00 F	*42.00 F
11	2		*FRONT BONNET LOGO CLIP (WCP)	Necessary	8.00 F	*8.00 F
12	1		*FRONT TOP PANEL (WCP)	Bent	68.00 F	*68.00 F
13	1		*FRONT BRACE PANEL (WCP)	Bent	39.00 F	*39.00 F
14	2		*FRONT BONNET BOTTOM LOCK (WCP)	Twisted	68.00 F	*68.00 F
15	1		*FRONT BONNET LOCK CABLE (WCP)	Not Necessary	35.00 F	*- F
16	2		*FRONT HEADLAMP (WCP)	N/S Cracked / O/S Broken	1,080.00 F	*1,080.00 F
17	2		*FRONT HEADLAMP PANEL (WCP)	Buckled	256.00 F	*256.00 F
18	2		*FRONT HEADLAMP SIDE FENDER BRACKET (WCP)	Not Necessary	36.00 F	*- F
19	2		*FRONT FENDER (WCP)	Repair	900.00 F	*- F
20	2		*FRONT FENDER UNDER SHIELD (WCP)	Not Necessary	120.00 F	*- F
21	2		*FRONT FENDER CHROME MOULDING (WCP)	Necessary	44.00 F	*44.00 F
22	2		*FRONT FENDER BLUE EFFICIENCY EMBLEM (WCP)	Necessary	76.00 F	*76.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
23	1		*FRONT NUMBER PLATE BASE (WCP)	Torn	85.00 F	*85.00 F
24	1		*FRONT BUMPER (WCP)	Distorted	690.00 F	*690.00 F
25	1		*FRONT BUMPER TOP COVER (WCP)	Torn	28.00 F	*28.00 F
26	2		*FRONT BUMPER CHROME MOULDING (WCP)	Necessary	96.00 F	*96.00 F
27	1		*FRONT BUMPER SIDE RETAINER (WCP)	O/S Cracked	30.00 F	*15.00 F
28	2		*FRONT BUMPER CORNER INNER PARTS (WCP)	No such part	90.00 F	*- F
29	2		*FRONT BUMPER CENTRE RETAINER (WCP)	Cracked	40.00 F	*40.00 F
30	2		*FOG LAMP (LED) (WCP)	Not Necessary	560.00 F	*- F
31	1		*FOG LAMP OUTER CHROME (WCP)	O/S Cracked	98.00 F	*49.00 F
32	1		*FRONT BUMPER SPONGE (WCP)	Torn	55.00 F	*55.00 F
33	1		*FRONT BUMPER AIR GRILLE (WCP)	Twisted	72.00 F	*72.00 F
34	1		*FRONT BUMPER REINFORCEMENT (WCP)	Distorted	185.00 F	*185.00 F
35	2		*FRONT BUMPER REINFORCEMENT BRACKET (WCP)	Repair	280.00 F	*- F
36	1		*AIRCON CONDENSOR (WCP)	Bent / Punctured	680.00 F	*680.00 F
37	1		*AIRCON CONDENSOR COWLING (WCP)	O/S Torn	64.00 F	*32.00 F
38	1		*POWER STEERING COOLING PIPE (WCP)	Bent	185.00 F	*185.00 F
39	1		*INTER COOLER (WCP)	Dented	650.00 F	*650.00 F
40	1		*INTER COOLER COWLING (WCP)	Cracked	90.00 F	*90.00 F
41	1		*RADIATOR ASSY (WCP)	Bent / Punctured	455.00 F	*455.00 F
42	1		*RADIATOR FAN ASSY (WCP)	Cracked / Jammed	640.00 F	*640.00 F
43	1		*FRONT TOP PANEL CENTRE PLATIS BRACKET (WCP)	Cracked	15.00 F	*15.00 F
44	1		*FRONT TOP PANEL COVER (WCP)	Torn	68.00 F	*68.00 F
45	1		*AIR DUCT (WCP)	Twisted	48.00 F	*48.00 F
46	2		*FRONT WINDSCREEN GLASS SIDE MOULDING (WCP)	Repair	360.00 F	*- F
47	1		*SET FRONT BONNET INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
48	2		*SET FRONT FENDER INNER SHIELD CLIP	Not Necessary	200.00 FS	*- FS
49	1		*FRONT NUMBER PLATE	Cracked	45.00 FS	*40.00 FS

F=Franchise part. S=SpcNett.

Sub Total (S\$) 10,471.60 7,559.00
+ Margin on L,N Items 10.00/10.00% (S\$) 1,017.66 751.90

Total Parts (S\$) 11,489.26 8,310.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	20.00
2	TOWING CHARGE	New	120.00	120.00
3	REMOVE,REFIX & RENEW AIRCON CONDENSOR & REFILL AIRCON GAS	New	200.00	100.00
4	REMOVE NAD RENEW RADIATOR	New	120.00	0.00
5	LABOUR CHARGE KNOCK DENTS ON FRONT DAMAGE PORTION CUTC WELDING & RENEW PARTS	New	1,500.00	850.00
6	TO SPRAY PAINTING AND ETC	New	1,800.00	1,000.00
Gross Labour Cost (S\$)			3,820.00	2,090.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >