

22/03/2018

ASS. REC. BY:

REF: CS/MSG18003352/Uvd3/n2

Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Irene Tan

of

MSG

Date/Time:

22/2/18 @ 9.16am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

GT 98754

Insured:

FU 7092G

at Workshop m/s

Hui Wang Enterprise

Tel:

62830717

of

B1K5 Defu Lane 10 # 01-576

Policy No:

MSD/VMT/18-377617

Claim No:

MSC/V/18-000260

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 13/02/2018

CA / REV / REP. / REV 24 HRS

wp

H.O.D. Endorsement:

Date/Time:

10.39am @ 22/2/18

Person Contacted:

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

GT 98754 - NA/MSG18003024/k4

D.O.A: 13/2/18

FU 7092G - NA/MSG18003024/k4

D.O.A: 13/2/18

2/3/18

Informed Irene pending est from repairer by merimen

(08/11/13) wef

ASS. REC. BY: *Merimen*

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *GT 9875*at Workshop m/s *hurry*

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *2* days Res.: Yes or NoLum Sum: *131* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *GT 98754*Yr Regn: *1200*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *Car*Make: *Toyota Liteace*c.c *2184*Colour: *silver*

A/C: Insured / Std / NI / NA

Sp. Reading: *362530*

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *CR 420015031*

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: *165R13*

R: _____

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *De 1, um*

Front

Rear

R/Bal. *6* mmR/Bal. *6* mmL/Bal. *6* mmL/Bal. *6* mmD.O.A. *13/2/18*D.O.I. *22/2/18*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<i>ATA 12710 30/11/2020</i>
	<i>summary Estimate</i>
	<i>no 11 repair work replaced new because no second hand parts.</i>
<i>21/3/18</i>	<i>confirmed final by \$646.21 with w.1501 (Red 1907.63, 759)</i>
<i>22/3/18</i>	<i>Send preli revised by merimen (No LS)</i>
	<i>RECEIVED 23 MAR 2018</i>
	<i>22/3/2018</i>

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) *22/3 - typist*Days Of Repair: *2*Resurvey No. of Trip: *1*

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format: *merimen*Lump Sum / I.B.I: (\$ *646.21*)

200

10

210

Survey Department Check List (Case Handler)

Reference No. : CS/MSG/800 3352/11vd3
 Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 22/3/18
 Case Handler Date

*C: Critical *N: Non-Critical



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18003352/Uvd3		
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 22-02-2018		
		Code : MSG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FU 7092G	Veh. Inspected	GT 9875U	
Policy No.	MSD/VMT/18-377617	Coverage (\$)	0.00	
Claim No.	MSC/V/18-000260	Excess (\$)	0.00	
Assign From	MERIMEN (IRENE TAN)	Assign Date	22/02/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	13/02/2018	Inspection Date	22/02/2018	
Survey held at	HUI WANG ENTERPRISE BLK 5 DEFU LANE 10 #01-576 SINGAPORE 539187			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	14 Feb 2018		22 Feb 2018 09:16 Assign				New Assignment Cancel Case

Main		Reference		Claim Details		Documents		Show All
CLAIM SUBFOLDER DETAILS								[Created by insurer]
Insured:	TAN JUN HONG, ID: S9504316Z							
Main Claimant:	HUI WANG ENTERPRISE PTE LTD, Co. Reg. No.: 201426468N							
Vehicle Reg. No.:	GT9875U			Date of Loss:	13/02/2018 08:00 - :59			
Claim Type:	TP / MSC/V/18-000260			Policy/Cover Note No.:	MSD/VMT/18-377617 (Third Party Only) Coverage: 19/01/2018 - 17/04/2019			
Vehicle Reg. No. (Insured):	FU7092G			Policy No. (Claimant):				
				Excess:				
Repairer:	Hui Wang Enterprise Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-576, 539187 Defu Lane - Tel: 6283 0717							
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Irene Tan Gek Ing - 6594 2541]							
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/02/2018]							
Driver/Custodian (Insured):	TAN JUN HONG (), NRIC: S9504316Z							
ASSOCIATED MAIL RECEIVED								View All Compose Case Mail
There are no mail for this case.								
ALL ASSOCIATED TASKS								
					View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On Done?
No results.								

View Sent Message

This mail is associated with :

***GT9875U (MSC/V/18-000260)**
[FU7092G]

TP

HUI WANG ENTERPRISE PTE LTD

Feb 13 2018 8:00AM

[TAN JUN HONG]

Hui Wang Enterprise Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 02/03/2018 10:21 AM.

To MSI_ITAN

Subject PENDING ESTIMATE FROM REPAIRER

Dear Irene,

Please be informed that we have inspected the vehicle GT 9875U on 22/2/2018.

We are pending estimate from repairer.

Best Regards,
Veron Chen

DOCUMENTS SUMMARY

There are no documents.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807	From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933
Attn: Irene Tan Gek Ing	Date: 22 Mar 2018
<u>Preliminary Advice</u>	

Insured Vehicle No : FU7092G	Accident Date : 13/02/2018
TP Vehicle No : GT9875U	Assignment Date : 22/02/2018
Make : TOYOTA LITEACE	Est. Duration of Repair : 2.00
Date of Inspection : 22/02/2018	
Inspection At : HUI WANG ENTERPRISE PTE LTD (HQ) BLK 5 DEFU LANE 10, #01-576 SINGAPORE 539187	

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,553.84
Revised Amount	:S\$	646.21
Check Items (Estimated)	:S\$	0.00
Total	:S\$	646.21

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	6468N

Vehicle Details

Vehicle No.:	GT9875U
Vehicle to be Exported:	No
Intended De-registration Date:	22 Feb 2018
Vehicle Make:	TOYOTA
Vehicle Model:	LITEACE 5 DR
Primary Colour:	Silver
Manufacturing Year:	2000
Engine No.:	3C3882267
Chassis No.:	CR420015031
Maximum Power Output:	-
Open Market Value:	\$21,662.00
Original Registration Date:	21 Dec 2000
First Registration Date:	21 Dec 2000
Transfer Count:	2
Actual ARF Paid:	\$1,084.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	30 Nov 2020
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$22,924.00
COE Rebate Amount:	\$12,710.00
Total Rebate Amount:	\$12,710.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 22 Feb 2018

8/17/22

Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18003352/UVD3N2

Date: 26/03/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	MSD/VMT/18-377617
Claimant Vehicle No :	GT9875U	Insured Vehicle No :	FU7092G
Date of Loss:	13/02/2018	Nature of Claim:	TP
		Claim No:	MSC/V/18-000260

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GT9875U	Engine No:	3C3882267
Make & Model:	TOYOTA LITEACE, 2.2 5 DR (A)	Chassis No:	CR420015031
Reg. Date:	21/12/2000 (Man. Year: 2000)	Odometer:	362530 km
Colour:	Silver		
Engine Capacity:	2184 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	165 R13	Rear Tyre Size:	165 R13
Front Left Side:	Delium 6 mm	Rear Left Side:	Delium 6 mm
Front Right Side:	Delium 6 mm	Rear Right Side:	Delium 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,953.84	346.21	1,607.63	82.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	300.00	300.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,553.84	646.21	1,907.63	74.70
+ GST 7.00/7.00% (S\$)	178.77	45.23	133.54	74.70
Nett Amount (S\$)	2,732.61	691.44	2,041.17	74.70

INSPECTION

Date of Assignment:	22/02/2018	
Date Inspected:	22/02/2018	Inspected At:
		Hui Wang Enterprise Pte Ltd (HQ) Blk 5 Defu Lane 10, #01-576 Singapore 539187

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Mar 2018)	
Parts:	N/A	TOYOTA LITEACE 2.2 5 DR (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GT9875U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,082.20 FL	*374.45 FL
2	1		*FRONT GRILLE	Not Necessary	652.20 FL	*- FL
3	1		*FRONT BUMPER BEAM	Not Necessary	547.25 FL	*- FL
4	1		*FOG LAMP COVER (LHS)	Missing	256.80 FL	*68.50 FL
5	1		*LICENSE PLATE	Cracked	50.00 FS	*14.00 FS
					Sub Total (\$\$)	2,588.45 456.95
					- List Item Discount on L Items 25.00/25.00% (\$\$)	634.61 110.74
					Total Parts (\$\$)	1,953.84 346.21

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	600.00	300.00
Gross Labour Cost (\$\$)			600.00	300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >