

ASS. REC. BY:

REF: CS/MSG18003353/R/qd3dz Special Instructions:

SURVEYOR:
Mennen

RASHU

ASSIGNMENT (Office)

From (Person):

Eliza Ho

of

MSG

Date/Time:

22/2/18 @ 9:26am

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

AIRSHOW 252

Insured:

at Workshop m/s

Performance

Tel:

63190174 / 91165600

of

303 Alexandra Road

Policy No:

29069451MTR

Claim No:

550332

Sum Insured:

Excess:

\$1,000.00

Make of Veh:

D.O.A.

08/02/2018

(Client's Record)

CA / (REV) / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:30am @ 22/2/18

Person Contacted:

KALVIN LEONG

Vehicle IN/OUT

Date/Time	Action/Instruction () Estimate
	AIRSHOW 252 - X
22/2/18 @ 2:27pm	visit to Eliza Ho via Mennen.
26/2/18 @ 3:37pm	Wing Shao informed C/A via Mennen.
02/3/18 @ 2:44pm	Informed Kevin C/A \$ EX: \$6000 by email.
06/3/18 @ 12:01pm	2nd visit to Eliza Ho via Mennen (supplementary).
14/3/18 @ 9:35am	Wing Shao informed C/A at \$3837.70 via Mennen.

Kase

MSIG

1559w

AS-1000101

Form 22/02/18

Estimate Date

00177 WS TRRES/ODRES/EVA/INV/MT

To: Insurance No AIRSHOW252

At: Location

303 Alexandra Rd

Insured

Policy No

Client No

Sum Insured Excess \$1,000.00

Client Name Calvin

Make of van

Policy Condition

Remark: The van had commenced its repair at the time of inspection.



Salvage Value

DAD Accident Report Consistent? Yes or No

DAD PR Seen Consistent? Yes or No

Est. Repair 3 days Fee Yes or No

Lum Sum 35 35 Yes or No

CA RE REP. 24 HRS

Date Person Contacted

Vehicle IN OUT

Date Time Action/Instructor

14/9/18 @ 10.24am confirmed with Caroline final fig \$3837.70, 3 days by email.
 cited to \$66.35, 23/10

RECEIVED 14 SEP 2018

Date Time File No

14/9/18 10.24am

☐ Prelim Report
☐ Final Report

Days Of Repair

Resurvey No. of Time

Add Fee

☐ Site Fee
☐ Travel
☐ Test
☐ Fee

Report Format

Unit Fee

 MER-00
 3837.70

AIRSHOW252

☒ 00177 WS TRRES/ODRES/EVA/INV/MT
 TRASH TRASH

Van B.M.W 520IA

Color WHITE

St. Repair 00066

Eng No

C No WBAJA12000 WCO9000

Car Cond Good (3) Poor (5)

Steering (3) Jammed (4) Leaked (5) Burnt (6)

Brake (3) Jammed (4) Leaked (5) Burnt (6)

Mod. M1 (3) STD (4) R (5)

Tyre Size R 245/45R18

R

BS/DUN/EXNOVA GH PR LIA MID/CHTL SUM TOYO/YOKO

Rear

Rear

Rear

Rear

Rear

Surveyed at

Date of Damages Fee Repair OS NS UC Potholes

The U/C Chassis frame Body Structure affected parts of car

 14/9/2018
 14/9/2018

200

10

210

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18003353/R1qd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 22-02-2018



Code : MSG

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	AIRSHOW 252
Policy No.	29069451MTR	Coverage (\$)	0.00
Claim No.		Excess (\$)	1,000.00
Assign From	MERIMEN (ELIZA HO)	Assign Date	22/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	08/02/2018	Inspection Date	22/02/2018
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A) THE MARKET VALUE IS S\$----- (EST. AVERAGE)
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Feb 2018		22 Feb 2018 09:26 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	PERFORMANCE MOTORS LIMITED, Co. Reg. No.: 197401559W								
Vehicle Reg. No.:	AIRSHOW252	Date of Loss:	08/02/2018 18:00 - :59						
Claim Type:	OD	Policy/Cover Note No.:	29069451MTR (Comprehensive) Coverage: 31/01/2018 - 11/02/2018						
		Excess:	S\$1,000.00						
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Eliza Ho Teng Boon - 6594 2554]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 23/02/2018]								
Driver/Custodian:	MUHAMMAD HAMDAN FATHULLAH BIN ABDUL HALIM (23 / Male), NRIC: S9411637F, Tel: +6598331860								
Adj Asg. Remarks:	REVERT								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• MSIG_SG (21/02/2018): Cancellation of Assignment: AIRSHOW252									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 14 September 2018 10:24 AM
To: 'PBSP'
Cc: SUR
Subject: RE: FINALISE OF VEHICLE AIRSHOW 252 (DOA: 08/02/2018)

Dear Caroline,

WITHOUT PREJUDICE

Confirm final fig \$3,837.70 before excess \$1,000.00 & GST and 3 repair days.

Kindly send the relevant documents to MSIG insurance company.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP <pml-pbsp@sime-darby.com.sg>
Sent: Tuesday, 28 August 2018 6:21 PM
To: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Subject: Re: FINALISE OF VEHICLE AIRSHOW 252 (DOA: 08/02/2018)

Dear Shiau Chan

Please refer to attach and kindly confirm COR at \$3837.70 before excess and GST.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: PBSP
Sent: Monday, 4 June 2018 4:16:55 PM
To: Shiau Chan (LKKAUTO); Kevin Leong Wai Kit
Subject: Re: FINALISE OF VEHICLE AIRSHOW 252 (DOA: 08/02/2018)

Dear Kevin

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	21 Feb 2018 18:29	Cim Veh Model Changed	(202194) BMW 520I 2.0 (A).	[I] Eliza Ho Teng Boon
2	21 Feb 2018 18:29	Cim Created	Reg No: AIRSHOW252WC09000. Policy No: 29069451MTR. Acct Date: 2018/02/08. Claim Type: OD. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ). Workshop: Performance Motors Limited (Alexandra). Ins.Status => Incoming Claim. Created from SAS:MPML18024914	[I] Eliza Ho Teng Boon
3	21 Feb 2018 18:30	Cim Registration Modified	Reg No: AIRSHOW252WC09000->AIRSHOW252.	[I] Eliza Ho Teng Boon
4	21 Feb 2018 18:39	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):REVERT	[I] Eliza Ho Teng Boon
5	21 Feb 2018 18:39	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/02/22	[I] Eliza Ho Teng Boon
6	21 Feb 2018 18:39	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Eliza Ho Teng Boon
7	21 Feb 2018 18:50	Adj Assignment Cancelled		[I] Eliza Ho Teng Boon
8	21 Feb 2018 18:50	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Eliza Ho Teng Boon
9	22 Feb 2018 09:26	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):REVERT	[I] Eliza Ho Teng Boon
10	22 Feb 2018 09:26	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/02/23	[I] Eliza Ho Teng Boon
11	22 Feb 2018 09:26	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Eliza Ho Teng Boon
12	22 Feb 2018 09:35	Assignment 1st Accessed		[A] SHIAU CHAN
13	22 Feb 2018 13:01	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] Nivitha Govindasamy
14	26 Feb 2018 14:17	Adj Rpt Initiated		[A] SHIAU CHAN
15	26 Feb 2018 14:20	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/03/24	[A] SHIAU CHAN
16	26 Feb 2018 14:20	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/24	[A] SHIAU CHAN
17	26 Feb 2018 14:22	Adj Mandate Request	Cur.Req:2693.10:DAMAGES CONSISTENT. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	26 Feb 2018 15:22	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/24. Mandate Remarks: CHECK ITEMS TO BE VERIFIED AND CONFIRMED.	[I] Koh Ming Shao
19	26 Feb 2018 15:22	Adj Mandate Set	Approved:2239.00:CHECK ITEMS TO BE VERIFIED AND CONFIRMED.	[I] Koh Ming Shao
20	06 Sep 2018 12:01	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/03/24	[A] SHIAU CHAN
21	06 Sep 2018 12:01	Adj Mandate Request	Cur.Req:3837.70:DAMAGES CONSISTENT. REPAIR COST ECONOMICAL. KINDLY APPROVE ON SUPPLEMENTARY.	[A] SHIAU CHAN
22	14 Sep 2018 09:35	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/24	[I] Koh Ming Shao
23	14 Sep 2018 09:35	Adj Mandate Set	Approved:3837.70.	[I] Koh Ming Shao

Date From



Date To



Audit Type None

Go

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1731900	26/02/2018 14:17	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	AIRSHOW252		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eliza Ho Teng Boon

Date: 06 Sep 2018

Preliminary Advice

Vehicle No	: AIRSHOW252	Accident Date	: 08/02/2018
Make	: BMW 520I	Policy No.	: 29069451MTR
Assignment Date	: 22/02/2018	Excess	: S\$1,000.00
Date of Inspection	: 22/02/2018	Est. Duration of Repair	: 3.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,004.45	(ESTIMATE \$3,714.10 + SUPPLEMENTARY \$1,290.35)
Revised Amount	:S\$	3,837.70	(INCLUSIVE OF SUPPLEMENTARY)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	3,837.70	
Lump Sum Repair	:S\$		

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	NOT ADVISED
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

(X) The vehicle is economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. KINDLY APPROVE ON SUPPLEMENTARY.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Tuesday, 27 February 2018 2:44 PM
To: kevin.leong.waikit@simedarby.com.sg
Cc: PBSP; SUR
Subject: VEHICLE AIRSHOW 525 (DOA: 08/02/18)

Dear Kevin,

As instructed by our client MSIG, please proceed to repair the insured vehicle **AIRSHOW 252 (excess \$1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,
Shiau Chan (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Claim Audit

AUDIT TRAIL				
No.	On	Audit	Remarks	By
1	21 Feb 2018 18:29	Cim Veh Model Changed	(202194) BMW 520I 2.0 (A).	[I] Eliza Ho Teng Boon
2	21 Feb 2018 18:29	Cim Created	Reg No: AIRSHOW252WC09000. Policy No: 29069451MTR. Acct Date: 2018/02/08. Claim Type: OD. Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ), Workshop: Performance Motors Limited (Alexandra). Ins.Status => Incoming Claim. Created from SAS:MPML18024914	[I] Eliza Ho Teng Boon
3	21 Feb 2018 18:30	Cim Registration Modified	Reg No:AIRSHOW252WC09000->AIRSHOW252.	[I] Eliza Ho Teng Boon
4	21 Feb 2018 18:39	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):REVERT	[I] Eliza Ho Teng Boon
5	21 Feb 2018 18:39	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/02/22	[I] Eliza Ho Teng Boon
6	21 Feb 2018 18:39	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Eliza Ho Teng Boon
7	21 Feb 2018 18:50	Adj Assignment Cancelled		[I] Eliza Ho Teng Boon
8	21 Feb 2018 18:50	Adj Est Details Deleted	Deleting Est Details For Cancelling Adjuster Assignment	[I] Eliza Ho Teng Boon
9	22 Feb 2018 09:26	Adj Co Assigned	LKK Auto Consultants Pte Ltd (HQ):REVERT	[I] Eliza Ho Teng Boon
10	22 Feb 2018 09:26	Adj Next Rpt Changed	Next Rpt:Im. Advice.Due Date:2018/02/23	[I] Eliza Ho Teng Boon
11	22 Feb 2018 09:26	Adj Mandate Set	Approved:25000.00.Reinsp:Adj decides.	[I] Eliza Ho Teng Boon
12	22 Feb 2018 09:35	Assignment 1st Accessed		[A] SHIAU CHAN
13	22 Feb 2018 13:01	Adj Adjuster Assigned	[None] -> MOHD RASUL	[A] Nivitha Govindasamy
14	26 Feb 2018 14:17	Adj Rpt Initiated		[A] SHIAU CHAN
15	26 Feb 2018 14:20	Adj Im. Advice Submitted	Next Rpt:Final Rpt.Due Date:2018/03/24	[A] SHIAU CHAN
16	26 Feb 2018 14:20	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/24	[A] SHIAU CHAN
17	26 Feb 2018 14:22	Adj Mandate Request	Cur.Req:2693.10:DAMAGES CONSISTENT. WE HAVE NOT AUTHORISE REPAIR.	[A] SHIAU CHAN
18	26 Feb 2018 15:22	Adj Next Rpt Changed	Next Rpt:Final Rpt.Due Date:2018/03/24. Mandate Remarks: CHECK ITEMS TO BE VERIFIED AND CONFIRMED.	[I] Koh Ming Shao
19	26 Feb 2018 15:22	Adj Mandate Set	Approved:2239.00:CHECK ITEMS TO BE VERIFIED AND CONFIRMED.	[I] Koh Ming Shao

ACTIVITY

No record

Merimen Billing for this case - Transaction History

Bill Ref No	Bill Date	Acc Type	Acc Name	Co Name (Branch)	Ref 1	Ref 2	Amount
1731900	26/02/2018 14:17	Motor	LKK Auto Consultants Pte Ltd	LKK Auto Consultants Pte Ltd (HQ)	AIRSHOW252		10.70

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Eliza Ho Teng Boon

Date: 26 Feb 2018

Preliminary Advice

Vehicle No	: AIRSHOW252	Accident Date	: 08/02/2018
Make	: BMW 520I	Policy No.	: 29069451MTR
Assignment Date	: 22/02/2018	Excess	: S\$1,000.00
Date of Inspection	: 22/02/2018	Est. Duration of Repair	: 3.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	3,674.10
Revised Amount	:S\$	2,239.00
Check Items (Estimated)	:S\$	454.10
Total	:S\$	2,693.10

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	NOT ADVISED
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

(X) The vehicle is economical economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis. WE HAVE NOT AUTHORISE REPAIR.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/02/2018 10:39
Date Of Accident	08/02/2018 18:00
Exact Location Of Accident	ESPLANADE B2 CAR PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	AIRSHOW252WC09000
Insured/Policyholder	
Name Of Registered Owner	PERFORMANCE MOTORS LIMITED
Co Reg No	197401559W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-63190100

Vehicle Particulars

Manufacturer	BMW
Model	520
Exact Purpose for which vehicle was being used at time of accident	AIRSHOW

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	121482
Cover Note Number	

Driver

Name of Driver	MUHAMMAD HAMDAN FATHULLAH BIN ABDUL HALIM
NRIC No	S9411637F
Date Of Birth	10/04/1994
Occupation	INDOOR
Date Of Driving Pass	12/05/2015
Driving Experience	2 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98331860
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 615 ELIAS ROAD #03-108
Postcode	510615
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	NO
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	QUEENSTOWN N.P.C
Police Station Address	ROAD: 3 QUEENSWAY #01-03 , POSTCODE: 149073 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4719999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

- Nothing to sketch -

- damaged front both
front kidney grill of
the car & front bumper
as well.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

AIRSTOW 252 of chassis number WC09000, was gazetted from
1st - 8th Feb 2018. The car was not in use from 1st - 7th Feb 2018.
On the 8th, when we were about to send the car back to
PD1 (Benci), the car was found in that manner. Front grills
were misaligned.

As per police report

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



**SINGAPORE
POLICE FORCE**



T/20180220/2043

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999

1 of 3

Report No. T/20180220/2043

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 20/02/2018 12:03		Vide Report No.:		Station Diary No.: 36	
Informant's Particulars					
Name of Informant: MUHAMMAD HAMDAN FATHULLAH BIN ABDUL HALIM			Address: APT BLK 615 ELIAS ROAD #03-108 SINGAPORE 510515		
ID Type / ID No.: NRIC NO / S9411637F			Contact No.: Home/Office: Mobile: 98331860		
Nationality: SINGAPORE CITIZEN			Email:		
Sex: Male	Age: 23	Date of Birth: 10/04/1994	Type of Informant: VEHICLE MANAGER		
Race: Malay			Language: English		Institution / School Name:
Occupation: OPERATION EXECUTIVE			Driving Licence Information: Class: 3		Date of Expiry:

General Information of the Accident				
Type of Accident:	Non-Injury Hit and Run	Drink Drive: No	Date/Time of Accident: 08/02/2018 18:00	Type of Location: Car Park
Location: Along Road 1 ESPLANADE DRIVE Esplanade B2 Car Park				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control: Not Controlled	Traffic Volume:	
Type of Collision: Moving Vehicle Against - Parked Vehicle				Anyone conveyed by ambulance: No

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
AIRSHOW2 52	Car	BMW		Blue	Slightly Damaged	0

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180220/2043

2 of 3

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999

Report No. T/20180220/2043

CONTINUATION OF REPORT

VEHICLE MANAGER			
Name	MUHAMMAD HAMDAN FATHULLAH BIN ABDUL HALIM	ID No.	S9411637F
Related Vehicle	AIRSHOW252 (Car)	Contact No.	98331860
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 01/02/2018, we had parked vehicle AIRSHOW252 at B2 Car Park of Esplanade. When we picked up the vehicle on 08/02/2018 at about 1800hrs, we discovered that the front grills of the vehicle were misaligned. The vehicle was not moved from 01/02/2018 to 07/02/2018. I am lodging this report as I am in charge of the management of the vehicles of the Airshow.



**SINGAPORE
POLICE FORCE**



T/20180220/2043

Police Station Of Origin:
Queenstown N.P.C
3 Queensway #01-03 SINGAPORE 149073
Tel No: 1800-4719999

3 of 3

Report No: T/20180220/2043

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474865 stating the report number as reference.

Signature Of Officer Recording The Report: D / Sgt 2 HO YUAN REN, JUSTIN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 20/02/2018 12:03
Officer In Charge Of Case: TP / HRT / SI ABDUL KAREEM BIN ABDUL HAGUE Contact No.: 65176079	Classification Of Case:
Authentication Stamp NP168	SN 46
SIGNATURE	



MSIG

DEALER/PROPOSER

MC N^o 121482

MOTOR INSURANCE COVER NOTE

Whereas the Applicant named in the Schedule below having proposed for insurance in respect of the Motor Vehicle described in the Schedule below the risk is hereby HELD COVERED in the terms of the Company's usual form of Policy applicable thereto for the period as stated below unless the cover be terminated by the Company by notice in writing in which case the insurance will thereupon cease and a proportionate part of the annual premium otherwise payable for such insurance will be charged for the time the Company has been on risk.

SCHEDULE

Name of Applicant: PERFORMANCE MOTORS LIMITED Existing Policy No. TBA

DESCRIPTION OF MOTOR VEHICLE

Registered Number: 305 units of unregistered cars & 45 units of registered cars as attached

Make / Model: BMW Type of vehicle: ☒ Private

Year of Manufacture: Engine Capacity / Tonnage: ☐ Commercial

Seating Capacity: Engine No:

Sum Insured: Chassis No:

COVERAGE

☒ Comprehensive ☐ Third Party Fire/Theft ☐ Third Party Only
☐ MotorMax ☐ MotorMax Plus (Apply only private vehicle)

PERIOD OF COVER 31 JAN 2018 TO 11 FEB 2018

One year from date and time of registration of Motor Vehicle.

VALIDITY PERIOD OF COVER NOTE

14 days from date of issue

Special terms / Excess
EXCESS = \$1000/- per unit for each & every claim
EXCESS = \$200/- for Windscreen
including Hire & Reward.

We hereby certify that this Cover Note is issued in accordance with the provisions of Road Transport Act 1987 (Malaysia), Motor Vehicles (Third Party Risks & Compensation) Act (Cap. 189) (Republic of Singapore), Road Traffic Act (Cap 276) (Republic of Singapore) or any Amendment, Act or Acts passed in substitution.

Signed For And On Behalf Of
 MSIG Insurance (Singapore) Pte. Ltd.



Authorized Signatory

Date of Issue 24/01/2018

MSIG Insurance (Singapore) Pte. Ltd. 4 Shenton Way, #21-01, SGX Centre 2, Singapore 068807
 Tel +65 6827 7888 Fax +65 6827 7800 Co. Reg. No. 200412212G www.msig.com.sg

MDN-0314



The image shows a sample of a Singapore Identity Card. At the top, it reads "REPUBLIC OF SINGAPORE" and "IDENTITY CARD NO. S9411637F". On the right is the national emblem. On the left is a black and white portrait of a man. To the right of the portrait, the cardholder's details are listed: Name: MUHAMMAD HAMDAN FATHULLAH BIN ABDUL HALIM, Race: MALAY, Date of birth: 10-04-1994, and Country of birth: SINGAPORE. At the bottom right, there is a small circular stamp with the number "S9411637F".

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S9411637F

Name
MUHAMMAD HAMDAN
FATHULLAH BIN ABDUL
HALIM

Race
MALAY

Date of birth
10-04-1994

Country of birth
SINGAPORE

S9411637F

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licensee's Name: S9411637F

Age: 21

MUHAMMAD HAMQAN
FATHULLAH BIN ABUL
HALIM

Valid Until: 10 Apr 1994

Issue Date: 12 May 2015

002426327F

NS

4547176



ISSUE No. **S9411637F**



Date of issue
02-02-2009


Address
**APT BLK 615 ELIAS ROAD
#03-105
SINGAPORE 510615**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(S)

EFFECTIVE DATE

Class 3 Motor Cars \leq 3000kg with \leq 7 passengers, exclusive of the driver; and other motor vehicles \leq 2500kg **12 May 2015**

Licence No: S94116379



NP 426A

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 1974015598 GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64767770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

313, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63198828 (AfterSales)
63198833/530 (Motorrad)
Fax. 64786601 (AfterSales)
64786604 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45984
Date Estimated : 21/02/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 1

- ESTIMATE REPAIR FOR -
Errol Sanath Nanayakara
276 Westwood Avenue

- ACCOUNT - 40000
Cash Sales - Service
Singapore

Singapore 648476

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
	WC09000		520iA	66

DESCRIPTION

To repair on front bumper including remove and install all attachments.

VALUE
850 1,700.00

Painting on front bumper assembly

934 1,038.00

To check electrical wiring systems at the front section for proper function.

150 177.00

Sundries.

NE 70 40.00

Total Labour 1: 2,955.00

DESCRIPTION

FRT BUMPER TOWING COVER PRIMED
SET MOUNTING PDC/PMA SENSOR FRT
FRAME BOTTOM
FRT LH GRILLE (M/SPORT)
FRT RH GRILLE (M/SPORT)
AIR FLAPS TOP
DECOUPING RING PDC TORQUE CONVERTER

QTY	PRIC	VALUE
1	51.10	51.10
1	62.95	62.95
1	51.50	51.50
1	132.50	132.50
1	132.50	132.50
1	268.35	268.35
4	5.05	20.20

Total Parts : 719.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1 : 2,955.00
Parts : 719.10
Labour 2 : 0.00
Excess : 0.00
Total GST @ 7% : 257.19
Grand Total : 3,931.29

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Time-Darby Group
Co. Reg. No. 197401155W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45984
Date Estimated : 21/02/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Errol Sanath Nanayakara
276 Westwood Avenue

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 648476

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
	WC09000	28/02/2018	520iA	66
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
To replace front bumper and attachments, top air flaps include knocking out dents caused by the accident	850.00		850.00	
To spray paint front bumper	934.00		934.00	
To check electrical wiring systems at the front section for proper function.	150.00		150.00	
Sundries.	80.00		80.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT BUMPER PANEL PRIMED (PMA/PDC) *	1,290.35	1.00		1,290.35
FRT LH GRILLE (M/SPORT)	132.50	1.00		132.50
FRT RH GRILLE (M/SPORT)	132.50	1.00		132.50
AIR FLAPS TOP	268.35	1.00		268.35

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	1,823.70
Total Labour & Parts :	3,837.70
Deduction for Excess :	1,000.00
Total Repair Costs less Excess:	2,837.70
GST @7%:	198.64
Grand Total :	3,036.34

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401558W, GST Reg. No. M2-002081-X



SUPPLEMENTARY

Estimate No. : b1 45984
Date Estimated : 21/02/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Errol Sanath Nanayakara
276 Westwood Avenue

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 648476

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
	WC09000	28/02/2018	520iA	66
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# FRT BUMPER PANEL PRIMED (PMA/PDC) *	1,290.35	1.00		1,290.35

Total Labour :	
Total Parts :	1,290.35
Total Labour & Parts :	1,290.35

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Feb 2018		22 Feb 2018 09:26 Edit Adj Rpt	\$53,837.70 Edit Estimates	\$53,837.70 View Rpt		Pending for Survey Report Cancel Case








Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: PERFORMANCE MOTORS LIMITED , Co. Reg. No.: 197401559W									
Vehicle Reg. No.: AIRSHOW252		Date of Loss: 08/02/2018 18:00 - :59 [1 Months and 7 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / 550332		Policy/Cover Note No.: 29069451MTR (Comprehensive) Coverage: 31/01/2018 - 11/02/2018							
		Excess: \$51,000.00							
Repairer: Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Eliza Ho Teng Boon - 6594 2554]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 24/03/2018]									
Driver/Custodian: MUHAMMAD HAMDAN FATHULLAH BIN ABDUL HALIM (23 / Male), NRIC: S9411637F, Tel: +6598331860									
Adj Asp. Remarks: REVERT									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> MSIG_SG (14/09/2018): Alert - Adj Mandate Approved (\$53837.70) - AIRSHOW252 - Claim Handler: Eliza Ho ... MSIG_SG (26/02/2018): Alert - Adj Mandate Approved (\$2239.00) - AIRSHOW252 - Claim Handler: Eliza Ho ... MSIG_SG (21/02/2018): Cancellation of Assignment: AIRSHOW252 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									








































Claim Documents

*AIRSHOW252 (550332)
OD
Feb 8 2018 6:00PM
[PERFORMANCE MOTORS LIMITED]
Performance Motors Limited


[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View [View in Browser](#)

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print	
1	21/02/18 11:03	Accident Statement	 Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	26/02/18 14:20	Adjuster Immediate Advice	 Load HTM		
2	06/09/18 12:01	Adjuster Immediate Advice	 Load HTM		
Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print	
1	21/02/18 10:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
2	21/02/18 10:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
3	21/02/18 10:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
4	21/02/18 10:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
5	21/02/18 10:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
6	21/02/18 10:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
7	21/02/18 10:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
8	21/02/18 10:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
9	21/02/18 10:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
10	21/02/18 10:59	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
11	21/02/18 11:03	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
12	21/02/18 11:03	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
13	21/02/18 11:03	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
14	21/02/18 11:03	Accident Photo [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	26/02/18 14:21	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>	
2	26/02/18 14:21	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>	
3	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>	
4	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>	
5	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>	
6	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>	
7	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>	
8	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>	
9	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>	
10	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>	
11	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>	
12	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>	
13	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
14	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
15	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
16	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
17	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
18	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
19	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
20	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
21	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
22	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
23	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
24	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
25	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
26	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
27	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
28	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
29	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
30	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
31	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
32	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
33	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
34	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
35	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
36	26/02/18 14:21	General View	 Load JPG	<input checked="" type="checkbox"/>
37	06/09/18 11:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	06/09/18 11:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	06/09/18 11:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	06/09/18 11:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	06/09/18 11:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	06/09/18 11:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	06/09/18 11:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	06/09/18 11:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	06/09/18 11:57	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	12/09/18 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	12/09/18 16:25	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	21/02/18 18:34	ESTIMATE	 Load PDF	
2	21/02/18 18:40	KEVIN REQUEST FOR SURVEY	 Load HTM	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	26/02/18 14:21	ESTIMATE	 Load PDF	
2	06/09/18 11:56	SUPPLEMENTARY LIST	 Load PDF	
3	06/09/18 11:56	REVISED ESTIMATE	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	21/02/18 11:03	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	21/02/18 10:59	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	21/02/18 10:59	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	21/02/18 10:59	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	21/02/18 10:59	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	21/02/18 10:59	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	21/02/18 10:59	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	21/02/18 10:59	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	21/02/18 10:59	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	21/02/18 10:59	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	21/02/18 10:59	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	21/02/18 11:03	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
12	21/02/18 11:03	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
13	21/02/18 11:03	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
14	21/02/18 11:03	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	21/02/18 10:57	Sketch Plan		Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way, #21-01 SGX Centre 2
Singapore 068807

Our File No: CS/MSG18003353/R1QD3E2

Date: 17/09/2018

REFERENCE

Insured/Claimant: PERFORMANCE MOTORS LIMITED
Date of Loss: 08/02/2018

Policy No: 29069451MTR
Nature of Claim: OD Claim No: 550332

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	AIRSHOW252	Engine No:	HIDDEN
Make & Model:	BMW 520i, 2.0 (A)	Chassis No:	WBAJA12000WC09000
Reg. Date:	01/01/2018 (Man. Year: 2018)	Odometer:	66 km
Colour:	White		
Engine Capacity:	0 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R18	Rear Tyre Size:	245/45 R18
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,089.45	1,903.70	185.75	8.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,915.00	1,934.00	981.00	33.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,004.45	3,837.70	1,166.75	23.31
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	4,004.45	2,837.70	1,166.75	29.14
+ GST 7.00/7.00% (S\$)	280.31	198.64	81.67	29.14
Nett Amount (S\$)	4,284.76	3,036.34	1,248.42	29.14

INSPECTION

Date of Assignment: 22/02/2018

Date Inspected: 22/02/2018 Inspected At:

Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Sep 2018)
Parts:	143	BMW 520i 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for AIRSHOW252)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	80.00 F	*80.00 F
2	1		*FRT BUMPER TOWING COVER PRIMED	Serviceable	51.10 F	*- F
3	1		*SET MOUNTING PDC/PMA SENSOR FRT	Serviceable	62.95 F	*- F
4	1		*FRAME BOTTOM	Serviceable	51.50 F	*- F
5	1		*FRT LH GRILLE (M/SPORT)	Cracked	132.50 F	*132.50 F
6	1		*FRT RH GRILLE (M/SPORT)	Cracked	132.50 F	*132.50 F
7	1		*AIR FLAPS TOP	Cut	268.35 F	*268.35 F
8	4		*DECOUPING RING PDC TORQUE CONVERTE	Not Necessary	20.20 F	*- F
9	1		*FRT BUMPER PANEL PRIMED (PMA/PDC)	Deformed	1,290.35 F	*1,290.35 F
Total Parts (S\$)					2,089.45	1,903.70

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPAIR ON FRONT BUMPER INCLUDING REMOVE AND INSTALL ALL ATTACHMENTS	New	1,700.00	850.00
2	PAINTING ON FRONT BUMPER ASSEMBLY	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (S\$)			2,915.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >