

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 27 Feb 2018

Preliminary Advice

Insured Vehicle No	: SJK4398A	Accident Date	: 14/02/2018
TP Vehicle No	: FBF3948R	Assignment Date	: 21/02/2018
Make	: YAMAHA SPARK	Est. Duration of Repair	: 4.00
Date of Inspection	: 26/02/2018		
Inspection At	: COMPLETE VMS PTE LTD (HQ) 176 SIN MING DRIVE #03-14 SIN MING AUTOCARE COMPLEX SINGAPORE 575721		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,992.00
Revised Amount	:S\$	1,192.50
Check Items (Estimated)	:S\$	1,342.80
Total	:S\$	2,535.30

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.