

**Repair Estimates** 

## ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

						100	7 /	Wither	w
arts (a) Cost / List	Price Items _	\$	1,382.50			Miss	/	31	
Plus/Less	25%	\$	345.63			, - 0,0,	1	Rother BI	12
Total of	Cost / List	\$	1,036.88						
(b) Nett Price	Items _								
Less									
Total of N	lett Item _								
(c) Special N	ett Items _	\$	200.00						
otal Parts Cost		\$	1,236.88						
abour		\$	770.00						
about									
otal he above total will be	=	\$ G.S.T.	2,006.88						
otal  he above total will be  Name of Surveyor	= e subjected to 7%		2,006.88	Ker	nnerh				
otal he above total will be	= e subjected to 7%		2,006.88	He, 6, 5/3/1	nners Elle				
Name of Surveyor Company Survey conducted Remarks By Surve	e subjected to 7%	: :		5/3/1	at at				
Name of Surveyor Company Survey conducted Remarks By Surve (a) The repair of	e subjected to 7%  on  eyor  this vehicle is aut	G.S.T.	2,006.88	5/3/	at at				
Name of Surveyor Company Survey conducted Remarks By Surve (a) The repair of	e subjected to 7%	G.S.T.		5/3/1	at at				
Name of Surveyor Company Survey conducted Remarks By Surve (a) The repair of	e subjected to 7%  on  eyor  this vehicle is authed Days of Repair	G.S.T.		5/3/1 until further no	at tice.				
Name of Surveyor Company Survey conducted Remarks By Surve (a) The repair of	e subjected to 7%  on  eyor  this vehicle is authed Days of Repair	G.S.T.	is not authorized	5/3/1 until further no	at tice.				

SLJ 1690 G



## **ESTEEM PERFORMANCE PTE LTD**

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536. Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

			$D_{-}$	rts
_	na	ro	$rac{1}{2}$	PT C

Vehicle No. :	SLJ 1690 G	Submit By	:	Carmen Lim
Make & Model:	TOYOTA PRIUS	Year Manufacture	:	2016
Chassis No :	JTDKB3FUX03537939	Engine No.	:	
_		Cost / List		

S/No.	Part Description		Qty	Unit Price	Price	Disposition by Surveyor
1	Reverse sensor	Sh	1	\$200.00	S.N	X
2	Rear bumper	Bu	~ 1	\$497.50		
3	Rear bumper clip	n	10	\$40.00		-
4	Rear bumper side retainer RH	D	77 1	\$112.70		-
5	Rear bumper lower garnish centre		1	\$582.60	1	?
6	Rear bumper lower garnish RH		1	\$149.70		7
7						
8						
9						
10				1		
11						
12						
13						
14					ue.	
15		th	e Renairer	sultants hence not the following:		
16		0	To resurvey be	ore/after spray painting re	ig survev	
17			Dade prices at	e subject to confirmat	on	
18			No illocal mod	vey is on a "Without P fication(s) is allowed		
19			Supplementar	v item(s) must be rest nal approval from Insu	rance Company	
20			cknowledged			
21			ignature:			
22			ato:			
23						

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



## **ESTEEM PERFORMANCE PTE LTD**

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

## Labour

Vehicle No.	: _	SLJ 1690 G	Submit By :	Carmen Lim
Make & Model	: _	TOYOTA PRIUS	Year of Manufacture:	2016

S/No	Labour Description	Esimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT		
	REPAIR AREA. (REAR BUMPER)	\$300.00	2001
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT		
	REPAIR AREA. (REAR BUMPER)	\$300.00	
3	To remove & refit reverse sensor to assit work load	\$120.00	501
4	To tuff coat An	\$50.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.