COMFORTDELGRO ENGINEERING PTE LTD REPAIR ESTIMATE*

ALGIASIACPIP) -



DATE 21/2/2018

VEHICLE NO: SHA 7827K

MAKE : MODEL : HYUNDAI i40 LKK-Kalvin

Qty	Parts Description/ Labour		Unit Price		Amount	
	Rear Bumper	Type			\$	603.60
	Rear Bumper Reinforcement .?				\$	504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$	180.00	\$	360.00
	Rear Bumper Side Bracket ?				\$	49.00
	Rear Bumper Clips —				\$	22.00
	Rear Bumper Sponge ?				\$	143.40
	Rear Bumper Under Cover				\$	225.00
	Total Bumper Chief Cover				Ψ	225.00
	SUB TOTAL				\$	1,907.35
	LESS 20%				\$	381.47
	DISCOUNTED TOTAL				\$	1,525.88
	DISCOUNTED TOTAL				J.	1,525.00
	D. D. D. C. C.				0	125.70
	Rear Bumper Reverse Sensor				\$	135.70
					_	
					\$	135.70
			-			
	Labour Charge					200
	Panel Beating				\$	380.00
	Spray Painting Charge				\$	200.00
	Wiring Charge				\$	50.00
	R/Refix Reverse Sensor				\$	120.00
	TOTAL LABOUR				\$	750.00
	ESTIMATE TOTAL				\$	2,411.58
	Kahn ICtki	LV	M Auto Cons	ultanta kanaa		
	Cars. 10			ultants hence the following:		y
	2 1/2/8 1035 hs.	• To	resurvey befor	e/after spray pair	ting	
	// 21/2/			ed part(s) during ubject to confirm		/ey
	2 1675			y is on a "Without		dice" basis
	20%			ation(s) is allowe		
	PIP Beton Point phot	• St	upplementary its	em(s) must be re- approval from Ins	urvey	ed and
	2/2/1/	IS	adoject to final	approvar from this	uranc	e Company
	Retore Point pris		nowledged by F	Repairer		
			nature:			
		Date	8			

be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.