

INS. CASE OWNER:

Shawank

CC 3 /AIG1800

7764, Kwb39

LKK:

IDAC:

Surveyor:

Kenneth

DOI:

ASSIGNMENT

2/2/18

Date / Time:

21/2/18

Registered in Merimen:

27/2/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLE 7909K

Name of Insured:

HOPE FIRST RESPONSE PIV

Insured Tel No.:

HP:

D.O.A:

18/2/18

Excess Sec II :SS

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

MUHAMMAD ZAKI BIN MUHAMMAD

Driver Tel No.:

(V/L YES / NO)

Claim No.:

68105143766

Policy No.:

99994476 / 100830577

Make / Model:

MERLEDS

Place of Accident:

JURONG YISHUN CENTRAL & YISHUN

KNO 2

OI GIA REPORT (YES / NO) : TP GIA REPORT (YES / NO)

Insured Liability:

%

Final ? Yes / No

SIC 5576B



INSRS:

WSP:

Tel:

Liability:

RMKS:

Trans
Cnb

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

26/2/18

victim

5/3/18

5/3/18

Receive video from AIG.

email to AIG to seek advice

Email from AIG to reject claim

email to workshop reject claim

RECEIVED 11 MAR 2018

1/1/18
V
21-03-18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

SS

(Agreed / Assessed) BOLA S/N No.:

If NO or B 28, Ass. Lia:

Repair Cost:

SS

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

(\$

x

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

LOI only

GIA/LTA Search

SS

Medical

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

reject.

\$320.00

ASS. REC. BY:

REF:

AIG/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S14C 3528B

Yr Regn:

08.14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Renault Latitude

cc

1995

Colour

n. white / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

378913

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VIFIABL15AUC 278869

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S / R / STD A / R / or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Giti

Front

Rear

R/Bal.

7

mm

R/Bal.

9

mm

L/Bal.

7

mm

L/Bal.

9

mm

D.O.A.

18/2/18

D.O.A.

21/2/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/2

File poss to Co-Insurer N/A

L1 Enq. 88051 with 5 working days.

(Rd. # 36352.46
82%)

Date/Time, File Pass to?



: Prel. Report



: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee

Transportation

S + RS \$

Photos

Others

TOTAL

Report Format:

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC3/AIG18003364/Kwb3

78 SHENTON WAY #08-16
CHARTIS BUILDING
SINGAPORE 079120

Date : 22-02-2018



Code : AIG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLE 7509K	Veh. Inspected	SHC 5528B
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	22/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	18/02/2018	Inspection Date	21/02/2018
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5528B -**AAD 302-194***Not Authored
1/1/2018*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5528B - JHOW

VF1ABL15AUC278869

RENAULT

LATITUDE

18.02.2018

AIG**PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>Re</i> 768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Re</i> 113.47	✓
4	1	BUMEP R BRACKET SIDE RH REAR	\$	<i>Sm</i> 135.97	X
5	1	BUMEP R RETAINER RH REAR	\$	<i>Sm</i> 44.99	X
6	1	BUMPER REFLECTOR RH	\$	<i>Sm</i> 43.61	X
7	1	BUMEP R BRACKET SIDE LH REAR	\$	<i>Sm</i> 135.97	X
8	1	BUMEP R RETAINER LH REAR	\$	<i>Sm</i> 44.99	X
9	1	BUMPER REFLECTOR LH	\$	<i>Sm</i> 43.61	X
10	1	BUMPER BEAM REAR	\$	<i>Bz</i> 777.52	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>Bz</i> 225.95	✓
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	X
13	1	BOOT REAR	\$	<i>Bz</i> 2,872.68	—
14	1	BOOT FINISHER	\$	<i>Wap</i> 470.06	✓
15	1	BOOT WHEATERSTRIP	\$	<i>Sm</i> 323.05	X
16	1	BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 493.35	✓
17	1	BOOT REFLECTOR LAMP RH	\$	<i>CM</i> 493.35	—
18	1	BOOT BADGE 'RENAULT'	\$	<i>Re</i> 225.36	✓
19	1	BOOT BADGE	\$	<i>Re</i> 225.36	✓
20	1	BOOT STRUT LH	\$	<i>Sm</i> 276.08	} X
21	1	BOOT STRUT RH	\$	<i>Sm</i> 276.08	
22	1	BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1	BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1	BOOT INNER TRIM	\$	<i>Sm</i> 586.45	
25	1	BOOT SWITCH	\$	<i>Sm</i> 168.13	
26	1	BOOT LOCK	\$	<i>R</i> 202.67	
27	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2	LICENCE PLATE LAMP	\$	<i>Sm</i> 50.52	
29	2	BOOT RUBBER PLUG	\$	<i>Sm</i> 221.81	
30	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13	
31	1	WHEELARCH REAR LH	\$	<i>Sm</i> 543.47	
32	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13	
33	1	WHEELARCH REAR RH	\$	<i>Sm</i> 543.47	
34	1	TAILLAMP RH	\$	<i>Sm</i> 552.55	

TRANS-CAB AUTO SERVICES PTE LTD**AAD1802-194**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5528B -

35	1	TAILLAMP PANEL RH	\$	Sn	986.70	X
36	1	TAILLAMP LH	\$	R	552.55	X
37	1	TAILLAMP PANEL LH	\$	R	986.70	X
38	1	OUTER PANEL REAR (End Panel)	\$	B	1,471.77	—
39	1	OUTER PANEL REAR (End Panel)TRIM	\$	Sn	404.56	X
40	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
41	1	SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
42	1	EXHAUST REAR	\$	R	7,489.05	X
43	1	EXHAUST CAP REAR	\$	R	230.49	X

TOTAL	\$	34,526.04
10%	\$	3,452.60
	\$	31,073.44

Specical Nett

1	1SET	PARKING AID	\$	Sn	700.00	X
2	1SET	REAR BUMPER CLIP	\$	R	66.00	—
3	1SET	BUMPER BRACKET CTR CLIP	\$	R	33.00	—
4	1SET	BUMEP R BRACKET SIDE CLIP RH RR	\$	R	10.00	X
5	1SET	BUMEP R RETAINER RH CLIP RR	\$	R	20.00	X
6	1SET	BUMEP R BRACKET SIDE CLIP LH RR	\$	R	10.00	X
7	1SET	BUMEP R RETAINER CLIP LH RR	\$	R	20.00	X
8	1SET	BUMPER LOWER REAR RIVET	\$	R	22.00	X
9	1SET	BUMPER LOWER REAR CLIP	\$	R	66.00	—
10	1	EXHAUST MOUNTING REAR	\$	Sn	17.82	X
11	1SET	BOOT FINISHER CLIP	\$	R	24.20	X
12	1	BOOT STICKER "Trans-cab"	\$	R	30.00	—
13	1	BOOT STICKER "6555-3333"	\$	R	30.00	—
14	1	BOOT INNER TRIM CLIP	\$	R	45.00	X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	R	35.00	X
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	R	35.00	X
19	1	TAILLAMP CLIP RH	\$	R	5.00	X
20	1	TAILLAMP CLIP LH	\$	R	5.00	X
21	2	REAR WINDSCREEN SELANT	\$	R	80.00	X
22	1	WINDSCREEN MOULDING	\$	R	100.00	X
23	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	R	100.00	X
24	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn	385.00	X
25	1	SPARE TYRE	\$	Sn	330.00	X

TOTAL	\$	2,169.02
TOTAL PARTS	\$	33,242.46

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-194

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5528B -

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 <i>660</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 <i>600</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>60</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>60</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>60</i>
To repair and realign rear exhaust pipe.	\$	<i>~</i> 170.00 <i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>~</i> 170.00 <i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>na</i> 380.00 <i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 <i>X</i>
Towing Fees	\$	<i>na</i> 120.00 <i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>na</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>na</i> 220.00 <i>X</i>

(PARTS BY PARTS)**Repair Days****15 Days***5 days*

LIOK Auto Consultants hence notify the Repairer of the following: • To survey vehicle damage • To do a full body painting • Parts and labour subject to confirmation	
TOTAL	\$ 11,160.00
Over All Total	\$ 44,402.46
This is on a "Without Prejudice" basis • No claim for reimbursement is allowed • Compensation must be claimed and is subject to approval from Insurance Company	
Address: _____ Signature: _____ Date: _____	

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	3878K
Vehicle Details	
Vehicle No.:	SHC5528B
Vehicle to be Exported:	Yes
Intended De-registration Date:	20 Feb 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001876
Chassis No.:	VF1ABL15AUC278869
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	15 Aug 2014
First Registration Date:	15 Aug 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Aug 2022
PARF Rebate Amount:	\$9,373.00
Intended COE Rebate Details	

COE Expiry Date:	14 Aug 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,088.00
COE Rebate Amount:	\$28,073.00
Total Rebate Amount:	\$37,446.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 20 Feb 2018

OK



Vivian Lau (LKKAuto)

From: Wui, Shawnkaijye <Shawnkaijye.Wui@aig.com>
Sent: Monday, 5 March, 2018 4:21 PM
To: Vivian Lau (LKKAuto)
Cc: Joy Irene (LKKAuto)
Subject: RE: Your Ref : 6812051433SG, Our Ref : CC3/AIG18003364/Kwb3, ACCIDENT INVOLVING SLE 7509K (Insured) & SHC 5528B (Third Party) ON 18/02/2018 ALONG JUNCTION OF YISHUN CENTRAL & YISHUN AVE 2

Dear Vivian,

As spoken, TP stopped without reason. Please reject TP claim.

Thanks and Regards,
Shawn Wui
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way, #08-16, Singapore 079120

Tel +(65) 6419 1959 | Fax +(65) 6835 7416

Shawnkaijye.Wui@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

From: Vivian Lau (LKKAuto) [mailto:vivianlau@lkkauto.com]
Sent: Monday, March 05, 2018 4:15 PM
To: Wui, Shawnkaijye
Cc: Joy Irene (LKKAuto)
Subject: Your Ref : 6812051433SG, Our Ref : CC3/AIG18003364/Kwb3, ACCIDENT INVOLVING SLE 7509K (Insured) & SHC 5528B (Third Party) ON 18/02/2018 ALONG JUNCTION OF YISHUN CENTRAL & YISHUN AVE 2

Your Ref : 6812051433SG
Our Ref : CC3/AIG18003364/Kwb3

Dear Shawn,

ACCIDENT INVOLVING SLE 7509K (Insured) & SHC 5528B (Third Party) ON 18/02/2018 ALONG JUNCTION OF YISHUN CENTRAL & YISHUN AVE 2

We refer to the above matter

The third party reported that he was travelling on the centre lane. When traffic light is red, suddenly felt an impact from the rear.

Insured reported that he collided onto TP's rear portion

Based on the circumstances of both parties and available information in hand. We are in the opinion that TP move off and stop in the middle of the road with no reason.

As such, we intend to reject the claim.

Kindly advice on your view/opinion/instruction for this claim.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Vivian Lau (LKKAUTO)

From: Vivian Lau (LKKAUTO)
Sent: Monday, 5 March, 2018 4:41 PM
To: 'Jasmine Tan'; 'claims@transcab.com.sg'; 'Ng Wai Yin'; 'Zhe Wei'
Cc: Joy Irene (LKKAUTO)
Subject: Your Ref: SHC 5528B, Our Ref: CC3/AIG18003364/Kwb3,
Attachments: SLE 7509K.MP4; Sketch Plan .pdf

WITHOUT PREJUDICE

Your Ref: SHC 5528B
Our Ref: CC3/AIG18003364/Kwb3

Dear Sir/Madam,

Accident on 18/02/2018 involving SHC 5528B & SLE 7509K

We refer to the above matter

Our insured driver has reiterated that the accident was caused due to the entire negligence of your client. Your client stopped without reason

We attached herewith our insured's accident report and our insured's video for your perusal.

Under such circumstances, we have our principal's instruction to deny liability of your client's claim.

As such, we will close the matter at our end.

Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	20 Feb 2018 Edit Reg		21 Feb 2018 00:00 Edit Adj Rpt	S\$8,050.00 Edit Estimates	S\$8,050.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	HOPE FIRST RESPONSE PTE LTD, Co. Reg. No.: NA								
Main Claimant:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K								
Vehicle Reg. No.:	SHC5528B	Date of Loss:	18/02/2018 18:00 - :59						
Claim Type:	TP / 6812051433SG	Policy/Cover Note No.:	0999994976 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLE7509K	Policy No. (Claimant):	VPX/P1680520						
		Excess:							
Repairer:	Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63, 569111 Ang Mo Kio - Tel: 62876666								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Wui, Shawn-KJ] Shawnkaijye.Wui@aig.com								
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 05/03/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SHC5528B (6812051433SG)**
[SLE7509K]
TP
TRANS-CAB SERVICES PTE LTD
Feb 18 2018 6:00PM
[HOPE FIRST RESPONSE PTE LTD]
Trans-cab Auto Services Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser
------------------	---------------	--------------------	--------------	--------------	---

Video					1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print		
1	23/02/18 16:05	Video - Accident From: OD - Reg. No: SLE7509K, Claimant: HOPE FIRST RESPONSE PTE LTD	Load MP4	☐		

Assessment Reports					1 per page	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print		
1	23/02/18 16:05	Accident Statement From: OD - Reg. No: SLE7509K, Claimant: HOPE FIRST RESPONSE PTE LTD	Load HTM	☐		

Photos/Images					3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print		
1	05/03/18 16:49	General View	Load JPG	☒		
2	05/03/18 16:49	General View	Load JPG	☒		
3	05/03/18 16:49	General View	Load JPG	☒		
4	05/03/18 16:49	General View	Load JPG	☒		
5	05/03/18 16:49	General View	Load JPG	☒		
6	05/03/18 16:49	General View	Load JPG	☒		
7	05/03/18 16:49	General View	Load JPG	☒		
8	05/03/18 16:49	General View	Load JPG	☒		
9	05/03/18 16:49	General View	Load JPG	☒		
10	05/03/18 16:49	General View	Load JPG	☒		
11	05/03/18 16:49	General View	Load JPG	☒		
12	05/03/18 16:49	General View	Load JPG	☒		
13	05/03/18 16:49	General View	Load JPG	☒		
14	05/03/18 16:49	General View	Load JPG	☒		
15	05/03/18 16:49	General View	Load JPG	☒		
16	05/03/18 16:49	General View	Load JPG	☒		
17	05/03/18 16:49	General View	Load JPG	☒		
18	05/03/18 16:49	General View	Load JPG	☒		
19	05/03/18 16:49	General View	Load JPG	☒		
20	05/03/18 16:49	General View	Load JPG	☒		
21	05/03/18 16:49	General View	Load JPG	☒		
22	05/03/18 16:49	General View	Load JPG	☒		
23	05/03/18 16:49	General View	Load JPG	☒		

Documentation					1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print		
1	22/02/18 18:43	TP ESTIMATE- MARKED	Load PDF	☐		
2	22/02/18 18:43	TP GIA REPORT	Load PDF	☐		

3	05/03/18 16:18	Email to AIG to seek advise 5.3.18	1	Load PDF	
4	05/03/18 16:50	Email from AIG to reject claim 5.3.18	1	Load PDF	
5	05/03/18 16:50	Email to wkshop reject claim 5.3.18.	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#)[Save](#)[Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18003364/KWB3Q2

Date: 07/03/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994976
 Claimant Vehicle No: SHC5528B Insured Vehicle No: SLE7509K
 Date of Loss: 18/02/2018 Nature of Claim: TP Claim No: 6812051433SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHC5528B
 Make & Model: RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A) Engine No: M9R8839C001876
 Reg. Date: 15/08/2014 (Man. Year: 2014) Chassis No: VF1ABL15AUC278869
 Colour: Metallic White/Red Odometer: 378913 km
 Engine Capacity: 1995 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
 Front Left Side: Giti 7 mm Rear Left Side: Giti 9 mm
 Front Right Side: Giti 7 mm Rear Right Side: Giti 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	33,242.44	8,546.55	24,695.89	74.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,160.00	1,500.00	9,660.00	86.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	44,402.44	10,046.55	34,355.89	77.37
Approved Total (Overridden) (S\$)		8,050.00		
(S\$)	44,402.44	8,050.00	36,352.44	81.87
+ GST 7.00/7.00% (S\$)	3,108.17	563.50	2,544.67	81.87
Nett Amount (S\$)	47,510.61	8,613.50	38,897.11	81.87
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 21/02/2018
 Date Inspected: 21/02/2018 Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
 2, Ang Mo Kio Street 63
 Singapore 569111
 Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	1,108.46 FL	*1,108.46 FL
2	1		*BUMPER LOWER REAR	Dented	768.84 FL	*768.84 FL
3	1		*BUMPER BRACKET CTR REAR	Dented	113.47 FL	*113.47 FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	135.97 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	44.99 FL	*- FL
6	1		*BUMPER REFLECTOR RH	Serviceable	43.61 FL	*- FL
7	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	135.97 FL	*- FL
8	1		*BUMPER RETAINER LH REAR	Serviceable	44.99 FL	*- FL
9	1		*BUMPER REFLECTOR LH	Serviceable	43.61 FL	*- FL
10	1		*BUMPER BEAM REAR	Bent	777.52 FL	*777.52 FL
11	1		*BUMPER BEAM BRACKET LH REAR	Bent	225.95 FL	*225.95 FL
12	1		*BUMPER BEAM BRACKET RH REAR	Repair	225.95 FL	*- FL
13	1		*BOOT REAR	Bent	2,872.68 FL	*2,872.68 FL
14	1		*BOOT FINISHER	Warped	470.06 FL	*470.06 FL
15	1		*BOOT WEATHERSTRIP	Serviceable	323.05 FL	*- FL
16	1		*BOOT RELECTOR LAMP LH	Cracked	493.35 FL	*493.35 FL
17	1		*BOOT RELECTOR LAMP RH	Cracked	493.35 FL	*493.35 FL
18	1		*BOOT BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
19	1		*BOOT BADGE	Necessary	225.36 FL	*225.36 FL
20	1		*BOOT STRUT LH	Serviceable	276.08 FL	*- FL
21	1		*BOOT STRUT RH	Serviceable	276.08 FL	*- FL
22	1		*BOOT HINGE LH	Repair	367.84 FL	*- FL
23	1		*BOOT HINGE RH	Repair	367.84 FL	*- FL
24	1		*BOOT INNER TRIM	Serviceable	586.45 FL	*- FL
25	1		*BOOT SWITCH	Serviceable	168.13 FL	*- FL
26	1		*BOOT LOCK	Repair	202.67 FL	*- FL
27	1		*BOOT LOCK CATCH	Repair	74.40 FL	*- FL
28	2		*LICENCE PLATE LAMP	Serviceable	50.52 FL	*- FL
29	1		*BOOT RUBBER PLUG	Serviceable	221.81 FL	*- FL
30	1		*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
31	1		*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
32	1		*FENDER PANEL REAR RH	Repair	3,299.13 FL	*- FL
33	1		*WHEELARCH REAR RH	Serviceable	543.47 FL	*- FL
34	1		*TAILLAMP RH	Serviceable	552.55 FL	*- FL
35	1		*TAILLAMP PANEL RH	Serviceable	986.70 FL	*- FL
36	1		*TAILLAMP LH	Repair	552.55 FL	*- FL
37	1		*TAILLAMP PANEL LH	Repair	986.70 FL	*- FL
38	1		*OUTER PANEL REAR (END PANEL)	Bent	1,471.77 FL	*1,471.77 FL
39	1		*OUTER PANEL REAR (END PANEL)TRIM	Serviceable	404.56 FL	*- FL
40	1		*SPARE WHEEL PANEL(LUGGAGE FLOOR PANEL)	Repair	2,189.88 FL	*- FL
41	1		*SPARE WHEEL PANEL TRIM	Serviceable	612.21 FL	*- FL
42	1		*EXHAUST REAR	Repair	7,489.05 FL	*- FL
43	1		*EXHAUST CAP REAR	Repair	230.49 FL	*- FL
44	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
45	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
46	1		*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
47	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
48	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
49	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
51	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS
52	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
53	1		*EXHAUST MOUNTING REAR	Serviceable	17.82 FS	*- FS
54	1		*SET BOOT FINISHER CLIP	Not Necessary	24.20 FS	*- FS
55	1		*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
56	1		*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
57	1		*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
58	1		*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary	35.00 FS	*- FS
59	1		*SET FENDER WHEELARCH REAR LH CLIP	Not Necessary	35.00 FS	*- FS
60	1		*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*- FS
61	1		*TAILLAMP CLIP LH	Not Necessary	5.00 FS	*- FS
62	2		*REAR WINDSCREEN SEALANT	Not Necessary	80.00 FS	*- FS
63	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
64	1		*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
65	1		*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*- FS
66	1		*SPARE TYRE	Serviceable	330.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	36,695.04	9,471.17
- List Item Discount on L Items 10.00/10.00% (\$\$)	3,452.60	924.62
Total Parts (\$\$)	33,242.44	8,546.55

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,500.00	660.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	4,200.00	600.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	60.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
5	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	60.00
6	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
7	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
8	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST)	New	170.00	60.00
9	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST)	New	170.00	0.00
10	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
11	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
12	TOWING FEES	New	120.00	0.00
13	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST	New	170.00	0.00
14	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
Gross Labour Cost (S\$)			11,160.00	1,500.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >