

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5528B -**AAD1802-194***Not Authored
1/1/2018*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5528B - JHOW

VF1ABL15AUC278869

RENAULT

LATITUDE

18.02.2018

AIG

PART			LIST		
1	1	BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>Net</i> 768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Net</i> 113.47	✓
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sm</i> 135.97	X
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sm</i> 44.99	X
6	1	BUMPER REFLECTOR RH	\$	<i>Sm</i> 43.61	X
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sm</i> 135.97	X
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sm</i> 44.99	X
9	1	BUMPER REFLECTOR LH	\$	<i>Sm</i> 43.61	X
10	1	BUMPER BEAM REAR	\$	<i>Bz</i> 777.52	✓
11	1	BUMPER BEAM BRACKET LH REAR	\$	<i>Bz</i> 225.95	✓
12	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	X
13	1	BOOT REAR	\$	<i>Bz</i> 2,872.68	—
14	1	BOOT FINISHER	\$	<i>Wap</i> 470.06	✓
15	1	BOOT WHEATERSTRIP	\$	<i>Sm</i> 323.05	X
16	1	BOOT REFLECTOR LAMP LH	\$	<i>CM</i> 493.35	—
17	1	BOOT REFLECTOR LAMP RH	\$	<i>CM</i> 493.35	—
18	1	BOOT BADGE 'RENAULT'	\$	<i>Sm</i> 225.36	—
19	1	BOOT BADGE	\$	<i>Sm</i> 225.36	—
20	1	BOOT STRUT LH	\$	<i>Sm</i> 276.08	} X
21	1	BOOT STRUT RH	\$	<i>Sm</i> 276.08	
22	1	BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1	BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1	BOOT INNER TRIM	\$	<i>Sm</i> 586.45	
25	1	BOOT SWITCH	\$	<i>Sm</i> 168.13	
26	1	BOOT LOCK	\$	<i>R</i> 202.67	
27	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2	LICENCE PLATE LAMP	\$	<i>Sm</i> 50.52	
29	2	BOOT RUBBER PLUG	\$	<i>Sm</i> 221.81	
30	1	FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13	
31	1	WHEELARCH REAR LH	\$	<i>Sm</i> 543.47	
32	1	FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13	
33	1	WHEELARCH REAR RH	\$	<i>Sm</i> 543.47	
34	1	TAILLAMP RH	\$	<i>Sm</i> 552.55	

TRANS-CAB AUTO SERVICES PTE LTD**AAD1802-194**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5528B -

35	1	TAILLAMP PANEL RH	\$	Sn 986.70 X
36	1	TAILLAMP LH	\$	R 552.55 X
37	1	TAILLAMP PANEL LH	\$	R 986.70 X
38	1	OUTER PANEL REAR (End Panel)	\$	B 1,471.77 —
39	1	OUTER PANEL REAR (End Panel)TRIM	\$	Sn 404.56 X
40	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R 2,189.88 X
41	1	SPARE WHEEL PANEL TRIM	\$	Sn 612.21 X
42	1	EXHAUST REAR	\$	R 7,489.05 X
43	1	EXHAUST CAP REAR	\$	R 230.49 X

TOTAL	\$	34,526.04
10%	\$	3,452.60
	\$	31,073.44

Specical Nett

1	1SET	PARKING AID	\$	Sn 700.00 X
2	1SET	REAR BUMPER CLIP	\$	R 66.00 —
3	1SET	BUMPER BRACKET CTR CLIP	\$	R 33.00 —
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	R 10.00 X
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	R 20.00 X
6	1SET	BUMEPR BRACKET SIDE CLIP LH RR	\$	R 10.00 X
7	1SET	BUMEPR RETAINER CLIP LH RR	\$	R 20.00 X
8	1SET	BUMPER LOWER REAR RIVET	\$	R 22.00 X
9	1SET	BUMPER LOWER REAR CLIP	\$	R 66.00 —
10	1	EXHAUST MOUNTING REAR	\$	Sn 17.82 X
11	1SET	BOOT FINISHER CLIP	\$	R 24.20 X
12	1	BOOT STICKER "Trans-cab"	\$	R 30.00 —
13	1	BOOT STICKER "6555-3333"	\$	R 30.00 —
14	1	BOOT INNER TRIM CLIP	\$	R 45.00 X
15	1SET	FENDER WHEELARCH REAR RH CLIP	\$	R 35.00 X
16	1SET	FENDER WHEELARCH REAR LH CLIP	\$	R 35.00 X
19	1	TAILLAMP CLIP RH	\$	R 5.00 X
20	1	TAILLAMP CLIP LH	\$	R 5.00 X
21	2	REAR WINDSCREEN SELANT	\$	R 80.00 X
22	1	WINDSCREEN MOULDING	\$	R 100.00 X
23	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	R 100.00 X
24	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	Sn 385.00 X
25	1	SPARE TYRE	\$	Sn 330.00 X

TOTAL	\$	2,169.02
TOTAL PARTS	\$	33,242.46

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-194

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5528B -

Putty And Spray Painting Of The Affected Portion.	\$	4,500.00 <i>660</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00 <i>600</i>
To Rust-Proofing Of The Affected Areas.	\$	170.00 <i>60</i>
To reinstall rear bumper parking sensor.	\$	170.00 <i>60</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 <i>60</i>
To repair and realign rear exhaust pipe.	\$	<i>~</i> 170.00 <i>X</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	<i>~</i> 170.00 <i>X</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00 } <i>60</i>
To supply and re-do rear luggage floor panel insulation padding.	\$	<i>~</i> 380.00 <i>X</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>~</i> 380.00 <i>X</i>
Towing Fees	\$	<i>~</i> 120.00 <i>X</i>
To transfer of rear windscreen fittings and conduct water seepage test.	\$	<i>~</i> 170.00 <i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>~</i> 220.00 <i>X</i>

(PARTS BY PARTS)**Repair Days**

LKK Auto Consultants hence notify the Repairer of the following:

• To resurvey before/after spray painting

• To display damaged parts for survey

• Parts prices are subject to confirmation

• Survey is on a "Without Prejudice" basis

• No illegal modification(s) is allowed

• Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL \$**11,160.00****Over All Total \$****44,402.46****15 Days***5 day*