

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02

SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511

CO. REG:200707743D GST REG:200707743D

14-Feb-18

## ESTIMATE REPAIR BILL FOR TOYOTA PRIUS REGN NO: SHD 1830 Z

1 pc	N/s taillamp <i>X old large</i>	\$	541.70
1 pc	Rear bumper lower cover <i>X</i>	\$	118.10
1 pc	Rear Bumper <i>/</i>	\$	458.60
2 pcs	Rear bumper side bracket @\$94.80 <i>?</i>	\$	189.60
1 pc	Rear bumper reinforcement <i>?</i>	\$	205.70
2 pcs	Rear Bumper Stay o/s & n/s @\$139.60 <i>X</i>	\$	279.20

\$ 1,792.90

Less 25%

\$ 448.22

\$ 1,344.68

### S/NETT

1 set	Rear bumper clips <i>/</i>	\$	48.00
1 set	Reverse sensor <i>/</i>	\$	280.00 <i>200</i>

Sundry

\$ 50.00 *X*

To check wiring

\$ 50.00 *X*

To dismantle and refit the inner garnishes, inner linings, inner trims, inner trays to facilitate repairs.

\$ 200.00 *X*

To dismantle / refit reverse sensor into new bumper and test system

\$ 80.00 *20*

To dismantle and replace the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the end panel, etc.

\$ 600.00 *200*

To putty and spray painting on the rear bumper, end panel. *X*

\$ 550.00 *180*

To apply rustproofing onto the repaired and replaced panels.

\$ 150.00 *X*

\$ 3,352.68

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

the Repairer of the following:

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Calu 1664*  
*2/2/18 1005h.*  
*2 P.T.*  
*4/3*  
*After Repair photo*