

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018613
HY-5 Solution Pte Ltd

Page 1 of 3
Your ref. TP-SHC 2193C India
Job No. 69251
Our ref. 18.02.28
Payment
Date 21/2/2018

Attn

Vehicle No GV 5985B
Vehicle Model : Isuzu TFS69H29
Accident on ... 18/2/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Front bumper	600.00	15.00	510.00
1.00	Pc	Front bumper beam LH	200.00	15.00	170.00
1.00	Pc	Front bumper beam RH	200.00	15.00	170.00
1.00	Pc	Front bumper bracket LH	90.00	15.00	76.50
1.00	Pc	Front bumper bracket RH	90.00	15.00	76.50
1.00	Pc	Front bumper signal lamp LH	90.00	15.00	76.50
1.00	Pc	Front bumper retainer LH	35.00	15.00	29.75
1.00	Pc	Front bumper retainer RH	35.00	15.00	29.75
1.00	Pc	Front bumper retainer, centre	45.00	15.00	38.25
1.00	Pc	Radiator grille	720.00	15.00	612.00
1.00	Pc	Radiator grille logo	90.00	15.00	76.50
1.00	Pc	Front headlamp with bracket LH	250.00	15.00	212.50
1.00	Pc	Front headlamp with bracket RH	250.00	15.00	212.50
1.00	Pc	Front side lamp LH	90.00	15.00	76.50
1.00	Pc	Front side lamp RH	90.00	15.00	76.50
1.00	Pc	Air con condenser	200.00	15.00	170.00
1.00	Pc	Front brace panel	50.00	15.00	42.50
1.00	Pc	Radiator	1,150.00	15.00	977.50

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。
除外，还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018613
HY-5 Solution Pte Ltd

Page 2 of 3
Your ref. TP-SHC 2193C India
Job No. 69251
Our ref. 18.02.28
Payment
Date 21/2/2018

Attn

Vehicle No GV 5985B
Vehicle Model : Isuzu TFS69H29
Accident on ... 18/2/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00	Pc	Radiator fan clutch	P 400.00	15.00	340.00
1.00	Pc	Radiator fan blade	P 35.00	15.00	29.75
3.00	Pcs	Radiator fan clutch silicon	P 5.00	25.00	11.25
1.00	Pc	Front support panel	R ✓ 600.00	15.00	510.00
Special nett item:					
1.00	Pc	Front number plate	35.00	✓	35.00
Labour & Misc:					
1.00		Towing fee	180.00	✓ 20	180.00
1.00		To dismantle + renew air con condenser and refill gas	120.00	✓ 10	120.00
1.00		To dismantle + renew radiator fan clutch + blade, etc	60.00	✓	60.00
1.00		To straighten front body including cutting	700.00	650	700.00

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。
除外, 还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018613
HY-5 Solution Pte Ltd

Page 3 of 3
Your ref. TP-SHC 2193C India
Job No 69251
Our ref 18.02.28
Payment
Date 21/2/2018

Attn

Vehicle No GV 5985B
Vehicle Model : Isuzu TFS69H29
Accident on ... 18/2/2018

Quantity	Unit	Description	Unit price	Disc. pot	Amount
		and welding, to knock dents on front fender RH and renew of parts			
1.00		To spray paint	600.00		600.00 550.00

note:
To add labour for
repairing support frame
~~Radiator fan~~
Clutch fan gear.
To disassemble take photo

Not Authorised
H&S Repair.
After paint photo
NKK Auto (M)
22/2/2018
6w plays

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Sub-Total 6,219.75
GST 7.00% 435.38
Total S\$ 6,655.13

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。
除外, 还有先进的 SAICO Deluxe 喷漆烘炉。
"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."