

来發 (明记) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 375679, Tel: 6453 8110 Fax: 6459 6267
 RCB No: 199407592C

ESTIMATE

EST. No: EST0018613
 HY-5 Solution Pte Ltd

Page: 1 of 3
 Your ref.: TP-SHC 2193C India
 Job No.: 69251
 Our ref.: 18.02.28
 Payment
 Date: 21/2/2018

Attn

Vehicle No: GV 5985B
 Vehicle Model : Isuzu TFS69H29
 Accident on ...: 18/2/2018

Quantity	Unit	Description	Unit price	Disc. pct	Amount
Supply of Parts:					
1.00	Pc	Front bumper	det ✓ 600.00	15.00	510.00
1.00	Pc	Front bumper beam LH	bt ✓ 200.00	15.00	170.00
1.00	Pc	Front bumper beam RH	bt ✓ 200.00	15.00	170.00
1.00	Pc	Front bumper bracket LH	bt ✓ 90.00	15.00	76.50
1.00	Pc	Front bumper bracket RH	bt ✓ 90.00	15.00	76.50
1.00	Pc	Front bumper signal lamp LH	av ✓ 90.00	15.00	76.50
1.00	Pc	Front bumper retainer LH	dis ✓ 35.00	15.00	29.75
1.00	Pc	Front bumper retainer RH	dis ✓ 35.00	15.00	29.75
1.00	Pc	Front bumper retainer, centre	bt ✓ 45.00	15.00	38.25
1.00	Pc	Radiator grille	mic ✓ 720.00	15.00	612.00
1.00	Pc	Radiator grille logo	mic ✓ 90.00	15.00	76.50
1.00	Pc	Front headlamp with bracket LH	bt ✓ 250.00	15.00	212.50
1.00	Pc	Front headlamp with bracket RH	bt ✓ 250.00	15.00	212.50
1.00	Pc	Front side lamp LH	av ✓ 90.00	15.00	76.50
1.00	Pc	Front side lamp RH	av ✓ 90.00	15.00	76.50
1.00	Pc	Air con condenser	bt ✓ 200.00	15.00	170.00
1.00	Pc	Front brace panel	bt ✓ 50.00	15.00	42.50
1.00	Pc	Radiator	bt ✓ 1,150.00	15.00	977.50

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 记) 摩 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018613
HY-5 Solution Pte Ltd

Page 2 of 3
Your ref. TP-SHC 2193C India
Job No. 69251
Our ref. 18.02.28
Payment
Date 21/2/2018

Attn

Vehicle No ... GV 5985B
Vehicle Model : Isuzu TFS69H29
Accident on ... 18/2/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00	Pc	Radiator fan clutch	400.00	15.00	340.00
1.00	Pc	Radiator fan blade	35.00	15.00	29.75
3.00	Pcs	Radiator fan clutch silicon	5.00	15.00	11.25
1.00	Pc	Front support panel	600.00	15.00	510.00
Special nett item:					
1.00	Pc	Front number plate	35.00		35.00
Labour & Misc:					
1.00		Towing fee	180.00		180.00
1.00		To dismantle + renew air con condenser and refill gas	120.00		120.00
1.00		To dismantle + renew radiator fan clutch + blade, etc	60.00		60.00
1.00		To straighten front body including cutting	700.00		700.00

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0018613
HY-5 Solution Pte Ltd

Page 3 of 3
Your ref. TP-SHC 2193C India
Job No 69251
Our ref 18.02.28
Payment
Date 21/2/2018

Attn

Vehicle No GV 5985B
Vehicle Model : Isuzu TFS69H29
Accident on ... 18/2/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
		and welding, to knock dents on front fender RH and renew of parts			
1.00		To spray paint	600.00		550.00

note:
To add labour for
repairing support panel
Radiator fan
Clutch fan jam.
To dismantle take photo

Not Authorised
HS Repair.
After paint photo
LKK Auto (M).
22/2/2018.
6w/1day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Sub-Total 6,219.75
GST 7.00% 435.38
Total \$ 6,655.13

本公司拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给予快速与准确的测量方式和大铁修理。除外, 还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明 记) 嘛 哆 有 限 公 司
LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

SUPPLEMENTARY

ESTIMATE

EST No EST0018613
HY-5 Solution Pte Ltd

Page 1 of 1
Your ref. TP-SHC 2193C India
Job No 69251
Our ref 18.02.28
Payment
Date 28/2/2018

Attn

Vehicle No GV 5985B
Vehicle Model .. Isuzu TFS69H29
Accident on ... 18/2/2018

Quantity	Unit	Description	Unit price	Disc. pct	Amount
SUPPLEMENTARY ITEM:					
1.00		To knock dents on front chassis panel RH	250.00		250.00

Sub-Total 250.00
GST 7.00% 17.50
Total S\$ 267.50

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给予快速与准确的测量方式和大快修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."