

ASS. REC. BY:

REF:

es/FCI18003375/Ktd300

Special Instruction:

Surveyor:

CWS

Kenneth

ASSIGNMENT (Office)

From (Person):

Eileen Lee

of

FCI

Date/Time:

20/2/18 @ 2:28pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJJ 8500A

Insured:

SHD 3678J

at Workshop in/s

Esteem Performance

Tel:

6753 2112

of

Blk S033, AMK Ind. Prk 2 # 01-251/259

Policy No:

Claim No:

D18001442MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

15/2/2018

CA / REV / REP. / REV 24 HRS

wp

H.O.D. Endorsement:

Date/Time:

5:28pm @ 20/2/18

Person Contacted:

Carmen

Vehicle IN/OUT

Date/Time	Action/Instruction	Estimate
	SJJ 8500A - NS/INC18003375/PL13	D.O.A. 15/2/18
	SHD 3678J - CC3/AXA/11011431/1119/CS7	D.O.A. 13/06/11
7/7/18 @ 4.56pm	Varied to Eileen Lee by email.	
	Part by Part \$7251.12 (Red. 3748.50, 34%)	

02 16

22/2 Rk pass to write

$$= 1 \text{ ton kok}$$
[illegible]

RECEIVED 27 JUL 2010

7251.12

100 0 100 0 100 0

30

365




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18003375/Ktd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 22-02-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 3678J	Veh. Inspected	SJJ 8500A
Policy No.		Coverage (\$)	0.00
Claim No.	D18001442MFSH	Excess (\$)	0.00
Assign From	CWS (EILEEN LEE)	Assign Date	22/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	15/02/2018	Inspection Date	21/02/2018
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

MOTOR SURVEY ASSIGNMENT

Date	19-02-2018	Our Ref No. D18001442MFSH
Accident Date	15-02-2018	Claim Type. Third Party
Insured Vehicle	SHD3678J	Third Party Vehicle. SJJ8500A
Survey Location	BLK 5033 ANG MO KIO, IND PARK 2 #01-251/259	
Contact Person.	CARMEN LIM	
Contact No.	64841221/ 0	Fax No. 64847829
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	ESTEEM PERFORMANCE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235104)



PRI Documents



Close



PRI Header Details

Claim No	D18001442MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & ESTEEM P
Workshop Name	ESTEEM PERFORMANCE PTE LTD (Contact Person : CARMEN LIM)	Survey Location & Contact Details	BLK 5033 ANG MO KIO, IND PARK 2 #01-251/259 Mobile: 0 , Phone: 64841221 , Fax: 64847829 EmailId: CARMEN@ESTEEMPERF.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHD3678J	TP Vehicle No	SJJ8500A
PRI Recieved Date	20-02-2018 01:03:11 PM	Surveyor Appointed Date	20-02-2018 02:27:58 PM	Surveyor Accept Date	22-02-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	22-02-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Friday, 23 February 2018 4:56 PM
To: 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18001442MFSH/1
Attachments: CSFCI18003375Ktd3.pdf

Importance: Low

Dear Eileen,

Enclosed herewith preliminary advice of SJJ 8500A.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)

Sent: Tuesday, 20 February 2018 5:36 PM

To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>

Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>

Subject: RE: SURVEY ASSESSMENT - D18001442MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]

Sent: Tuesday, 20 February 2018 2:28 PM

To: ASSIGNMENTS@LKKAUTO.COM

Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG

Subject: PRI: SURVEY ASSESSMENT - D18001442MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001442MFSH

Date: 23 February 2018

Our Ref: CS/FCI18003375/Ktd3

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SJJ 8500A .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 21/02/2018 at the premises of M/s ESTEEM PERFORMANCE. and have the following to report:-

Workshop Estimate Amount	: <u>S\$ 10,999.68</u> .
Revised Estimate Amount	: <u>S\$ 6,961.44</u> .
"Check" Items Amount	: <u>S\$ 1,417.44</u> .
Market Value	: <u>S\$ -</u> .
LTA Reimbursement Value	: <u>S\$ -</u> .
Nett Value	: <u>S\$ -</u> .

Description of Damage:

The vehicle sustained damages at the rear & front o/s portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	15/02/2018 08:39
Date Of Accident	15/02/2018 06:40
Exact Location Of Accident	CHANGI AIRPORT TERMINAL 2 DEPARTURE HALL
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJJ8500A
Insured/Policyholder	
Name Of Registered Owner	CHUAN TRANSPORT LINK
Co Reg No	53354297M
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-86123733
Alternative Phone No	OFFICE-86123733

Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5087921467-01
Cover Note Number	

Driver

Name of Driver	NG SOON CHUAN
NRIC No	S1369255F
Date Of Birth	09/09/1959
Occupation	OUTDOOR
Date Of Driving Pass	30/03/1978
Driving Experience	39 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-86123733
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	BLK 296B #02-70 BUKIT BATOK STREET 22 SKYLINE II @ BUKIT BATOK
Postcode	652296
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

THE TRAFFIC WAS HEAVY. A VEHICLE KNOCKED INTO ME FROM BEHIND, CAUSING ME TO HIT THE VEHICLE IN FRONT. (ATTENDED BY: JAMES NG)

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	CANNOT BE UPLOADED
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHD3678J
Vehicle Make/Model/Colour	TOYOTA / BLUE COMFORT TAXI
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	TAN CHENG SWEE
NRIC/Passport Number	S1218598G
Contact Number	
Address	BLK 275 TOH GUAN ROAD #15-153
Postcode	600275
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SH9778M
Vehicle Make/Model/Colour	HYUNDAI / BLUE COMFORT TAXI
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	S0239121Z
Contact Number	
Address	BLK 181 BISHAN ST 13 #05-247
Postcode	570181
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

CHUAN TRANSPORT LINK
Co Reg No: 53354297M

Policyholder's Signature

Date & Time: **15 FEB 2018**

Driver's Signature
(If driver is not the policyholder)

Date & Time: **15 FEB 2018**


Reporting Centre Personnel's Signature

Name: **NG WING KIN JAMES**
NRIC/FIN No.: **S7927881E**



CHUAN TRANSPORT LINK
Co Reg No: 53354297M

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

A: SHJ 8500A
B: SHV 3678J
C: SH 9 778M

Refer
Statement

DECLARATION

I/We declare the foregoing particulars are true in every respect.

CHUAN TRANSPORT LINK
Co Reg No: 53354297M

Policyholder's Signature

Date & Time: 15 FEB 2018

Driver's Signature

(If driver is not the policyholder)

Date & Time: 15 FEB 2018



Reporting Centre Personnel's Signature

Name: NG WING KIN JAMES
NRIC/FIN No.: S7927881E

TP. Just Capital.

1/17



ESTEEM PERFORMANCE PTE LTD

Bik 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7828 Website: www.esteemperf.com.sg

Repair Estimates

SJJ 8500 A

Parts	(a) Cost / List Price Items	\$	8,837.10
	Plus/Less 20%	\$	1,767.42
	Total of Cost / List	\$	7,069.68
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	250.00
Total Parts Cost		\$	7,319.68
Labour		\$	3,680.00
Total		\$	10,999.68

Finalised.

5913.90
1182.78
4731.12

Not Authorized
1.B1
Resurvey B4 part

240

4971.12

2280

7251.12

✓ ok

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Kenneth

Company

Ukle

Survey conducted on

21/2/18

at

10:00

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 07 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$

(e) Signature of surveyor

Le

Date: 21/2/18



ESTEEM PERFORMANCE LIMITED

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemparf.com.sg

Spare Parts

Vehicle No. : **SJJ 8500 A**
Make & Model : **HONDA VEZEL**
Chassis No : **RU1-1105271**

Submit By : **Carmen Lim**
Year Manufacture : **2015**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Headlamp RH <i>CND</i>	1	\$1,784.50		✓
2	Front bumper <i>Bz</i>	1	\$463.70		✓
3	Front bumper clip <i>mu</i>	10	\$39.00		✓
4	Front bumper reinforcement <i>R</i>	1	\$321.00		✓ X
5	Front bumper side retainer RH <i>Diy</i>	1	\$22.00		✓
6	Front bumper bracket RH <i>R</i>	1	\$35.00		✓ X
7	Front bumper lower garnish <i>Bur</i>	1	\$225.60		✓
8	Fog lamp RH <i>CND</i>	1	\$357.70		✓
9	Fog lamp garnish RH <i>Sm</i>	1	\$65.00		✓ X
10	RH front fender <i>Bur</i>	1	\$598.70		✓
11	RH front fender undershield <i>Sm</i>	1	\$160.00		X
12	RH front fender undershield clip <i>mu</i>	10	\$35.00		X
13	RH front fender protector <i>Bur</i>	1	\$183.00		✓
14	RH front fender protector clip <i>mu</i>	10			✓
15	Rear windscreen moulding <i>mu</i>	1	\$155.00		✓
16	Rear windscreen sealant <i>mu</i>	1	\$50.00	S.N	<i>Pass</i>
17	Reverse sensor <i>Short</i>	2	\$200.00	S.N	✓
18	Rear bumper <i>Bz</i>	1	\$493.70		✓
19	Rear bumper clip <i>mu</i>	10	\$39.00		✓
20	Rear bumper side retainer LH <i>Sm</i>	1	\$32.00		X
21	Rear bumper side retainer RH <i>Sm</i>	1	\$32.00		X
22	Rear bumper reflector LH <i>Sm</i>	1	\$145.00		X
23	Rear bumper reflector RH <i>Sm</i>	1	\$145.00		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

4361.90
240 (S.N).

Spare Parts

Vehicle No. : **SJJ 8500 A**
 Make & Model : **HONDA VEZEL**
 Chassis No : **RU1-1105271**

Submit By : **Carmen Lim**
 Year Manufacture : **2015**
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail door <i>Ry</i>	1	\$953.70		✓
25	Tail door lock <i>Tm</i>	1	\$180.00		✓
26	Tail door emblem <i>Nu</i>	1	\$22.00		X
27	Wording "VEZEL" <i>Nu</i>	1	\$56.20		✓
28	Tail end panel <i>Repair</i>	1	\$415.60		X
29	Tail end panel garnish <i>Nd</i>	1	\$92.30		✓
30	Tail end panel garnish clip <i>Nu</i>	8	\$28.00		✓
31	Boot weatherstrip <i>Cut</i>	1	\$116.80		✓
32	Tail door trim <i>Sm</i>	1	\$225.00		X
33	Tail door trim clip <i>un</i>	10	\$35.00		X
34	Spare tyre well panel <i>K</i>	1	\$1,130.00		X
35	Spare tyre board <i>Sm</i>	1	\$250.60		X
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SJJ 8500 A** Submit By : **Carmen Lim**
Make & Model : **HONDA VEZEL** Year of Manufacture : **2015**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER,RHF FENDER,RR BUMPER, TAILDOOR,END PANEL,SPARE TYRE WELL PANEL)	\$1,400.00	900
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER,RHF FENDER,RR BUMPER, TAILDOOR,END PANEL,SPARE TYRE WELL PANEL)	\$1,400.00	1000
3	To check wiring	\$50.00	40
4	To remove & refit reverse sensor	\$120.00	50
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>nn</i>	\$150.00	60 70
6	To remove & refit rear windscreen.	\$120.00	✓
7	To tuff coat.	\$200.00	90
8	To transfer boot mechanism to new boot	\$120.00	60
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteempert.com.sg

Repair Estimates

SJJ 8500 A

Parts	(a) Cost / List Price Items	\$	8,837.10
	Plus/Less 20%	\$	1,767.42
	Total of Cost / List	\$	7,069.68
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	250.00
Total Parts Cost		\$	7,319.68
Labour		\$	3,680.00
Total		\$	10,999.68

Not Authorized
I.B.I
Resurvey B4 pain

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before respray painting
- To display damaged parts during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be submitted and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 21/12/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 07 day(s)

(c) Resurvey : Required / ~~Not Required~~

(d) Excess : \$ _____

(e) Signature of surveyor : Lc Date: 21/12/18

ESTEEM PERFORMANCE PTE LTD

BLK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-259 SINGAPORE 569536

Tel:64841221 Fax:64847829

Spare Parts

Vehicle No. :

Make & Model :

Chassis No. :

SJJ 8500 A

HONDA VEZEL

RU1-1105271

Submit By :

Year Manufacture :

Engine No. :

Cost / List**CARMEN LIM**

2015

Supplementary

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Buzzer Sensor <i>cm</i>	1	\$125.00 ✓		
2		1			
3		1			
4		1			
5		1			
6		1			
7		1			
8		1			
9		1			
10		1			
11		1			
12		1			
13		1			
14		1			
15		1			
16		1			
17		1			
18		1			
19		1			
20		4			
21		1			
22		1			
23		1			

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge

125



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SJJ 8500 A**
Make & Model : **HONDA VEZEL**
Chassis No. : **RU1-1105271**

Submit By : **Carmen Lim**
Year Manufacture : **2015**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Headlamp RH <i>CMJ</i>	1	\$1,784.50		✓
2	Front bumper <i>Ry</i>	1	\$463.70		✓
3	Front bumper clip <i>Mr</i>	10	\$39.00		✓
4	Front bumper reinforcement	1	\$321.00		?
5	Front bumper side retainer RH <i>D.Y</i>	1	\$22.00		✓
6	Front bumper bracket RH	1	\$35.00		?
7	Front bumper lower garnish <i>Bu</i>	1	\$225.60		✓
8	Fog lamp RH <i>CMJ</i>	1	\$357.70		✓
9	Fog lamp garnish RH	1	\$65.00		?
10	RH front fender <i>Bu</i>	1	\$598.70		✓
11	RH front fender undershield <i>Sh</i>	1	\$160.00		X
12	RH front fender undershield clip <i>Mr</i>	10	\$35.00		X
13	RH front fender protector <i>Bu</i>	1	\$183.00		✓
14	RH front fender protector clip <i>Mr</i>	10			✓
15	Rear windscreen moulding <i>Mr</i>	1	\$155.00		✓
16	Rear windscreen sealant <i>Mr</i>	1	\$50.00	S.N	<i>Pass</i>
17	Reverse sensor <i>Shorn</i>	2	\$200.00	S.N	✓
18	Rear bumper <i>Ry</i>	1	\$493.70		✓
19	Rear bumper clip <i>Mr</i>	10	\$39.00		✓
20	Rear bumper side retainer LH <i>Sh</i>	1	\$32.00		X
21	Rear bumper side retainer RH <i>Sh</i>	1	\$32.00		X
22	Rear bumper reflector LH <i>Sh</i>	1	\$145.00		X
23	Rear bumper reflector RH <i>Sh</i>	1	\$145.00		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SJJ 8500 A**
 Make & Model : **HONDA VEZEL**
 Chassis No. : **RU1-1105271**

Submit By : **Carmen Lim**
 Year Manufacture : **2015**
 Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	Tail door <i>R₁</i>	1	\$953.70		✓
25	Tail door lock <i>T₁</i>	1	\$180.00		✓
26	Tail door emblem <i>N₂</i>	1	\$22.00		X
27	Wording "VEZEL" <i>N₂</i>	1	\$56.20		✓
28	Tail end panel	1	\$415.60		?
29	Tail end panel garnish	1	\$92.30		?
30	Tail end panel garnish clip	8	\$28.00		?
31	Boot weatherstrip	1	\$116.80		?
32	Tail door trim	1	\$225.00		?
33	Tail door trim clip	10	\$35.00		?
34	Spare tyre well panel <i>R</i>	1	\$1,130.00		X
35	Spare tyre board	1	\$250.60		?
36					
37					
38					
39					
40					
41					
42					
43					
44					
45					
46					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : SJJ 8500 A Submit By : Carmen Lim
Make & Model : HONDA VEZEL Year of Manufacture : 2015

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER,RHF FENDER,RR BUMPER, TAILDOOR,END PANEL,SPARE TYRE WELL PANEL)	\$1,400.00	900
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (FRONT BUMPER,RHF FENDER,RR BUMPER, TAILDOOR,END PANEL,SPARE TYRE WELL PANEL)	\$1,400.00	1000
3	To check wiring	\$50.00	40
4	To remove & refit reverse sensor	\$120.00	50
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	7
6	To remove & refit rear windscreen.	\$120.00	✓
7	To tuff coat.	\$200.00	90
8	To transfer boot mechanism to new boot	\$120.00	60
9	To conduct water leakage tests to ensure proper air and sealing	\$120.00	20

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18003375/Ktd3e2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 09-05-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHD 3678J	Veh. Inspected	SJJ 8500A	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18001442MFSH	Excess (\$)	0.00	
Assign From	EILEEN LEE	Assign Date	20/02/2018	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	RU11105271	Colour	METALLIC SILVER	
Odometer	151538	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	YOKOHAMA	8 mm	
L/H Front Tyre	215/60 R16	YOKOHAMA	8 mm	
R/H Rear Tyre	215/60 R16	HANKOOK	7 mm	
L/H Rear Tyre	215/60 R16	HANKOOK	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/02/2018	Inspection Date	21/02/2018	
Survey held at	ESTEEM PERFORMANCE PTE LTD BLK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-259 SINGAPORE 569536			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJJ 8500A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	HEADLAMP RH	CRACKED	1,784.50	1,784.50
1	FRONT BUMPER	BENT	463.70	463.70
10	FRONT BUMPER CLIP	NECESSARY	39.00	39.00
1	FRONT BUMPER REINFORCEMENT	TO REPAIR SEE LABOUR	321.00	-
1	FRONT BUMPER SIDE RETAINER RH	DISTORTED	22.00	22.00
1	FRONT BUMPER BRACKET RH	TO REPAIR SEE LABOUR	35.00	-
1	FRONT BUMPER LOWER GARNISH	BUCKLED	225.60	225.60
1	FOG LAMP RH	CRACKED	357.70	357.70
1	FOG LAMP GARNISH RH	SERVICEABLE	65.00	-
1	RH FRONT FENDER	BUCKLED	598.70	598.70
1	RH FRONT FENDER UNDERSHIELD	SERVICEABLE	160.00	-
10	RH FRONT FENDER UNDERSHIELD CLIP	NOT NECESSARY	35.00	-
1	RH FRONT FENDER PROTECTOR }	BUCKLED	183.00	183.00
10	RH FRONT FENDER PROTECTOR CLIP }	NECESSARY	-	-
1	REAR WINDSCREEN MOULDING	NECESSARY	155.00	155.00
1	REAR BUMPER	BENT	493.70	493.70
10	REAR BUMPER CLIP	NECESSARY	39.00	39.00
1	REAR BUMPER SIDE RETAINER LH	SERVICEABLE	32.00	-
1	REAR BUMPER SIDE RETAINER RH	SERVICEABLE	32.00	-
1	REAR BUMPER REFLECTOR LH	SERVICEABLE	145.00	-
1	REAR BUMPER REFLECTOR RH	SERVICEABLE	145.00	-
1	TAIL DOOR	BENT	953.70	953.70
1	TAIL DOOR LOCK	JAMMED	180.00	180.00
1	TAIL DOOR EMBLEM	NOT NECESSARY	22.00	-
1	WORDING "VEZEL"	NECESSARY	56.20	56.20
1	TAIL END PANEL	TO REPAIR SEE LABOUR	415.60	-
1	TAIL END PANEL GARNISH	DENTED	92.30	92.30
8	TAIL END PANEL GARNISH CLIP	NECESSARY	28.00	28.00
1	BOOT WEATHERSTRIP	CUT	116.80	116.80

Report Ref No. CS/FCI18003375/Ktd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAIL DOOR TRIM	SERVICEABLE	225.00	-
10	TAIL DOOR TRIM CLIP	NOT NECESSARY	35.00	-
1	SPARE TYRE WELL PANEL	TO REPAIR SEE LABOUR	1,130.00	-
1	SPARE TYRE BOARD	SERVICEABLE	250.60	-
1	BUZZER SENSOR (ADDITIONAL)	CRACKED	125.00	125.00
	LESS 20% DISCOUNT		-1,792.42	-1,182.78
			7,169.68	4,731.12
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
2	REVERSE SENSOR (SN)	SHORTED	200.00	200.00
			250.00	240.00
	LABOUR			
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (FRONT BUMPER, RH FENDER, RR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL). INCLUSIVE OF THE REPAIR OF FRONT BUMPER REINFORCEMENT, FRONT BUMPER BRACKET RH, TAIL END PANEL AND SPARE TYRE WELL PANEL.		1,400.00	900.00
	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA (FRONT BUMPER, RH FENDER, RR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL).		1,400.00	1,000.00
	TO CHECK WIRING.		50.00	40.00
	TO REMOVE & REFIT REVERSE SENSOR.		120.00	50.00
	TO REMOVE & REFIT SPARE TYRE, SPARE TYRE BOARD, CARPET TRIM TO ASSIST WORK LOAD.	NOT NECESSARY	150.00	-
	TO REMOVE & REFIT REAR WINDSCREEN.		120.00	120.00
	TO TUFF COAT.		200.00	90.00
	TO TRANSFER BOOT MECHANISM TO NEW BOOT.		120.00	60.00
	TO CONDUCT WATER LEAKAGE TESTS TO ENSURE PROPER AIR AND SEALING.		120.00	20.00
			3,680.00	2,280.00
	GRAND TOTAL		11,099.68	7,251.12
RECOMMENDED COST OF REPAIRS				7,251.12

Report Ref No. CS/FCI18003375/Ktd3e2



Report Ref No. CS/FCI18003375/Ktd3e2

A handwritten signature in black ink, appearing to be 'KSC'.

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.