



LIU'S BROTHER AUTO ENGINEERING WORKSHOP

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793 - Tel: 6741-1730 / 731 - Fax: 6744-5746, Email: lbro@ymail.com

Invoice/Ref No: GZ8794U180125

Estimate

Customer

Name: AXA Insurance Singapore Pte Ltd

Address: Motor Claims Department

8 Shenton Way #27-01

AXA Tower Singapore 068811

Date: 22-02-18

Vehicle No: GZ8794U

Model/Make: Mitsubishi

FB70AB0SRDEB

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Front Lh Head Lamp <i>one</i>	\$ 768.10	
2	Signal Lamp <i>one</i>	\$ 316.60	
3	<i>fu</i> Grille <i>one</i>	\$ 859.20	
4	Grille Clip Bottom 02 pcs (@ S\$6.50) <i>nee</i>	\$ 13.00	
5	Grille Clip Top 04 pcs (@ S\$6.50) <i>nee</i>	\$ 26.00	
6	"FUSO" Emblem <i>nee</i>	\$ 149.00	
7	"MITSUBISHI" Logo Motif <i>nee</i>	\$ 119.50	
8	Number Plate (Metal) <i>nee</i>	\$ 28.00	
	To check all wiring & electrical component for proper function	\$ 60.00	
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 400.00	
	To putty & spray painting & including touch up paint on accident affected areas	\$ 500.00	

(25%)

20
350
400

Total Parts & Labour of estimate for damaged vehicle

\$ 3,239.40

Total amount in Lump Sum Basis for repaired vehicle

\$

SDLS:

not allowed

2/s \$1900/2

3 days

take photo of the repair

27/2/18



M/s Liu's Brother Auto Engrg Wks

2184.1

1638.2

2408.2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: