

22/03/2018

ASS. REC. BY:

REF: CS/FC18003382/Gad3<sup>n2</sup>

Special Instruction:

Surveyor:

CWS

GA

ASSIGNMENT (Office)

From (Person):

Sithara

of FCI

Date/Time:

22/2/18 @ 9.44am

Estimated Cost:

Bill to:

OD: TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLB 96227

Insured:

SHA 8162M

at Workshop m/s

Auto N cars

Tel:

65552909

of

Biki Kaki Bkt Ave 6 # 01-04 Autobuy

Policy No:

P18088937MFSH

Claim No:

D18001533MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

16/2/18

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

10:20am @ 22/2/18

Person Contacted:

Barla

Vehicle

IN OUT

Date/Time

Action/Instruction ( ) Estimate

SLB 96227-X

SHA 8162M-CS/QW11005367/Rfg

D.O.A: 21/3/11

26/2/18 @ 3.05pm revised to Sithara by audit.

19/2/18 @ 9.10am barla informed that the vehicle has not send in for repair due to liability unclear.

19/2/18 Submit Multi. report. - the vehicle has not send in for repair.





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18003382/Gqd3

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 22-02-2018



Code : FCI2

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHA 8162M	Veh. Inspected	SLB 9622T
Policy No.		Coverage (\$)	0.00
Claim No.	D18001533MFSH	Excess (\$)	0.00
Assign From	CWS (SITHARA)	Assign Date	22/02/2018

## 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	16/02/2018	Inspection Date	22/02/2018
Survey held at	AUTO N CARS SERVICES PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883.		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18001533MFSH  
Our Ref: CS/FCI18003382/Gqd3

Date: 26 February 2018

The Motor Claims Department  
First Capital Insurance Ltd


Dear Sir/Madam,

**INITIAL INSPECTION REPORT OF VEHICLE NO. SLB 9622T**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 22/02/2018 at the premises of M/s AUTO N CARS and have the following to report:-

Workshop Estimate Amount	: S\$ <u>7,271.40</u>
Revised Estimate Amount	: S\$ <u>2,707.44</u>
"Check" Items Amount	: S\$ <u>1,713.36</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:  
The vehicle sustained damages  
at the front o/s portion.



Yours faithfully

Guo Qiang  
Automotive Assessor

**MOTOR SURVEY ASSIGNMENT**

Date	21-02-2018	Our Ref No. D18001533MFSH
Accident Date	16-02-2018	Claim Type. Third Party
Insured Vehicle	SHA8162M	Third Party Vehicle. SLB9622T
Survey Location	AUTOBAY @ KAKI BUKIT BLK 1 AREA "A" KAKI BUKIT AVE 6#01-04	
Contact Person.	DARLA BALINGIT	
Contact No.	65552909/ 84993326	Fax No. 68417181
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

Cc : Workshop	AUTO N CARS SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/235217)



PRI Documents



Close



## PRI Header Details

<b>Claim No</b>	D18001533MFSH	<b>Policy No</b>	D-18088937MFSH	<b>Claimant S.No &amp; Name</b>	1 & AUTO N C
<b>Workshop Name</b>	AUTO N CARS SERVICES PTE LTD (Contact Person : DARLA BALINGIT)	<b>Survey Location &amp; Contact Details</b>	AUTOBAY @ KAKI BUKIT BLK 1 AREA "A" KAKI BUKIT AV <b>Mobile:</b> 84993326 , <b>Phone:</b> 65552909 , <b>Fax:</b> 6841718 <b>EmailId:</b> DARLA@AUTONCARS.COM.SG		
<b>Our Surveyor</b>	LKK AUTO CONSULTANTS PTE LTD	<b>Instructions To Surveyor</b>	WITHOUT PREJUDICE:		
<b>Insured Name</b>	CITYCAB PTE LTD	<b>Insured Vehicle No</b>	SHA8162M	<b>TP Vehicle No</b>	SLB9622T
<b>PRI Recieved Date</b>	21-02-2018 08:12:20 PM	<b>Surveyor Appointed Date</b>	22-02-2018 09:43:25 AM	<b>Surveyor Accept Date</b>	22-02-2018 0

## Survey Report Upload

<b>Surveyor Inspection Date *:</b>	<input type="text"/>	<b>Surveyor Report Date</b>	22-02-2018	<b>Upload Survey Report *:</b>	<input type="button" value="Choose File"/>
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

## Vehicle Particulars

<b>Make</b>	<input type="text" value="Please Select Make"/>	<b>Model</b>	<input type="text" value="Please Select Model"/>	<b>Year</b>	<input type="text" value="Select Year"/>
<b>Chasis No</b>	<input type="text"/>	<b>Engine No</b>	<input type="text"/>	<b>Mileage</b>	<input type="text"/>
<b>Color</b>	<input type="text"/>	<b>Cubic Capacity</b>	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks

## Shiau Chan (LKKAuto)

---

**From:** Darla Balingit <darla@autoncars.com.sg>  
**Sent:** Thursday, 19 July 2018 9:10 AM  
**To:** Shiau Chan (LKKAuto)  
**Subject:** Re: FINALISE OF VEHICLE SLB 9622T (DOA: 16/02/2018)

Dear Shiau Chan,

Liability is not clear for this case therefore, we didn't proceed to repair our client's vehicle.

On Wed, Jul 18, 2018 at 4:23 PM, Shiau Chan (LKKAuto) <[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)> wrote:

Dear Darla,

As spoken with you.

Kindly advise vehicle status.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Thursday, 31 May 2018 5:51 PM  
**To:** 'Darla Balingit' <[darla@autoncars.com.sg](mailto:darla@autoncars.com.sg)>  
**Subject:** FINALISE OF VEHICLE SLB 9622T (DOA: 16/02/2018)

Dear Darla,

Kindly advise vehicle status.

## Shiau Chan (LKKAuto)

---

**From:** Shiau Chan (LKKAuto)  
**Sent:** Monday, 26 February 2018 3:05 PM  
**To:** 'Claim Workflow System'; assignments  
**Cc:** SUR; SITHARA@MSFIRSTCAPITAL.COM.SG  
**Subject:** RE: SURVEY ASSESSMENT - D18001533MFSH/1  
**Attachments:** CSFCI18003382Gqd3.pdf

Dear Sithara,

Enclosed herewith preliminary advice of SLB 9622T.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Thursday, 22 February 2018 11:24 AM  
**To:** 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>; SITHARA@MSFIRSTCAPITAL.COM.SG  
**Subject:** RE: SURVEY ASSESSMENT - D18001533MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]  
**Sent:** Thursday, 22 February 2018 9:44 AM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [SITHARA@MSFIRSTCAPITAL.COM.SG](mailto:SITHARA@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18001533MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited



Co. Reg: 200922097K GST Reg.No: 200922097K  
 Auto Bay @ Kaki Bukit Blk 1 Area "D" Kaki Bukit Ave 6 #01-90 (S) 417883  
 • Tel (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

Date : 22/02/2018

TO: First Capital Insurance Ltd  
 36 Robinson Road  
 #16-01 City House  
 Singapore 068877

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Total Pages : 1  
 Acknowledged by Repairer: **AHMED RAZA KHAN**  
 Our Customer : SLB9622T  
 Vehicle No : SLB9622T  
 Date: Model : HONDA VEZEL 1.5

Manufacture Year : 2015  
 Date of Accident : 16/02/2018  
 Total Estimate Repair Days : 8

Attn : Motor Claim Department  
 Fax : 6829 9248

Re: Repair Estimate For Third Party Claim against : SHA8162M

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks From Surveyor
<b>A. Spare Parts</b>					
1	Front bumper assembly / <i>OC</i>	1	\$790.20	\$790.20	
2	Front bumper clips / <i>MC</i>	12	\$3.80	\$45.60	
3	RH fog lamp	1	\$420.90	\$420.90	
4	RH fog lamp cover / <i>SCR</i>	1	\$195.80	\$195.80	
5	Front bumper retainer / <i>MC</i>	2	\$78.50	\$157.00	
6	RH front fender assembly / <i>x repair</i>	1	\$750.50	\$750.50	
7	RH front fender splash shield / <i>OC</i>	1	\$228.50	\$228.50	
8	RH front fender splash shield clips / <i>MC</i>	14	\$3.80	\$53.20	
9	RH front headlamp	1	\$1,720.80	\$1,720.80	
10	RH front fender protect clips / <i>MC</i>	12	\$3.80	\$45.60	
11	RH front fender protect / <i>SCR</i>	1	\$380.90	\$380.90	
<b>Sub Total</b>				<b>\$4,789.00</b>	
				Less 20%	\$957.80
<b>B. Spare Parts (S/Nett)</b>					
1	Front RH sport rim / <i>Cut</i>	1	\$980.20	\$980.20	<i>300</i>
2	RH front tyre / <i>X NN</i>	1	\$380.00	\$380.00	
<b>Sub Total 2</b>				<b>\$1,360.20</b>	
<b>Total Spare Parts</b>				<b>\$5,191.40</b>	
<b>C. Labour</b>					
1	To knock and straighten RH front inner panel. Removed and renew damaged parts. Adjust and realign the same			\$980.00	<i>400</i>
2	To putty and spray RH front fender, front bumper, front bonnet and inner panel			\$900.00	<i>600</i>
3	To check wiring and all lighting			\$80.00	<i>30</i>
4	To do 4 wheel alignment			\$120.00	<i>60</i>
<b>Total Labour</b>				<b>\$2,080.00</b>	
<b>(* The above quoted are exclusive of GST.) Total Repair Cost</b>				<b>\$7,271.40</b>	

*4 Days.  
 lumpsum repair.  
 After repair photos.  
 bua Qian - 8288082  
 22/2/18.*

Yours faithfully,

*[Signature]*  
 Darla  
 f Auto N Cars Services Pte Ltd

Surveyor's Details	
Name	
Contact	
Survey Date	
Recommender	Authorize / Not Authorize
Before Paint	Yes / No
Signature	

DATE	Remark From MR CHOO
12/27/2016	Please arrange for survey asap



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FC118003382/Gqd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 19-07-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 8162M	Veh. Inspected	SLB 9622T
Policy No.	D-18088937MFSH	Coverage (\$)	0.00
Claim No.	D18001533MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	22/02/2018
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11109632	Colour	WHITE
Odometer	27323	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	7 mm
L/H Front Tyre	215/60 R16	DUNLOP	7 mm
R/H Rear Tyre	215/60 R16	DUNLOP	7 mm
L/H Rear Tyre	215/60 R16	DUNLOP	7 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	16/02/2018	Inspection Date	22/02/2018
Survey held at	AUTO N CARS SERVICES PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883.		
5a. Remarks			
A)THE VEHICLE HAS NOT SEND IN FOR REPAIRS. B)DAMAGES CONSISTENT TO ACCIDENT REPORT. C)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. D)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 9622T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT BUMPER ASSEMBLY	DEFORMED	790.20	790.20
12	FRONT BUMPER CLIPS @\$3.80	NECESSARY	45.60	45.60
1	RH FOG LAMP	* CHECK	420.90	-
1	RH FOG LAMP COVER	SCRATCHED	195.80	195.80
2	FRONT BUMPER RETAINER @\$78.50	NECESSARY	157.00	157.00
1	RH FRONT FENDER ASSEMBLY	TO REPAIR SEE LABOUR	750.50	-
1	RH FRONT FENDER SPLASH SHIELD	DEFORMED	228.50	228.50
14	RH FRONT FENDER SPLASH SHIELD CLIPS @\$3.80	NECESSARY	53.20	53.20
1	RH FRONT HEADLAMP	* CHECK	1,720.80	-
12	RH FRONT FENDER PROTECT CLIPS @\$3.80	NECESSARY	45.60	45.60
1	RH FRONT FENDER PROTECT	SCRATCHED	380.90	380.90
	LESS 20% DISCOUNT		-957.80	-379.36
			3,831.20	1,517.44
<b>SPECIAL NETT ITEMS</b>				
1	FRONT RH SPORT RIM (SN)	CUT	980.20	300.00
1	RH FRONT TYRE (SN)	NOT NECESSARY	380.00	-
			1,360.20	300.00
<b>LABOUR</b>				
	TO KNOCK AND STRAIGHTEN RH FRONT INNER PANEL.REMOVED AND RENEW DAMAGED PARTS.ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF RH FRONT FENDER ASSEMBLY.		980.00	400.00
	TO PUTTY AND SPRAY RH FRONT FENDER.FRONT BUMPER,FRONT BONNET AND INNER PANEL.		900.00	400.00
	TO CHECK WIRING AND ALL LIGHTING.		80.00	30.00
	TO DO 4 WHEEL ALIGNMENT.		120.00	60.00
			2,080.00	890.00
<b>GRAND TOTAL</b>			<b>7,271.40</b>	<b>2,707.44</b>



RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,713.36 NETT)			2,707.44
---	--	--	----------

Report Ref No. CS/FCI18003382/Gqd3n2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.