

# PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02  
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511  
CO. REG:200707743D GST REG:200707743D

*AxA*

22-Feb-18

## ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6907 J

1 pc	Front n/s wheel cover <i>X</i>	\$	116.00
1 pc	Front n/s fender inner shield <i>X</i>	\$	120.00
1 pc	n/s head lamp <i>—</i>	\$	1,028.00
1 pc	Front bumper <i>—</i>	\$	531.00
1 pc	Front bumper lip <i>—</i>	\$	52.00
1 pc	Front bumper n/s side retainer <i>X</i>	\$	16.00
1 pc	Front bumper n/s protector <i>—</i>	\$	51.00
1 pc	Front bumper emblem <i>—</i>	\$	44.00
1 pc	Front bumper n/s fog lamp cover <i>X</i>	\$	66.00
			\$ 2,024.00
Less 10%			\$ 202.40
			\$ 1,821.60

### S/NETT

1 set	Front bumper clips <i>—</i>	\$	48.00
1 set	Front n/s fender inner shield clips <i>X</i>	\$	28.00
Sundry			\$ <del>50.00</del> <i>X</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.			\$ <del>180.00</del> <i>X</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the bonnet			\$ <del>650.00</del> <i>200</i>
To putty and spray painting on front bumper, bonnet			\$ <del>400.00</del> <i>180</i>
To apply rustproofing on the repaired and replaced panels.			\$ <del>200.00</del> <i>X</i>
			\$ 3,377.60

( ALL THE REPAIR COSTS ARE SUBJECTED TO GST )

**THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.**

- the Repairer will be responsible for the following:
- To resurvey before repair/spray painting
  - To dismantle damaged parts during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*Kalvin (KKK)*  
*26/2/18 1340hrs*  
*2 Days*  
*PIP*  
*Before Paint photo*