

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05735

Vehicle Insured : SLK 6395X
Accident Date : 17-Feb-2018

Date : 22-Feb-2018

Our Ref : 218034 (AIG) / CHAN

PAGE : 1

KENTUCKY FRIED CHICKEN MGT PTE LTD
17 KALLANG JUNCTION
#02-01
Singapore 339274

*Not Withstand
11 Day @
Recovery After Paint*

ESTIMATED COST OF REPAIR FOR NISSAN NV200 1.5D MT ABS AIRBAG GBD681P

1 pc Rear o/s door
1 pc Rear o/s door "dci" emblem
1 pc Rear o/s door lower hinge
1 pc Rear o/s taillamp
1 pc Rear o/s taillamp corner panel
1 pc Rear bumper fascia
1 pc Rear o/s bumper reflector

Bz 960.90 ✓
nn 73.60 ✓
n 99.10 X
Bz 252.10 ✓
n 207.50 X
Bz 624.80 ✓
nn 55.00 X

2,273.00

Less 10% : 227.30

1 pc Rear o/s door 6pax sticker
1 pc Rear o/s door glass sealant

2,045.70
nn 15.00 sn ✓
nn 60.00 sn ✓
40sn

To remove & refix rear windscreen glass and conduct water leak test.

100.00 *60d*

To remove roof lining, front and rear seats, trim board and carpet

nn 80.00 X

To putty and spray replaced parts

800.00 *60d*

To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts

900.00 *50d*

Total : S\$ 4,000.70

Singapore Dollars Four Thousand and Cents Seventy
Only

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: