

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Khor Saw Theng

Date: 23 Feb 2018

Preliminary Advice

| | | | |
|--------------------|-----------------------------------|-------------------------|--------------|
| Insured Vehicle No | : SHB7879E | Accident Date | : 16/02/2018 |
| TP Vehicle No | : SHC5558P | Assignment Date | : 21/02/2018 |
| Make | : RENAULT LATITUDE | Est. Duration of Repair | : 2/Days |
| Date of Inspection | : 21/02/2018 | | |
| Inspection At | : TRANS-CAB AUTO SERVICES PTE LTD | | |

Point of Impact / General Description of Damages

The vehicle sustained impact / damagesN/S Front... portion and parts claimed are consistent to the accident.

| | | |
|-----------------------------|------|-----------|
| Repairer's Estimate (Gross) | :S\$ | 42,502.34 |
| Revised Amount | :S\$ | 3,200.00 |
| Check Items (Estimated) | :S\$ | 0.00 |
| Total | :S\$ | 3,200.00 |

Lump Sum Repair :S\$

Total Loss Consideration

| | |
|--------------------|------|
| New for Old Value | :S\$ |
| Pre-Accident Value | :S\$ |
| COE / PARF Rebate | :S\$ |
| Salvage Value | :S\$ |
| Margin for Repair | :S\$ |

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :We have not authorized repairs.