

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5558P - AXA

AAD1802-183

*Not Authored
11 Sep @ 3800*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHC5558P - CANDY
VF1ABL15AUC279250
RENAULT
LATITUDE
16.02.2018
AXA

PART		LIST
1	1 BUMPER COVER FRT	\$ <i>CM</i> 1,259.42 ✓
2	1 BUMPER ABSORBER FRT	\$ <i>Sm</i> 394.68 X
3	1 BUMPER BEAM FRT	\$ <i>R</i> 914.08 X
4	1 BUMPER SPOILER FRT	\$ <i>Sm</i> 181.75 X
5	1 BUMPER GRILLE LOWER FRT	\$ <i>Sm</i> 266.80 X
6	1 BUMPER FOG LAMP GRILLE LH	\$ <i>Sm</i> 207.22 X
7	1 BUMPER RETAINER FRT LH	\$ <i>Nil</i> 151.41 ✓
8	1 BUMPER BRACKET FRT LH	\$ <i>Sm</i> 181.75 X
9	1 BUMPER RETAINER FRT RH	\$ <i>Sm</i> 151.41 X
10	1 BUMPER BRACKET FRT RH	\$ <i>Sm</i> 181.75 X
11	1 HEADLAMP LH	\$ <i>mgcm</i> 1,184.43 ✓
12	1 HEADLAMP PANEL FRT LH	\$ <i>R</i> 152.15 X
13	1 FENDER PANEL FRT LH	\$ <i>R</i> 783.83 ✓
14	1 FENDER INSULATOR LH	\$ <i>Sm</i> 130.84
15	1 FENDER BRACKET FRT LH	\$ <i>R</i> 34.14
16	1 WHEELARCH FRT LH	\$ <i>Sm</i> 278.84
17	1 AIR CLEANER LOWER	\$ <i>Sm</i> 352.64
18	1 AIR CLEANER HOSE	\$ <i>Sm</i> 76.14
19	1 RADAITOR GRILLE	\$ <i>Sm</i> 1,707.78
20	1 RADAITOR GRILLE BADGE 'RENAULT'	\$ <i>Sm</i> 173.36
21	1 RADAITOR GRILLE FRAME	\$ <i>Sm</i> 1,353.75
22	1 FRAME FULL SUPPORT PANEL	\$ <i>Sm</i> 615.90
23	1 FRAME FULL SUPPORT BRACKET	\$ <i>R</i> 89.79 X
24	1 BONNET	\$ <i>R</i> 1,941.63
25	1 BONNET HINGE LH	\$ <i>R</i> 348.31
26	1 BONNET HINGE RH	\$ <i>R</i> 348.31
27	1 WHEEL HOUSING PANEL FRT LH	\$ <i>R</i> 5,173.47
28	1 LOWER ARM LH	\$ <i>Sm</i> 685.76
29	1 KUNCKLE ARM LH	\$ <i>Sm</i> 846.98
30	1 ABSORBER FRT LH	\$ <i>Sm</i> 360.54
31	1 AIR CLEANER LOWER	\$ <i>Sm</i> 271.26
32	1 AIR CLEANER HOSE	\$ <i>Sm</i> 76.14
33	1 AUTO COMPUTER	\$ <i>Sm</i> 5,032.17
34	1 STEERING PUMP ELECTRIC	\$ <i>Sm</i> 2,306.90

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-183

NO.2 ANJ MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5558P - AXA

35	1	DOOR PANEL FRT LH	\$	<i>R</i>	2,844.66	}
36	1	DOOR HINGE UPPER LH	\$	<i>R</i>	274.50	
37	1	DOOR HINGE LOWER LH	\$	<i>R</i>	300.55	
38	1	DOOR MIRROR LH	\$	<i>S_L</i>	1,483.40	
39	1	DOOR MIRROR GLASS LH	\$	<i>S_L</i>	148.20	
40	1	DOOR MIRROR BACK COVER LH	\$	<i>S_L</i>	218.46	
41	1	ROCKER PANEL OUTER LH	\$	<i>R</i>	987.49	

TOTAL	\$	<u>34,472.60</u>
10%	\$	<u>3,447.26</u>
	\$	<u>31,025.34</u>

Special Nett

1	1SET	WHEELARCH CLIP FRT LH	\$	<i>nn</i>	66.00	X
2	1SET	FRONT BUMPER CLIP	\$	<i>nn</i>	66.00	✓
3	1	RIM LH FRT	\$	<i>S_L</i>	385.00	X
4	1	TYRE LH FRT	\$	<i>S_L</i>	330.00	X
5	1	DOOR STICKER "Trans-cab"	\$	<i>nn</i>	80.00	X
6	1	DOOR STICKER "Classic"	\$	<i>nn</i>	30.00	X
7	1	DOOR STICKER "6555-3333"	\$	<i>nn</i>	80.00	X

TOTAL	\$	<u>1,037.00</u>
TOTAL PARTS	\$	<u>32,062.34</u>

To Check Electrical Lighting Concerned.	\$	170.00	<i>201</i>
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,200.00	<i>4001</i>
Putty and spray painting of the affected portion.	\$	4,500.00	<i>4401</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	<i>301</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	X
To check steering geometry and computer wheel alignment	\$	<i>nn</i> 220.00	X
To Remove And Refit Front W/Screen Glass To Facilitate Bodywork Repair.	\$	<i>nn</i> 170.00	X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1802-183

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5558P - AXA

To transfer of door fittings, attachment and perform water seepage test.	\$	<i>nn</i> 170.00 X
Towing fees	\$	<i>nn</i> 120.00 X
To rust-proofing of the affected areas.	\$	170.00 <i>3rd</i>
To dismantle and refit front end suspension, undercarriage parts, final checking and testing.	\$	<i>nn</i> 380.00 X
TOTAL		\$ 10,440.00
Over All Total		\$ 42,502.34

(PARTS BY PARTS) Repair Days

15 Days

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: