

# ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SLH8546E (CHINA)

Accident Date : 04-02-2018

Date : 06-02-2018

Our Ref : SJQ8575Y /CHAN

YEW HUP HUAT TRADING  
C/O ALAN'S UNITED AUTO PTE LTD  
BLK 7 SIN MING IND. EST. SECTOR C  
# 01-76  
SINGAPORE 575642

*Not Noted*  
*Running After Paint*  
*3 days*

## ESTIMATE REPAIR FOR MERCEDES-BENZ R280L SJQ8575Y

1 PC	FRONT BUMPER FASCIA	<i>Br</i>	\$2,249.00	—
1 PC	FRONT O/S BUMPER SIDE RETAINER	<i>Br</i>	\$61.00	—
1 PC	FRONT O/S BUMPER SIDE PARKING SENSOR		\$212.00	?
1 PC	FRONT O/S BUMPER FOGLAMP COVER	<i>Br</i>	\$77.00	X
1 PC	FRONT O/S FENDER	<i>R</i>	\$1,220.00	X
8 PCS	FRONT O/S FENDER INNER SHIELD RIVET @ \$5.00	<i>nn</i>	\$40.00	X
			<u>\$3,859.00</u>	
			LESS 10%	<u>\$385.90</u>
				<u>\$3,473.10</u>

\$3,473.10

TO PUTTY AND SPRAY REPLACED PARTS

\$600.00 *500*

TO REMOVE ,RENEW ,ALIGN,ADJUST REPLACED PARTS

\$600.00 *400*  
\$4,673.10

Singapore Dollars Four Thousand Six Hundred Seventy Three

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: