50 G	ASS. REC. BY: REF: CS   ICS   8003415/ Ugo 3n2 Special Instruction:
	ASSIGNMENT (Office)
	From (Person): Claims of ECICS Date/Time: 21/2/180 4-44pm
	Estimated Cost: Bill to:
	Fo Inspect Vehicle No. SKT 58922 Insured:
	at Workshop m/s   Nuns Funder   Tel: 6 395 7874
	of Subiclose
	Policy No: Claim No: DM PC 1800060 H
7	Sum Insured: Excess: \$500-00
	Make of Veh: DOA 16 02 2018
	(Chent's Record)
	CA (REV) / REP. / REV 24 HRS H.O.D. Endorsement:
	Date/Time: 8:8m 222 2K Person Contacted: JUS - Vehicle IN OUT
	Date/Time Action/Instruction ( ) Estimate
	S1C15892Z-X
	26 2/18@ 2.34 pr verent to Love by email.
	29/1/18 @ 10,13m Truice Est informed GA by encil.
	29/1/80 1138an informed Jess C/A & EX. \$50 /4 email.

(08/11/13) wef . ASS. REC. BY: MCV CLS	REF:	105/
ASS. REC. BY: 1907 24	A:	SSIGNMENT
<u>0</u>		
From:	Date:	Veh No: 5 K7 S & P22 Yr Regn: 6 15
Estimated Cost:		Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD THE DWS ! TP RES! OD RES!	EVA/INV/MV	Truck / Trailer or
To Inspect Vehicle No:	SKJ 88114	Make: Messag 3 c.c 1496
at Workshop m/s	Then Enter	Colour Qued A/C: Insured / Std / NI / NA
of		Sp.Reading F40V T/Radio: Insured / Std / NI / NA
Insured:		Eng/No:
Policy No.		C/No: JM6BM 42A.860310671
Claims No.		Gen. Cond Good / Fair / Poor / Burnt
Sum Insured:	Excess: (vo	Steering: Lorder / Jammed / Leaked / Burnt or
(Client's Record)	3	Brake: Inorder Jammed / Leaked / Burnt or
Make of Veh:		Modi: Nil (S/Rim / STD A/Rim or
	11020-1111-11110-1111	Tyre Size: F: 205/602/6
(Policy Condition)		R:
Remark: The veh had commenced	d its N/S O/	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU PIR SUMI /
repair at the time of insp	pection.	TOYO/YOKO or
Bal. or Market Value:	71K.	Front Rear
IDAC Accident Rport:	Consistent? : Yes or No	R/Bal. 6 mm R/Bal. 6 mm
GIA / PR Seen:	Consistent? : Yes or No	L/Bal. / mm L/Bal. mm
Est. Repairs: 7 days	Res.: Yes or No	D.O.A. 16/2/18 D.O.I. 22/2/18
Lum Sum: %	3 Val.: Yes or No	Survey held at
4.01		Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS	Vehicle: IN / C	11221-
Date: Person Con		The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction / Instructi	1 0 100	9902.01 with colliere.
	RECEIVED 2.7	MAR 2018
Date/Time, File Pass to?	reli. Report	Days Of Repair:
1) 22 3 Move : Fill Date/Time, File Return to?	inal Report	Resurvey No. of Trip: Survey Fee: Transportation:
2		
2)	Add F	ee: Site Insp (\$)S+RSSI
2)	Add F	Site Insp (\$)S+RSSI           Interview (\$) Photos
	## Add F	
Report Format :		: Interview (\$ ) Photos

(08/11/13)

wef



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

=CIC	SLTD		Ref : CS/ICS180034	15/Uqd3
_0,0	70 210			
	MASEK BOULEVA			
	01 SUNTEC TOWN		Date: 22-02-2018	
SINC	SAPORE 038987&	nosp, anosp,	Code: ICS	
		Dallas Ba		
1.		Policy Pa	rticulars :- OWN DAMAGE	SKT 5892Z
	Insured Veh.		Veh. Inspected	24/10/20
	Policy No.		Coverage (\$)	0.00
	Claim No.	DMPC1800060H	Excess (\$)	500.00
	Assign From	CLAIMS (ECICS)	Assign Date	22/02/2018
2.		Vehicle	Particulars & Condition	
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	•	Steering	
	Brakes		Modification	
	General			
3.		C	onditions of Tyres	
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4.		Des	scription of Damages	
-			seneral Information	
5.		16/02/2018		22/02/2018
	Accident Date	TRANS EUROKARS PTE	Inspection Date	22/02/2010
	Survey held at		- 610	
		NO 5 UBI CLOSE SINGAPORE 408605		
5a.			Remarks	

#### Nivitha (LKK Auto)

From:

jess.francis@eurokars.com.sq

Sent:

Wednesday, 21 February 2018 4:44 PM

To:

claims@ecics.com.sg; admin-d@lkkauto.com; assignments@lkkauto.com

Cc:

kevin.lee@eurokars.com.sg; eric.pau@eurokars.com.sg; ronald.yap@eurokars.com.sg; vion.lim@eurokars.com.sg;

catherinechua@eurokars.com.sg; sur@lkkauto.com

Subject:

Re: OUR REF: SKT5892Z \*\*od claim. req for survey.

Hi Lionel,

Than you.

Regards.

Jess Francis Carlos Insurance Claim Executive TRANS EUROKARS PTE LTD 5 Ubi Close Singapore 408605 DID 6395 7874

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: ECICS Claims <claims@ecics.com.sg> Sent: Wednesday, February 21, 2018 4:31 PM

To: Jess Francis; admin-d@lkkauto.com; assignments@lkkauto.com

Cc: ECICS Claims; Kevin Lee; Eric Pau; Ronald Yap; Vion Lim; Siew Guek Catherine Chua; SUR

Subject: RE: OUR REF: SKT5892Z \*\*od claim. req for survey.

Our claim no. DMPC1800060H

Dear Jess.

We will arrange LKK to conduct the OD survey and our surveyor will contact you shortly.

Aside to LKK

Please arrange to conduct for (OD) own damage survey.

Excess applicable is \$500.00

Thank you.

Regards,

Lionel Chua

DID: +65 6303 0167 FAX: +65 6338 9267 ECICS LIMITED

Email: claims@ecics.com.sg

From: jess.francis@eurokars.com.sg [mailto:jess.francis@eurokars.com.sg]

Sent: Wednesday, 21 February, 2018 4:01 PM

To: ECICS Claims

Cc: kevin.lee@eurokars.com.sg; eric.pau@eurokars.com.sg; ronald.yap@eurokars.com.sg;

vion.lim@eurokars.com.sg; catherinechua@eurokars.com.sg
Subject: Re: OUR REF: SKT5892Z \*\*od claim. reg for survey.

Hi Lionel.

We got no access on merimen.

Please arrange the survey. You insured is chasing us.

Regards.

Jess Francis Carlos Insurance Claim Executive TRANS EUROKARS PTE LTD 5 Ubi Close Singapore 408605 DID 6395 7874

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: ECICS Claims < claims@ecics.com.sg > Sent: Wednesday, February 21, 2018 2:49 PM

To: Jess Francis

Cc: ECICS Claims; Kevin Lee; Eric Pau; Ronald Yap; Vion Lim; Siew Guek Catherine Chua

Subject: RE: OUR REF: SKT5892Z \*\*od claim, reg for survey.

Our claim no. DMPC1800060H

Dear Jess.

Could you pls submitted all your documents via by Merimen for us to assign the case. So that we can appoint for OD Survey.

Thank you.

Regards, Lionel Chua

DID: +65 6303 0167

Email: claims@ecics.com.sq



From: jess.francis@eurokars.com.sg [mailto:jess.francis@eurokars.com.sg]

Sent: Wednesday, 21 February, 2018 12:41 PM

To: ECICS Claims

Cc: kevin.lee@eurokars.com.sg; eric.pau@eurokars.com.sg; ronald.yap@eurokars.com.sg

Subject: Re: OUR REF: SKT5892Z \*\*od claim. req for survey.

Hi ECICS Motor Claims,

Kindly arrange the survey to your insured's car.

The car is inside our workshop.

Regards.

Jess Francis Carlos Insurance Claim Executive TRANS EUROKARS PTE LTD 5 Ubi Close Singapore 408605 DID 6395 7874

This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Eric Pau

Sent: Wednesday, February 21, 2018 12:20 PM

To: claims@ecics.com.sg; Jess Francis

Cc: Ronald Yap; Vion Lim; Siew Guek Catherine Chua; Kevin Lee

Subject: OUR REF: SKT5892Z OWN DAMAGE CLAIM

**OUR REF: SKT5892Z OWN DAMAGE CLAIM** 

Dear Sir/Mdm,

Kindly arrange the survey of our client's vehicle ASAP. Car is in the workshop.

Attached is the ESTIMATE, SAS REPORT, SKETCH PLAN for your perusal.

Liaise with Jess for survey arrangement.

Best Regards,

Eric Pau

Insurance Claims Officer

#### TRANS EUROKARS PTE LTD

5 Ubi Close, Singapore 408605 D: (65) 6395 8685 H: (65) 9618 5991

E: eric.pau@eurokars.com.sq


This email, including any attachment, is intended for the sole use of the recipient(s) named above and may contain information that is confidential and/or proprietary to the Eurokars Group. If you have received it in error, please notify us immediately by reply email and then delete this message from your system. Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: mazdacanon@mazda.com.sg [mailto:mazdacanon@mazda.com.sg]

Sent: Wednesday, February 21, 2018 12:30 PM

To: Eric Pau <eric.pau@eurokars.com.sg>

Subject: Attached Image



This message may contain privileged and confidential information and is only intended for use by the addressee. No representation, warranty, guarantee or undertaking expressed or implied is made by ECICS Limited; as to the fairness, accuracy or completeness of any information, projections or opinions contained in this message. Any unauthorized disclosure, use or dissemination either in whole or in part is prohibited. If you are not the addressee indicated in his message (or responsible for delivery of the message to such person), you may not copy or deliver this message to anyone. In such case, you should destroy this message and kindly notify the sender by reply email. Opinions contained herein are the personal opinions of the sender and do not necessarily represent the views of ECICS Limited.

#### Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Tuesday, 27 February 2018 11:38 AM

To:

'jess.francis@eurokars.com.sg'; SUR

Cc:

kevin.lee@eurokars.com.sg; eric.pau@eurokars.com.sg; ronald.yap@eurokars.com.sg

Subject:

RE: OUR REF: SKT5892Z OWN DAMAGE CLAIM

Dear Jess,

As instructed by our client ECICS, please proceed to repair the insured vehicle SKT 5892Z (Excess \$500/-).

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: jess.francis@eurokars.com.sg [mailto:jess.francis@eurokars.com.sg]

Sent: Thursday, 22 February 2018 9:36 AM

To: PhoebeJay\_Xie@ecics.com.sg; Admin A <admin-a@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: claims@ecics.com.sg; kevin.lee@eurokars.com.sg; eric.pau@eurokars.com.sg; ronald.yap@eurokars.com.sg

Subject: RE: OUR REF: SKT5892Z OWN DAMAGE CLAIM

Ok Ma'am.

Regards.

Jess Francis Carlos Insurance Claims Executive Trans Eurokars Pte Ltd 5 Ubi Close Singapore 408605 Tel no.: 63958784

From: Phoebe Jay Xie (ECICS, Claims) [mailto:PhoebeJay Xie@ecics.com.sg]

Sent: Thursday, 22 February 2018 9:37 AM

To: Jess Francis < jess.francis@eurokars.com.sg >; admin-a@lkkauto.com; sur@lkkauto.com Cc: ECICS Claims < claims@ecics.com.sg >; Kevin Lee < kevin.lee@eurokars.com.sg >; Eric Pau

<eric.pau@eurokars.com.sg>; Ronald Yap <ronald.yap@eurokars.com.sg>

Subject: RE: OUR REF: SKT5892Z OWN DAMAGE CLAIM

Dear Jess,

We are awaiting LKK's advice before authorising.

#### Shiau Chan (LKKAuto)

From:

ECICS Claims <claims@ecics.com.sg>

Sent:

Tuesday, 27 February 2018 10:13 AM

To:

Shiau Chan (LKKAuto); ECICS Claims; assignments

Cc:

SUR

Subject:

RE: OUR REF: SKT5892Z \*\*od claim. req for survey.

Our ref

DMPC1800060H/JG

Dear Shiau Chan

Please proceed with the repair.

Thank you.

Regards, Janice Goh Claims Division DID: +65 6303 0182 FAX: +65 6338 9267

#### **ECICS Limited**

7 Temasek Boulevard, #10-01 Suntec Tower One, Singapore 038987

WITH IMMEDIATE EFFECT FOR ALL PRE-REPAIR INSPECTION/SURVEY, please email to motorsurvey@ecics.com.sg directly.

\*\*Please bear with us should we take longer to response as we are currently experiencing a high volume of claims. Thank you for your kind patience and understanding. \*\*

From: Shiau Chan (LKKAuto) [mailto:siewsc@lkkauto.com]

Sent: Monday, 26 February, 2018 2:34 PM

To: ECICS Claims; assignments

Cc: SUR

Subject: RE: OUR REF: SKT5892Z \*\*od claim. req for survey.

Dear Lionel,

Enclosed herewith preliminary advice of SKT 5892Z.

We have NOT authorise repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: <u>siewsc@lkkauto.com</u> | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 22 February 2018 4:30 PM

To: 'ECICS Claims' < claims@ecics.com.sg>; assignments < assignments@lkkauto.com>

Cc: SUR < sur@lkkauto.com>

Subject: RE: OUR REF: SKT5892Z \*\*od claim. req for survey.

Dear Sir/Mdm,

#### Shiau Chan (LKKAuto)

From:

Shiau Chan (LKKAuto)

Sent:

Monday, 26 February 2018 2:34 PM

To:

'ECICS Claims'; assignments

Cc:

SUR

Subject:

RE: OUR REF: SKT5892Z \*\*od claim. req for survey.

Attachments:

CSICS18003415Uqd3.pdf

Dear Lionel,

Enclosed herewith preliminary advice of SKT 5892Z. We have NOT authorise repair.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)

Sent: Thursday, 22 February 2018 4:30 PM

To: 'ECICS Claims' <claims@ecics.com.sg>; assignments <assignments@lkkauto.com>

Cc: SUR <sur@lkkauto.com>

Subject: RE: OUR REF: SKT5892Z \*\*od claim. req for survey.

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ECICS Claims [mailto:claims@ecics.com.sg] Sent: Wednesday, 21 February 2018 4:32 PM

To: jess.francis@eurokars.com.sg; admin-d@lkkauto.com; assignments@lkkauto.com

Cc: ECICS Claims < claims@ecics.com.sg>; kevin.lee@eurokars.com.sg; eric.pau@eurokars.com.sg; ronald.yap@eurokars.com.sg; vion.lim@eurokars.com.sg; catherinechua@eurokars.com.sg; SUR

<sur@lkkauto.com>

Subject: RE: OUR REF: SKT5892Z \*\*od claim. req for survey.

Our claim no. DMPC1800060H

Dear Jess,

We will arrange LKK to conduct the OD survey and our surveyor will contact you shortly.

Aside to LKK

Please arrange to conduct for (OD) own damage survey.



51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: DMPC1800060H

Date: 26th February 2018

Our Ref: CS/ICS18003415/Uqd3

The Motor Claims Department ESICS Limited

Attn: Lionel

Dear Sirs/Mdm

# PRELIMINARY ADVICE OF VEHICLE NO. SKT 5892Z .

We thank you for the instruction on <u>21/02/2018</u>.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 22/02/2017 at the premises of M/s TRANS EUROKARS and have the following to report:-

Workshop Estimate Amount	: <u>S</u> \$	20,510.64	
Revised Estimate Amount	: <u>S</u> \$	9,826.50	=
"Check" Items Amount	: <u>S</u> \$	3,217.05	
Market Value	: <u>S\$</u>	71,000.00	- 6
Salvage Value Nett Value	: <u>S\$</u>	54,082.00	_
Nett value	: <u>S\$</u>	16,918.00	

Description of Damage:

The vehicle sustained damages at the

front o/s portion.

rear from offside

Comments/ Present Status:

Damages consistent.

Repair cost economical.

We have NOT authorize repair.

Yours faithfully

CHUA KANG SENG Licensed Appraiser

# Enquire PARF/COE Rebate for Registered Vehicle

ehicle Owner Particular	S
wner ID Type:	Singapore NRIC
wner ID:	28571
ehicle Details	
hicle No.:	SKT5892Z
hicle to be Exported:	No
tended De-registration ate:	23 Feb 2018
hicle Make:	MAZDA
hicle Model:	MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT
imary Colour:	Red
anufacturing Year:	2015
igine No.:	P520284937
nassis No.:	JM6BM42A8G0310676
aximum Power Output:	88.0 kW (118 bhp)
pen Market Value:	\$17,179.00
riginal Registration Date:	16 Jun 2015
rst Registration Date:	16 Jun 2015
ansfer Count:	0
tual ARF Paid:	\$7,179.00 3581
tended PARF Rebate De	No. October
ARF Eligibility:	Yes
ARF Eligibility Expiry ate:	15 Jun 2025
ARF Rebate Amount:	\$5,384.00
tended COE Rebate De	tails
OE Expiry Date:	15 Jun 2025
OE Category:	A - Car up to 1600cc & 97kW (130bhp)
OE Period(Years):	10
P Paid:	\$66,590.00
OE Rebate Amount:	\$48,698.00
otal Rebate Amount:	\$54,082.00

The information contained herein is correct as at 23 Feb 2018

#### SGCARMART.COM

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Article:

- Got my NS50 pack liow!
- Taiwan earthquake 6 Feb 2018
- Maxus G10 SE The full-size MPV that got

Post an Advertisement Sell it yourself! Advertise it at just \$58 until it's SOLD!

Post an Ad

Advertiser Login

350

Ways of Selling

New 5 Years COE Renewal Toyota Estima 2.4A



\$6800 Downpayment! Monthly \$938 Onwards! Lowest 3.68% P.A@GV Cars Financing! GV Credit Pte Ltd StarAd



Browse by Category

« Back (12) Next »

Sort by

25 vehicles

Mazda 3

Price

Depreciation

Reg Date

Advano

Any

Any

2015

Any

Mile

Search Selection

Mazda 3

Make

\$72,000

\$8,820 /yr

22-Sep-2015

1,496 cc

Eng Cap

36,

One Owner, Low Mileage, Good Condition, CALL FOR VIEWING.

Model

Posted: 22-Feb-2018 Tags: 2015 Mazda 3, Mazda 3, Mazda, 3, Used Mazda



Mazda 3 SP 1.5A

Mazda 3 SP 1.5A

\$76,000

\$9,090 /yr

27-Nov-2015

1,496 cc

32,

Single Owner, Low Mileage, Well-kept Condition. View To Believe. Viewings Strictly Via Appointment Only.

Carro

Posted: 22-Feb-2018 Tags: 2015 Mazda 3, Mazda 3, Mazda, 3, Used Mazda



Mazda 3 SP 1.5A

\$74,800

\$9,050 /vr

30-Oct-2015

1,496 cc

High/Flexible Loan Available! Under Agent 3 Years Warranty Scheme, Maintained With Agent! One Of Mazda Most Popula Sales Team Now To Arrange For A Viewing In Our Air Conditio...

GS Automobiles Pte Ltd

Posted: 22-Feb-2018 Tags: 2015 Mazda 3, Mazda 3, Mazda, 3, Used Mazda



Mazda 3 SP 1.5A

\$72,800

\$8,930 /yr

25-Sep-2015

1,496 cc

Impressive Showroom Condition! New Era Mazda 3 Is Top Choice Sedan! Sporty Aggressive Styling With Improved Fuel E Eurokars! Contact/SMS Our Professional Friendly Sales Execut...

Posted: 22-Feb-2018 Tags: 2015 Mazda 3, Mazda 3, Mazda, 3, Used Mazda

Car Buying

Car Selling

Car Aftermarket

Car Ownership

On The Move

Lifestyle

1,998 cc

Mazda 3 Sedan 2.0A Sport

\$85,800

\$9,860 /yr

30-Nov-2015

\$40K Off From New Car! One And Only Top Spec Mazda 3 2.0! Feature Rich Compare To The 1.5 Model. Sporty Sedan W Handling, Sunroof To Enjoy The Sun And Night Sky, Full Agent ...

# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties. Any false reporting may be referred to the Police for Investigation.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available atoresaid.

ACCIDENT	STATEM	ENT
----------	--------	-----

Date Of Report

19/02/2018 17:43

Date Of Accident

16/02/2018 23:35

Exact Location Of Accident

ALONG RD 1 GUILLEMARD RD TOWARDS GEYLANG

SINGAPORE

Country/State of Loss

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number

SKT5892Z

Insured/Policyholder

Name Of Registered Owner

ZAINAL ABIDIN BIN HUSSAIN

NRIC No

S12628571

Email Address

ZAINAL.ABIDIN.HUSSAIN@CHANGIAIRPORT.COM

Mobile Phone No

(LOCAL) +65-84845812

Alternative Phone No

OTHERS-84845812

Vehicle Particulars

Manufacturer

MAZDA

Model

Exact Purpose for which vehicle was being used at

time of accident Are you claiming under your own insurance policy

YES

for repair to your vehicle? If No, Please state action to be taken

Vehicle Category

PRIVATE CAR

Insurance Company

Name of Insurance Company

ECICS LIMITED

Type Of Coverage

Fleet Policy

COMPREHENSIVE

NO

Policy Number

MPC17A00258301

Cover Note Number

Driver

ZAINAL ABIDIN BIN HUSSAIN

Name of Driver

S12628571

NRIC No

21/08/1957

Date Of Birth

INDOOR

Occupation

Date Of Driving Pass

12/05/1975

Driving Experience

42 YEARS AND 9 MONTHS

MALE

Gender

(LOCAL) +65-84845812

Mobile Number

Fax Number

OTHERS-84845812

Contact Number EMail Address

ZAINAL.ABIDIN.HUSSAIN@CHANGIAIRPORT.COM

Page 1 of 14

Address

BLK 3 TANJONG PAGAR PLAZA #22-31

Postcode

081003

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured

OWNER

Vehicle Registration Number of Driver's Own

Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident

COLLISION - CHANGE/CROSS LANE

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident?

NO

Number of vehicles involved in the accident Was any body injured in the Accident?

Was any injured conveyed to hospital by

NO

ambulance?

NO

Was any other material or property damaged?

YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance.

NO

Number of Passengers (Including Driver)

2

Passenger 1

NAME:

: NGUYEN THI THU HIEN

GENDER:

: FEMALE

**Details of Police Action** 

Was the accident reported to the police? If Yes, Please state which Police Station

YES

Police Station Name

TAMPINES N.P.C

Police Station Address

ROAD: TAMPINES N.P.C , POSTCODE: 529682 , COUNTRY: SINGAPORE

TEL NO: - FAX NO: Police Station Contact

Was notice of intended Prosecution given?

NO

If Yes, against whom?

REFER TO ATTACHED STATEMENT RECORDED BY LILY - PROGRESSIVE AUTOMOTIVE PTE LTD 67415336

Attachment(s)

Are accident photos available for attachment?

YES

Was there any video captured by Car Camera?

YES

Remarks/ Reasons:

REQUEST FROM OWNER

Was there any audio recorded? DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SBS8568C

Vehicle Make/Model/Colour

Details Of Properties

BUS

Vehicle Category

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode Insurance Company Name Nature Of Damage No. Of Passenger (Including Driver)

#### SKETCH PLAN

#### IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This form must be completed by the Policyholder and/or the Authorised Oriver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GiA) for archiving and that copies of this report will for a fee be made available upon application by
- By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

l understand, acknowledge, agree and consent that:

- My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s)
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary Investigations relating to the claims;
  - (ii) Investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal information for one or more of the above Purposes; and
  - (c) my Personal information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
  - my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
  - (e) the information so collected under (d) above may be shared / disclosed:
    - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud. regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
    - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

1912/18 Date & Times

Oriver's Signature (If driver is not the policyholder)

Date & Time:

nnel's Signature Reporting Centre P

Name: NRIC/FIN No.:

GIARMC ShorchPlanForm\_V3

# Sketch Plan #2

CETCH PLAN		11111				Vehicle No.
	-+-					B- 865 85
er as						Lac
1	Cervi	lenson of	Hd			+++++
1111	+					La ye
dilli				100		1216
				1,04	TALL	
$+\pm\pm\pm$			1			
++++			1	++++++		D A
	++++		1 200	+ I dece		IAI 5
	0000	++++	1	111111		Vehicle Bike
	Leasts	<del></del>	+++++	111/14/1		Astricia
DESCRIBE CI	RCUMSTANCES	OF THE ACCID	ENT	<i>J</i> .	,	
P	pare Inch	er to Pol	the Repor	-attacked		
					72,15	
-						
-						
1000						
-						
		100000				
DECLAR	ATION					
DECLAR I/we dec	ATION	poarticulars are tr	un in every respect	whereby the claim	against own policy	must be made wi
DECLAR I/We dec Please b stipulate	ATION lare the foregoing a advised that yo d timeframe from	poarticulars are tr ur inturer may hi n the date of occ	ue in every respect ave a 14 day clausi urrence. Kindly ch	whereby the claim eck your policy for m	sgainst own policy	must be made wi
DECLAR I/we dec Please b stipulate	ATION lare the foregoing a advised that yo d timeframe from	-qc		whereby the claim a	against own policy ore details	must be made wit
Policyhol	ATION lare the foregoing a advised that you der's senatura irrest 1712 113 seetch Flan Form you	Orth	ue in every respect ave a 14 day claus urrence. Kindly ch rer's Signature friver is not the polic	in and the second	Reporting Centry	must be made wit

### Police report pg 1 Pg. 1

Vide Report No.:



REPORT OF A TRAFFIC ACCIDENT



1 of 3

Police Station Of Origin: Tampines N.P.C

6 Tampines Avenue 4 SINGAPORE 529682

Tel No: 1800-5871999

Report No. T/20180216/2092

Station Diary No.:

ate/Time R 6/02/2018 2	eport M	lade:	VI	de Rep	OIT TO.			93	2.58UNO. 408NO. 1/18
		ulars			LEAVER NA	0.00	8.0 Va 12 W	<b>没想到了那样</b>	<b>有关的特殊的</b>
lama of Info	ormant:	ulars. N HUSSAIN	A	81003	3 TANJONG	PAGAR		- 1970/ife == 0.	
Type / ID	No.: S12628	571	H	ontact I	No.: ffice:		Mobile:	84845812	2
Nationality:				mall:					
Sex:	Age:	Date of Bi 21/08/195	2000	ype of Oriver	Informant:		Transitort	ion / Scho	ol Name:
Male Race:	00		L	angua			Institut	1011 / 00110	
Malay Occupation MANAGER				Oriving Class:	Licence Inform	nation:	Date o	of Expiry:	
	-					mar Jacob	九郎歌号等	hat see Marin A.	
Coneral In	formati	on of the Acc	cident™	W 164	THE PERSON	Date/Ti	ALC: NO STATE OF THE PARTY OF T	T	pe of Location
Type of Accident:		Non-Injury			Drink Drive: No	Accider			
Along Ros GUILLEN towards of Weather:	ARD R			Road	Surface:				Speed Limit:
Traffic FI	ow:			Traffic	Control:			-1.000047038	Volume:
Type of		n: *						Anyon ambul No	e conveyed by ance:
					New York Street		CENT EDICALIE		Constitute Constitute
Details	of Veh	icle involved	See Se		Model	Color		Condition	No of Passer
Vehicle	No.: T	ype.	Make	POLICE AND ADDRESS OF THE PARTY	Model	3000		Slightly	20
SBS856		Bus/Coach/Mi hibus		8	MAZDA3 4-	Red	-	Damaged Slightly	1
SKT58	92Z (	Car	MAZDA	8	DOOR SEDAN 1.5L SP.6EAT			Damaged	
		hicle Insuran	CO NOTE	<b>医克尔斯</b>	CONTRACTOR OF THE			Effectiv	e Éxpliry l
	CONTRACT DESCRIPTION	i-la neuran	COMPRESENT	CONTRACTOR OF THE PARTY OF	THE REAL PROPERTY AND ADDRESS OF THE PARTY AND	THE RESERVE AND ADDRESS OF	the street beautiful that the	WARRIED WARRENDS	D XDIV





Police Station Of Origin;

Tampines N.P.C

6 Tampines Avenue 4 SINGAPORE 529682

Tel No. 1800-5871999

CONTINUATION OF REPORT

2 of 3 Report No. T/20180216/2092

Details of V	ehicle insurance	Insurance No		Expiry Date
Vehicle No.	Insurance Company	MPC17A00258301	16/06/2017	15/06/2018
SKT5892Z	Andrewson and the statement of the state	MFCTTAGE		

Any Pedestrian I	n Involved nvolved; No	Use of Ped	estrian Cr	rossing: NA
No. of Pedestrian			10 110	S1262857I
Driver	ZAINAL ABIDIN BIN HUSSAIN		ID No.	012020
Name	Dan e e e e		Contact	No. 84845812
n i i d Mehicle	SKT5892Z (Car)		Contact	140. 040.02.1
Related Vehicle	VIII.		Class of	Class: NIL
Hospital/Clinic	NIL		Driving Licence Expiry D	Date of Expiry: NIL
		I m to Disc	The second second second	NIL
Date Treatmen	NIL	Date Disc	f Injury	
No of Days or	nted Medical Leave NIL	Degree o	MANUFACTURE PARTY	THE RESIDENCE OF THE PARTY OF T
Passenger		B.C. College Manager	TID No.	G3360691K
Name	NGUYEN THI THU HIEN			
			Contac	t No. 85816372
Related Vehicl	e SKT5892Z (Car)			
			Class	
Hospital/Clinic	NIL		Driving Licence Expiry	pe & Date
1		Date Di	scharge	NIL
	nt NIL NIL	Date:	of Injury	

On the 16/02/2018, at about 10pm, I was travelling along Guillemard road towards Geylang on the left most lane of a three lane carriageway. Subsequently, there was a bus travelling on the centre lane who then cut into my lane and thus this caused it to hit my vehicle on my right front side bumper and lights.

Both myself and my passenger at that point of time was unburt from the accident.





3 of 3

Report No. T/20180216/2092

Police Station Of Origin: Tampines N.P.C

6 Tampines Avenue 4 SINGAPORE 529682 CONTINUATION OF REPORT Tel No: 1800-5871999

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: Sgt 2 MUHAMMAD FIRDAUS BIN YUSOFF G/ Signature Of Interpreter: Not applicable Officer In Charge Of Case:

TP / GIA / Staff Sgt TANG SIEW PING Contact No.: 65476430

Authentication Stamp NP168

Signature Of Informant:

Date/Time: 16/02/2018 23:35

Classification Of Case:

SINGAPORE POLICE FORCE

SIGNATURE



### TRANS EUROKARS PTE LTD NO:5 UBI CLOSE, SINGAPORE 408605



ESTIMATE COST OF REPAIRS

NAME: **ECICS LIMITED** 

Mr Zainal Abidin Bin Hussain

WIP:

63601

7 Temasek Boulevard

ADDRESS:

Blk 788d Woodlands Cresent

EXCESS:

21-Feb-18

#10-01 Suntec Tower One

#02-192

DATE:

Singapore 038987.

TEL:

DATE IN:

Singapore 734788

FAX:

ATTN.:

MOTOR CLAIMS

84845812

JESS 6395 7874 CONTACT PERSON:

CHASSIS NO:

JM6BM42A8G0310676

SKT5892Z

MILEAGE:

TYPE OF CLAIM:

MODEL:

VEH NO:

MAZDA3 1.5L

DATE REG.: 16-Jun-15 POLICY NO. : OWN DAMAGE CLAIM

#### NATURE OF WORKS

		Parts Description	on .		
NO		QTY		REVISED	PRICES
1	FRONT BUMPER	1	MBHR3-50-031BBB	27 75	1,031.70
2	RETAINER(RHS), FRONT BUMPER	1	MBHN1-50-0T1F	sur 15	18.70
3	BRACKET(RHS), FRONT BUMPER	1	MBHN1-50-152	sul 15	15.10
4	COVER(LHS), FRONT BUMPER	1	MBHN1-50-102	17 XS	28.00
5	COVER(RHS), FRONT BUMPER	1	MBHN1-50-101	cm 15	28.00
6	FRONT REINFORCEMENT	1	MB45A-50-070A	1 *5	
7	COVER(RHS), FOGLAMP	1	MBJE1-50-C11A	cu?	46.40
8	CHROME(RHS), FOGLAMP	1	MBJE1-50-C12	SINS	106.70
9	GROMMET, FRONT BUMPER	2	MGHP9-50-0Z5	ner	5.40
10	CLIP, FRONT BUMPER	12	MC274-50-133	ner !	42.00
11	FASTENER, FRONT BUMPER	2	MB45A-56-146A	ser	5.60
12	GRILLE TOP	1	MBHN1-50-033 62	Yuy 1	335.00
13	RIVET, GRILLE TOP	6	MS51S-51-833	ner	22.80
14	RIVET, GRILLE TOP	4	MTK21-50-355	nu	
15	BRACKET TOP, GRILLE	1	MBHN1-50-717D	tre	102.40
16	CHROME(LHS), FRONT BUMPER	1	MBHN1-50-7K1A	111	176.70
17	CHROME(RHS), FRONT BUMPER	1	MBHN1-50-7J1A	660	\$ 176.70
18	GRILLE:BLACK (GLOSS)	1	MBJE1-50-712B	11 x	\$ 581.60
19	MASCOT, FRONT	1	MC235-51-731A	17 X	\$ 44.20
20	BRACKET(LHS), GRILLE	1	MBHN1-50-163	nu -	\$ 15.10
21	BRACKET(RHS), GRILLE	1	MBHN1-50-153	su -	\$ 15.10
22	PIN LOCATOR, GRILLE	2	MKD45-50-1K5A	nu -	\$ 5.40
23	GROMMET, GRILLE	2	MKD45-50-ES1	ru -	\$ 5.40
24		2	MEA01-50-037	ne -	
25	FASTENER, GRILLE	8	MGD7A-50-EA1	nu t	\$ 24.00
26	The same transfer of the same to the same	1	MBHN3-50-1C0	nnx	\$ 92.70
27	NAME OF THE PARTY	4	MGD7A-50-EA1	500000000000000000000000000000000000000	\$ 12.00
28		1	MGHR5-53-110B	<i>\text{\rm -\lambda}</i>	\$ 469.70
29	ADDIOUS AND CONTRACTOR OF THE	1	MBHY0-52-31XA	20/suc	\$ 1,067.30
30	ST ASSESSMENT OF THE PARTY OF T	1	MB45A-52-420A	n	\$ 41.00

	HINGE(RHS), BONN	ET	1	MB45A-52-410A		<b>*</b> \$	41.00
32	WEATHERSTRIP, BO	ONNET	1	MBHN9-56-770A	per	-\$	63.60
33	RHS FRONT FENDER	R	1	MB45A-52-111B	34	-\$	333.90
34	STAY(RHS), FRONT	FENDER	1	MB4YA-52-10Y	Sul	\$	39.90
35	RHS FRONT MUDG	UARD	1	MB45A-56-130H	70-1	+\$	97.00
36	FASTENER, MUDGU	JARD	10	MB45A-56-146A	ser	13	28.00
37	COVER(RHS), HEAD	LAMP WASHER	1	MBHT4-51-8G1 62	Mis		85.10
38	ACTUATOR(RHS), H	HEADLAMP WASHER	1	MBHT4-51-82X	cm	100	242,40
39	CLAMP, ACTUATOR	₹	1	MTK33-51-829	ne	\$	16.40
40	TANK, WASHER		1	MGHP9-67-481	De	1\$	104.00
41	HEADLAMP RHS		1	MBHT6-51-031A	300	+	2,245.00
42	CLIP, HEADLAMP		2	MFB01-50-133C	nu	5	7.60
43	RIVET, HEADLAMP		1	MB092-51-833	ner	\$	3.30
32055	H I D CONTROL UN	IIT (HEADLAMP)	1	MBHN3-51-0H3	11	\$	895.50
45	LAMP(RHS), FRON	U MVC ACMS	1	MB45A-51-350A	17	\$	157.30
46	RHS FOGLAMP		1	MTK21-51-680A	11	\$	351.40
47	BRACKET(RHS), FO	GLAMP	1	MBHR1-51-684A	11	\$	17.30
48	WHEEL DISC (RHF)	1	1	M9965-D0-6560	11	\$	1,101.70
49	TYRE (RHF)		1	0	17	\$	350.00
				TOTAL PARTS		\$	11,189.60
				I STATE OF THE STA		-	1,118.96
				LESS 10%		\$	1,110.30
			Labour Descrip	TOTAL PARTS COST		-	10,070.64
8		TO REPLACE FRONT BUMPER, FRO	ONT REINFORCEMEN	TOTAL PARTS COST  tion  NT, GRILLE TOP, BONNET AND FRON		\$	10,070.64
1	MZ-BR-FRONT6	TO REPLACE FRONT BUMPER, FRO FENDER, REPAIR ALL AREAS AFFE	ONT REINFORCEMEN	TOTAL PARTS COST  tion  NT, GRILLE TOP, BONNET AND FRON	1890	\$	3,960.00
1 2	MZ-BR-FRON16	FENDER. REPAIR ALL AREAS AFFE	ONT REINFORCEMEN CTED BY THE ACCIL	TOTAL PARTS COST  Stion  NT, GRILLE TOP, BONNET AND FRONT	1890	\$	3,960.00
	MZ-SP-SFRT06	FENDER, REPAIR ALL AREAS AFFE  TO RESPRAY FRONT BUMPER, FRO	ONT REINFORCEMENT CTED BY THE ACCIDENT REINFORCEMENT GOVERNMENT GO	TOTAL PARTS COST  Ation  NT, GRILLE TOP, BONNET AND FRONT DENT. 660  NT, GRILLE TOP, BONNET AND FRON	1890	\$ 5	3,960.00 3,780.00
2	MZ-BR-FRON16  MZ-SP-SFRT06  MZ-BR-PANEL1	TO RESPRAY FRONT BUMPER, FROF FENDER.  TO REMOVE & INSTALL RADIATOR CONDUCT PRESSURE TEST & PER	ONT REINFORCEMENT ONT REINFORCEMENT ONT REINFORCEMENT ON THE PROPERTY OF THE P	TOTAL PARTS COST  Ation  NT, GRILLE TOP, BONNET AND FRONT DENT. 660  NT, GRILLE TOP, BONNET AND FRON	1890	\$ \$	3,960.00 3,780.00 660.00
2	MZ-BR-FRON16  MZ-SP-SFRT06  MZ-BR-PANEL1  MZ-BR-TOP-UP	TO RESPRAY FRONT BUMPER, FROF FENDER.  TO REMOVE & INSTALL RADIATOR CONDUCT PRESSURE TEST & PER	ONT REINFORCEMENT OF THE ACCILINATION OF THE A	TOTAL PARTS COST  ATT, GRILLE TOP, BONNET AND FRONT DENT. 660  NT, GRILLE TOP, BONNET AND FRONT D FRONT SUPPORT PANEL. TO  AND TOP-UP GAS COOLING SYSTEM	1890 1890 11)	\$ \$	3,960.00 3,780.00 660.00
3	MZ-BR-FRON16  MZ-SP-SFRT06  MZ-BR-PANEL1  MZ-BR-TOP-UP  MZ-BR-WHEBAL	TO RESPRAY FRONT BUMPER, FROM FENDER.  TO REMOVE & INSTALL RADIATOR CONDUCT PRESSURE TEST & PER  TO REMOVE & INSTALL CONDENSOR	ONT REINFORCEMENT ONT REINFORCEMENT ONT REINFORCEMENT ON THE STANDARD ON THE S	TOTAL PARTS COST  ST. GRILLE TOP, BONNET AND FRONT DENT. 660  NT, GRILLE TOP, BONNET AND FRONT D FRONT SUPPORT PANEL. TO  AND TOP-UP GAS COOLING SYSTEM  CING.	1890 1890 11)	\$ \$	3,960.00 3,780.00 660.00
3 4 5	MZ-BR-FRON16  MZ-SP-SFRT06  MZ-BR-PANEL1  MZ-BR-TOP-UP  MZ-BR-WHEBAL	TO RESPRAY FRONT BUMPER, FROF FENDER.  TO REMOVE & INSTALL RADIATOR CONDUCT PRESSURE TEST & PER  TO REMOVE & INSTALL CONDENSO  TO MOUNT SPORT RIM AND COND	ONT REINFORCEMENT CTED BY THE ACCIDENT REINFORCEMENT OF A SAME OF	TOTAL PARTS COST  Ation  IT, GRILLE TOP, BONNET AND FRONT DENT. 660  INT, GRILLE TOP, BONNET AND FRONT DENT SUPPORT PANEL. TO  AND TOP-UP GAS COOLING SYSTEM  CING. 19 X	1890 1890 111)	\$ \$	3,960.00 3,780.00 660.00 120.00
3 4 5	MZ-BR-FRONT6  MZ-SP-SFRT06  MZ-BR-PANEL1  MZ-BR-TOP-UP  MZ-BR-WHEBAL  MZ-BR-WHEALI  MZ-BR-WHEALI	TO RESPRAY FRONT BUMPER, FROF FENDER.  TO REMOVE & INSTALL RADIATOR CONDUCT PRESSURE TEST & PER  TO REMOVE & INSTALL CONDENSO  TO MOUNT SPORT RIM AND COND  TO CHECK STEERING GEOMETRY	ONT REINFORCEMENT CTED BY THE ACCID DNT REINFORCEMENT AND	TOTAL PARTS COST  INT. GRILLE TOP, BONNET AND FRONT DENT. 660  INT. GRILLE TOP, BONNET AND FRONT DENT SUPPORT PANEL. TO  AND TOP-UP GAS COOLING SYSTEM  CING. IN IN IN INTERPRETATION  WHEEL ALIGNMENT. IN INTERPRETATION  TIONING.	/890 /890 //1/2	\$ \$ \$	3,960.00 3,780.00 660.00 120.00 560.00
2 3 4 5 6	MZ-BR-FRONT6  MZ-SP-SFRT06  MZ-BR-PANEL1  MZ-BR-TOP-UP  MZ-BR-WHEBAL  MZ-BR-WHEALI  MZ-BR-WHEALI	TO RESPRAY FRONT BUMPER, FROFENDER.  TO REMOVE & INSTALL RADIATOR CONDUCT PRESSURE TEST & PER  TO REMOVE & INSTALL CONDENSO  TO MOUNT SPORT RIM AND COND  TO CHECK STEERING GEOMETRY  TO CHECK ELECTRICAL SYSTEM FOR THE AND CORDUCT PRESSURE TEST & PER  TO REPROGRAMME AFTER THE A	ONT REINFORCEMENT CTED BY THE ACCID DNT REINFORCEMENT AND	TOTAL PARTS COST  INT. GRILLE TOP, BONNET AND FRONT DENT. 660  INT. GRILLE TOP, BONNET AND FRONT DENT SUPPORT PANEL. TO  AND TOP-UP GAS COOLING SYSTEM  CING. IN IN IN INTERPRETATION  WHEEL ALIGNMENT. IN INTERPRETATION  TIONING.	/890 /890 //1) // NETT	\$ \$ \$	3,960.00 3,780.00 660.00 120.00 560.00

TOTAL PARTS	\$	\$ 10	,070.64
TOTAL	\$ (*)	\$ 20	,510.64
LESS EXCESS	\$	\$	
TOTAL AFTER EXCESS	\$		
GST 7%	\$	\$	162
GRAND TOTAL	\$ -3	\$	-

#### TRANS EUROKARS PTE LTD

Authorised Signature

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Not Arlborn Luch
Luch
Exuss & 500
The photo Behre panty.
Whish

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



# TRANS EUROKARS PTE LTD NO:5 UBI CLOSE, SINGAPORE 408605



# SUPPLEMENTARY ESTIMATE COST OF REPAIRS

Tema: #10-01	-	ADDRESS :	Mr Zainal Abi Blk 788d Woodl #02-192 Singapore 7347 84845812		WIP: EXCESS: DATE:	7874	636 21-Fe	601 eb-18
VEH N		DATE IN :		TYPE OF CLAIM:	OWN DAM	1AGE	CLAIM	
CHASS	IS NO: JM6BM42A8G03106	The Company of the Con-		POLICY NO. :				
MODE	L: MAZDA3 1.5L	DATE REG.:	16-Jun-15	- Indiana and the second				
			Parts Description					
_			QTY		REVISE	D	PR	ICES
NO	TURNI MAR		1	MB45A-51-354			\$	39.00
1	SOCKET(RHS), TURN LAMP		1	M9970-06-210Y			\$	7.60
2	BULB(RHS), TURN LAMP		1	MBHN9-67-290			\$	37.30
3	CORD, SHORT (TURN LAMP)							
				TOTAL PARTS			\$	83.90
				LESS 10%			\$	8.39
				TOTAL PARTS COST			\$	75.51
		1	abour Descripti	o <u>n</u>				
				TOTAL LABOUR	\$			
				TOTAL PARTS	\$		\$	75.5
				TOTAL	\$		\$	75.5
				LESS EXCESS	\$	-	\$	
				TOTAL AFTER EXCESS	\$			
				GST 7%	\$		\$	•
				GRAND TOTAL	\$		\$	

TRANS EUROKARS PTE LTD

REMARKS:
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD
THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF
REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING
CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED
WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED
ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS
PRICE AS WELL AS LABOUR CHARGES.

**Authorised Signature** 



#### TRANS EUROKARS PTE LTD NO:5 UBI CLOSE, SINGAPORE 408605



FINALISED COST OF REPAIRS

**ECICS LIMITED** 

NAME:

Mr Zainal Abidin Bin Hussain

WIP:

63601

7 Temasek Boulevard

Blk 788d Woodlands Cresent ADDRESS :

EXCESS:

500.00

#10-01 Suntec Tower One

#02-192

21-Feb-18 DATE:

Singapore 038987.

Singapore 734788

FAX:

ATTN. :

CHASSIS NO:

MOTOR CLAIMS

TEL:

84845812

JESS 6395 7874

VEH NO:

SKT5892Z JM6BM42A8G0310676

DATE IN: MILEAGE:

TYPE OF CLAIM: POLICY NO. :

CONTACT PERSON:

OWN DAMAGE CLAIM

MODEL:

16-Jun-15 DATE REG.: MAZDA3 1.5L

NATURE OF WORKS

Parts Description REVISED PRICES QTY NO 1,031.70 1,031.70 \$ MBHR3-50-031BBB \$ 1 FRONT BUMPER 1 18.70 \$ 18.70 MBHN1-50-0T1F 1 RETAINER(RHS), FRONT BUMPER 2 15.10 \$ 15.10 MBHN1-50-152 1 BRACKET(RHS), FRONT BUMPER 3 28.00 MBHN1-50-102 1 COVER(LHS), FRONT BUMPER 4 28.00 \$ 28.00 \$ MBHN1-50-101 1 COVER(RHS), FRONT BUMPER 5 444.50 MB45A-50-070A 1 FRONT REINFORCEMENT 6 46.40 46.40 MBJE1-50-C11A 1 COVER(RHS), FOGLAMP 7 106.70 \$ 106.70 MBJE1-50-C12 1 CHROME(RHS), FOGLAMP 8 5.40 \$ 5.40 \$ MGHP9-50-0Z5 2 GROMMET, FRONT BUMPER 9 42.00 \$ 42.00 MC274-50-133 12 CLIP, FRONT BUMPER 10 \$ 5.60 5.60 MB45A-56-146A 2 FASTENER, FRONT BUMPER 11 335.00 \$ \$ 335.00 MBHN1-50-033 62 1 **GRILLE TOP** 12 22.80 22.80 MS51S-51-833 6 RIVET, GRILLE TOP 13 34.80 34.80 \$ MTK21-50-355 4 RIVET, GRILLE TOP 14 102.40 102.40 \$ MBHN1-50-717D 1 BRACKET TOP, GRILLE 15 176.70 MBHN1-50-7K1A 1 CHROME(LHS), FRONT BUMPER 16 176.70 \$ 176.70 \$ MBHN1-50-7J1A 1 CHROME(RHS), FRONT BUMPER 17 581.60 MBJE1-50-712B 1 GRILLE:BLACK (GLOSS) 18 44.20 MC235-51-731A 1 MASCOT, FRONT 19 15.10 \$ 15.10 \$ MBHN1-50-163 1 BRACKET(LHS), GRILLE 20 15.10 \$ \$ 15.10 MBHN1-50-153 1 BRACKET(RHS), GRILLE 21 5.40 5.40 \$ \$ MKD45-50-1K5A 2 PIN LOCATOR, GRILLE 22 5.40 \$ 5.40 \$ MKD45-50-ES1 2 GROMMET, GRILLE 23 15.20 15.20 \$ MEA01-50-037 2 RIVET, GRILLE 24 24.00 \$ 24.00 \$ MGD7A-50-EA1 8 FASTENER, GRILLE 25 92.70 \$ MBHN3-50-1C0 1 PLATE, SET (REINFORCEMENT) 26 \$ 12.00 MGD7A-50-EA1 4 FASTENER, PLATE SET 27 469.70 MGHR5-53-110B 1 SUPPORT PANEL 28 1,067.30 1,067.30 \$ MBHY0-52-31XA 1 BONNET 29 41.00 \$ MB45A-52-420A 1 HINGE(LHS), BONNET 30 41.00 \$ MB45A-52-410A 1 HINGE(RHS), BONNET 31

2   V	WEATHERSTRIP, BON	NET		1	MBHN9-56-770A		\$	63.60		63.60
-	RHS FRONT FENDER	Vessi//II		1	MB45A-52-111B		\$	333.90	\$	333.90
100	TAY(RHS), FRONT FI	ENDER		1	MB4YA-52-10Y		\$	39.90	\$	39.90
1000	RHS FRONT MUDGU			1	MB45A-56-130H		\$		\$	97.00
	ASTENER, MUDGUA			10	MB45A-56-146A		\$		\$	28.00
1000	COVER(RHS), HEADL			1	MBHT4-51-8G1 62		\$		\$	85.10
	ACTUATOR(RHS), HE		HER	1	MBHT4-51-82X		\$		\$	242.40
2.0	CLAMP, ACTUATOR			1	MTK33-51-829		\$		\$	16.40
	TANK, WASHER			1	MGHP9-67-481		\$		\$	104.00
	HEADLAMP RHS			1	MBHT6-51-031A		\$	2,245.00	\$	2,245.00
-	CLIP, HEADLAMP			2	MFB01-50-133C		\$	7.60	\$	7.60
	RIVET, HEADLAMP			1	MB092-51-833		\$	3.30	\$	3.30
	H I D CONTROL UNI	T (HEADLAMP)		1	MBHN3-51-0H3				\$	895.50
	LAMP(RHS), FRONT			1	MB45A-51-350A				\$	157.30
	RHS FOGLAMP			1	MTK21-51-680A				\$	351.40
	BRACKET(RHS), FOO	SLAMP		1	MBHR1-51-684A				\$	17.30
	WHEEL DISC (RHF)			1	M9965-D0-6560				\$	1,101.70
49	TYRE (RHF)			1	0				\$	350.00
43	SUPPLEMENTARY I	TEMS								
43	SOCKET(RHS), TURI	And the second second		1	MB45A-51-354	cru	\$	39.00	\$	39.00
7.00	BULB(RHS), TURN L		400	1	M9970-06-210Y	Daye	\$	7.60	\$	7.60
43	CORD, SHORT (TUR		14.0	1	MBHN9-67-290	Dale	\$	37.30	\$	37.30
43	CORD, SHORT (TOR	IIA EMAIL I				1				
_					TOTAL PARTS		\$	6,468.90	\$	11,273.50
					LESS 10%		\$	646.89	\$	1,127.35
					TOTAL PARTS CO	ST	\$	5,822.01	\$	10,146.15
				Labour Descrip	otion		Т		Т	
	1						-		+-	
1	MZ-BR-FRONT6	TO REPLACE FF FENDER, REPAI	RONT BUMPER, FRO	ONT REINFORCEMENT ECTED BY THE ACCIO	NT, GRILLE TOP, BONNE DENT.	T AND FRON	\$	1,890.00	\$	3,960.0
2	MZ-BR-FRONT6	FENDER, REPAI	IR ALL AREAS AFFE	CTED BY THE ACCIL	NT, GRILLE TOP, BONNE DENT. NT, GRILLE TOP, BONNE		+	•	-	
1.0	MZ-BR-FRONT6 MZ-SP-SFRT06	TO RESPRAY FI	RONT BUMPER, FR	ONT REINFORCEME	JENI.	ET AND FRON	+	•	-	3,780.0
2	MZ-BR-FRONT6  MZ-SP-SFRT06  MZ-BR-PANEL1	TO RESPRAY FEEDDER.  TO REMOVE & I CONDUCT PRES	R ALL AREAS AFFE RONT BUMPER, FR INSTALL RADIATOR SSURE TEST & PER	ONT REINFORCEME  R, RADIATOR FAN AN RFORM LEAK TEST.	NT, GRILLE TOP, BONNI	ET AND FRON	\$	•	\$	3,780.0 660.0
2	MZ-BR-FRONT6  MZ-SP-SFRT06  MZ-BR-PANEL1  MZ-BR-TOP-UP	TO RESPRAY FIFENDER.  TO REMOVE & I CONDUCT PRES  TO REMOVE &	IR ALL AREAS AFFE	ONT REINFORCEME  R, RADIATOR FAN AN RFORM LEAK TEST.	NT, GRILLE TOP, BONNI D FRONT SUPPORT PAI AND TOP-UP GAS COO	ET AND FRON	\$	•	\$	3,780.0 660.0
3 4	MZ-BR-FRONT6  MZ-SP-SFRT06  MZ-BR-PANEL1  MZ-BR-TOP-UP  MZ-BR-WHEBAL	TO REMOVE & TO MOUNT SPO	IR ALL AREAS AFFE RONT BUMPER, FR INSTALL RADIATOR SSURE TEST & PER INSTALL CONDENS ORT RIM AND CONI	ONT REINFORCEME  R, RADIATOR FAN AN RFORM LEAK TEST.  SOR, AIR COND PIPE	NT, GRILLE TOP, BONNI D FRONT SUPPORT PAI AND TOP-UP GAS COOL	ET AND FRON	\$	•	\$	3,780.0 660.0
2 3 4 5	MZ-BR-FRONT6  MZ-SP-SFRT06  MZ-BR-PANEL1  MZ-BR-TOP-UP  MZ-BR-WHEBAL  MZ-BR-WHEALI	TO REMOVE & TO MOUNT SPO	IR ALL AREAS AFFE RONT BUMPER, FR INSTALL RADIATOR SSURE TEST & PER INSTALL CONDENS ORT RIM AND CONI	ONT REINFORCEME  R, RADIATOR FAN AN RFORM LEAK TEST.  SOR, AIR COND PIPE  DUCT WHEEL BALAN  Y & CONDUCT FULL 1	NT, GRILLE TOP, BONNI D FRONT SUPPORT PAI AND TOP-UP GAS COOL ICING. WHEEL ALIGNMENT.	ET AND FRON	\$	•	\$ \$	3,780.0 660.0 660.0
3 4 5	MZ-BR-FRONT6  MZ-SP-SFRT06  MZ-BR-PANEL1  MZ-BR-TOP-UP  MZ-BR-WHEBAL  MZ-BR-WHEBAL  MZ-BR-WHEALI	TO REMOVE & TO MOUNT SPO	IR ALL AREAS AFFE RONT BUMPER, FR INSTALL RADIATOR SSURE TEST & PER INSTALL CONDENS ORT RIM AND CONI	ONT REINFORCEME  R, RADIATOR FAN AN RFORM LEAK TEST.  SOR, AIR COND PIPE	NT, GRILLE TOP, BONNI D FRONT SUPPORT PAI AND TOP-UP GAS COOL ICING. WHEEL ALIGNMENT.	ET AND FRON	\$	1,890.00	\$ \$	3,780.0 660.0 660.0 120.0

GRAND TOTAL	\$ 10,060.15	\$	(27)
GST 7%	\$ 658.14	\$	
TOTAL AFTER EXCESS	\$ 9,402.01	_	
LESS EXCESS	\$ 500.00	\$	
TOTAL	\$ 9,902.01	\$	20,586.15
TOTAL PARTS	\$ 5,822.01	\$	10,146.15
TOTAL LABOUR	\$ 4,080.00	_	

REMARKS: SKT5892Z

7 REPAIR DAYS (exclude preparation of estimate, wait for survey/authorization/spare parts, Sat/Sun/PH)



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

# ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKT 5892Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DISTORTED	1,031.70	
1	RETAINER (RHS),FRONT BUMPER	BENT	18.70	18.70
	BRACKET (RHS), FRONT BUMPER	BENT	15.10	15.10
	COVER (LHS), FRONT BUMPER	NOT NECESSARY	28.00	
1	COVER (RHS), FRONT BUMPER	CRACKED	28.00	28.0
1	FRONT REINFORCEMENT	TO REPAIR SEE LABOUR	444.50	
1	COVER (RHS),FOGLAMP	CUT	46.40	46.4
1	CHROME (RHS), FOGLAMP	SCRATCHED	106.70	106.7
2	GROMMET, FRONT BUMPER	NECESSARY	5.40	5.4
	CLIP,FRONT BUMPER	NECESSARY	42.00	1
	FASTENER, FRONT BUMPER	BENT	5.60	1
	GRILLE TOP	TWISTED	335.00	
	RIVET, GRILLE TOP	NECESSARY	22.80	
4	RIVET, GRILLE TOP	NECESSARY	34.80	34.8
	BRACKET TOP, GRILLE	CRACKED	102.40	102.4
	CHROME (LHS), FRONT BUMPER	NOT NECESSARY	176.70	
	CHROME (RHS), FRONT BUMPER	CRACKED	176.70	176.7
	GRILLE,BLACK (GLOSS)	NOT NECESSARY	581.60	P
	MASCOT,FRONT	NOT NECESSARY	44.20	2 P
	BRACKET (LHS),GRILLE	NECESSARY	15.10	
	BRACKET (RHS),GRILLE	NECESSARY	15.10	1000000
	PIN LOCATOR, GRILLE	NECESSARY	5.40	300
	2 GROMMET,GRILLE	NECESSARY	5.40	
	2 RIVER,GRILLE	NECESSARY	15.2	15.3
	8 FASTENER, GRILLE	NECESSARY	24.0	0 24.
	1 PLATE, SET (REINFORCEMENT)	NOT NECESSARY	92.7	0
	4 FASTENER,PLATE SET	NOT NECESSARY	12.0	0
	1 SUPPORT PANEL	NOT NECESSARY	469.7	
	1 BONNET	DENTED / BUCKLED	1,067.3	
	1 HINGE (LHS),BONNET	TO REPAIR SEE LABOUR	41.0	
	1 HINGE (RHS),BONNET	TO REPAIR SEE LABOUR	41.0	0

Report Ref No. CS/ICS18003415/Uqd3n2



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WEATHERSTRIP,BONNET	NECESSARY	63.60	63.60
20	RHS FRONT FENDER	BENT	333.90	333.90
	STAY (RHS), FRONT FENDER	BENT	39.90	39.90
	RHS FRONT MUDGUARD	TORN	97.00	97.00
	FASTENER, MUDGUARD	NECESSARY	28.00	28.00
	COVER (RHS), HEADLAMP WASHER	MISSING	85.10	85.10
	ACTUATOR (RHS), HEADLAMP WASHER	CRACKED	242.40	242.40
	CLAMP.ACTUATOR	NECESSARY	16.40	16.40
	TANK,WASHER	DEFORMED	104.00	104.00
	HEADLAMP RHS	BROKEN	2,245.00	2,245.00
	CLIP,HEADLAMP	NECESSARY	7.60	7.60
	RIVET,HEADLAMP	NECESSARY	3.30	3.30
	H I D CONTROL UNIT (HEADLAMP)	NOT NECESSARY	895.50	-
	LAMP (RHS), FRONT TURN	NOT NECESSARY	157.30	-
	RHS FOGLAMP	NOT NECESSARY	351.40	-
	BRACKET (RHS),FOGLAMP	NOT NECESSARY	17.30	-
	WHEEL DISC (RHS)	NOT NECESSARY	1,101.70	
	TYRE (RHF)	NOT NECESSARY	350.00	-
	SOCKET (RHS),TURN LAMP (ADDITIONAL)	CRACKED	39.00	39.00
	BULB (RHS), TURN LAMP (ADDITIONAL)	DAMAGED	7.60	7.60
	CORD, SHORT TURN LAMP (ADDITIONAL)	DAMAGED	37.30	37.30
	LESS 10% DISCOUNT		-1,127.3	-646.89
	LESS 10% BIGGOOM		10,146.1	5,822.01
	SPECIAL NETT ITEMS			
180	SUNDRIES (SN)	NECESSARY	100.0	
			100.0	0 30.00
	LABOUR			0 1,890.00
	TO REPLACE FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP, BONNET AND FRONT FENDER. REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT REINFORCEMENT, HINGE (LHS), BONNET AND HINGE (RHS), BONNET.		3,960.0	
	TO RESPRAY FRONT BUMPER, FRONT REINFORCEMENT, GRILLE TOP, BONNET AND FRONT FENDER.		3,780.0	1,890.0



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & INSTALL RADIATOR, RADIATOR FAN AND FRONT SUPPORT PANEL. TO CONDUCT PRESSURE TEST & PERFORM LEAK TEST.	NOT NECESSARY	660.00	-
	TO REMOVE & INSTALL CONDENSOR, AIR COND PIPE AND TOP-UP GAS COOLING SYSTEM.	NOT NECESSARY	660.00	_
	TO MOUNT SPORT RIM AND CONDUCT WHEEL BALANCING.	NOT NECESSARY	120.00	7.5
	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	NOT NECESSARY	560.00	
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	150.00
			10,340.00	4,050.00
	GRAND TOTAL		20,586.15	9,902.01
	RECOMMENDED COST OF REPAIRS			9,902.01

RECOMMENDED COST OF REPAIRS 9,902.01
LESS EXCESS -500.00
NETT LIABILITY 9,402.01

Report Ref No. CS/ICS18003415/Uqd3n2

CHUA KANG SENG

Licensed Appraiser



51. Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation	Internationale Des	Experts En A	Automobile
--------------------------	--------------------	--------------	------------

ECICS LTD

Ref: CS/ICS18003415/Uqd3n2

TEMASEK BOULEVARD #10-01 SUNTEC TOWER ONE BINGAPORE 038987		Date: 02-04-2018				
SINGAL SILE SEESE.		Code: ICS				
	Policy Partic	culars :- OWN DAMAGE				
Insured Veh.		Veh. Inspected	SKT 5892Z			
Policy No.	MPC17A00258301	Coverage (\$)	0.00			
Claim No.	DMPC1800060H	Excess (\$)	500.00			
Assign From	CLAIMS	Assign Date	21/02/2018			
2.	Vehicle Pa	articulars & Condition	<b>计是数据等数据</b> 等			
Make & Model	MAZDA 3 (A)	c.c	1496			
Engine No.	HIDDEN	Year of Reg.	2015			
Chassis No.	JM6BM42A8G0310676	Colour	RED			
Odometer	84021	Steering	IN ORDER			
Brakes	IN ORDER	Modification	SPORTS RIM			
General	GOOD					
3.	Cor	ditions of Tyres				
	Size	Make	Balance			
R/H Front Tyre	205/60 R16	PIRELLI	6 mm			
L/H Front Tyre	205/60 R16	PIRELLI	6 mm			
R/H Rear Tyre	205/60 R16	PIRELLI	6 mm			
L/H Rear Tyre	205/60 R16	PIRELLI	6 mm			
4.	A SHEWAY TO SHEW AS A SHEWAY TO SHEW	ription of Damages				
THE VEHICLE S	USTAINED DAMAGES AT THE	FRONT O/S PORTION.				
DAMAGES SEE	DETAILS.					
5.		neral Information				
Accident Date	16/02/2018	Inspection Date	22/02/2018			
Survey held at	TRANS EUROKARS PTE L	.TD				
	NO 5 UBI CLOSE SINGAPORE 408605					
5a.		Remarks				
A)THE MARKET B)IN ACCORDA	A)THE MARKET VALUE IS \$\$71,000.00 (EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.					
5b.		nate Days of Repair				
ESTIMATED NO	RMAL PERIOD FOR REPAIR:	7 Working Da	ays			