

1999.00

INS. CASE OWNER:

Jane

CC6 / LCR18003421 / APS

PLKK:
IDAC:

Surveyor:

ADRIAN

DOI:

2/02/18

Date / Time:

2/02/18

Registered in Merimen:

22/02/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SLH 79406

Claim No. : 158722362559

Name of Insured : LCR

Policy No. : 0000000174

Insured Tel No. : HP:

Make / Model : HONDA

Excess Sec II :SS D.O.A : 16/02/18

Place of Accident : JP Ubi Ave 1

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age : Cheung Khuan Yang
Driver Tel No. : (V/L: YES / NO)

OI GIA REPORT YES / NO : YES / NO

Insured Liability : % Final ? Yes / No

SBL 86R



INSRS:
WSP: Hua Meng
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:



INSRS:
WSP:
Tel :
Liability :
RMKS:

Date/ Time	STAGE	DATE / PIC
01/03/18 (HR)	Non-Reporting Itr (1st): Non-Reporting Itr (2nd): Non-Reporting Itr (Final): Notification Itr (if non-pickup): Call OI: After call Itr to OI:	
2/3/18	Email to ALG - REQUEST OI GIA No OI GIA	
2/3/18	Sent NR Itr to OI	
7/3/18	OI GIA ✓	
5/1/18	to close	
	Documentation Check List: Handler Typist	
	Notification Itr (if non-pickup)	
	After call Itr to OI:	✓
	Authorisation To Act:	✓
	Release Voucher:	✓
	Final Repair Bill:	✓
	Car Rental Invoice:	✓
	Towing Invoice	
	LTA / GIA :	✓
	Medical Bill:	
	PIR:	
	Mandate/Reject Instruction:	
	LOD	✓
	Payment Breakdowns Form:	
	Post-Repair Photos:	
	Others:	

RECEIVED 08 JUN 2018

PRELIMINARY ADVICE	Date/Time: 19/5/2018	Sent By:	
FINALIZATION	Date/Time:	Confirm with:	
Repair Cost:	SS 3,500.00	(5 days) Reduction: 69 %	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT	Date/Time: 4/6/2018	Confirm with: June	Email <input checked="" type="checkbox"/> Call <input type="checkbox"/>
Final Liability:	% 100 (Agreed / Assessed) BOLA S/N No. : 4(a).		If NO or B 28, Ass. Lia :
Repair Cost:	SS 3,500.00		
Loss of Rental (LOR):	SS 200.00 (2 days) x #100		
Loss of Use (LOU):	SS - (S x days)		
Loss of Income (LOI):	SS - (S x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/> LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>		[Tick only one]	
GIA/LTA Search:	SS 7.45		
Medical:	SS -		
Disbursement:	SS - (e.g. Tow/ Independent)		
Legal Cost:	SS -		
Total:	SS 3,707.45	Global Sum SS:	
FINAL PAYMENT	Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>
Payee 1:	SS 3,707.45	Name 1: Hua Meng Spray Painting Workshop	
Payee 2: (Strike if N.A.)	SS	Name 2:	
Payee 3: (Strike if N.A.)	SS	Name 3:	

COPIED 6/6/18

ckh 5/6/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/LCR18003421/Aps3	
78 SHENTON WAY #08-16 CHARTIS BUILDINGS SINGAPORE 079120		Date : 22-02-2018	
		Code : LCR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLH 7940G	Veh. Inspected	SBL 86R
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	22/02/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	16/02/2018	Inspection Date	21/02/2018
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

NZE1416052531

ONG GUAY HUA JESSY
19 EASTWOOD TERRACE
S 486489

TPPCR.
Xiao Tong

Date : 15.03.2018
Vehicle no : SBL 86 R
Make/Model : TOYOTA AXIO
Accident date : 16.02.2018

No	Description	Qty	Amount (\$)
List Items			
1	Rear bumper <i>Defined</i>	1	\$ 454.6 ✓
2	Rear bumper side hodler @ \$89.90 <i>HT new</i>	2	\$ 179.8 <i>89.90</i>
3	Rear bumper clips (1sets) <i>new</i>	1	\$ 50 <i>30</i>
4	Rear LH lamp <i>cracked</i>	1	\$ 413 <i>353.60</i>
5	Rear LH fender <i>dent</i>	1	\$ 880.1 ✓
6	Rear LH fender inner shield <i>defined</i>	1	\$ 57.7 ✓
7	Rear LH door <i>Repair</i>	1	\$ 832.3 <i>x</i>
8	Rear windscreen rubber <i>new</i>	1	\$ 91.7 ✓
9	Rear LH shock absorber <i>new</i>	1	\$ 176.2 ✓
10	Rear LH knuckle arm <i>new</i>	1	\$ 588 <i>x</i>
11	Rear LH knuckle arm bearing <i>new</i>	1	\$ 661.9 ✓
12	Rear axle <i>new</i>	1	\$ 2417.9 <i>x</i>
13	Rear LH fender lower air vent <i>cracked</i>	1	\$ 42 ✓
14	Rear LH lamp lower garnish <i>new</i>	1	\$ 94.4 <i>x</i>
15	Rear end panel <i>new</i>	1	\$ 499.7 <i>x</i>
			\$ 7439.3
		Less 25% Disc	\$ 1859.83
		Total	\$ 5579.47
Special Nett Items			
1	Rear bumper reverse sensor <i>new</i>	1	\$ 380 <i>x</i>
2	Rear number plate wheel Rim <i>cut</i>	1	\$ 800 <i>500</i>
3	Rear number plate holder Type <i>new</i>	1	\$ 380 <i>x</i>
		Total	\$ 1560

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

ONG GUAY HUA JESSY
19 EASTWOOD TERRACE
S 486489

Date : 15.03.2018
Vehicle no : SBL 86 R
Make/Model : TOYOTA AXIO
Accident date : 16.02.2018

No	Description	Qty	Amount (S\$)
Labour Cost			
1	To supply rear windscreen sealant		\$ 50
2	Remove & reinstall rear windscreen		\$ 150 ¹²⁰
3	Remove & reinstall roof lining & cushion		\$ 200 ⁵⁰
4	Remove & reinstall petrol tank		\$ 150 ⁸⁰
5	Remove & reinstall rear suspension	1880.	\$ 300 ¹⁰⁰
6	Remove, replace & repair consistent to the accident		\$ 1800 ⁷⁰⁰
7	Respray painting		\$ 1300 ⁷⁰⁰
8	Tuff kote		\$ 150 ⁴⁰
9	Remove & reinstall reverse sensor		\$ 150 ⁴⁰
	Total		\$ 4250
	Grand Total		\$ 11389.47

total 4376.12

L/S: 35K

05 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

35K

Poh Kin (LKKAuto)

From: Hua Meng <huameng@live.com.sg>
Sent: Friday, 1 June 2018 7:05 PM
To: Poh Kin (LKKAuto)
Subject: AIG INSURED:SLH 7940 G OUR REF:SBL 86 R D.O.A:16.02.2018
Attachments: img-601190053.pdf
Categories: clear

Hi PohKin

We refer above mentioned accident.

We would like to inform that we have finalized with your surveyor.

Kindly revert your offer.

Your prompt reply will be appreciated by us.

We enclose relevant documents for your attention.

Thanks & regards,

June

Hua Meng Spray Painting Workshop

1 Kaki Bukit Ave 6, Blk C

#01-61 Autobay @ Kaki Bukit

S 417883

Tel: 6746 5519

Fax: 6743 4896



華 明 噴 漆 廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883
 Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680
 Reg. No.: 254678/00M



Your Ref :

Our Ref :

Date: 24-05-2018

Attn: Motor Claims Dept

**ACCIDENT ON 16.02.2018 INVOLVING VEHICLE SBL 86 R & SLH 7940 G ALONG
 CARPARK OF UBI AVE 1**

With regards to the above, we are writing on behalf of the registered owner of vehicle SBL 86 R which was involved in the above mentioned accident.

We are informed that the above accident was caused solely by the negligence of your insured vehicle GBB 5124 JSLH 7940 G. As a result of the accident, our client's vehicle was damaged and our client had instructed us to submit his claims for loss and expenses, particulars of which are follows:

1) Repair Cost	\$	3,500.00
2) Loss of rental-\$120 X 02days	\$	240.00
3) LTA serach	\$	7.45
Total	\$	3,747.45

We hereby enclosed herewith the following documents for your consideration of the above claim.

- a) Final Repair Bill Of SBL 86 R
- b) GIA report 明噴漆廠
- c) LTA SEARCH
- d) Owner / Driver NRIC & Driving License

HUA MENG SPRAY PAINTING WORKSHOP
 AUTOBAY@KAKI BUKIT
 1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61 SINGAPORE 417883
 TEL: 6747 8064, 6746 5519 FAX: 6743 4896

Yours faithfully,
HUA MENG SPRAY PAINTING WORKSHOP

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
 MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1996
 ROAD TRANSPORT ACT, 1987 (MALAYSIA)
 MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)
 OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

Form X1

CERTIFICATE NUMBER : MP302856

Type of Coverage	: Comprehensive	Own Damage Excess	: SGD500.00
Sum Insured	: Market Value	Windscreen Excess	: SGD100.00

- | | |
|--|-------------------------|
| 1. Index Mark and Registration Number of Vehicle | SBL86R |
| Chassis Number of Vehicle | NZE1416052531 |
| 2. Name of Policyholder | ONG, GUAY HUA JESSY |
| 3. Effective date of the Commencement of Insurance for the purposes of the Act | 12 Dec 2017 |
| 4. Date of Expiry of Insurance | 11 Dec 2018 |
| 5. Persons or Classes of Persons entitled to drive* | |
| 01. LIN, WEI YANG BENJAMIN | 02. ONG, GUAY HUA JESSY |
| 03. LIM, TAI NGEE | 04. N/A |
| 05. N/A | 06. N/A |

(b) Any other person who is driving on the Policyholder's order or with his/her permission.

*Provided that the person driving is permitted in accordance with the licensing or other laws or laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use*

Use only for social domestic and pleasure purposes and for the Policyholder's business or profession. The Policy does not cover use for hire or reward, racing, pace-making, reliability trial, speed testing, the carriage of goods (other than samples) in connection with any trade or business or use for any purpose in connection with the Motor Trade.

*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

Please note that the Own Damage Excess will be halved if claims related repairs are done at HL Assurance Approved Workshops listed in the attached.

This Certificate is not transferable to a new owner of the Motor Vehicle. If for any reason the Policy is terminated during its currency, the Certificate must be returned to HL Assurance Pte. Ltd. Within 7 days of the termination or if the Certificate has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189).

Hire Purchase Company : N/A

I/WE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or any Amendment, Act or Acts passed in substitution thereof.

HL ASSURANCE PTE. LTD.



Authorized Signature

Issue on: 08 Nov 2017

Poh Kin (LKKAUTO)

From: Poh Kin (LKKAUTO)
Sent: Monday, 4 June 2018 9:51 AM
To: 'Hua Meng'
Cc: Hsiao Tong (LKKAUTO); Vic (LKKAUTO)
Subject: OFFER/ OUR REF: CC6/LCR18003421/Apb3 YOUR REF:SBL 86 R D.O.A:16.02.2018
Importance: High

WITHOUT PREJUDICE

Our Ref: CC6/LCR18003421/Apb3
Your Ref: SBL 86R

Dear June,

ROAD TRAFFIC ACCIDENT INVOLVING SLH 7940G AND SBL 86R ON 16.02.2018

We refer to the above matter and your letter of demand dated 24th May 2018.

On a without prejudice basis and purely for an amicable settlement and without admission of liability to our Insured's part, we offer settlement as below:

1. Cost of Repair	S\$ 3,500.00
2. Loss of Rental (\$100.00 x 2days)	S\$ 200.00
3. GIA search fee	S\$ 7.45
	<u>S\$ 3,707.45</u>

Kindly confirm acceptance.

Kindly let us have your reply as soon as possible.

Your prompt reply will be very much appreciate.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Wednesday, 7 March 2018 5:02 PM
To: 'Eileen, May Hwee Yap'
Subject: ACCIDENT INVOLVING SLH 7940G(AIG) & SBL 86R ON 16/02/2018

Your Ref: **SLH 7940G**
Our Ref: CC6/LCR18003421/Aps3

Dear Sirs/Madam,

ACCIDENT INVOLVING SLH 7940G(AIG) & SBL 86R ON 16/02/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from SBL 86R against your insurance policy.

Based on the accident report and accident scenario, liability is down against us.
We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewhit@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

AUTHORISATION TO ACT

I/We, ONG Guay Hua Jessy ("the third party claimant") of
19 Eastwood Terrace. S(486489) (address),
owner of SBL86R (vehicle no.) hereby authorise **HUA MENG SPRAY PAINTING**
WORKSHOP ("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SBL86R that was damaged pursuant
to the accident which occurred on 16-02-2018 (date) along carpark of 401 Ave 1
(location) involving vehicle no/s SLH7940G ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem
fit and the workshop is further authorized to receive payment further to settlement of my claim
with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 16 (day) of Feb (month) 2018 (year)

+ Jessy

Signed by "the third party claimant"
(with company stamp if applicable)

明噴漆廠
HUA MENG SPRAY PAINTING WORKSHOP
AUTOBAY@KAKI BUKIT
401-AVE 5 #01-34 SINGAPORE 41788
TEL: 6746 5819 FAX: 6743 489

Signed by "the workshop"
(with company stamp)

RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, **Hua Meng Spray Painting Workshop** ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd **LKK AUTO CONSULTANTS PTE LTD** (name of surveyor) with respect to the amount claimed for **S\$3,500.00** (Repair Cost), **S\$200.00** (Loss of Use/Rental), **S\$7.45** (Disbursement) for vehicle no. **SBL 86R** that was damaged pursuant to the accident which occurred on **16/02/2018** (date) along **Carpark of Ubi Avenue 1** (location) involving vehicle no/s **SLH 7940G**. This is pursuant to the inspection conducted on **21/02/2018** (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner **Ong Guay Hua Jessy** ("the third party claimant") of vehicle no. **SBL 86R** make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to **SBL 86R** (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 04 (day) of June (month) 2018 (year)



LWP

Signed by appointed surveyor

明噴漆廠
HUA MENG SPRAY PAINTING WORKSHOP
AUTOBAY@KAKI BUKIT
1100 JALAN AVE 5 #01-34 SINGAPORE 417883
TEL: 6743 1895

Signed by "the workshop" (with the)

WITHOUT PREJUDICE
TO OUR CLIENT'S PERSONAL INJURY
CLAIM (PRESENT OR FUTURE) WHICH IS
EXPRESSLY RESERVED



華明噴漆廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883
Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680
Reg. No.: 254678/00M



Your Ref : SH 79406

Our Ref : SBL 86 R

Date: 18/5/2018

VEHICLE NO :SBL 86 R
MAKE / MODEL :TOYOTA AXIO
NAME :ONG GUAY HUA JESSY
ADDRESS :19 EASTWOOD TERRACE
S 486489

FINAL REPAIR BILL FOR VEHICLE NO:SBL 86 R

TO SUPPLY AND REPLACE PARTS, LABOUR CHARGES FOR
REPAIRING, KNOCKING, WELDING AND TO RESPRAY PAINTING
(LUMP SUM REPAIR)

\$ 3,500.00

SINGAPORE DOLLARS:THREE THOUSAND FIVE HUNDRED ONLY



INVOICE

KS LEASING
 BLK 806 WOODLANDS RING ROAD
 #11-267 S'PORE 730606
 ROB: 53367173J
 Singapore
 9387 4964

BILL TO
ONG GUAY HUA JESSY

Invoice Number: 97820201
Invoice Date: February 28, 2018
Payment Due: February 28, 2018

Amount Due (SGD): \$0.00

Rental	Days	Rate	Amount
CAR DAILY RENTAL	2	\$120.00	\$240.00

Total: \$240.00

Payment on March 9, 2018 using cash: \$240.00

Amount Due (SGD) : \$0.00



S/NO: _____

DATE: _____

RENTAL AGREEMENT

HIRER'S PARTICULARS

Name: ONG Guay Hua Jessy

Address: _____

NRIC/Passport No: _____ Country: _____

Occupation: _____

Date of Birth: _____ Age: _____

Driving Licence No: _____ Date Passed: _____

Tel (Mobile): _____ (Residence): _____

DRIVER'S PARTICULARS

Name: Lin Weiyang Benjamin

Address: 19 Eastwood Terrace
S 1486489

NRIC/Passport No: S8140304 Country: SG

Occupation: _____

Date of Birth: _____ Age: _____

Driving Licence No: _____ Date Passed: _____

Tel (Mobile): _____ (Residence): _____

Make/Model: <u>Mit Lancer</u>	Vehicle No: <u>SJK9782R</u>
Date & Time Out: <u>21.02.2018 @ 11:30 hrs</u>	Date & Time In: <u>23/02/2018 @ 15:51</u>
<input type="checkbox"/> 0 <input type="checkbox"/> 1/4 <input type="checkbox"/> 1/2 <input type="checkbox"/> 3/4 <input type="checkbox"/> Full Mileage Out: _____	<input type="checkbox"/> 0 <input type="checkbox"/> 1/4 <input type="checkbox"/> 1/2 <input type="checkbox"/> 3/4 <input type="checkbox"/> Full Mileage In: _____
DAILY RENTAL CHARGES: \$ _____	DEPOSIT: \$ _____
TOTAL DAYS USAGES: _____	TOTAL RENTAL: \$ _____

Remarks: _____

Terms & Conditions:

- 1 No Insurance Coverage if the driver is below 24 years old or less than 2 years driving licence.
- 2 This vehicle is licenced to carry _____ passengers only.
- 3 Hirer is liable to pay first \$ _____ as excess all claims any accident plus loss of earning while damaged vehicle is under repair.
- 4 For usage to Malaysia subject to higher excess all claim of S\$5000/- and different rental rate.
- 5 Please notify our office should there be any accident involving this hired vehicle within 24 hrs.
- 6 No refund will be given for vehicle which returns early.
- 7 No refund will be given for petrol left in the vehicle.
- 8 Hirer is liable to pay all parking fines and traffic summones should there be any during renting period.
- 9 Vehicle to be return during office hour only.

Hirer's Signature _____

Driver Signature _____



KS Leasing _____

* I/We have read and understood the Terms & Conditions above and hereby agreed to abide.



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 21 Feb 2018 / 14:57:52

Receipt Date/Time : 21 Feb 2018 / 14:57:52

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180221-001322

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLH7940G As at 16 Feb 2018/13:35:00 Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLH7940G Enquiry Fee 20180221145636833027	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Result of Insurance Enquiry - SLN2873T As at 16 Feb 2018/21:15:00 Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
2	Insurance Enquiry - SLN2873T Enquiry Fee 20180221145636870552	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		14.00	0.98	14.98
Rounding Difference				0.03
Total Amount Payable				14.95
Paid By				
	20180221145712599	Direct Debit: eNETS Debit (Internet Banking)		14.95
Total				14.95
Cash Change				0.00
Tendered Amount				14.95
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt | OK | Save as PDF

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	22 Feb 2018 Edit Reg		21 Feb 2018 00:00 Edit Adj Rpt	S\$3,500.00 Edit Estimates	S\$3,500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF PTE LTD, Co. Reg. No.: 201624597K								
Main Claimant:	ONG GUAY HUA JESSY, ID: S1185786H								
Vehicle Reg. No.:	SBL86R	Date of Loss:	16/02/2018 00:00 - :59 [122 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 1587223625SG	Policy/Cover Note No.:	0999994967						
Vehicle Reg. No. (Insured):	SLH7940G	Policy No. (Claimant):	MP302856						
		Excess:							
Repairer:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Boyogan, Joane] Joane.Boyogan@aig.com								
Claimant's Insurer:	HL Assurance Pte Ltd (HQ) - Tel: 69226030								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 05/03/2018]								
ASSOCIATED MAIL RECEIVED				View All	Compose Case Mail				
<ul style="list-style-type: none"> AIG_SG (23/02/2018): Request To Upload TP GIA Report AIG_SG (23/02/2018): No OI GIA Report 									
ALL ASSOCIATED TASKS View All									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SBL86R (1587223625SG)
[SLH7940G]**

TP

ONG GUAY HUA JESSY

Feb 16 2018 12:00AM

[LCRF PTE LTD]

Hua Meng Spray Painting Workshop

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View <input type="button" value="View in Browser"/>			
Letters/Correspondences															1 per page			<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print					
1	(Draft)	Third Party Express Settlement – Payment Breakdown											Edit					
Photos/Images															3 per page			<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)										Thumbnail	Print					
1	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
2	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
3	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
4	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
5	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
6	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
7	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
8	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
9	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
10	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
11	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
12	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
13	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
14	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
15	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
16	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
17	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
18	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
19	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
20	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
21	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
22	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
23	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
24	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
25	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
26	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
27	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
28	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
29	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
30	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
31	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
32	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
33	10/05/18 19:02	General View											Load JPG	<input checked="" type="checkbox"/>				
34	10/05/18 19:02	Reinspection Photo											Load JPG					

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
35	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
55	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
56	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
57	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
58	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
59	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
60	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
61	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
62	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
63	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
64	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
65	10/05/18 19:02	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/03/18 14:10	TP GIA REPORT	Load PDF	
2	19/05/18 12:43	TP ESTIMATE.	Load PDF	
3	07/06/18 08:52	WORKSHOP INVOICE	Load PDF	
4	07/06/18 08:52	AUTHORISATION TO ACT FORM	Load PDF	
5	07/06/18 08:52	Release Voucher	Load PDF	
6	07/06/18 08:52	RENTAL RECEIPT	Load PDF	
7	07/06/18 08:52	LTA SEARCH	Load PDF	
8	07/06/18 08:52	LETTER TO OI	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	07/03/18 16:28	E-filed GIA Report	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SLH7940G (Insd veh)	Model:	TOYOTA COROLLA 1.5 X AXIO (A)
	SBL86R (TP veh)		
Date of Accident:	16/02/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	: \$	11,389.47	
Final Repair Cost	: \$	3,500.00	
Loss of Use	: \$		days at \$0.00 per day
Rental (if any)	: \$	200.00	2 days
LTA / GIA Search Fee	: \$	7.45	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	3,707.45	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Hua Meng Spray Painting Workshop	: \$	3,707.45
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

07 Jun
2018

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18003421/APB3Q2

Date: 07/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994967
 Claimant Vehicle No : SBL86R Insured Vehicle No : SLH7940G
 Date of Loss: 16/02/2018 Nature of Claim: TP Claim No: 1587223625SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SBL86R**
 Make & Model: TOYOTA COROLLA, 1.5 X AXIO (A) Engine No: 1Nzc759342
 Reg. Date: 12/12/2007 (Man. Year: 2007) Chassis No: NZE1416052531
 Colour: Silver Odometer: 124169 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/50 R16 Rear Tyre Size: 205/50 R16
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,139.47	2,496.12	4,643.35	65.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,250.00	1,880.00	2,370.00	55.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	11,389.47	4,376.12	7,013.35	61.58
Approved Total (Overridden) (S\$)		3,500.00		
Nett Amount (S\$)	11,389.47	3,500.00	7,889.47	69.27
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,707.45		

INSPECTION

Date of Assignment: 21/02/2018
 Date Inspected: 21/02/2018 Inspected At: Hua Meng Spray Painting Workshop (HQ)
 No 1 Kaki Bukit Avenue 6, #01-61
 Autobay@Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	454.60 FL	*454.60 FL
2	1		*REAR BUMPER SIDE HOLDER	N/S Necessary	179.80 FL	*89.90 FL
3	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
4	1		*REAR LH LAMP	Cracked	413.00 FL	*353.60 FL
5	1		*REAR LH FENDER	Dented	880.10 FL	*880.10 FL
6	1		*REAR LH FENDER INNER SHIELD	Deformed	57.70 FL	*57.70 FL
7	1		*REAR LH DOOR	Repair	832.30 FL	*- FL
8	1		*REAR WINDSCREEN RUBBER	Necessary	91.70 FL	*91.70 FL
9	1		*REAR LH SHOCK ABSORBER	Not Necessary	176.20 FL	*- FL
10	1		*REAR LH KNUCKLE ARM	Not Necessary	588.00 FL	*- FL
11	1		*REAR LH KNUCKLE ARM BEARING	Damaged	661.90 FL	*661.90 FL
12	1		*REAR AXLE	Not Necessary	2,417.90 FL	*- FL
13	1		*REAR LH FENDER LOWER AIR VENT	Cracked	42.00 FL	*42.00 FL
14	1		*REAR LH LAMP LOWER GARNISH	Not Necessary	94.40 FL	*- FL
15	1		*REAR END PANEL	Not Necessary	499.70 FL	*- FL
16	1		*REAR BUMPER REVERSE SENSOR	Not Necessary	380.00 FS	*- FS
17	1		*REAR WHEEL RIM	Cut	800.00 FS	*500.00 FS
18	1		*REAR TYRE	Not Necessary	380.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,999.30	3,161.50
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,859.83	665.38
Total Parts (\$\$)	7,139.47	2,496.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SUPPLY REAR WINDSCREEN SEALANT	New	50.00	50.00
2	REMOVE & REINSTALL REAR WINDSCREEN	New	150.00	120.00
3	REMOVE & REINSTALL ROOF LINING & CUSHION	New	200.00	50.00
4	REMOVE & REINSTALL PETROL TANK	New	150.00	80.00
5	REMOVE & REINSTALL REAR SUSPENSION	New	300.00	100.00
6	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,800.00	700.00
7	RESPRAY PAINTING	New	1,300.00	700.00
8	TUFF KOTE	New	150.00	40.00
9	REMOVE & REINSTALL REVERSE SENSOR	New	150.00	40.00
Gross Labour Cost (\$\$)			4,250.00	1,880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >