

# HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

## ESTIMATE

NZE1416052531

ONG GUAY HUA JESSY  
19 EASTWOOD TERRACE  
S 486489

TPPCR  
Xiao Tong

Date : 15.03.2018  
Vehicle no : SBL 86 R  
Make/Model : TOYOTA AXIO  
Accident date : 16.02.2018

No	Description	Qty	Amount (\$)
<b>List Items</b>			
1	Rear bumper <i>Deformed</i>	1	\$ 454.6 ✓
2	Rear bumper side hodler @ \$89.90 <i>LH New</i>	2	\$ <del>179.8</del> 89.90
3	Rear bumper clips (1sets) <i>New</i>	1	\$ 50.30
4	Rear LH lamp <i>Cracked</i>	1	\$ <del>413</del> 353.60
5	Rear LH fender <i>Dented</i>	1	\$ 880.1 ✓
6	Rear LH fender inner shield <i>Deformed</i>	1	\$ 57.7 ✓
7	Rear LH door <i>Repair</i>	1	\$ 832.3 X
8	Rear windscreen rubber <i>New</i>	1	\$ 91.7 ✓
9	Rear LH shock absorber <i>New</i>	1	\$ 176.2 +
10	Rear LH knuckle arm <i>New</i>	1	\$ 588 X
11	Rear LH knuckle arm bearing <i>Dented</i>	1	\$ 661.9 ✓
12	Rear axle <i>New</i>	1	\$ 2417.9 X
13	Rear LH fender lower air vent <i>Cracked</i>	1	\$ 42 ✓
14	Rear LH lamp lower garnish <i>New</i>	1	\$ 94.4 X
15	Rear end panel <i>New</i>	1	\$ 499.7 X
			\$ 7439.3
		Less 25% Disc	\$ 1859.83
		Total	\$ 5579.47
<b>Special Nett Items</b>			
1	Rear bumper reverse sensor <i>New</i>	1	\$ 380 X
2	Rear number plate wheel Rim <i>cut</i>	1	\$ <del>800</del> 500
3	Rear number plate holder <i>Tyre New</i>	1	\$ 380 X
		Total	\$ 1560

# HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

## ESTIMATE

ONG GUAY HUA JESSY  
19 EASTWOOD TERRACE  
S 486489

Date : 15.03.2018  
Vehicle no : SBL 86 R  
Make/Model : TOYOTA AXIO  
Accident date : 16.02.2018

No	Description	Qty	Amount (S\$)
<b>Labour Cost</b>			
1	To supply rear windscreen sealant		\$ 50 -
2	Remove & reinstall rear windscreen		\$ 150 120
3	Remove & reinstall roof lining & cushion		\$ 200 50
4	Remove & reinstall petrol tank		\$ 150 80
5	Remove & reinstall rear suspension	1880.	\$ 300 100
6	Remove, replace & repair consistent to the accident		\$ 1800 700
7	Respray painting		\$ 1300 700
8	Tuff kote		\$ 150 40.
9	Remove & reinstall reverse sensor		\$ 150 40.
	<b>Total</b>		<b>\$ 4250</b>
	<b>Grand Total</b>		<b>\$ 11389.47</b>

total 4376.12

4/5: 3.5K

05 Days

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

3.5K