


SMRT Accident Vehicle Repair Estimates

China Taiping

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB133U
 Ref. No : TAX/02/18/2117
 Reg. Date : 25/10/2013
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : HAROON S/O MOHAMED RASHEED
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 15/02/2018 09:50:00 PM
 Accident Reported Date / Time : 20/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094673
 Special Instruction to ARC, if any :
 SLN3952S - CHINA TAIPING - LKK
 Prepared Date : 21/02/2018 10:36:53 AM



Sebastian
21/2/18
 - Lump Sum Repair.
 - Question Mark Item
 Photo
 - Photo After Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U40-5692918

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 338.00	0.00
Total Spray Painting Charges	: 558.00	0.00
Total Material Charges	: 573.30	573.30
Other Charges	: 240.00	0.00
TOTAL	: 1,709.30	0.00
Lum Sum Total	: 1,700.00	0.00
No. of Repair Days	: 3.00	0.00
Prepared / Adjusted By	:	<i>2 days</i>
Arc / Surveyor Sign Off Date	: 21/02/2018 01:45:44 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 21/02/2018 01:45:44 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Section B - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	338.00	0.00 200
Total Labour	338.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0.00 100
Total Spray Painting & Panel Beating	558.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	240.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace	No <i>R</i>
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace	No <i>✓ cut</i>
52114-47140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace	No <i>?</i>
			NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace	No <i>✓ ms</i>
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace	No <i>✓ ms</i>
TOTAL MATERIALS								704.63	704.62	
TOTAL MATERIALS(Discounted)								573.30	573.30	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									