

SMRT Accident Vehicle Repair Estimates

AK

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5373K
 Ref. No : TAX/02/18/2116
 Reg. Date : 30/11/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : LIM CHEE YIN
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 20/02/2018 03:36:00 AM
 Accident Reported Date / Time : 20/02/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024094669
 Special Instruction to ARC, if any :
 SLL1570J
 Prepared Date : 20/02/2018 04:22:59 PM



Sebastian.
 21/2/18.

- Part by part repair.
 - Question Mark Item
 Photo
 - Photo Before Paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU103575513

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 338.00	0.00
Total Spray Painting Charges	: 558.00	0.00
Total Material Charges	: 1,309.34	1,309.34
Other Charges	: 280.00	0.00
TOTAL	: 2,485.34	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 4.00	0.00
Prepared / Adjusted By	:	2 days
Arc / Surveyor Sign Off Date	: 20/02/2018 07:38:00 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 20/02/2018 07:38:00 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	338.00	0.00 200
Total Labour	338.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00 ?	0.00
Total Spray Painting & Panel Beating	558.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	280.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52159479 13			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace ✓ <i>CRK</i>	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ?	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace ✓ <i>NEC</i>	No
52462470 30			PAD, RR BUMPER, RH & LH , 1	2	3.80	25.00	5.70	Replace	Replace ?	No
52462470 20			PAD, RR BUMPER, RH & LH , 2	2	3.80	25.00	5.70	Replace	Replace ?	No
52462470 10			PAD, RR BUMPER, RH & LH , 3	2	3.80	25.00	5.70	Replace	Replace ?	No
52191470 30			SEAL, RR BUMPER ARM, RH & LH	2	11.00	25.00	16.50	Replace	Replace ?	No
52023470 30			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace ?	No
52453470 10			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.72	Replace	Replace <i>R</i>	No
TOTAL MATERIALS								1,309.35	1,309.34	
TOTAL MATERIALS(Discounted)								1,309.34	1,309.34	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									