

INS. CASE OWNER:

Norsiah

CCG/LCR18003426 / AWS3

LKK
IDAC

Surveyor:

ADRIAN

DOI:

21/02/18

Date / Time:

21/02/18

Registered in Merimen:

22/02/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLN 2873T

Claim No.:

67598714654

Name of Insured:

LCR

Policy No.:

A111111111

Insured Tel No.:

HP:

Make / Model:

MTN 11111

Excess Sec II :SS

D.O.A.:

11/02/18

Place of Accident:

WRI TA BYYON EXIT PHE

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SCA 11662



INSRS:

WSP:

Tel:

Liability:

RMKS:

Hua mang



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

SCA 11662 - NA/AG/18003426/18 Det 11/02/18
 SLN 2873T - NA/AG/18003426/18 Det 11/02/18
 01/03/18 Curian * OLAR - SEND PERI EMAIL TO LCR.
 * no estimate.

5/3/18

Email non reporting letter.

20/3/18

email letter to OJ

RECEIVED - 5 MAR 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 39, Ass. in

Repair Cost:

SS

3200.00

Loss of Rental (LOR):

SS

200.00

(2 days)

1700.00

Loss of Use (LOU):

SS

(5

x

days)

Loss of Income (LOI):

SS

(5

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

7-45

Medical:

SS

Disbursement:

SS

(e.g. Tow/Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS

3407.45

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

3407.45

Name 1:

Hua Mang Spray Painting Workshop

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AIG ASIA PACIFIC INSURANCE PTE LTD

Ref : CC6/LCR18003426/Aws3

78 SHENTON WAY #08-16
CHARTIS BUILDINGS SINGAPORE 079120

Date : 22-02-2018



Code : LCR

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLN 2873T	Veh. Inspected	SCQ 1166Z
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	22/02/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	16/02/2018	Inspection Date	21/02/2018
Survey held at	HUA MENG SPRAY PAINTING WKSP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

MR053REH10455.6610

GAN KEONG

BLK 49 LOR 5 TOA PAYOH

#10-77

S 310049

TPACR

Vivian

Date

:23.02.2018

Vehicle no

:SCQ 1166 Z

Make/Model

:TOYOTA ALTIS

Accident date

:16.02.2018

No	Description	Qty	Amount (\$\$)
<u>List Items</u>			
1	Rear boot lid <i>Buckled</i>	1	\$ 666.4 ✓
2	Rear boot lid hinges @ \$71.70 <i>new</i>	2	\$ 143.4 ✓
3	Rear boot lid upper lock <i>new</i>	1	\$ 420.2 ✓
4	Rear boot lid lower lock <i>new</i>	1	\$ 32.7 ✓
5	Rear boot lid centre logo	1	\$ 57.4 ✓
6	Rear boot lid COROLLA emblem <i>new</i>	1	\$ 46.5 ✓
7	Rear boot lid ALTIS emblem	1	\$ 48.5 ✓
8	Rear boot lid reflector @ \$334.70 <i>new</i>	2	\$ 669.4 ✓
9	Rear boot lid weather strip <i>new</i>	1	\$ 183 ✓
10	Rear boot lid cable <i>new</i>	1	\$ 73 ✓
11	Rear bumper <i>Deformed</i>	1	\$ 530.2 ✓
12	Rear bumper side holder @ \$114.80 <i>new</i>	2	\$ 229.6 ✓
13	Rear bumper reinforcement <i>Deformed</i>	1	\$ 419.8 ✓ <i>395</i>
14	Rear bumper bracket @ \$47.00 <i>new</i>	2	\$ 94 ✓
15	Rear bumper clips (1set) <i>new</i>	1	\$ 50.30
16	Rear bumper lower reflector @ \$62.40 <i>RH cracked</i>	2	\$ 124.8 <i>62.40</i>
17	Rer RH lamp <i>cracked</i>	1	\$ 310.1 ✓
18	Rear end panel <i>Repair</i>	1	\$ 639.3 ✓
19	Rear exhaust pipe <i>Bent</i>	1	\$ 952.3 ✓
			\$ 5690.6
Less 25%			\$ 1138.12
Total			\$ 4552.48

Special Nett Items

1	Rear boot lid camera <i>new</i>	1	\$ 800 ✓
2	Rear bumper reverse sensor (1set) <i>new</i>	1	\$ 380 <i>200</i>
3	Rear camera <i>new</i>	1	\$ 800 ✓
Total			\$ 1980

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

GAN KEONG
BLK 49 LOR 5 TOA PAYOH
#10-77
S 310049

Date :23.02.2018
Vehicle no :SCQ 1166 Z
Make/Model :TOYOTA ALTIS
Accident date :16.02.2018

No	Description	Qty	Amount (\$\$)
----	-------------	-----	---------------

Labour Cost

- 1 To supply rear end panel inner sealant
- 2 Remove & reinstall reverse sensor
- 3 Remove & reinstall camera
- 4 Remove & reinstall boot lid inner garnish
- 5 Remove & reinstall exhaust pipe
- 6 Remove ,replace & repair consistent to the accident
- 7 Respray painting
- 8 Tuff kote

\$ 50 x
\$ 150 60
\$ 100 60
\$ 200 x
\$ 150 x 80
\$ 1200 500
\$ 1100 600
\$ 100 X
Total \$ 3050

Grand Total \$ 9582.48

total : 3996.3
A/S 3.2K
040mp

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary dem(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



華明噴漆廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883

Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680

Reg. No.: 254678/00M



Your Ref :

Our Ref :

Date: 25-05-2018

Attn: Motor Claims Dept

**ACCIDENT ON 16.02.2018 INVOLVING VEHICLE SCQ 1166 Z & SLN 2873 T ALONG
LOR 6 TOA PAYOH SLIP RD INTO PIE(CHANGI)**

With regards to the above, we are writing on behalf of the registered owner of vehicle SCQ 1166 Z which was involved in the above mentioned accident.

We are informed that the above accident was caused solely by the negligence of your insured vehicle SLN 2873 T. As a result of the accident, our client's vehicle was damaged and our client had instructed us to submit his claims for loss and expenses, particulars of which are follows:

1) Repair Cost	\$	3,200.00
2) Loss of rental-\$120 X 02days	\$	240.00
3) LTA serach	\$	7.45
Total	\$	3,447.45

We hereby enclosed herewith the following documents for your consideration of the above claim.

a) Final Repair Bill Of SCQ 1166 Z

c) LTA SEARCH

b) GIA report

d) Owner / Driver NRIC & Driving License

華明噴漆廠
HUA MENG SPRAY PAINTING WORKSHOP
AUTOBAY@KAKI BUKIT
1, Kaki Bukit Avenue 6 Blk C #01-34 SINGAPORE 417883
TEL: 6747 8064, 6746 5519 FAX: 6743 4896

Yours faithfully,

HUA MENG SPRAY PAINTING WORKSHOP

Vivian Lau (LKKAuto)

From: Vivian Lau (LKKAuto)
Sent: Tuesday, 20 March, 2018 3:14 PM
To: 'eyap@lioncityrentals.com.sg'
Cc: Hsiao Tong (LKKAuto); Joy Irene (LKKAuto)
Subject: ACCIDENT INVOLVING SLN 2873T & SCQ 1166Z ON 16/02/2018

Our Ref: CC6/LCR18003426/Aws3

20 March 2018

LION CITY RENTALS PTE LTD

Dear Sir/Madam,

ACCIDENT INVOLVING SLN 2873T & SCQ 1166Z ON 16/02/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please call us if you have further queries.

Thank you

Best Regards,

Vivian Lau | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-8625 | email: Vivianlau@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

AUTHORISATION TO ACT

I/We, Gan Keng ("the third party claimant") of
Blk 49 Lor 5 Toa Payoh #10-77, SL310049 (address),
owner of SLA1166Z (vehicle no.) hereby authorise **HUA MENG SPRAY PAINTING**
WORKSHOP ("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SLA1166Z that was damaged pursuant
to the accident which occurred on 16-02-2018 (date) along Lor 6 Toa Payoh
Slip Rd into Pte Limanji (location) involving vehicle no/s SLN2873T ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem
fit and the workshop is further authorized to receive payment further to settlement of my claim
with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 21 (day) of Feb (month) 2018 (year)



Signed by "the third party claimant"
(with company stamp if applicable)

明噴漆廠
HUA MENG SPRAY PAINTING WORKSHOP
AUTOBAY@KAKI BUKIT
#01-34 SINGAPORE 417883
TEL: 6746 5519 FAX: 6743 4896

Signed by "the workshop"
(with company stamp)

RELEASE VOUCHER
(AIG ASIA PACIFIC-EXPRESS THIRD PARTY CLAIM)

"We/I, Hua Meng Spray Painting Workshop (the workshop)" hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD ("name of surveyor") with respect to the amount claimed for S\$ 3,200.00 (repair cost), S\$ 200.00 (loss of ~~rental~~/use), S\$ 7.45 (disbursement), for vehicle no. SCQ 1166Z that was damaged pursuant to the accident which occurred on 16/02/2018 (date) along TOA PAYOH LOR 6 SLIP RD (location) involving vehicle no/s SLN 2873T.

This is pursuant to the inspection conducted on 21/02/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner GAN KEONG (the third party claimant") of vehicle no. SCQ 1166Z make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SCQ 1166Z (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 25 (day) of May (month) 2018 (year)

LWP



Signed by AIG appointed surveyor

明噴漆廠
HUA MENG SPRAY PAINTING WORKSHOP
AUTOBAY@KAKI BUKIT
#01-24 SINGAPORE 417883
TEL: 6746 5519 FAX: 6743 4896

Chopped & Signed by "the workshop"

WITHOUT PREJUDICE
TO OUR CLIENT'S PERSONAL INJURY
CLAIM (PRESENT OR FUTURE) WHICH IS
EXPRESSLY RESERVED



華 明 噴 漆 廠
HUA MENG SPRAY PAINTING WORKSHOP

AUTOBAY@KAKIBUKIT

1, Kaki Bukit Avenue 6 Blk C #01-34/#01-61, Singapore 417883
Tel: 6747 8064, 6746 5519 Fax: 6743 4896 H/P: 9666 9680
Reg. No.: 254678/00M



Your Ref : GLN 2873T

18/5/2018

Our Ref : SCQ 1166Z

Date:.....

VEHICLE NO :SCQ 1166 Z
MAKE / MODEL :TOYOTA ALTIS
NAME :GAN KEONG
ADDRESS :BLK 49 LOR 5 TOA PAYOH
#10-77
S 310049

FINAL REPAIR BILL FOR VEHICLE NO:SCQ 1166 Z

TO SUPPLY AND REPLACE PARTS, LABOUR CHARGES FOR
REPAIRING, KNOCKING, WELDING AND TO RESPRAY PAINTING
(LUMP SUM REPAIR)

\$ 3,200.00

SINGAPORE DOLLARS:THREE THOUSAND TWO HUNDRED ONLY



DAWN ENTERPRISES

21 SELETAR WEST FARMWAY 1

SINGAPORE 798125

TEL: 6383 2661 FAX: 6484 2836

REG. NO. 430058/000

No. 19117

Date, 23/2/18

OFFICIAL RECEIPT

Received from

Gan Keong

the sum of Dollars

Two hundred forty only

being Payment Of

S54 57205 (21/2/18 - 23/2/18)

DAWN ENTERPRISES

\$

240/-

Cash/Cheque No.



DAWN ENTERPRISES

21 Seletar West Farmway 1
Singapore 798125
Tel: 63832661 Fax: 64842836
Reg No.430058/00D

Nº 35159
SCQ 11662

RENTAL AGREEMENT

DATE 21 Feb 2018

HIRER'S PARTICULARS

Name Gan Keong
Address Blk 49 Lor 5 Toa Payoh
10-77, S(310049)
I/C or Passport No. S0028675C Country SG
Occupation _____
Date of Birth _____ Age _____
Driving Licence No. _____ Date Passed _____
Tel: (HP) _____ (Residence) 91479204

DRIVER'S PARTICULARS

Name _____
Address _____
I/C or Passport No. _____ Country _____
Occupation _____
Date of Birth _____ Age _____
Driving Licence No. _____ Date Passed _____
Tel: (Office) _____ (Residence) _____

IMPORTANT NOTES:

1. No insurance coverage if the driver is below 24yrs old or less than 2 years driving licence.
2. This vehicle is licenced to carry 04 passengers only.
3. Hirer is liable to pay first \$ 2000 as excess all claims any accident plus loss of earning while damaged vehicle is under repair.
4. For usage to Malaysia subject to higher excess all claims of S\$5,000.00 and different rental rate.
5. Please notify our office should there be any accident involving this hired vehicle within 24 hrs.
6. No refund will be given for vehicle returns early.
7. No refund will be given for petrol left in vehicle.
8. Hirer is liable to pay all parking fee and traffic summonses.
9. Vehicles to be return during office hour only.
10. No Service on Public Holiday and Sunday.

CHARGES

2 Day at \$ 120.00 per days \$ 240.00
Day at \$ _____ per week
Day at \$ _____ per month

TOTAL AMOUNT \$ 240.00

AMOUNT PAID \$ 240.00

BALANCE DUE

Days Extension From To

Amount Deposit (refundable) \$

SCHEDULE

MODEL

SJ45730T

7/Altis

Date

Time

Mileage

21-02-2018 1515hrs

23-02-2018 1430hrs

FROM

21/2/18

TO

23/2/18

I/we have read and understood the terms and conditions above and hereby agreed to abide

Hirer's Signature

Driver/Gurantor's Signature

DAWN ENTERPRISES

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	22 Feb 2018 Edit Reg		21 Feb 2018 00:00 Edit Adj Rpt	S\$3,200.00 Edit Estimates	S\$3,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	LCRF PTE LTD , Co. Reg. No.: 201624597K								
Main Claimant:	GAN KEONG , ID: S0028675C								
Vehicle Reg. No.:	SCQ1166Z	Date of Loss:	16/02/2018 21:00 - :59 [15 Months and 21 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6575987196SG	Policy/Cover Note No.:	0999995090						
Vehicle Reg. No. (Insured):	SLN2873T	Policy No. (Claimant):	2100487319-00000						
		Excess:							
Repairer:	Hua Meng Spray Painting Workshop (HQ) No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki Bukit, 417883 Kaki Bukit - Tel: 67478064, 67465519								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Olea, Maricel] Maricel.Olea@aig.com								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 05/03/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG (23/02/2018): No OI GIA Report									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SCQ1166Z (6575987196SG)**
[SLN2873T]
TP
GAN KEONG
Feb 16 2018 9:00PM
[LCRF PTE LTD]
Hua Meng Spray Painting Workshop

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page			<input type="checkbox"/>		
No	Finalized On		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	(Draft)		Third Party Express Settlement – Payment Breakdown															Edit		
Assessment Reports															1 per page			<input type="checkbox"/>		
No	Finalized On		AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail			Print		
1	20/03/18 14:51		Accident Statement From: SC - Reg. No: SLN2873T, Claimant: LCRF PTE LTD															Load HTM		
Photos/Images															3 per page			<input type="checkbox"/>		
No	Relabel/Reorder		LKK Auto Consultants Pte Ltd (HQ)												Thumbnail			Print		
1	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
2	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
3	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
4	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
5	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
6	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
7	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
8	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
9	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
10	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
11	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
12	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
13	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
14	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
15	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
16	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
17	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
18	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
19	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
20	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
21	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
22	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
23	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
24	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
25	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
26	10/05/18 18:39		General View															Load JPG <input checked="" type="checkbox"/>		
27	10/05/18 18:39		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
28	10/05/18 18:39		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
29	10/05/18 18:39		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		
30	10/05/18 18:39		Reinspection Photo															Load JPG <input checked="" type="checkbox"/>		

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
32	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
33	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
34	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
35	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
36	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
37	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
38	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
39	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
40	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
41	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
42	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
43	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
44	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
45	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
46	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
47	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
48	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
49	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
50	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
51	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
52	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
53	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
54	10/05/18 18:39	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	23/02/18 08:58	TP GIA REPORT	Load PDF	
2	05/03/18 17:08	Email non reporting letter ACCIDENT INVOLVING SLN 2873T AND SCQ 1166Z ON 16.02.2018 2115 Hrs ALONG T	Load PDF	
3	20/03/18 15:15	Email letter to OI ACCIDENT INVOLVING SLN 2873T & SCQ 1166Z ON 16.02.2018	Load PDF	
4	31/05/18 10:12	WORKSHOP INVOICE	Load PDF	
5	31/05/18 10:13	AUTHORISATION TO ACT FORM	Load PDF	
6	31/05/18 10:13	Release Voucher	Load PDF	
7	31/05/18 10:13	RENTAL RECEIPT	Load PDF	
8	31/05/18 10:13	LTA SEARCH	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 100px; width: 100%;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLN2873T (Insd veh)	Model:	TOYOTA COROLLA ALTIS
	SCQ1166Z (TP veh)		1.6 CLASSIC CVT (A)
Date of Accident:	16/02/2018		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:	\$	9,297.95	
Final Repair Cost	:	\$	3,200.00	
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$	200.00	2 days
LTA / GIA Search Fee	:	\$	7.45	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	3,407.45	

Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ 100 _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____ (%) Assessed Liability (*): _____ (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Hua Meng Spray Painting Workshop	:	\$ 3,407.45
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

LKK Auto Consultants Pte Ltd

31 May
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/LCR18003426/AWB3Q2

Date: 31/05/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999995090
Claimant Vehicle No : SCQ1166Z **Insured Vehicle No :** SLN2873T
 Date of Loss: 16/02/2018 Nature of Claim: TP Claim No: 6575987196SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SCQ1166Z**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A) Engine No: 1ZRY327358
 Reg. Date: 26/10/2016 (Man. Year: 2016) Chassis No: MR053REH104556610
 Colour: Grey Odometer: 15040 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,247.95	2,696.30	3,551.65	56.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,050.00	1,300.00	1,750.00	57.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,297.95	3,996.30	5,301.65	57.02
Approved Total (Overridden) (S\$)		3,200.00		
Nett Amount (S\$)	9,297.95	3,200.00	6,097.95	65.58
+ Car Rental (2.0 x S\$100.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		3,407.45		

INSPECTION

Date of Assignment: 21/02/2018
 Date Inspected: 21/02/2018 Inspected At: Hua Meng Spray Painting Workshop (HQ)
 No 1 Kaki Bukit Avenue 6, #01-61
 Autobay@Kaki Bukit
 Singapore 417883
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Buckled	666.40 FL	*666.40 FL
2	2		*REAR BOOT LID HINGES	Not Necessary	143.40 FL	*- FL
3	1		*REAR BOOT LID UPPER LOCK	Not Necessary	420.20 FL	*- FL
4	1		*REAR BOOT LID LOWER LOCK	Not Necessary	32.70 FL	*- FL
5	1		*REAR BOOT LID CENTRE LOGO	Necessary	57.40 FL	*57.40 FL
6	1		*REAR BOOT LID COROLLA EMBLEM	Necessary	46.50 FL	*46.50 FL
7	1		*REAR BOOT LID ALTIS EMBLEM	Necessary	48.50 FL	*48.50 FL
8	2		*REAR BOOT LID REFLECTOR	Not Necessary	669.40 FL	*- FL
9	1		*REAR BOOT LID WEATHER STRIP	Not Necessary	183.00 FL	*- FL
10	1		*REAR BOOT LID CABLE	Not Necessary	73.00 FL	*- FL
11	1		*REAR BUMPER	Deformed	530.20 FL	*530.20 FL
12	2		*REAR BUMPER SIDE HOLDER	Necessary	229.60 FL	*229.60 FL
13	1		*REAR BUMPER REINFORCEMENT	Dented	419.80 FL	*395.00 FL
14	2		*REAR BUMPER BRACKET	Not Necessary	94.00 FL	*- FL
15	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FL	*30.00 FL
16	1		*REAR BUMPER LOWER REFLECTOR	O/S Cracked	124.80 FL	*62.40 FL
17	1		*REAR RH LAMP	Cracked	310.10 FL	*310.10 FL
18	1		*REAR END PANEL	Repair	639.30 FL	*- FL
19	1		*REAR EXHAUST PIPE	Bent	952.30 FL	*952.30 FL
20	1		*REAR BOOT LID CAMERA	Not Necessary	800.00 FS	*- FS
21	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
22	1		*REAR CAMERA	Not Necessary	800.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,670.60	3,528.40
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,422.65	832.10
Total Parts (\$\$)	6,247.95	2,696.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO SUPPLY REAR END PANEL INNER SEALANT	New	50.00	0.00
2	REMOVE & REINSTALL REVERSE SENSOR	New	150.00	60.00
3	REMOVE & REINSTALL CAMERA	New	100.00	60.00
4	REMOVE & REINSTALL BOOT LID INNER GARNISH	New	200.00	0.00
5	REMOVE & REINSTALL EXHAUST PIPE	New	150.00	80.00
6	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,200.00	500.00
7	RESPRAY PAINTING	New	1,100.00	600.00
8	TUFF KOTE	New	100.00	0.00
Gross Labour Cost (S\$)			3,050.00	1,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >