


SMRT Accident Vehicle Repair Estimates

Ty

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHD6355X
Ref. No : TAX/02/18/2081
Reg. Date : 14/12/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : CHEONG WING FATT
Type of Accident : SIDE SWIPE
Date / Time of Accident : 12/02/2018 10:09:00 AM
Accident Reported Date / Time : 12/02/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024094658
Special Instruction to ARC, if any :
SHC8382J(COMFORT) - III
Prepared Date : 20/02/2018 10:18:08 AM



*Submission
24/2/18*

- Part by part repair
- Question Mark Item
- Photo
- Photo Before Painting

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU303576730

Mileage

:

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 676.00	0.00
Total Spray Painting Charges	: 756.00	0.00
Total Material Charges	: 4,498.26	4,498.26
Other Charges	: 340.00	0.00
TOTAL	: 6,270.26	0.00
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 5.00	0.00
Prepared / Adjusted By	:	4 days
Arc / Surveyor Sing Off Date	: 20/02/2018 04:59:12 PM	01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 20/02/2018 04:59:12 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH FRONT PORTION	676.00	0.00 400
Total Labour	676.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
Total Spray Painting & Panel Beating	756.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 40
TO REPLACE SUNDRY PARTS	100.00	0.00 X
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	340.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119479 62			COVER, FR BUMPER	1	495.50	25.00	371.62	Replace	Replace ✓	No CRK
81220470 20			LAMP ASSY, FOG, LH	1	910.20	10.00	819.18	Replace	Replace ✓	No SCK
81185476 91			UNIT, HEADLAMP, LH	1	2,558.90	10.00	2,303.01	Replace	Replace ✓	No SCK
52116470 50			SUPPORT, FR BUMPER LH	1	82.30	25.00	61.72	Replace	Replace ?	No
53802471 00			FENDER SUB-ASSY, FR, LH	1	933.10	25.00	699.82	Replace	Replace ✓	No DT
75374471 40			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	25.00	39.67	Replace	Replace ✓	No NSC
53876471 10			LINER, FR FENDER, LH	1	194.30	25.00	145.72	Replace	Replace ✓	No TW
53214470 50			SUPPORT, RADIATOR UPPER LH	1	76.70	25.00	57.52	Replace	Replace ?	No
TOTAL MATERIALS								4,498.29	4,498.26	
TOTAL MATERIALS(Discounted)								4,498.26	4,498.26	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									