

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9835T -**AAD1802-165***Not Authorized**1/12/2018 @ 1150L*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHB9835T - JHOW

VF1ABL15AUC273341

RENAULT

LATITUDE

17.02.2018

AIG

PART			LIST	
1	1	BUMPER COVER FRT	\$	<i>SL</i> 1,259.42 X
2	1	BUMPER RETAINER FRT LH	\$	<i>SL</i> 151.41 X
3	1	BUMPER SUPPORT FRT LH	\$	<i>SL</i> 123.88 X
4	1	FENDER PANEL FRT LH	\$	<i>R</i> 783.83 X
5	1	WHEELARCH FRT LH	\$	<i>SL</i> 278.84 X
6	1	DOOR MIRROR LH	\$	<i>CM</i> 1,483.40 ✓
7	1	DOOR MIRROR GLASS LH	\$	<i>NP</i> 148.20
8	1	DOOR MIRROR BACK COVER LH	\$	<i>NN</i> 218.46
9	1	DOOR PANEL FRT LH	\$	<i>R</i> 2,844.66
10	1	DOOR HINGE UPPER LH	\$	<i>R</i> 274.50
11	1	DOOR HINGE LOWER LH	\$	<i>R</i> 300.55
12	1	DOOR GLASS FRT LH	\$	<i>SL</i> 722.26
TOTAL			\$	8,589.42
10%			\$	858.94
			\$	7,730.48

Specical Nett

1	1SET	FRONT BUMPER CLIP	\$	<i>NN</i> 66.00
2	1SET	WHEELARCH CLIP LH	\$	<i>NN</i> 66.00
3	1	TOW COVER FRT	\$	<i>SL</i> 14.50
4	1	CAP HUB LH FRT	\$	<i>SL</i> 35.00
5	1	RIM LH FRT	\$	<i>SL</i> 385.00
6	1	TYRE LH FRT	\$	<i>SL</i> 330.00
7	1SET	BUMPER SUPPORT FRT CLIP LH	\$	<i>NN</i> 9.80
8	1SET	BUMEPR RETAINER FRT CLIP LH	\$	<i>NN</i> 12.50
9	1	DOOR STICKER "Trans-cab"	\$	<i>NN</i> 80.00
10	1	DOOR STICKER "Classic"	\$	<i>NN</i> 30.00
TOTAL			\$	1,028.80
TOTAL PARTS			\$	8,759.28

TRANS-CAB AUTO SERVICES PTE LTD**AAD1802-165**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHB9835T -

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,800.00	601
To Check Electrical Lighting Concerned.	\$	170.00	201
Putty and spray painting of the affected portion.	\$	3,000.00	501
To check steering geometry and computer wheel alignment	\$	220.00	~ X
Towing Fees	\$	120.00	~ X
To transfer of tire, rim and on wheel balancing.	\$	170.00	~ X
To rust-proofing of the affected areas.	\$	170.00	~ X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	170.00	~ X
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	~ X

TOTAL	\$	6,990.00
Over All Total	\$	15,749.28

(PARTS BY PARTS) Repair Days**10 Days***1 day*

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: _____ Date: _____
--